



Punjab Municipal Development Fund Company

Hiring of Consulting Services for Preparation of Integrated Development and Asset Management Plan (IDAMP) for 16 selected MCs In Punjab under Punjab Cities Program (PCP)

**IDAMP - Municipal Committee Burewala
May 2023**



Table of Contents

| | |
|---|----|
| Section 1. Introduction | 5 |
| Section 2. Overview - Municipal Committee Burewala | 12 |
| Section 3. Existing Asset Inventory Analysis | 15 |
| Section 4. Level of Services (LOS) | 19 |
| Section 5. IDAMP Projects | 29 |
| Section 6. Financial and Economic Analysis | 40 |
| Annexure | 43 |

List of Tables

| | |
|---|----|
| Table 1: Existing Assets Summary | 15 |
| Table 2: Condition of Existing Assets | 16 |
| Table 3: Current & Target LOS | 19 |
| Table 4: IDAMP Projects | 29 |
| Table 5: Projects Detail | 31 |
| Table 6: Annual Financial Projections | 42 |

01 Introduction

Section 1. Introduction

1.1. Context

Punjab's urban metropolises are growing at an alarming rate thereby accelerating the demand at the municipal service levels. The gap between supply and demand in terms of quality of services at the municipal level rings a bell at the corridors of stakeholders both at government and local levels. Accordingly, the study seeks to identify viable business solutions for effective service deliveries. In particular, this report investigates the conditions of assets, both moveable and immovable, at the MC level to elucidate the foundation for the development of IDAMP.

Infrastructure plays a pivotal role in achievement of service delivery objectives of public sector entities. Without long term planning and optimal management of infrastructure, risk of failure to meet the service delivery program increases significantly. Thus, infrastructure management is a critical concern for the sustainability of public sector entities.

Keeping in view the importance of infrastructure, an IDAMP Framework has been developed which spells out the principles for effective development and management of asset portfolio in order to achieve service delivery objectives, prescribes a consistent approach and a common methodology for development and management of assets and provides guidelines to ensure informed decision making by Municipal Committees for investment in and management of those assets which help the achievement of the service delivery objectives.

1.2. Scope

This document has been prepared for Integrated Development and Asset Management Planning of Municipal Committee (MC) Burewala. Thus, this document is confined to the planning and management of assets of MC Burewala.

1.3. Brief Methodology for IDAMP Development

The methodology employed for the preparation of the Integrated Development and Asset Management Plan (IDAMP) involved several key steps, which are summarized as follows:

1. Development of Asset Inventory Database

The first step in the IDAMP methodology was to develop a comprehensive asset inventory by PMDFC. This included identifying different asset categories and collecting relevant attribute data. Further, data available at PMDFC and MCs was thoroughly reviewed to ensure accurate and synchronized documentation. This involved cross-referencing and aligning the available data with the requirements of the project. This served as a fundamental basis for integrated asset management.

2. Asset Condition Analysis

It was imperative to have a clear picture of the physical condition of assets and current level of service. Decisions regarding maintenance, rehabilitation and renewal revolved around these two aspects. Asset physical condition analysis was used to determine the need and timing of some preventative or corrective maintenance to ensure desired Level of Service and prevent service breakdown. Below is given the different categories of condition together with reasons/actions for the applicable condition:

| Category | Asset Condition | Actions Required |
|----------|-----------------|---------------------|
| <i>A</i> | Excellent | Routine Maintenance |
| <i>B</i> | Good | Minor Repair |
| <i>C</i> | Fair | Major Repair |
| <i>D</i> | Poor | Rehabilitation |
| <i>E</i> | Failing | Replacement |

3. Current and Target Level of Services (LOS)

To ensure optimal service delivery, an analysis of asset divergence was conducted to assess the alignment between the existing asset inventory and the desired level of service (LOS). This step involved identifying the current level of services, setting target LOS, evaluating the service delivery gap, assessing asset condition assessment, and planning for necessary asset improvements accordingly.

Gap analysis reports and energy audit reports (where available) were reviewed to identify and define the existing infrastructure assets. These reports provided insights into the gaps and deficiencies in the current infrastructure and helped in formulating appropriate strategies for improvement. Further, sectoral plans for infrastructure investments were carefully reviewed to ensure synchronization with the target level of service.

Additionally, community consultative sessions were conducted to gather valuable insights into the needs and desires of the local community. Furthermore, it was made a priority to consult with the management and staff of the respective MCs during our field visits. Please refer **Annexure F** for details.

4. Identification of Projects

Once the inventory and performance targets were updated, project proposals were developed to bridge the service delivery gap. Project were identified based on asset types, for rehabilitation/replacement of existing assets or the creation of new assets. The project proposals encompassed project identification, preparation, and appraisal, ensuring that steps were taken to achieve the target LOS.

Preliminary estimates for capital expenditure and Operating and Maintenance (O&M) costs of identified projects were made. Considering the project scope, capital cost of the projects incorporated both the initial one-off costs such as engineering cost, project construction cost, development cost, procurement cost of equipment, machinery & other assets, utility set up cost, and any other costs to be incurred during the construction period. O&M cost to be incurred during operational phases of the project, which included preventive maintenance cost, electricity and other utility cost, administrative expenses, payroll cost and other overheads etc.

Following matrix is used for the computation of O&M costs:

| Sr. | Sectors/ Projects | Annual O&M Cost (%age of Capital Cost) |
|-----|---------------------------------|--|
| 1 | Water Supply | 5% |
| 2 | Filtration Plants/OHR | 10% |
| 3 | GST (Ground Storage Tank) | 2.50% |
| 4 | Sewerage Network | 2.50% |
| 5 | Roads | 5% |
| 6 | Street Lights | 2.50% |
| 7 | Parks, Playgrounds, Open Spaces | 2.50% |
| 8 | Buildings | 0.5% |

| Sr. | Sectors/ Projects | Annual O&M Cost (%age of Capital Cost) |
|-----|-----------------------|--|
| 9 | Bus stand | 2.50% |
| 10 | Slaughterhouse | 2.50% |
| 11 | Storm water drainage; | 1% |
| 12 | Municipal libraries; | 0.5% |
| 13 | Solarization | 0.5% |

5. Financial Capacity Analysis

Analyzing potential financial sources was a crucial step to finance capital investments. This involved examining local capital revenues, planned operating surplus, provincial government transfers, and donor grants as potential funding sources. This analysis provided insights into the available financial capacity to support selected projects, guiding decision-making regarding project selection and phasing.

6. Project Screening & Phasing

Projects were screened and phased over a three-year period based on specific criteria. Projects were evaluated against each of the following factors and assigned scores:

- Project purpose and service delivery improvement
- Public Response/Community and citizens feedback
- Environment and Social Impacts
- Socio-economic impacts analysis
- Ease of implementation

Relative scoring criteria was used for the phasing, wherein projects achieving the highest scores are prioritized in the first year, subject to the availability of finances. Similarly, the scores are reviewed to determine the phasing of projects in the second and third years. This approach ensures the prioritized implementation of projects based on their relative merits.

1.4. Technical Inputs, Assumptions and Limitations

- The initial information of existing assets was obtained from PMDFC and MC Burewala. The data was obtained from multiple sources including Asset Management Information System. Additionally, energy audit reports, shape files, and gap analysis reports were also used to supplement the initial information.
- Asset inventory forms were designed to compile the asset attribute and condition information in consultation with the PMDFC management. The baseline data used for carrying out the condition assessment of assets was sourced from various reports provided by the PMDFC and MC Burewala. It primarily consisted of information related to the existing assets, including their names, numbers, residual life, technical specifications and other attributes of assets.
- Site surveys were also conducted to verify the information and collect any missing information. The compiled information was then shared with the MC Burewala management for their verification and endorsement.
- Age was the primary factor considered for assessing the condition of the water and sewerage network.
- The determination of the current and target level of service has been formulated through a consultative process involving relevant MC staff, and the analysis of data obtained from energy audit reports and gap analysis reports. For the computation of current level of service, following sources were consulted:
 - Served and built-up areas for different sectors were calculated from the relevant sectors' maps;
 - Total population of MC was taken from the census report of Pakistan Bureau of Statistics (PBS) while applying population growth rates for the incremental period;
 - Daily water supplied to the distribution system was calculated on the basis of capacity of tubewell and average daily operational hours of tubewell;
 - Non revenue water was computed by considering actual revenue collected by MC and total connections in the served area;
 - Total number of pipe leakages of the water distribution network was computed on the basis of number of complaints received by MC. It was assumed that one complaint represented one pipe leakage;
 - Total number of sewerage blockages was computed on the basis of number of complaints received by MC. It was assumed that one complaint represented one sewerage blockage; and

- The total annual operating expenses for each sector were determined based on the expenditure report provided by the MC staff, which covered nine (9) months' worth of data. To obtain the annual operating expenses, an extrapolation method was used to estimate the remaining three (3) months' expenditures.
- Target level of services were determined considering the findings from condition assessment, findings of energy audit reports, findings from gap analysis reports, consultative sessions with MC management and community.
- PMDFC has actively engaged in community consultative sessions to gather valuable insights into the needs and desires of the local community. Furthermore, we have made it a priority to consult with the management and staff of the respective Municipal Committees (MCs) during our field visits. This collaborative approach has allowed us to gain valuable perspectives from those directly involved in the day-to-day operations of the MCs and the feedback and insights gathered from these consultative sessions, both with the community and MC stakeholders, have been carefully analyzed and incorporated into the IDAMPs of the respective MCs.
- Projects (repair/ rehabilitation/ new creation) were identified in consultation with the respective Asset Managers keeping in view the service delivery gaps.
- Rough cost estimates (Capital and Operational & Maintenance) was performed on the basis of Market Rating System (MRS) and Non MRS rates of items.
- Identified projects were evaluated on the basis of project screening and phasing criteria prescribed in the IDAMP Framework.
- The cost and book values of the MC assets have been provided by PMDFC staff.

02 Overview - Municipal Committee Burewala

Section 2. Overview - Municipal Committee Burewala

2.1. Introduction

Burewala is a city of Vehari District in southern Punjab, Pakistan. It is located at 30°10'0N 72°39'0E and has an altitude of 133 metres (439 feet). As of 2000, it is the 31st biggest city in Pakistan by population. The city of Burewala is the headquarters of Burewala Tehsil, an administrative subdivision of the district. It is located 1035 km away from Karachi, 187 km from Faisalabad, 208 km from Lahore, 135 km from Multan, 35 km from Vehari, 40 km from Arifwala, 75 km from Pakpattan and 103 km from Bahawalpur.¹

2.2. Functions of Municipal Committee Burewala

Section 31(p) of the Local Government Act, 2022, the Municipal Committees to provide, manage, operate, maintain and improve municipal infrastructure and services, including:

- water supply and control and development of water sources
- sewage and sewage treatment and disposal
- storm water drainage
- sanitation and solid waste collection and disposal of solid wastes, treatment and disposal including landfill site and recycling plants
- roads and streets
- public transport and mass transit systems, construction of express ways, flyovers, bridges, roads, under passes, traffic planning, engineering and management including traffic signaling systems, signs on roads, street markings
- firefighting
- street lighting
- parks, playgrounds, open spaces
- parking stands

¹ <https://mcburewala.lgpunjab.org.pk/about-us/history/>

- graveyards
- arboriculture/ tree afforestation;
- parking places;
- transport stations, stops, stands and terminals;
- slaughterhouses;
- municipal libraries;
- community and cultural centers;
- land use planning;
- building control; and
- environmental protection.

03 Existing Asset Inventory Analysis

Section 3. Existing Asset Inventory Analysis

Over the years, MC Burewala has accumulated a large inventory of assets through development schemes and direct procurements. However, a centralized record of assets had not been maintained due to absence of a proper asset management system. Furthermore, as the development work used to be carried out through 'schemes', the asset generated through schemes could not be identified and classified into appropriate asset categories.

3.1. Existing Assets Summary

The summary of existing assets of MC Burewala based on its' functions is presented below:

Table 1: Existing Assets Summary

| Sr No. | Asset Category | Asset Sub-Category | Unit | Total |
|--------|---------------------|----------------------|-------|--------|
| 1 | Water Supply System | Tube wells | No. | 50 |
| | | Water Supply Network | Meter | 186854 |
| | | OHR | No. | 13 |
| | | Filtration Plants | No. | 20 |
| | | Vehicles | No. | 4 |
| 2 | Sewerage System | Sewerage Network | Meter | 191166 |
| | | Disposal Stations | No. | 4 |
| | | Vehicles/ Machinery | No. | 16 |
| 3 | Recreational | Park | No. | 4 |
| 4 | SWM Resource | Machinery/ Vehicles | No. | 660 |
| | | Dumping Site | No. | 3 |
| 5 | Buildings | Offices | No. | 1 |

| Sr No. | Asset Category | Asset Sub-Category | Unit | Total |
|--------|-----------------|--------------------|------|-------|
| | | Library | No. | 1 |
| 6 | Public Places | Slaughter Houses | No. | 1 |
| | | Bus Stand | No. | 1 |
| 7 | Shops | Shops | No. | 1034 |
| 8 | Office Vehicles | Office Vehicles | No. | 3 |
| 9 | Street Lights | Street Lights | No. | 209 |
| 10 | Roads | Roads | No. | 27 |

The detail of asset is provided in Annexure A.

3.2. Condition of Existing Assets

The condition of assets of MC is presented below:

Table 2: Condition of Existing Assets

| Sr No. | Asset Category | Asset Sub-Category | Asset Condition | | | | | Unit | Total |
|--------|---------------------|----------------------|-----------------|----------|----------|----------|-------------|-------|--------|
| | | | Excellent (A) | Good (B) | Fair (C) | Poor (D) | Failing (E) | | |
| 1 | Water Supply System | Tube wells | - | 9 | 23 | 1 | 17 | No. | 50 |
| | | Water Supply Network | - | 56055 | - | - | 130798 | Meter | 186854 |
| | | OHR | - | - | - | 1 | 12 | No. | 13 |
| | | Filtration Plants | - | 2 | 9 | 5 | 4 | No. | 20 |
| | | Vehicles | - | 1 | 3 | - | - | No. | 4 |

| Sr No. | Asset Category | Asset Sub-Category | Asset Condition | | | | | Unit | Total |
|--------|-----------------|---------------------|-----------------|----------|----------|----------|-------------|-------|--------|
| | | | Excellent (A) | Good (B) | Fair (C) | Poor (D) | Falling (E) | | |
| 2 | Sewerage System | Sewerage Network | - | - | - | - | 191166 | Meter | 191166 |
| | | Disposal Stations | - | - | 3 | 1 | - | No. | 4 |
| | | Vehicles/ Machinery | - | 4 | 12 | - | - | No. | 16 |
| 3 | Recreational | Park | - | 1 | 2 | 1 | - | No. | 4 |
| 4 | SWM Resource | Machinery/ Vehicles | 599 | 52 | 7 | 2 | - | No. | 660 |
| | | Dumping Site | - | - | 1 | 2 | - | No. | 3 |
| 5 | Buildings | Offices | - | 1 | - | - | - | No. | 1 |
| | | Library | - | - | 1 | - | - | No. | 1 |
| 6 | Public Places | Slaughter Houses | - | - | 1 | - | - | No. | 1 |
| | | Bus Stand | - | - | 1 | - | - | No. | 1 |
| 7 | Shops | Shops | - | 1030 | 4 | - | - | No. | 1034 |
| 8 | Office Vehicles | Office Vehicles | - | - | 2 | 1 | - | No. | 3 |
| 9 | Street Lights | Street Lights | 191 | - | - | - | 18 | No. | 209 |
| 10 | Roads | Roads | - | - | 1.5 | 25.5 | - | No. | 27 |

04 Level of Services (LOS)

Section 4. Level of Services (LOS)

Assets are planned and managed for the service delivery to the consumers. Therefore it is pertinent to assess the current service level and set out the desired service level over a certain period by keeping in view the community needs and demands. In order to measure the service levels, indicators are designed on which periodic assessments of the level of service are carried out.

A set of Level of Service (LOS) indicators has been prescribed for the MCs for achievement of the service delivery objectives. The MCs shall compute their existing LOS and set the target LOS for the next three years. Target LOS shall be used as key performance indicators to assess the performance of assets and monitor the extent of service delivery by the MCs.

The current and target level of service for MC Burewala are provided here under:

Table 3: Current & Target LOS

| Functions of MCs (municipal services) | Level of Service Indicators | Description | Current LOS | Target LOS for three years | Project Name | Timeframe (FY) |
|--|--|--|-------------|----------------------------|--|----------------|
| Water supply and control and development of water sources; | Water Supply Coverage by MC % | Percentage of area, where water supply network is available in comparison to total built up area. | 55% | 70% | Improvement & Rehabilitation of Water Supply system in Burewala City | 2023-2024 |
| | Water Supply Coverage by private wells % | Percentage of area, where residents have own water sources. | 45% | 30% | | |
| | Water production GPCD | Total daily water supplied to the distribution system (ex-treatment plant and including purchased water, if any) expressed by population served per day. | 9 | 15 | | |
| | Non-revenue water % | Difference between total water produced (ex -treatment plant) and total water sold expressed as a percentage of total water produced. | 98% | 98% | | |

| Functions of MCs (municipal services) | Level of Service Indicators | Description | Current LOS | Target LOS for three years | Project Name | Timeframe (FY) |
|---------------------------------------|---|--|-------------|------------------------------|---|----------------|
| | Pipe breaks (Leakages/Breaks /Km) | Total number of pipe leakages/breaks per year expressed per km of the water distribution network. | N/A | Reduced leakages | Improvement & Rehabilitation of Water Supply system in Burewala City | 2023-2024 |
| | Unit operational cost - water sold (production cost at consumer end) (PKR) | Total annual operating expenses divided by the total annual volume of water sold. | 0.13 | 0.11 | Solarization of Tube wells and Water Supply System | 2023-2024 |
| | Water supply staff per 1000 water connections (No.) | Total number of water supply staff expressed as per thousand water connections. | 17.4 | 17.4 | | |
| | Salary cost as proportion of Operating costs | Total annual salary costs (including salaries, wages, pensions, other benefits, etc.) Expressed as a percentage of total annual operating costs. | 46% | 46% | | |
| | Power and Electricity Costs as proportion of Operating Costs | Total annual power/electricity costs of the utility expressed as a percentage of total annual operating costs. | 52% | 44% | Solarization of Tube wells and Water Supply System | 2023-2024 |
| | Unfit water samples % (not conforming with the requirements of NEQ) | Total number of unfit water samples (not conforming with the requirements of NEQ) expressed as a percentage of total samples taken. | N/A | Improved water quality | Improvement & Rehabilitation of Water Supply system in Burewala City | 2023-2024 |
| | Continuity of Service Hrs. / Day Average hours of service per day for water supply. | Average hours of service per day for water supply. (Average operational hours of tube well per day) | 5 | 5 | | |
| | Water Supply Complaints % | Total number of water supply complaints per year expressed as a percentage of the total number of water supply connections. | N/A | Reduced number of complaints | 1.Improvement & Rehabilitation of Water Supply system in Burewala City. | 2023-2024 |

| Functions of MCs (municipal services) | Level of Service Indicators | Description | Current LOS | Target LOS for three years | Project Name | Timeframe (FY) |
|---|--|--|-------------|----------------------------|---|----------------|
| | | | | | 2.SCADA system for tube wells and disposal stations. | |
| | Operational cost coverage (Ratio) | Total annual operational revenues/Total annual operating cost. | 3% | 3.45% | Solarization of Tube wells and Water Supply System | 2023-2024 |
| Sewage and sewage treatment and disposal; | Sewerage Coverage % | Population with sewerage services (direct service connection) as a percentage of the total population. (Total served area as a percentage of the total built up area) | 47% | 47% | | |
| | Risk of crown failure | Whether there is an indication of crown failure? | Yes | No | Improvement of Existing Sewerage System and Disposal Stations for Burewala City | 2023-2026 |
| | Sewerage blockages (Blockages/KM) | Total number of blockages/ complaints per year expressed per km of sewers | 2 | 0.82 | | |
| | Sewerage staff per 1000 sewerage connections | Total number of sewerage staff expressed as per thousand sewerage connections | 1.49 | 1.49 | | |
| | Waste water Treatment - Primary (%) | Proportion of collected sewage that receives primary treatment only, i.e. involving settlement with the intention of removing solids, but not biological treatment. Both lagoon and mechanical treatment can be included, where appropriate. | N/A | 100% | Improvement of Existing Sewerage System and Disposal Stations | 2023-2026 |

| Functions of MCs (municipal services) | Level of Service Indicators | Description | Current LOS | Target LOS for three years | Project Name | Timeframe (FY) |
|--|---|---|-------------|----------------------------|-------------------|----------------|
| | Waste water Treatment - Secondary (%) | Proportion of collected sewage that receives at least secondary treatment, i.e. removing oxygen demand as well as solids, normally biological. Both lagoon and mechanical treatment can be included, where appropriate. | N/A | 100% | for Burewala City | |
| | Sewerage Complaints (%) | Total number of sewerage complaints per year expressed as a percentage of the total number of sewerage connections. | 0.3% | Reduced complaints | | |
| Storm water drainage; | Storm water drainage coverage (%) | The percentage of MC area that the drainage system protects from flooding. | 47% | 47% | | |
| Sanitation and solid waste collection and disposal of solid wastes, treatment and disposal including landfill site and recycling plants; | Collection efficiency (%) | Total amount of solid waste collected expressed as a percentage of total solid waste produced. | 55% | 55% | | |
| | Disposal efficiency (%) | Total amount of solid waste disposed off expressed as a percentage of total solid waste collected. | 100% | 100% | | |
| | Door-to-door (%) | Percentage of area with door-to-door solid waste collection. | 0% | 0% | | |
| | Primary SWM Coverage each day in localities (%) | Percentage of area from which the sanitary staff sweeps & collects waste each day | 55% | 55% | | |
| | Primary SWM Coverage each day in Roads (%) | Primary SWM Coverage each day in Roads | 55% | 55% | | |
| | Open Collection Points (No.) | Open Collection Points | 38 | 38 | | |
| | Secondary collection machinery (No.) | Secondary collection machinery | 8 | 8 | | |
| | Adequacy of parking facilities for SWM vehicles | Adequacy of parking facilities for SWM vehicles | Yes | Yes | | |
| Waste transported in covered vehicles | Waste transported in covered vehicles | No | No | | | |

| Functions of MCs (municipal services) | Level of Service Indicators | Description | Current LOS | Target LOS for three years | Project Name | Timeframe (FY) |
|---------------------------------------|---|--|------------------|----------------------------|---------------------------------------|----------------|
| | Sufficiency of existing dumping area (Landfill site). | Sufficiency of existing dumping area (Landfill site). | Yes | Yes | | |
| | Mechanism for Final Disposal | Is there any mechanism for final disposal? | No Landfill Site | No Landfill Site | | |
| Roads and streets; | Roads with condition "A" (Excellent) % | Total length of roads with condition "A" expressed as a percentage of total roads. | 0% | 95% | Improvement & Rehabilitation of Roads | 2023-2024 |
| | Roads with condition "B" (Good) % | Total length of roads with condition "B" expressed as a percentage of total roads. | 0% | 5% | | |
| | Roads with condition "C" (Fair) % | Total length of roads with condition "C" expressed as a percentage of total roads. | 6% | 0% | | |
| | Roads with condition "D" (Poor) % | Total length of roads with condition "D" expressed as a percentage of total roads. | 94% | 0% | | |
| | Roads with condition "E" (Failing) % | Total length of roads with condition "F" expressed as a percentage of total roads. | 0% | 0% | | |
| | Beautification of chowks % | Number of chowks having monuments expressed as a percentage of total chowks. | | | | |
| Streetlighting; | Streetlight coverage. (%) | Percentage of area/roads with streetlights. | 37.1% | 37.1% | | |
| | Working Streetlight % | Percentage of working streetlights as of total streetlights. | 91% | 100% | | |
| Parks, Playgrounds, Open spaces; | Open spaces as percentage of total MC area. % | Open spaces as percentage of total MC area. % | 0% | 0% | | |

| Functions of MCs (municipal services) | Level of Service Indicators | Description | Current LOS | Target LOS for three years | Project Name | Timeframe (FY) |
|---------------------------------------|---|--|-------------|----------------------------|--|----------------|
| | Playgrounds as percentage of total MC area. % | Playgrounds as percentage of total MC area. % | 0% | 0% | | |
| | Parks with condition "A" (Excellent) % | Parks with condition "A" expressed as a percentage of total parks. | 0% | 0% | Improvement and Rehabilitation of Parks in Burewala City | 2025-2026 |
| | Parks with condition "B" (Good) % | Parks with condition "B" expressed as a percentage of total parks. | 25% | 50% | | |
| | Parks with condition "C" (Fair) % | Parks with condition "C" expressed as a percentage of total parks. | 50% | 50% | | |
| | Parks with condition "D" (Poor) % | Parks with condition "D" expressed as a percentage of total parks. | 25% | 0% | | |
| | Parks with condition "E" (Failing) % | Parks with condition "E" expressed as a percentage of total parks. | 0% | 0% | | |
| | Parks as percentage of total MC area. % | Parks as percentage of total MC area. % | 0.3% | 0.3% | | |
| Graveyards; | Graveyards as percentage of total MC area. % | Graveyards as percentage of total MC area. % | 0% | 0% | | |
| | Graveyards with condition "A" (Excellent) % | Total area of graveyards with condition "A" expressed as a percentage of total area of graveyards. | 0% | 0% | | |
| | Graveyards with condition "B" (Good) % | Total area of graveyards with condition "B" expressed as a percentage of total area of graveyards. | 0% | 0% | | |
| | Graveyards with condition "C" (Fair) % | Total area of graveyards with condition "C" expressed as a percentage of total area of graveyards. | 0% | 0% | | |
| | Graveyards with condition "D" (Poor) % | Total area of graveyards with condition "D" expressed as a percentage of total area of graveyards. | 0% | 0% | | |

| Functions of MCs (municipal services) | Level of Service Indicators | Description | Current LOS | Target LOS for three years | Project Name | Timeframe (FY) |
|--|--|--|-------------|----------------------------|--|----------------|
| | Graveyards with condition "E" (Failing) % | Total area of graveyards with condition "E" expressed as a percentage of total area of graveyards. | 0% | 0% | | |
| Transport stations, stops, stands and terminals; | Ratio of bus stations to the total length of roads | Ratio of bus stations to the total length of roads | 1:35 | 1:35 | | |
| | Adequacy of facilities at bus stands | Adequacy of facilities at bus stands | No | Yes | Construction of General Bus Stand (GSB) in Burewala City | 2024-2025 |
| Slaughterhouses; | Adequacy of slaughterhouses | Adequacy of slaughterhouses keeping in view the population of the MC | Yes | Yes | | |
| | Adequacy of facilities in slaughterhouses | Adequacy of facilities in slaughterhouses in terms of tools, disinfectants, refrigeration/ storage systems, drainage and disposal facility, etc. | No | Yes | Rehabilitation of slaughter house | 2025-2026 |
| Municipal libraries; | Total number of Libraries per 100,000 persons | Total number of Libraries per 100,000 persons | 1 | 1 | | |
| | Adequacy of facilities in library | Adequacy of facilities in library in terms of books, computers, furniture, air-conditioning, lighting, drinking water etc. | No | No | | |
| Buildings | Buildings with condition "A" (Excellent) % | Total number of buildings with condition "A" expressed as a percentage of total number of buildings. | | | | |
| | Buildings with condition "B" (Good) % | Total number of buildings with condition "B" expressed as a percentage of total number of buildings. | 50% | | | |
| | Buildings with condition "C" (Fair) % | Total number of buildings with condition "C" expressed as a percentage of total number of buildings. | 50% | | | |

| Functions of MCs (municipal services) | Level of Service Indicators | Description | Current LOS | Target LOS for three years | Project Name | Timeframe (FY) |
|---------------------------------------|--|---|-------------|----------------------------|---|----------------|
| | Buildings with condition "D" (Poor) % | Total number of buildings with condition "D" expressed as a percentage of total number of buildings. | | | | |
| | Buildings with condition "E" (Failing) % | Total number of buildings with condition "E" expressed as a percentage of total number of buildings. | | | | |
| | Solar Penetration Index (SPI) % | The Solar Penetration Index (SPI) measures the percentage of MC office buildings that have successfully undergone solarization. | 0% | 100% | Solarization of the municipal buildings | 2023-2024 |

Notes:

- While achieving the target level of service, MC shall ensure conformance with applicable laws and regulations including but not limited to land use planning, building control, environmental and social considerations.
- Environmental and social considerations are provided in Annex D.
- Comprehensive list of LOS indicators is provided in IDAMP Framework, please refer to section 5, however, certain LOS indicators are not applicable to MC Burewala such as metered water connections, firefighting coverage etc.
- For certain service levels, the existing level of service is sustained during the term of IDAMP i.e. three years, despite the recognized need for enhancements. This circumstance arises due to various factors, including but not limited to funding constraints, the reluctance of asset owners to initiate required modifications and the lack of suitable land availability. Nevertheless, it is crucial to emphasize that the preparation and revision of the IDAMP is an ongoing process. As a result, the target level of service in these areas may be redefined in the future, facilitating the implementation of potential improvements.
- The calculation of daily water supplied to the distribution system has considered the capacity of tubewells, in combination with the average hours of service per day for water supply.

- In order to reduce the reduction in non-revenue water, certain initiatives are required such as capacity building for MC staff, the installation of water meters, tariff revisions, regulatory reforms, among other measures. It's important to note that the percentage of non-revenue water may not necessarily improve solely with an increase in water production.
- As regards to landfilling, developing regional landfill sites, rather than smaller units for each city, would be advisable.

05 IDAMP Projects

Section 5. IDAMP Projects

Based on the asset condition analysis and target level of services, the following projects have been identified in respect of various asset categories. Preliminary cost estimates for the project, encompassing both capital and operational & maintenance expenses, were calculated using the current Market Rating System (MRS) and Non-MRS rates for items. It's important to note that this estimation does not factor in inflation. Further, the coding scheme adopted to allot codes to the projects and the proposed projects' screening and phasing evaluation is given in Annexure B and C respectively.

Table 4: IDAMP Projects

| Sr. No. | Project ID | Project Name | Asset Category | Total Capital Cost | 2023-24 | | 2024-25 | | 2025-26 | | Project Screening (Score) |
|------------|----------------|---|----------------|--------------------|---------|-------|---------|-------|---------|-------|---------------------------|
| | | | | | Capital | O&M | Capital | O&M | Capital | O&M | |
| (Millions) | | | | | | | | | | | |
| 1 | 03-13-01-02-01 | Improvement & Rehabilitation of Water Supply system in Burewala City | Water Supply | 500.00 | 500.00 | 25.00 | | 25.00 | | 25.00 | 84 |
| 2 | 03-13-01-06-01 | Construction of Underground Water Storage Tank | Water Supply | 550.00 | 137.50 | | 275.00 | | 137.50 | 13.75 | 84 |
| 3 | 03-13-02-01-01 | Improvement of Existing Sewerage System and Disposal Stations for Burewala City | Sewerage | 900.00 | 450.00 | | 450.00 | 22.50 | | 22.50 | 82 |
| 4 | 03-13-05-01-01 | Improvement and Rehabilitation of Parks in Burewala City | Parks | 370.00 | | | | | 370.00 | 9.25 | 69 |
| 5 | 03-13-05-04-01 | Construction of General Bus Stand (GSB) in Burewala City | Bus Stand | 40.84 | | | 40.84 | 1.02 | | 1.02 | 77 |

| Sr. No. | Project ID | Project Name | Asset Category | Total Capital Cost | 2023-24 | | 2024-25 | | 2025-26 | | Project Screening (Score) |
|---------------|----------------|--|-----------------|--------------------|-----------------|---------------|---------------|---------------|---------------|---------------|---------------------------|
| | | | | | Capital | O&M | Capital | O&M | Capital | O&M | |
| (Millions) | | | | | | | | | | | |
| 6 | 03-13-05-06-01 | Rehabilitation of slaughter house | Slaughter House | 27.23 | | | | | 27.23 | 0.68 | 69 |
| 7 | 03-13-06-01-01 | Solarization of the municipal buildings | Buildings | 330.00 | 330.00 | 1.65 | | 1.65 | | 1.65 | 80 |
| 8 | 03-13-01-01-01 | Solarization of Tube wells and Water Supply System | Water supply | 180.00 | 180.00 | 0.90 | | 0.90 | | 0.90 | 80 |
| 9 | 03-13-04-01-01 | Improvement & Rehabilitation of Roads | Roads | 1,250.12 | 1,250.12 | 62.51 | | 62.51 | | 62.51 | 80 |
| 10 | 03-13-04-01-02 | Improvement & Rehabilitation of Roads | Roads | 700.00 | 700.00 | 35.00 | | 35.00 | | 35.00 | 80 |
| 11 | 03-13-02-01-02 | Solarization of disposal stations | Sewerage | 148.01 | 148.01 | 0.74 | | 0.74 | | 0.74 | 80 |
| 12 | 03-13-01-01-02 | SCADA system for tube wells and disposal stations | Water Supply | 90.00 | 90.00 | 4.50 | | 4.50 | | 4.50 | 80 |
| Total. | | | | 5,086.19 | 3,785.63 | 130.30 | 765.84 | 153.82 | 534.73 | 177.50 | |

5.1. Detail of proposed projects:

The following section provides high-level particulars of the identified projects, serving as a point of reference for creating planning documents and PC forms²:

Table 5: Projects Detail

| Sr. No. | Project ID | Service Sector | Project Name | Project Objectives | Project Scope | Capital Cost (PKR million) | Recurrent Annual O&M Cost (PKR million) | Project Location |
|---------|----------------|----------------|--|---|---|----------------------------|---|------------------|
| 1 | 03-13-01-02-01 | Water Supply | Improvement & Rehabilitation of Water Supply system in Burewala City | 1) Rehabilitation of the components of existing water supply system to attain full efficiency out of these installations. 2) Supply of adequate quantity of water in water shortage areas. 3) Improvement of service delivery level in the entire city. 4) Augmentation of the source capacity 5) Equal distribution of water in the entire system 6) Improvement of terminal pressure at remote ends of the distribution system 7) Reduction of water borne diseases. 8) Improvement in local and province economy. | Replacement of outlived water supply distribution system, Construction of OHRs & GSTs, Rehabilitation of Tubewells, Installation of new Tubewells | 500 | 25 | Burewala City |

² <https://www.pc.gov.pk/web/downloads/pc>

| Sr. No. | Project ID | Service Sector | Project Name | Project Objectives | Project Scope | Capital Cost (PKR million) | Recurrent Annual O&M Cost (PKR million) | Project Location |
|---------|----------------|----------------|---|---|--|----------------------------|---|------------------|
| 2 | 03-13-01-06-01 | Water Supply | Construction of Underground Water Storage Tank | <p>The main objectives are</p> <ul style="list-style-type: none"> - To supply safe drinking water ub sufficient quantity at doorsteps of consumers with reasonable cost - To encouraging personal hygiene anad household cleanliness of users - Reduction of water borne diseases - Reduction in medical expenditures - Improvement in environment of the city | <p>Design and Engineering Site Preparation Excavation and Earthwork Foundation Works Masonry Works Coation and Insulation Piping and Connection Concrete Works</p> | 550 | 13.75 | Burewala City |
| 3 | 03-13-02-01-01 | Sewerage | Improvement of Existing Sewerage System and Disposal Stations for Burewala City | <p>The Project has the following objectives;</p> <ol style="list-style-type: none"> 1. To implement prioritized, need based and most cost-effective municipal service infrastructure sub projects for the year 2032. 2. To improve the service delivery level for the entire growing population of the city. 3. Protecting drinking water sources from contamination by waterborne waste 4. Improvement of the environment of the city making it livable. 5. To improve the economic growth of the city. | <p>Construction of WWTP, Rehabilitation of Disposal Stations, Replacement of Outlived Pipes, Replacement of Crown Failure Pipelines, Replacement of under-sized pipelines</p> | 900 | 22.5 | Burewala City |
| 4 | 03-13-05-01-01 | Parks | Improvement and Rehabilitation of Parks in Burewala City | <p>The project has the following objectives</p> <ol style="list-style-type: none"> 1. To reduce urban heat island effect. 2. To provide active and passive recreational opportunities 3. To contribute to the health and wellness of a community 4. To create valuable green space 5. To combat air pollution caused by vehicles and industries | <p>Provision of all the missing facilities from undermentioned facilities in all four parks of burewala</p> <ul style="list-style-type: none"> -Boundary wall with iron grill ▶ Entrance gates ▶ Tuff tile pathways | 370 | 9.25 | Burewala City |

| Sr. No. | Project ID | Service Sector | Project Name | Project Objectives | Project Scope | Capital Cost (PKR million) | Recurrent Annual O&M Cost (PKR million) | Project Location |
|---------|----------------|----------------|--|---|---|----------------------------|---|---------------------------|
| | | | | <p>6. Improvement in environments of the city making them livable.</p> <p>7. Improvement in local and province economy.</p> <p>8. Improvement in the economic growth potential of the city.</p> | <ul style="list-style-type: none"> ▸ Jogging track ▸ Rainwater recharge well ▸ Playing area for children ▸ Grassing and flower beds ▸ Water supply & drainage system | | | |
| 5 | 03-13-05-04-01 | Bus Stand | Construction of General Bus Stand (GSB) in Burewala City | <p>The Project has the following objectives;</p> <ol style="list-style-type: none"> 1. Provision of disciplined travelling facilities to the people. 2. Provision of waiting facilities for the travelers in the form of respectable sitting, ablution & prayer, drinking water, toilets, shopping and ticketing. 3. Provision of car parking facilities to the public, 4. Rickshaw stand facilities 5. Revenue generation from shops and parking lot 6. Improvement in the air pollution in city area due to parking and waiting by the buses 7. Reduction in the traffic congestion created by buses at various locations of the city 8. Effective protection of the buses against the solar radiation and Ultraviolet rays, rain, hail, wind, and dust. 9. Slowing down the deterioration of buses, therefore reducing the amount of maintenance. | <ol style="list-style-type: none"> 1. Bus Stand Require the following components <ul style="list-style-type: none"> ▸ Waiting hall ▸ Ticketing booths ▸ Toilets ▸ Ablution place ▸ Prayer place ▸ Tuck shop ▸ Drinking water facilities ▸ Parking sheds for buses 2. Workshop 3. Bus departure sheds 4. Car parking lot 5. Rickshaw stand 6. Shops 7. Water supply and drainage/sewerage facilities | 40.84 | 1.02 | Lari Adda Chowk, Burewala |

| Sr. No. | Project ID | Service Sector | Project Name | Project Objectives | Project Scope | Capital Cost (PKR million) | Recurrent Annual O&M Cost (PKR million) | Project Location |
|---------|----------------|-----------------|-----------------------------------|---|---|----------------------------|---|--|
| | | | | 10. Improvement in the economic growth potential of the city. | 8. Boundary wall and gates 9. Illumination & electrification | | | |
| 6 | 03-13-05-06-01 | Slaughter House | Rehabilitation of slaughter house | <p>Ensure compliance with sanitation and hygiene standards.</p> <p>Improve the welfare and treatment of animals.</p> <p>Enhance public health and safety.</p> <p>Increase the efficiency of the slaughter process.</p> <p>Reduce operating costs and increase profitability.</p> <p>Upgrade facilities and equipment to meet modern standards.</p> <p>Minimize the impact on the environment.</p> <p>Ensure compliance with regulatory requirements.</p> <p>Improve working conditions for employees.</p> <p>Improve the overall performance of the slaughterhouse.</p> | <ul style="list-style-type: none"> ▸ Boundary wall and gate ▸ Doctor’s room ▸ Slaughtering hall ▸ Evisceration hall ▸ Meet cutting room ▸ Blood collection arrangements ▸ Water supply systems ▸ Skin storage room ▸ Waste water disposal system ▸ Solid waste collection and disposal system ▸ Health and Hygiene SOPs ▸ Separate Facility for Sick Animals ▸ Tools Disinfectant System | 27.23 | 0.68 | PI Link Canal Multan Road, Burewala City |

| Sr. No. | Project ID | Service Sector | Project Name | Project Objectives | Project Scope | Capital Cost (PKR million) | Recurrent Annual O&M Cost (PKR million) | Project Location |
|---------|----------------|--|---|---|--|----------------------------|---|------------------|
| 7 | 03-13-06-01-01 | Buildings | Solarization of the municipal buildings | The primary objectives of solarization are as follows: a) Enhance Sustainability: By generating clean and renewable energy, the project can reduce its environmental impact and contribute to sustainable development. b) Reduce Carbon Footprint: Solar PV systems produce electricity with zero greenhouse gas emissions, helping to mitigate climate change and improve air quality. c) Cut Down Energy Costs: Utilizing solar energy can significantly reduce reliance on conventional grid electricity, resulting in long-term cost savings and improved financial viability. | Solarization of the municipal buildings based on the site load and installation capacity assessment | 330 | 1.65 | Burewala City |
| 8 | 03-13-01-01-01 | Solarization of Tube wells and Water Supply System | Water supply | The primary objectives of solarization are as follows: a) Enhance Sustainability: By generating clean and renewable energy, the project can reduce its environmental impact and contribute to sustainable development. b) Reduce Carbon Footprint: Solar PV systems produce electricity with zero greenhouse gas emissions, helping to mitigate climate change and improve air quality. c) Cut Down Energy Costs: Utilizing solar energy can significantly reduce reliance on conventional grid electricity, resulting in long-term cost savings and improved financial viability. | Solarization of the tubewells based on the site load and installation capacity assessment. Tubewell solarization project scope involves converting conventional water pumping systems into solar-powered ones to ensure sustainable and energy-efficient water supply for rural needs. | 180 | 0.9 | Burewala City |

| Sr. No. | Project ID | Service Sector | Project Name | Project Objectives | Project Scope | Capital Cost (PKR million) | Recurrent Annual O&M Cost (PKR million) | Project Location |
|---------|----------------|----------------|---------------------------------------|--|--|----------------------------|---|------------------|
| 9 | 03-13-04-01-01 | Roads | Improvement & Rehabilitation of Roads | "The Project has the following objectives; 1. Improvement of service delivery level of the municipal services in the sector of communication. 2. Better travelling facilities for the commuters. 3. Reduction in road accidents. 4. Saving in travelling and repair cost of the vehicles. 5. Reduction in annual maintenance charges of roads and parks 6. Better lit roads and streets adding to security of people travelling at night. 7. Improvement in environments of the city making them livable. 8. Improvement in local and province economy. 9. Improvement in the economic growth potential of the city." | "1-College Road 2-Arif Road 3-Vehari Bazar-1 4-Vehari Bazar-II (One way-each side) 5-Rail Bazar Road 6-E-Block Via D-Block & A-Block 7-E-Block H-School Wali Road 8-Lakar Mandi Road 9-Arabia Islamia Via Trunk Market Via Joya Road 10-P-Block to Fish Block 11-High School No.2 Road 12-Chak No. 423/EB Road+435/EB 13-Shadman Colony Road 14-Aziz Abad + 437/EB Main Road 15-High School No.2 Road 16-Stadium Road +Girls College Road 17-Tehsil Council Office Road 18-Habib Colony Play Ground Road" | 1250.12 | 62.506 | Burewala City |

| Sr. No. | Project ID | Service Sector | Project Name | Project Objectives | Project Scope | Capital Cost (PKR million) | Recurrent Annual O&M Cost (PKR million) | Project Location |
|---------|----------------|----------------|---------------------------------------|--|--|----------------------------|---|------------------|
| 10 | 03-13-04-01-02 | Roads | Improvement & Rehabilitation of Roads | <p>"The Project has the following objectives;</p> <ol style="list-style-type: none"> 1. Improvement of service delivery level of the municipal services in the sector of communication. 2. Better travelling facilities for the commuters. 3. Reduction in road accidents. 4. Saving in travelling and repair cost of the vehicles. 5. Reduction in annual maintenance charges of roads and parks 6. Better lit roads and streets adding to security of people travelling at night. 7. Improvement in environments of the city making them livable. 8. Improvement in local and province economy. 9. Improvement in the economic growth potential of the city." | <p>"1-Rehab of Metalled Road Fowara Chowk to GPS Chak 445. 2-Rehab of Metalled Road Filtration Plant St 1 via New Barki and Madina Garden 3-Rehab of Metalled Road Railway road via Braveli Masjid Habib Colony 4-Rehab of Metalled Road BTM Graveyard road to Zahid Abad. 5-Construction of Metalled Road St Masjid Bilal to St 8 Amjad Town 6-Construction of Tuff Tile Ghosia Block 7-Construction of tuff tile in St Masjid Taj park 8-Construction of tuff tile in St 12 Amjad town 9-Construction of tuff tile shah faiz 10-Construction of tuff tile Janzgah ward "</p> | 700 | 35 | Burewala City |

| Sr. No. | Project ID | Service Sector | Project Name | Project Objectives | Project Scope | Capital Cost (PKR million) | Recurrent Annual O&M Cost (PKR million) | Project Location |
|---------|----------------|----------------|---|---|---|----------------------------|---|------------------|
| 11 | 03-13-02-01-02 | Sewerage | Solarization of disposal stations | "The primary objectives of solarization are as follows: a) Enhance Sustainability: By generating clean and renewable energy, the project can reduce its environmental impact and contribute to sustainable development. b) Reduce Carbon Footprint: Solar PV systems produce electricity with zero greenhouse gas emissions, helping to mitigate climate change and improve air quality. c) Cut Down Energy Costs: Utilizing solar energy can significantly reduce reliance on conventional grid electricity, resulting in long-term cost savings and improved financial viability." | "Solarization of the disposal station based on the site load and installation capacity assessment. Disposal station solarization project scope involves converting conventional pumping systems into solar-powered ones to ensure sustainable and energy-efficient water supply for rural needs." | 148.01 | .74 | Burewala City |
| 12 | 03-13-01-01-02 | Water Supply | SCADA system for tube wells and disposal stations | For monitoring and controlling of efficient working of all tubewells Scda system would be required so that working hours of each tubewell will be monitor at a center point. | "Design and Installation of the following components: 1-Instrumentation Inputs 2-RTUs 3-Radio/Cellular Telemetry 4- SCADA Operator Terminal 5-Alarming Monitoring 6-Control System Adjustments 7-Internet Browser 8-Server HTML" | 90 | 4.5 | Burewala City |

06 Financial and Economic Analysis

Section 6. Financial and Economic Analysis

In this chapter, financial and economic analysis has been carried out for the new project proposed under IDAMP to assess its economic and financial viability and determine its do-ability by reference to its financial resources required next three financial years.

1.1. Qualitative Assessment

The qualitative benefits of the proposed projects are as under:

- (i) **The benefits of municipal project - Engines of Growth:** Among other benefits, municipal projects generate employment opportunities and create a positive impact on the standard of living. Few projects proposed under IDAMP are mega projects which would create their own economy, boost manufacturing & trading, create need for commerce value chain.
- (ii) **Environmental Up-gradation:** Development of wastewater treatment plant would provide primary and secondary treatment, thereby have a positive bearing on environment. Further, all projects will especially focus environmental considerations during construction and operational phases. Further green areas, trees and plantations will provide not only refreshing view but will enhance the environmental conditions and help climate stabilization.
- (iii) **Employment Opportunities:** The Project is likely to create employment opportunities for over 1,000 people during construction and about 500 people at operational stage in addition to indirect employment generation.
- (iv) **Improvement in Service Delivery of Water Supply:** Replacement of water supply system would improve the water quality for the target population, thus will help to improve public health index.
- (v) **Rehabilitation of Parks - Creation of Social Hub in the Locality:** These projects will provide a recreational facility to the residents of the catchment area of respective parks thus improve the visitors count of the parks and create social harmony and extended connectivity in the people.
- (vi) **Saving in Fuel Consumption and Improved Connectivity -** Rehabilitation of roads infrastructure would not only improve the service delivery level of the municipal services but also result in few road accidents, potential savings in travelling and repair cost of the vehicles, reduction in annual maintenance charges of roads and parks. Moreover, better lit roads and streets would add to security of people travelling at night.

- (vii) **Generation of Business Opportunities:** Projects will open new corridors for small- and large-scale businesses right from the construction phase and onwards throughout the life of the Project.
- (viii) **Revenue Generation:** Local government is estimated to generate direct and indirect revenue from the projects.

1.2. Quantitative Assessment of the Project

Various basis has been used, primarily relying on the results of the financial model which has been developed to conduct the financial analysis that assesses the viability and sustainability of this Project. Free Cash Flows (FCF) of the Project have been used to determine the key financial indicators of the projects.

Using the free cash flow model, given below are the key financial indicators for project appraisal:

- (i) **Net Present Value (NPV)** of the projects is calculated which represents in present value terms the net benefit that accrues from the Project after meeting its capital cost requirements as well as the cost of operations and other expenditures.
- (ii) **Financial Internal rate of return (FIRR)** of the projects is calculated While representing an average return and its comparison with the required rate of return, which is taken as KIBOR rate
- (iii) **Payback period** of the Project is estimated duly incorporating construction and operational period over the useful life of asset.
- (iv) **Cost benefit analysis** of the projects is made to determine the ratio of cumulative benefits versus cumulative cost of each project over its useful life.

1.3. Annual Financial Projections

The annual financial projection of Municipal Committee Burewala is given below.

Table 6: Annual Financial Projections

| Year | 2023-24 | | 2024-25 | | 2025-26 | |
|-----------------|--------------------------------|-----------------------------|--------------------------------|-----------------------------|--------------------------------|-----------------------------|
| Category | Total Capital Rs. (Million) | Total O&M Rs. (Millions) | Total Capital Rs. (Million) | Total O&M Rs. (Millions) | Total Capital Rs. (Million) | Total O&M Rs. (Millions) |
| Water Supply | 907.50 | 30.40 | 275.00 | 30.40 | 137.50 | 44.15 |
| Sewerage | 598.01 | 0.74 | 450.00 | 23.24 | - | 23.24 |
| Parks | - | - | - | - | 370.00 | 9.25 |
| Bus Stand | - | - | 40.84 | 1.02 | - | 1.02 |
| Slaughter House | - | - | - | - | 27.23 | 0.68 |
| Buildings | 330.00 | 1.65 | - | 1.65 | - | 1.65 |
| Roads | 1,950.12 | 97.51 | - | 97.51 | - | 97.51 |
| Total | 3,785.63 | 130.30 | 765.84 | 153.82 | 534.73 | 177.50 |

Capital cost of the projects incorporates both the initial one-off costs such as engineering cost, project construction cost, development cost, procurement cost of equipment, machinery & other assets, utility set up cost, and any other costs to be incurred during the construction period.



Operating and maintenance (O&M) cost shall be incurred during operational phases of the project. Operation and maintenance cost includes electricity and other utility cost, administrative expenses, maintenance cost, payroll cost and other overheads etc.

Annexure

Annexure A. Detail of Assets

1. Water Supply:

Key Components of a Water Supply System




A. Tube well




| Sr # | Name | Age (Years) | | Discharge Capacity (Cusecs) | Motor hp | Pump Make | Motor Make | Condition | Status | Book Value (PKR Mil) |
|------|-------------------------|-----------------|---------------|-----------------------------|---------------|--------------|------------|-----------|----------------|----------------------|
| | | Civil Structure | Pump | | | | | | | |
| 1 | Jinnah Hall MC Office | 48 | 48 | 0.75 | 20 | BECO | BECO | Fair | Functional | 0.2 |
| 2 | Iqbal Nagar | 14 | 14 | 1 | 60 | MECO | SIEMENS | Fair | No Motor | 0.1 |
| 3 | Fareed Town Pump # 31 | 14 | 14 | 1 | 30 | MECO | SIEMENS | Fair | Functional | 0.9 |
| 4 | Yousaf Block Marzi Pura | 3 | 3 | 1 | 40 | KSB | SIEMENS | Good | Functional | 9 |
| 5 | Gulshan E Rehman | 7 | 4 | 1 | 30 | HMA | SIEMENS | Good | Functional | 7 |
| 6 | Muhammad Nagar #1 | 21 | 21 | 1.5 | 40 | KSB | SIEMENS | Poor | Functional | 0.8 |
| 7 | Ahata Shah | Not Available | Not Available | 1 | 40 | Flowpak | PECO | Fair | Functional | 0.6 |
| 8 | Housing Scheme | 14 | 14 | 1 | 40 | MECO | SIEMENS | Fair | Functional | 1.2 |
| 9 | Bhatta Yousafabad | 43 | 33 | 1 | 25 | KSB | SIEMENS | Fair | Functional | 0.2 |
| 10 | Habib Colony | 42 | 6 | 1 | 40 | PECO | PECO | Fair | Functional | 3 |
| 11 | Habib Colony School | 32 | Not Available | 1 | 50 | PECO | PECO | Fair | Functional | 0.3 |
| 12 | 447 - E-B | 32 | 32 | 1 | 30 | FlowPak | Siemens | Fair | Functional | 0.2 |
| 13 | 445 - E-B | Not Available | Not Available | 1.5 | 40 | PECO | PECO | Fair | Functional | 0.2 |
| 14 | Mujahid Colony No.1 | 34 | 34 | 0.5 | 25 | PECO | PECO | Fair | Functional | 0.2 |
| 15 | Mujahid Colony-2 | 3 | 3 | 1 | 40 | KSB | SIEMENS | Good | Functional | 3 |
| 16 | Al Abad Water Works | Not Available | Not Available | 1 | 30 | HMA Grundfos | SIEMENS | Fair | Functional | Not Available |
| 17 | Satellite Town-1 | 3 | 3 | 1 | 40 | KSB | SIEMENS | Good | Functional | Not Available |
| 18 | Satellite Town-2 | 6 | 6 | 1 | 40 | HMA Grundfos | SIEMENS | Fair | Functional | Not Available |
| 19 | Azizabad | 44 | Not Available | 1 | 40 | PECO | PECO | Fair | Functional | Not Available |
| 20 | Ghoshala Water Filter | Not Available | Not Available | Not Available | Not Available | PECO | PECO | Failing | Locked by MC | Not Available |
| 21 | Water Supply Colony | 44 | 3 | 1 | 30 | PECO | PECO | Good | Functional | 0.1 |
| 22 | Gala Mandi | Not Available | 3 | 1 | 30 | KSB | SIEMENS | Failing | Non-Functional | 1.4 |



| Sr # | Name | Age (Years) | | Discharge Capacity (Cusecs) | Motor hp | Pump Make | Motor Make | Condition | Status | Book Value (PKR Mil) |
|------|------------------------|-----------------|---------------|-----------------------------|---------------|--------------|--------------|-----------|----------------|----------------------|
| | | Civil Structure | Pump | | | | | | | |
| 23 | N-Block | 14 | 14 | 1 | 30 | KSB | SIEMENS | Good | Functional | Not Available |
| 24 | P-Block-1 | 32 | 32 | 1.5 | 50 | PECO | SIEMENS | Fair | Functional | Not Available |
| 25 | W.W P-Block 2 | Not Available | Not Available | 1 | 40 | HMA Grundfos | SIEMENS | Good | Functional | Not Available |
| 26 | M-Block | Not Available | 24 | 1 | 30 | PECO | PECO | Fair | Functional | 0.2 |
| 27 | H-Block | Not Available | 5 | 1 | 30 | HMA Grundfos | HMA Grundfos | Fair | Functional | 1.1 |
| 28 | E-Block | Not Available | Not Available | Not Available | Not Available | PECO | PECO | Failing | Non-Functional | |
| 29 | Gulshan Ghani | 19 | 19 | 1 | 40 | General | BECO | Fair | Functional | 0.2 |
| 30 | Park I-Block | Not Available | Not Available | 1 | 30 | HMA Grundfos | SIEMENS | Fair | Functional | Not Available |
| 31 | Azeem Abad # 2 | 15 | 15 | 1 | 40 | PECO | PECO | Fair | Non-Functional | 0.2 |
| 32 | Khadija Tul Qubra | Not Available | Not Available | Not Available | Not Available | N/A | N/A | Failing | No Pumpset | Not Available |
| 33 | Canal Stadium | Not Available | Not Available | Not Available | Not Available | N/A | N/A | Failing | Locked by MC | Not Available |
| 34 | Shadman Colony | Not Available | Not Available | Not Available | Not Available | MECO | N/A | Failing | Non-Functional | Not Available |
| 35 | Ghulam Muhammad | Not Available | Not Available | Not Available | Not Available | N/A | N/A | Failing | Locked by MC | Not Available |
| 36 | Masoom Shah | Not Available | Not Available | Not Available | Not Available | N/A | N/A | Failing | Locked by MC | Not Available |
| 37 | Mujahid Colony Banki | Not Available | Not Available | Not Available | Not Available | N/A | N/A | Failing | Locked by MC | Not Available |
| 38 | Mujahid Colony Eid Gah | Not Available | Not Available | Not Available | Not Available | N/A | N/A | Failing | Locked by MC | Not Available |
| 39 | Dogar Market | Not Available | Not Available | Not Available | Not Available | N/A | N/A | Failing | No Pumpset | Not Available |
| 40 | 437 EB | Not Available | 3 | 1 | 40 | Ksb | SIEMENS | Good | Functional | 1.1 |

| Sr # | Name | Age (Years) | | Discharge Capacity (Cusecs) | Motor hp | Pump Make | Motor Make | Condition | Status | Book Value (PKR Mil) |
|------|-----------------------|-----------------|---------------|-----------------------------|---------------|---------------|---------------|-----------|--------------|----------------------|
| | | Civil Structure | Pump | | | | | | | |
| 41 | Shah Faisal Colony | Not Available | Not Available | Not Available | Not Available | N/A | N/A | Failing | Locked by MC | |
| 42 | Azeemabad | 15 | 15 | Not Available | | KSB | SIEMENS | Failing | Functional | 0.3 |
| 43 | Ilyas Garden | 5 | 3 | 1 | 40 | HMA | SIEMENS | Fair | Functional | 6 |
| 44 | 435-EB | 3 | 3 | 1 | 40 | KSB | SIEMENS | Good | Functional | 4 |
| 45 | Tibba Mustafabad | Not Available | Not Available | Not Available | Not Available | Not Available | Not Available | Failing | Locked by MC | Not Available |
| 46 | A Block Near Ground | Not Available | Not Available | Not Available | Not Available | Not Available | Not Available | Failing | Locked by MC | Not Available |
| 47 | Anwar Town | Not Available | Not Available | Not Available | Not Available | Not Available | Not Available | Failing | Locked by MC | Not Available |
| 48 | Lat Bhattian (451-EB) | Not Available | Not Available | Not Available | Not Available | Not Available | Not Available | Failing | Locked by MC | Not Available |
| 49 | M.Nagar # 2 | 2 | 2 | Not Available | Not Available | Not Available | Not Available | Fair | Locked by MC | Not Available |
| 50 | P Block Tanki#11 | Not Available | Not Available | 1 | 40 | BECO | BECO | Fair | Functional | Not Available |


| Integrated Development and Asset Management Plan (IDAMP) | | | |
|--|--------------------------------------|----------------|---------------------------------------|
| Municipal Committee Burewala | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 |
| Asset Detail | | Pictures | |
| Name | Jinnah Hall MC Office | | |
| Location | Latitude | 30.159589 | |
| | Longitude | 72.682041 | |
| Address | TMA Jinnah Hall MC Office | | |
| Area (Marla) | 1 | | |
| Working Status | Functional | Non-Functional | |
| Installation Year of Tube Well | 1975 | | |
| Installation Year of Pump | 1975 | | |
| Capital Cost of Machinery | | | |
| Operational Hours | 5 | | |





| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---------------------|--------------------------------------|-------------|---|-------------------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | | Tube Well Asset Condition Assessment | | | Asset Code: _____ |
| | | | | | Date: 05-05-2023 |
| Delivery Pipe | Dia | 6 | |  | |
| | Material | MS | | | |
| Chlorinator | | Yes | No | | |
| Chlorination Schedule | Once in a Year | After 6 Months | No Schedule |  | |
| Apron Around Pump House | Yes | No | | | |
| Hoisting Girder | Yes | No | | | |
| Civil Structure Condition | Good | Fair | Bad |  | |
| Approach to Pump House | Good | Fair | Bad | | |
| Pump Details | | | | | |
| Pump Type | Turbine | | | | |
| Pump Make | BECO | | | | |
| Discharge Capacity (Cusec) | 0.75 | | | | |
| Rotational Speed (RPM) | 1470 | | | | |
| Housing Dia (inches) | 12 | | | | |
| Bore Depth (ft.) | 450 | | | | |
| Head (ft.) | 200 | | | | |
| Impeller Installation Depth (ft.) | 100 | | | | |
| Paint of Pumping Unit | Good | Fair | Poor | | |
| Number of Valves | Gate Valve | 1 | | | |
| | Non-Returning Valve | 1 | | | |
| Base Plate | Yes | No | | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | 100 | | | | |
| Sanctioned Load (Kwh) | 22 | | | | |
| Motor Power (HP) | 20 | | | | |
| Motor Make | BECO | | | | |
| MCU | Yes | No | | | |
| Earthing of Motor | Yes | No | | | |
| Power Wiring | Yes | No | | | |
| Service Cable | Yes | No | | | |
| Earthing of MCU | Yes | No | | | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |




| Integrated Development and Asset Management Plan (IDAMP) | | |
|--|---|---|
| Municipal Committee Burewala | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 |
| <ul style="list-style-type: none"> No remarks | | |
| Data Collected By: Mr. Abdullah | Designation: Team Member |  Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |

| Integrated Development and Asset Management Plan (IDAMP) | | | |
|--|---|---------------------------------------|----------------|
| Municipal Committee Burewala | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | Pictures | |
| Name | | Water Supply Colony | |
| Location | Latitude | 30.160744 | |
| | Longitude | 72.673110 | |
| Address | | Water Supply Colony | |
| Area (Marla) | | 1 | |
| Working Status | | Functional | Non-Functional |
| Installation Year of Tube Well | | 1979 | |
| Installation Year of Pump | | 2020 | |
| Capital Cost of Machinery | | | |
| Operational Hours | | 5 | |
| Delivery Pipe | Dia | 6 | |
| | Material | MS | |
| Chlorinator | | Yes | No |
| Chlorination Schedule | | Once in a Year | After 6 Months |
| Apron Around Pump House | | Yes | No |
| Hoisting Girder | | Yes | No |
| Civil Structure Condition | | Good | Fair |
| Approach to Pump House | | Good | Fair |
| Bad | | | |
| Pump Details | | | |
| Pump Type | | Turbine | |
| Pump Make | | KSB | |
| Discharge Capacity (Cusec) | | 1 | |
| Rotational Speed (RPM) | | 1470 | |
| Housing Dia (inches) | | 12" | |
| Bore Depth (ft.) | | 450 | |
| Head (ft.) | | 200 | |











| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | |
|--|---|--------------------------|------|---|---------|--|--|
| Municipal Committee Burewala | | | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | | | |
| Impeller Installation Depth (ft.) | 100 | | |  | | | |
| Paint of Pumping Unit | Good | Fair | Poor | | | | |
| Number of Valves | Gate Valve | 1 | | | | | |
| | Non-Returning Valve | 1 | | | | | |
| Base Plate | Yes | No | | | | | |
| Electro-Mechanical Equipment Details | | | | | | | |
| Transformer Capacity (kVA) | 100 | | | | | | |
| Sanctioned Load (Kwh) | 29 | | | | | | |
| Motor Power (HP) | 30 | | | | | | |
| Motor Make | Siemens | | | | | | |
| MCU | Yes | No | | | | | |
| Earthing of Motor | Yes | No | | | | | |
| Power Wiring | Yes | No | | | | | |
| Service Cable | Yes | No | | | | | |
| Earthing of MCU | Yes | No | | | | | |
| Energy Meter | Yes | No | | | | | |
| Water Meter | Yes | No | | | | | |
| PFI Equipment | Yes | No | | | | | |
| Generator | Yes | No | | | | | |
| Change Over | Yes | No | | | | | |
| Overall Rating | | | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 | | |
| Asset Condition | Excellent | Good | Fair | Poor | Failing | | |
| Category | A | B | C | D | E | | |
| Remarks / Requirements | | | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | | | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | | | |




| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---------------------|--------------------------------------|----------------|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | | Tube Well Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | | Pictures | |
| Name | | Aziz Abad | | | |
| Location | Latitude | 30.163840 | | | |
| | Longitude | 72.671722 | | | |
| Address | | Aziz Abad | | | |
| Area (Marla) | | 1 | | | |
| Working Status | | Functional | Non-Functional | | |
| Installation Year of Tube Well | | 1979 | | | |
| Installation Year of Pump | | 1979 | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | 5 | | | |
| Delivery Pipe | Dia | 8 | | | |
| | Material | MS | | | |
| Chlorinator | | Yes | No | | |
| Chlorination Schedule | | Once in a Year | After 6 Months | No Schedule | |
| Apron Around Pump House | | Yes | No | | |
| Hoisting Girder | | Yes | No | | |
| Civil Structure Condition | | Good | Fair | Bad | |
| Approach to Pump House | | Good | Fair | Bad | |
| Pump Details | | | | | |
| Pump Type | | Turbine | | | |
| Pump Make | | PECO | | | |
| Discharge Capacity (Cusec) | | 1 | | | |
| Rotational Speed (RPM) | | 1470 | | | |
| Housing Dia (inches) | | 12" | | | |
| Bore Depth (ft.) | | 450 | | | |
| Head (ft.) | | 200 | | | |
| Impeller Installation Depth (ft.) | | 100 | | | |
| Paint of Pumping Unit | | Good | Fair | Poor | |
| Number of Valves | Gate Valve | 1 | | | |
| | Non-Returning Valve | 0 | | | |
| Base Plate | | Yes | No | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | | 100 | | | |
| Sanctioned Load (Kwh) | | 22 | | | |
| Motor Power (HP) | | 40 | | | |
| Motor Make | | PECO | | | |
| MCU | | Yes | No | | |
| Earthing of Motor | | Yes | No | | |
| Power Wiring | | Yes | No | | |
| Service Cable | | Yes | No | | |
| Earthing of MCU | | Yes | No | | |






| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|---------------------------------|------|---------------------------------------|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| <i>Data Collected By: Mr. Abdullah</i> | | <i>Designation: Team Member</i> | | <i>Sign & Date: 30-May-2023</i> | |
| <i>Data Checked By: Mr. M. Fiaz</i> | | <i>Designation: Team Lead</i> | | <i>Sign & Date: 30-May-2023</i> | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | |
|--|---|------------------|----------------|---------------------------------------|--|--|
| Municipal Committee Burewala | | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | | |
| Asset Detail | | | Pictures | | | |
| Name | | Tibba Mustafabad | | | |  |
| Location | Latitude | 30.163698 | | | | |
| | Longitude | 72.669445 | | | | |
| Address | | | | | | |
| Area (Marla) | | 1 | | | | |
| Working Status | | Abandoned | | | | |
| Installation Year of Tube Well | | | | | | |
| Installation Year of Pump | | | | | | |
| Capital Cost of Machinery | | | | | | |
| Operational Hours | | | | | | |
| Delivery Pipe | Dia | | | | | |
| | Material | | | | | |
| Chlorinator | | Yes | No | | | |
| Chlorination Schedule | | Once in a Year | After 6 Months | No Schedule | | |
| Apron Around Pump House | | Yes | No | | | |
| Hoisting Girder | | Yes | No | | | |
| Civil Structure Condition | | Good | Fair | Bad | | |
| Approach to Pump House | | Good | Fair | Bad | | |
| Pump Details | | | | | | |
| Pump Type | | | | | | |
| Pump Make | | | | | | |
|  | | | | | | |


| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Discharge Capacity (Cusec) | | | | | |
| Rotational Speed (RPM) | | | | | |
| Housing Dia (inches) | | | | | |
| Bore Depth (ft.) | | | | | |
| Head (ft.) | | | | | |
| Impeller Installation Depth (ft.) | | | | | |
| Paint of Pumping Unit | | | | | |
| Number of Valves | Gate Valve | | | | |
| | Non-Returning Valve | | | | |
| Base Plate | Yes | No | | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | | | | | |
| Sanctioned Load (Kwh) | | | | | |
| Motor Power (HP) | | | | | |
| Motor Make | | | | | |
| MCU | Yes | No | | | |
| Earthing of Motor | Yes | No | | | |
| Power Wiring | Yes | No | | | |
| Service Cable | Yes | No | | | |
| Earthing of MCU | Yes | No | | | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |



| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|-------------------------------|----------------|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | Pictures | | |
| Name | | Gulshan e Rehman | | |  |
| Location | Latitude | 30.159945 | | | |
| | Longitude | 72.661625 | | | |
| Address | | Gulshan e Rehman, Burewala | | | |
| Area (Marla) | | 1 | | | |
| Working Status | | Functional | Non-Functional | | |
| Installation Year of Tube Well | | 2016 | | | |
| Installation Year of Pump | | 2019 | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | 5 | | | |
| Delivery Pipe | Dia | 8 | | | |
| | Material | MS | | | |
| Chlorinator | | Yes | No | | |
| Chlorination Schedule | | Once in a Year | After 6 Months | No Schedule | |
| Apron Around Pump House | | Yes | No | | |
| Hoisting Girder | | Yes | No | | |
| Civil Structure Condition | | Good | Fair | Bad | |
| Approach to Pump House | | Good | Fair | Bad | |
| Pump Details | | | | | |
| Pump Type | | Turbine | | | |
| Pump Make | | HMA | | | |
| Discharge Capacity (Cusec) | | 1 | | | |
| Rotational Speed (RPM) | | 2950 | | | |
| Housing Dia (inches) | | 12" | | | |
| Bore Depth (ft.) | | 450 | | | |
| Head (ft.) | | 200 | | | |
| Impeller Installation Depth (ft.) | | 100 | | | |
| Paint of Pumping Unit | | Good | Fair | Poor | |
| Number of Valves | Gate Valve | 0 | | | |
| | Non-Returning Valve | 1 | | | |
| Base Plate | | Yes | No | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | | 50 | | | |
| Sanctioned Load (Kwh) | | 22 | | | |
| Motor Power (HP) | | 30 | | | |
| Motor Make | | Siemens | | | |
| MCU | | Yes | No | | |
| Earthing of Motor | | Yes | No | | |
| Power Wiring | | Yes | No | | |
| Service Cable | | Yes | No | | |
| | | | | |  |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | |  |
| | | | | | |




| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Earthing of MCU | Yes | No | | | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |



| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|-------------------------|--|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | Pictures | | |
| Name | | Yousaf Block | | | |
| Location | Latitude | 30.159952 | | | |
| | Longitude | 72.661635 | | | |
| Address | | Yousaf Block, Marzipura | | | |
| Area (Marla) | | 1 | | | |
| Working Status | | Functional | Non-Functional | | |
| Installation Year of Tube Well | | 2020 | | | |
| Installation Year of Pump | | 2020 | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | 5 | | | |
| Delivery Pipe | Dia | 8 | | | |
| | Material | MS | | | |
| | | |  | | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | |
|--|---|----------------|-------------|---------------------------------------|------|---------|
| Municipal Committee Burewala | | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | | |
| Chlorinator | Yes | | No | | | |
| Chlorination Schedule | Once in a Year | After 6 Months | No Schedule | | | |
| Apron Around Pump House | Yes | | No | | | |
| Hoisting Girder | Yes | | No | | | |
| Civil Structure Condition | Good | Fair | Bad | | | |
| Approach to Pump House | Good | Fair | Bad | | | |
| Pump Details | | | | | | |
| Pump Type | Turbine | | | | | |
| Pump Make | KSB | | | | | |
| Discharge Capacity (Cusec) | 1 | | | | | |
| Rotational Speed (RPM) | 1470 | | | | | |
| Housing Dia (inches) | 12" | | | | | |
| Bore Depth (ft.) | 450 | | | | | |
| Head (ft.) | 200 | | | | | |
| Impeller Installation Depth (ft.) | 100 | | | | | |
| Paint of Pumping Unit | Good | Fair | Poor | | | |
| Number of Valves | Gate Valve | 1 | | | | |
| | Non-Returning Valve | 1 | | | | |
| Base Plate | Yes | | No | | | |
| Electro-Mechanical Equipment Details | | | | | | |
| Transformer Capacity (kVA) | 50 | | | | | |
| Sanctioned Load (Kwh) | 19 | | | | | |
| Motor Power (HP) | 40 | | | | | |
| Motor Make | Siemens | | | | | |
| MCU | Yes | | No | | | |
| Earthing of Motor | Yes | | No | | | |
| Power Wiring | Yes | | No | | | |
| Service Cable | Yes | | No | | | |
| Earthing of MCU | Yes | | No | | | |
| Energy Meter | Yes | | No | | | |
| Water Meter | Yes | | No | | | |
| PFI Equipment | Yes | | No | | | |
| Generator | Yes | | No | | | |
| Change Over | Yes | | No | | | |
| Overall Rating | | | | | | |
| Average Score | 1 | 2 | | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | | Fair | Poor | Failing |
| Category | A | B | | C | D | E |
| Remarks / Requirements | | | | | | |
| <ul style="list-style-type: none"> • No remarks | | | | | | |





| Integrated Development and Asset Management Plan (IDAMP) | | |
|--|---|---|
| Municipal Committee Burewala | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 |
| Data Collected By: Mr. Abdullah | Designation: Team Member |  Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |


| Integrated Development and Asset Management Plan (IDAMP) | | | |
|--|---|--|-------------|
| Municipal Committee Burewala | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | Pictures | |
| Name | Iqbal Nagar | | |
| Location | Latitude | 30.156800 | |
| | Longitude | 72.661910 | |
| Address | Iqbal Nagar, Marzi Pura | | |
| Area (Marla) | 1 | | |
| Working Status | Functional | Non-Functional | |
| Installation Year of Tube Well | 2009 | | |
| Installation Year of Pump | 2009 | | |
| Capital Cost of Machinery | | | |
| Operational Hours | 5 | | |
| Delivery Pipe | Dia | 8 | |
| | Material | MS | |
| Chlorinator | Yes | No | |
| Chlorination Schedule | Once in a Year | After 6 Months | No Schedule |
| Apron Around Pump House | Yes | No | |
| Hoisting Girder | Yes | No | |
| Civil Structure Condition | Good | Fair | Bad |
| Approach to Pump House | Good | Fair | Bad |
| Pump Details | | | |
| Pump Type | Turbine | | |
| Pump Make | MECO | | |
| Discharge Capacity (Cusec) | 1 | | |
| Rotational Speed (RPM) | 1470 | | |
| Housing Dia (inches) | 12" | | |
| Bore Depth (ft.) | 450 | | |
| Head (ft.) | 200 | | |
| | |  | |
| | |  | |
| | |  | |


| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Impeller Installation Depth (ft.) | 100 | | | | |
| Paint of Pumping Unit | Good | Fair | Poor | | |
| Number of Valves | Gate Valve | 1 | | | |
| | Non-Returning Valve | 1 | | | |
| Base Plate | Yes | No | | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | 100 | | | | |
| Sanctioned Load (Kwh) | 30 | | | | |
| Motor Power (HP) | 60 | | | | |
| Motor Make | Siemens | | | | |
| MCU | Yes | No | | | |
| Earthing of Motor | Yes | No | | | |
| Power Wiring | Yes | No | | | |
| Service Cable | Yes | No | | | |
| Earthing of MCU | Yes | No | | | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---------------------|--------------------------------------|----------------|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | | Tube Well Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | | Pictures | |
| Name | | Fareed Town | | | |
| Location | Latitude | 30.152360 | | | |
| | Longitude | 72.657509 | | | |
| Address | | Fareed Town, Marzi Pura | | | |
| Area (Marla) | | 1 | | | |
| Working Status | | Functional | Non-Functional | | |
| Installation Year of Tube Well | | 2009 | | | |
| Installation Year of Pump | | 2009 | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | 5 | | | |
| Delivery Pipe | Dia | 8 | | | |
| | Material | MS | | | |
| Chlorinator | | Yes | No | | |
| Chlorination Schedule | | Once in a Year | After 6 Months | No Schedule | |
| Apron Around Pump House | | Yes | No | | |
| Hoisting Girder | | Yes | No | | |
| Civil Structure Condition | | Good | Fair | Bad | |
| Approach to Pump House | | Good | Fair | Bad | |
| Pump Details | | | | | |
| Pump Type | | Turbine | | | |
| Pump Make | | MECO | | | |
| Discharge Capacity (Cusec) | | 1 | | | |
| Rotational Speed (RPM) | | 1465 | | | |
| Housing Dia (inches) | | 12" | | | |
| Bore Depth (ft.) | | 450 | | | |
| Head (ft.) | | 200 | | | |
| Impeller Installation Depth (ft.) | | 100 | | | |
| Paint of Pumping Unit | | Good | Fair | Poor | |
| Number of Valves | Gate Valve | 1 | | | |
| | Non-Returning Valve | 1 | | | |
| Base Plate | | Yes | No | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | | 50 | | | |
| Sanctioned Load (Kwh) | | 22 | | | |
| Motor Power (HP) | | 30 | | | |
| Motor Make | | Siemens | | | |
| MCU | | Yes | No | | |
| Earthing of Motor | | Yes | No | | |
| Power Wiring | | Yes | No | | |
| Service Cable | | Yes | No | | |
| Earthing of MCU | | Yes | No | | |




| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|------------------------|--|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | Pictures | | |
| Name | | Lat Bhattian | | | |
| Location | Latitude | 30.149373 | | | |
| | Longitude | 72.658350 | | | |
| Address | | Lat Bhattian, Burewala | | | |
| Area (Marla) | | 1 | | | |
| Working Status | | Abandoned | | | |
| Installation Year of Tube Well | | | | | |
| Installation Year of Pump | | | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | | | | |
| Delivery Pipe | Dia | | | | |
| | Material | | | | |
| Chlorinator | | Yes | No | | |
| Chlorination Schedule | | Once in a Year | After 6 Months | No Schedule | |
| | | |  | | |



| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Apron Around Pump House | Yes | | | No | |
| Hoisting Girder | Yes | | | No | |
| Civil Structure Condition | Good | Fair | Bad | | |
| Approach to Pump House | Good | Fair | Bad | | |
| Pump Details | | | | | |
| Pump Type | | | | | |
| Pump Make | | | | | |
| Discharge Capacity (Cusec) | | | | | |
| Rotational Speed (RPM) | | | | | |
| Housing Dia (inches) | | | | | |
| Bore Depth (ft.) | | | | | |
| Head (ft.) | | | | | |
| Impeller Installation Depth (ft.) | | | | | |
| Paint of Pumping Unit | | | | | |
| Number of Valves | Gate Valve | | | | |
| | Non-Returning Valve | | | | |
| Base Plate | Yes | | | No | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | | | | | |
| Sanctioned Load (Kwh) | | | | | |
| Motor Power (HP) | | | | | |
| Motor Make | | | | | |
| MCU | Yes | | | No | |
| Earthing of Motor | Yes | | | No | |
| Power Wiring | Yes | | | No | |
| Service Cable | Yes | | | No | |
| Earthing of MCU | Yes | | | No | |
| Energy Meter | Yes | | | No | |
| Water Meter | Yes | | | No | |
| PFI Equipment | Yes | | | No | |
| Generator | Yes | | | No | |
| Change Over | Yes | | | No | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |




| Integrated Development and Asset Management Plan (IDAMP) | | |
|--|---|---|
| Municipal Committee Burewala | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |


| Integrated Development and Asset Management Plan (IDAMP) | | | | |
|--|---|-----------------------------|----------------|---------------------------------------|
| Municipal Committee Burewala | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 |
| Asset Detail | | | Pictures | |
| Name | | Muhammad Nagar #01 | | |
| Location | Latitude | 30.149384 | | |
| | Longitude | 72.658336 | | |
| Address | | Muhammad Nagar, Burewala | | |
| Area (Marla) | | 1 | | |
| Working Status | | Functional | Non-Functional | |
| Installation Year of Tube Well | | 2002 | | |
| Installation Year of Pump | | 2002 | | |
| Capital Cost of Machinery | | | | |
| Operational Hours | | 5 | | |
| Delivery Pipe | Dia | 6 | | |
| | Material | MS | | |
| Chlorinator | | Yes | No | |
| Chlorination Schedule | | Once in a Year | After 6 Months | No Schedule |
| Apron Around Pump House | | Yes | No | |
| Hoisting Girder | | Yes | No | |
| Civil Structure Condition | | No Pump House | | |
| Approach to Pump House | | Good | Fair | Bad |
| Pump Details | | | | |
| Pump Type | | Turbine | | |
| Pump Make | | KSB | | |
| Discharge Capacity (Cusec) | | 1.5 | | |
| Rotational Speed (RPM) | | 1470 | | |
| Housing Dia (inches) | | 12" | | |
| Bore Depth (ft.) | | 450 | | |
| Head (ft.) | | 200 | | |
| Impeller Installation Depth (ft.) | | 100 | | |
| Paint of Pumping Unit | | Good | Fair | Poor |
| Number of Valves | Gate Valve | 1 | | |
| | Non-Returning Valve | 1 | | |
| Base Plate | | Yes | No | |
| Electro-Mechanical Equipment Details | | | | |
| Transformer Capacity (kVA) | | 50 | | |
| Sanctioned Load (Kwh) | | 30 | | |
| Motor Power (HP) | | 40 | | |
| Motor Make | | Siemens | | |
| MCU | | Yes | No | |
| Earthing of Motor | | Yes | No | |
| Power Wiring | | Yes | No | |
| Service Cable | | Yes | No | |





| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Earthing of MCU | Yes | No | | | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|-----------------------------|----------|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | Pictures | | |
| Name | | Muhammad Nagar #2 | | | |
| Location | Latitude | 30.151513 | | | |
| | Longitude | 72.664395 | | | |
| Address | | Muhammad Nagar, Burewala | | | |
| Area (Marla) | | 1 | | | |
| Working Status | | Abandoned | | | |
| Installation Year of Tube Well | | 2021 | | | |
| Installation Year of Pump | | 2021 | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | | | | |
| Delivery Pipe | Dia | | | | |
| | Material | | | | |
| Chlorinator | | Yes | No | | |






| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|----------------|-------------|--|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Chlorination Schedule | Once in a Year | After 6 Months | No Schedule |  | |
| Apron Around Pump House | Yes | | No | | |
| Hoisting Girder | Yes | | No | | |
| Civil Structure Condition | Good | Fair | Bad | | |
| Approach to Pump House | Good | Fair | Bad | | |
| Pump Details | | | | | |
| Pump Type | | | | | |
| Pump Make | | | | | |
| Discharge Capacity (Cusec) | | | | | |
| Rotational Speed (RPM) | | | | | |
| Housing Dia (inches) | | | | | |
| Bore Depth (ft.) | | | | | |
| Head (ft.) | | | | | |
| Impeller Installation Depth (ft.) | | | | | |
| Paint of Pumping Unit | | | | | |
| Number of Valves | Gate Valve | | | | |
| | Non-Returning Valve | | | | |
| Base Plate | Yes | | | | No |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | | | | | |
| Sanctioned Load (Kwh) | | | | | |
| Motor Power (HP) | | | | | |
| Motor Make | | | | | |
| MCU | Yes | | | | No |
| Earthing of Motor | Yes | | | | No |
| Power Wiring | Yes | | | | No |
| Service Cable | Yes | | | | No |
| Earthing of MCU | Yes | | | | No |
| Energy Meter | Yes | | | | No |
| Water Meter | Yes | | | | No |
| PFI Equipment | Yes | | | | No |
| Generator | Yes | | | | No |
| Change Over | Yes | | | | No |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> Locked by MC due to connection cut of electricity. | | | | | |


| Integrated Development and Asset Management Plan (IDAMP) | | |
|--|---|---|
| Municipal Committee Burewala | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 |
| Data Collected By: Mr. Abdullah | Designation: Team Member |  Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |



| Integrated Development and Asset Management Plan (IDAMP) | | | |
|--|---|----------------|---------------------------------------|
| Municipal Committee Burewala | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 |
| Asset Detail | | Pictures | |
| Name | Ahata Shahnawat | | |
| Location | Latitude | 30.151528 | |
| | Longitude | 72.664640 | |
| Address | Ahata Shahnawat, Burewala | | |
| Area (Marla) | 1 | | |
| Working Status | Functional | Non-Functional | |
| Installation Year of Tube Well | | | |
| Installation Year of Pump | | | |
| Capital Cost of Machinery | | | |
| Operational Hours | 5 | | |
| Delivery Pipe | Dia | 6 | |
| | Material | MS | |
| Chlorinator | Yes | No | |
| Chlorination Schedule | Once in a Year | After 6 Months | No Schedule |
| Apron Around Pump House | Yes | No | |
| Hoisting Girder | Yes | No | |
| Civil Structure Condition | Good | Fair | Bad |
| Approach to Pump House | Good | Fair | Bad |
| Pump Details | | | |
| Pump Type | Turbine | | |
| Pump Make | Flow Pak | | |
| Discharge Capacity (Cusec) | 1 | | |
| Rotational Speed (RPM) | 1470 | | |
| Housing Dia (inches) | 12" | | |
| Bore Depth (ft.) | 450 | | |
| Head (ft.) | 200 | | |




| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | |
|--|---|--------------------------|------|---|---------|---|--|
| Municipal Committee Burewala | | | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | | | |
| Impeller Installation Depth (ft.) | 100 | | |  | | | |
| Paint of Pumping Unit | Good | Fair | Poor | | | | |
| Number of Valves | Gate Valve | | | | | 1 | |
| | Non-Returning Valve | | | | | 1 | |
| Base Plate | Yes | | No | | | | |
| Electro-Mechanical Equipment Details | | | | | | | |
| Transformer Capacity (kVA) | 100 | | | | | | |
| Sanctioned Load (Kwh) | 37 | | | | | | |
| Motor Power (HP) | 40 | | | | | | |
| Motor Make | PECO | | | | | | |
| MCU | Yes | No | | | | | |
| Earthing of Motor | Yes | No | | | | | |
| Power Wiring | Yes | No | | | | | |
| Service Cable | Yes | No | | | | | |
| Earthing of MCU | Yes | No | | | | | |
| Energy Meter | Yes | No | | | | | |
| Water Meter | Yes | No | | | | | |
| PFI Equipment | Yes | No | | | | | |
| Generator | Yes | No | | | | | |
| Change Over | Yes | No | | | | | |
| Overall Rating | | | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 | | |
| Asset Condition | Excellent | Good | Fair | Poor | Failing | | |
| Category | A | B | C | D | E | | |
| Remarks / Requirements | | | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | | | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | | | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | |
|--|---|-----------------------------|----------------|---------------------------------------|
| Municipal Committee Burewala | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 |
| Asset Detail | | | Pictures | |
| Name | | Housing Scheme | | |
| Location | Latitude | 30.159116 | | |
| | Longitude | 72.670408 | | |
| Address | | Housing Scheme, Burewala | | |
| Area (Marla) | | 1 | | |
| Working Status | | Functional | Non-Functional | |
| Installation Year of Tube Well | | 2009 | | |
| Installation Year of Pump | | 2009 | | |
| Capital Cost of Machinery | | | | |
| Operational Hours | | 5 | | |
| Delivery Pipe | Dia | 8 | | |
| | Material | MS | | |
| Chlorinator | | Yes | No | |
| Chlorination Schedule | | Once in a Year | After 6 Months | No Schedule |
| Apron Around Pump House | | Yes | No | |
| Hoisting Girder | | Yes | No | |
| Civil Structure Condition | | Good | Fair | Bad |
| Approach to Pump House | | Good | Fair | Bad |
| Pump Details | | | | |
| Pump Type | | Turbine | | |
| Pump Make | | MECO | | |
| Discharge Capacity (Cusec) | | 1 | | |
| Rotational Speed (RPM) | | 1465 | | |
| Housing Dia (inches) | | 12" | | |
| Bore Depth (ft.) | | 450 | | |
| Head (ft.) | | 200 | | |
| Impeller Installation Depth (ft.) | | 100 | | |
| Paint of Pumping Unit | | Good | Fair | Poor |
| Number of Valves | Gate Valve | 1 | | |
| | Non-Returning Valve | 1 | | |
| Base Plate | | Yes | No | |
| Electro-Mechanical Equipment Details | | | | |
| Transformer Capacity (kVA) | | 50 | | |
| Sanctioned Load (Kwh) | | 30 | | |
| Motor Power (HP) | | 40 | | |
| Motor Make | | Siemens | | |
| MCU | | Yes | No | |
| Earthing of Motor | | Yes | No | |
| Power Wiring | | Yes | No | |
| Service Cable | | Yes | No | |





| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Earthing of MCU | Yes | No | | | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |



| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|-----------------------------|----------|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | Pictures | | |
| Name | | Shadman Colony | | | |
| Location | Latitude | 30.158871 | | | |
| | Longitude | 72.670701 | | | |
| Address | | Shadman Colony, Burewala | | | |
| Area (Marla) | | 1 | | | |
| Working Status | | Abandoned | | | |
| Installation Year of Tube Well | | | | | |
| Installation Year of Pump | | | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | | | | |
| Delivery Pipe | Dia | | | | |
| | Material | | | | |
| Chlorinator | | Yes | No | | |




| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|-----------------------|--------------------|---------------------------------------|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Chlorination Schedule | Once in a Year | After 6 Month s | No Schedu le | | |
| Apron Around Pump House | Yes | | No | | |
| Hoisting Girder | Yes | | No | | |
| Civil Structure Condition | Good | Fair | Bad | | |
| Approach to Pump House | Good | Fair | Bad | | |
| Pump Details | | | | | |
| Pump Type | | | | | |
| Pump Make | | | | | |
| Discharge Capacity (Cusec) | | | | | |
| Rotational Speed (RPM) | | | | | |
| Housing Dia (inches) | | | | | |
| Bore Depth (ft.) | | | | | |
| Head (ft.) | | | | | |
| Impeller Installation Depth (ft.) | | | | | |
| Paint of Pumping Unit | | | | | |
| Number of Valves | Gate Valve | | | | |
| | Non-Returning Valve | | | | |
| Base Plate | Yes | | No | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | | | | | |
| Sanctioned Load (Kwh) | | | | | |
| Motor Power (HP) | | | | | |
| Motor Make | | | | | |
| MCU | Yes | | No | | |
| Earthing of Motor | Yes | | No | | |
| Power Wiring | Yes | | No | | |
| Service Cable | Yes | | No | | |
| Earthing of MCU | Yes | | No | | |
| Energy Meter | Yes | | No | | |
| Water Meter | Yes | | No | | |
| PFI Equipment | Yes | | No | | |
| Generator | Yes | | No | | |
| Change Over | Yes | | No | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> • No remarks | | | | | |



| Integrated Development and Asset Management Plan (IDAMP) | | |
|--|---|---|
| Municipal Committee Burewala | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 |
| Data Collected By: Mr. Abdullah | Designation: Team Member |  Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |

| Integrated Development and Asset Management Plan (IDAMP) | | |
|--|---|--|
| Municipal Committee Burewala | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 |
| Asset Detail | | Pictures |
| Name | | Ghulam M Colony |
| Location | Latitude | 30.154046 |
| | Longitude | 72.668959 |
| Address | | Ghulam M Colony, Burewala |
| Area (Marla) | | 1 |
| Working Status | | Abandoned |
| Installation Year of Tube Well | | |
| Installation Year of Pump | | |
| Capital Cost of Machinery | | |
| Operational Hours | | |
| Delivery Pipe | Dia | |
| | Material | |
| Chlorinator | | Yes <input type="checkbox"/> No <input type="checkbox"/> |
| Chlorination Schedule | | Once in a Year <input type="checkbox"/> After 6 Months <input type="checkbox"/> No Schedule <input type="checkbox"/> |
| Apron Around Pump House | | Yes <input type="checkbox"/> No <input type="checkbox"/> |
| Hoisting Girder | | Yes <input type="checkbox"/> No <input type="checkbox"/> |
| Civil Structure Condition | | Good <input type="checkbox"/> Fair <input type="checkbox"/> Bad <input type="checkbox"/> |
| Approach to Pump House | | Good <input type="checkbox"/> Fair <input type="checkbox"/> Bad <input type="checkbox"/> |
| Pump Details | | |
| Pump Type | | |
| Pump Make | | |
| Discharge Capacity (Cusec) | | |
| Rotational Speed (RPM) | | |
| Housing Dia (inches) | | |
| Bore Depth (ft.) | | |
| Head (ft.) | | |


| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Impeller Installation Depth (ft.) | | | | | |
| Paint of Pumping Unit | | | | | |
| Number of Valves | Gate Valve | | | | |
| | Non-Returning Valve | | | | |
| Base Plate | Yes | No | | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | | | | | |
| Sanctioned Load (Kwh) | 22 | | | | |
| Motor Power (HP) | | | | | |
| Motor Make | | | | | |
| MCU | Yes | No | | | |
| Earthing of Motor | Yes | No | | | |
| Power Wiring | Yes | No | | | |
| Service Cable | Yes | No | | | |
| Earthing of MCU | Yes | No | | | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|---------------------------------|-----------------------|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | | Pictures | |
| Name | | Masoom Shah Colony | | | |
| Location | Latitude | 30.146143 | | | |
| | Longitude | 72.675092 | | | |
| Address | | Masoom Shah Colony, Burewala | | | |
| Area (Marla) | | 1 | | | |
| Working Status | | Abandoned | | | |
| Installation Year of Tube Well | | | | | |
| Installation Year of Pump | | | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | | | | |
| Delivery Pipe | Dia | | | | |
| | Material | | | | |
| Chlorinator | | Yes | No | | |
| Chlorination Schedule | | Once in a Year | After 6 Month s | No Schedu le | |
| Apron Around Pump House | | Yes | No | | |
| Hoisting Girder | | Yes | No | | |
| Civil Structure Condition | | Good | Fair | Bad | |
| Approach to Pump House | | Good | Fair | Bad | |
| Pump Details | | | | | |
| Pump Type | | | | | |
| Pump Make | | | | | |
| Discharge Capacity (Cusec) | | | | | |
| Rotational Speed (RPM) | | | | | |
| Housing Dia (inches) | | | | | |
| Bore Depth (ft.) | | | | | |
| Head (ft.) | | | | | |
| Impeller Installation Depth (ft.) | | | | | |
| Paint of Pumping Unit | | | | | |
| Number of Valves | Gate Valve | | | | |
| | Non-Returning Valve | | | | |
| Base Plate | | Yes | No | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | | | | | |
| Sanctioned Load (Kwh) | | | | | |
| Motor Power (HP) | | | | | |
| Motor Make | | | | | |
| MCU | | Yes | No | | |
| Earthing of Motor | | Yes | No | | |
| Power Wiring | | Yes | No | | |
| Service Cable | | Yes | No | | |
| Earthing of MCU | | Yes | No | | |








| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |



| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------|----------|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | Pictures | | |
| Name | Bhatta Yousafabad | | | | |
| Location | Latitude | 30.149021 | | | |
| | Longitude | 72.675727 | | | |
| Address | Bhatta Yousafabad, Burewala | | | | |
| Area (Marla) | 1 | | | | |
| Working Status | Functional | Non- Functional | | | |
| Installation Year of Tube Well | 1980 | | | | |
| Installation Year of Pump | 1990 | | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | 5 | | | | |
| Delivery Pipe | Dia | 5 | | | |
| | Material | MS | | | |
| Chlorinator | Yes | No | | | |




| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | |
|--|---|----------------|-------------|---------------------------------------|---------|--|--|
| Municipal Committee Burewala | | | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | | | |
| Chlorination Schedule | Once in a Year | After 6 Months | No Schedule | | | | |
| Apron Around Pump House | Yes | | No | | | | |
| Hoisting Girder | Yes | | No | | | | |
| Civil Structure Condition | Good | Fair | Bad | | | | |
| Approach to Pump House | Good | Fair | Bad | | | | |
| Pump Details | | | | | | | |
| Pump Type | Turbine | | | | | | |
| Pump Make | KSB | | | | | | |
| Discharge Capacity (Cusec) | 1 | | | | | | |
| Rotational Speed (RPM) | 1460 | | | | | | |
| Housing Dia (inches) | 10" | | | | | | |
| Bore Depth (ft.) | 450 | | | | | | |
| Head (ft.) | 200 | | | | | | |
| Impeller Installation Depth (ft.) | 100 | | | | | | |
| Paint of Pumping Unit | Good | Fair | Poor | | | | |
| Number of Valves | Gate Valve | 1 | | | | | |
| | Non-Returning Valve | 1 | | | | | |
| Base Plate | Yes | No | | | | | |
| Electro-Mechanical Equipment Details | | | | | | | |
| Transformer Capacity (kVA) | 50 | | | | | | |
| Sanctioned Load (Kwh) | 19 | | | | | | |
| Motor Power (HP) | 25 | | | | | | |
| Motor Make | Siemens | | | | | | |
| MCU | Yes | No | | | | | |
| Earthing of Motor | Yes | No | | | | | |
| Power Wiring | Yes | No | | | | | |
| Service Cable | Yes | No | | | | | |
| Earthing of MCU | Yes | No | | | | | |
| Energy Meter | Yes | No | | | | | |
| Water Meter | Yes | No | | | | | |
| PFI Equipment | Yes | No | | | | | |
| Generator | Yes | No | | | | | |
| Change Over | Yes | No | | | | | |
| Overall Rating | | | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 | | |
| Asset Condition | Excellent | Good | Fair | Poor | Failing | | |
| Category | A | B | C | D | E | | |
| Remarks / Requirements | | | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | | | |



| Integrated Development and Asset Management Plan (IDAMP) | | |
|--|---|---|
| Municipal Committee Burewala | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 |
| Data Collected By: Mr. Abdullah | Designation: Team Member |  Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |

| Integrated Development and Asset Management Plan (IDAMP) | | | |
|--|---|--|---------------------------------------|
| Municipal Committee Burewala | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 |
| Asset Detail | | Pictures | |
| Name | | Habib Colony | |
| Location | Latitude | 30.151722 | |
| | Longitude | 72.676347 | |
| Address | | Habib Colony, Burewala | |
| Area (Marla) | | 1 | |
| Working Status | | Functional | Non-Functional |
| Installation Year of Tube Well | | 1981 | |
| Installation Year of Pump | | 2017 | |
| Capital Cost of Machinery | | | |
| Operational Hours | | 5 | |
| Delivery Pipe | Dia | 6 | |
| | Material | MS | |
| Chlorinator | | Yes | No |
| Chlorination Schedule | | Once in a Year | After 6 Months No Schedule |
| Apron Around Pump House | | Yes | No |
| Hoisting Girder | | Yes | No |
| Civil Structure Condition | | Good | Fair Bad |
| Approach to Pump House | | Good | Fair Bad |
| Pump Details | | | |
| Pump Type | | Turbine | |
| Pump Make | | KSB | |
| Discharge Capacity (Cusec) | | 1 | |
| Rotational Speed (RPM) | | 1470 | |
| Housing Dia (inches) | | 12" | |
| Bore Depth (ft.) | | 450 | |
| Head (ft.) | | 200 | |
| | |  | |
| | |  | |
| | |  | |


| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Impeller Installation Depth (ft.) | 100 | | | | |
| Paint of Pumping Unit | Good | Fair | Poor | | |
| Number of Valves | Gate Valve | | 1 | | |
| | Non-Returning Valve | | 1 | | |
| Base Plate | Yes | No | | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | 50 | | | | |
| Sanctioned Load (Kwh) | 22 | | | | |
| Motor Power (HP) | 40 | | | | |
| Motor Make | Siemens | | | | |
| MCU | Yes | No | | | |
| Earthing of Motor | Yes | No | | | |
| Power Wiring | Yes | No | | | |
| Service Cable | Yes | No | | | |
| Earthing of MCU | Yes | No | | | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | |
|--|---------------------|--------------------------------------|----------------|---------------------------------------|
| Municipal Committee Burewala | | | | |
| Form: IDAMP-A1 | | Tube Well Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 |
| Asset Detail | | | Pictures | |
| Name | | Habib Colony School | | |
| Location | Latitude | 30.153495 | | |
| | Longitude | 72.679150 | | |
| Address | | Habib Colony School, Burewala | | |
| Area (Marla) | | 1 | | |
| Working Status | | Functional | Non-Functional | |
| Installation Year of Tube Well | | 1991 | | |
| Installation Year of Pump | | 2017 | | |
| Capital Cost of Machinery | | | | |
| Operational Hours | | 5 | | |
| Delivery Pipe | Dia | 8 | | |
| | Material | MS | | |
| Chlorinator | | Yes | No | |
| Chlorination Schedule | | Once in a Year | After 6 Months | No Schedule |
| Apron Around Pump House | | Yes | No | |
| Hoisting Girder | | Yes | No | |
| Civil Structure Condition | | Good | Fair | Bad |
| Approach to Pump House | | Good | Fair | Bad |
| Pump Details | | | | |
| Pump Type | | Turbine | | |
| Pump Make | | PECO | | |
| Discharge Capacity (Cusec) | | 1 | | |
| Rotational Speed (RPM) | | 1470 | | |
| Housing Dia (inches) | | 12" | | |
| Bore Depth (ft.) | | 450 | | |
| Head (ft.) | | 200 | | |
| Impeller Installation Depth (ft.) | | 100 | | |
| Paint of Pumping Unit | | Good | Fair | Poor |
| Number of Valves | Gate Valve | 1 | | |
| | Non-Returning Valve | 1 | | |
| Base Plate | | Yes | No | |
| Electro-Mechanical Equipment Details | | | | |
| Transformer Capacity (kVA) | | 50 | | |
| Sanctioned Load (Kwh) | | 30 | | |
| Motor Power (HP) | | 50 | | |
| Motor Make | | PECO | | |
| MCU | | Yes | No | |
| Earthing of Motor | | Yes | No | |
| Power Wiring | | Yes | No | |
| Service Cable | | Yes | No | |





| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Earthing of MCU | Yes | No | | | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|-------------------|----------------|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | Pictures | | |
| Name | | H-Block | | | |
| Location | Latitude | 30.159713 | | | |
| | Longitude | 72.684095 | | | |
| Address | | H-Block, Burewala | | | |
| Area (Marla) | | 1 | | | |
| Working Status | | Functional | Non-Functional | | |
| Installation Year of Tube Well | | | | | |
| Installation Year of Pump | | 2018 | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | 5 | | | |
| Delivery Pipe | Dia | 8 | | | |
| | Material | MS | | | |
| Chlorinator | | Yes | No | | |






| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | |
|--|--------------------------------------|----------------|-------------|---------------------------------------|---------|--|--|
| Municipal Committee Burewala | | | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | | | |
| Chlorination Schedule | Once in a Year | After 6 Months | No Schedule | | | | |
| Apron Around Pump House | Yes | | No | | | | |
| Hoisting Girder | Yes | | No | | | | |
| Civil Structure Condition | Good | Fair | Bad | | | | |
| Approach to Pump House | Good | Fair | Bad | | | | |
| Pump Details | | | | | | | |
| Pump Type | Turbine | | | | | | |
| Pump Make | HMA | | | | | | |
| Discharge Capacity (Cusec) | 1 | | | | | | |
| Rotational Speed (RPM) | 2945 | | | | | | |
| Housing Dia (inches) | 12" | | | | | | |
| Bore Depth (ft.) | 450 | | | | | | |
| Head (ft.) | 200 | | | | | | |
| Impeller Installation Depth (ft.) | 100 | | | | | | |
| Paint of Pumping Unit | Good | Fair | Poor | | | | |
| Number of Valves | Gate Valve | 1 | | | | | |
| | Non-Returning Valve | 1 | | | | | |
| Base Plate | Yes | No | | | | | |
| Electro-Mechanical Equipment Details | | | | | | | |
| Transformer Capacity (kVA) | 50 | | | | | | |
| Sanctioned Load (Kwh) | 30 | | | | | | |
| Motor Power (HP) | 30 | | | | | | |
| Motor Make | Grundfos | | | | | | |
| MCU | Yes | No | | | | | |
| Earthing of Motor | Yes | No | | | | | |
| Power Wiring | Yes | No | | | | | |
| Service Cable | Yes | No | | | | | |
| Earthing of MCU | Yes | No | | | | | |
| Energy Meter | Yes | No | | | | | |
| Water Meter | Yes | No | | | | | |
| PFI Equipment | Yes | No | | | | | |
| Generator | Yes | No | | | | | |
| Change Over | Yes | No | | | | | |
| Overall Rating | | | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 | | |
| Asset Condition | Excellent | Good | Fair | Poor | Failing | | |
| Category | A | B | C | D | E | | |
| Remarks / Requirements | | | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | | | |


| Integrated Development and Asset Management Plan (IDAMP) | | |
|--|---|---|
| Municipal Committee Burewala | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 |
| Data Collected By: Mr. Abdullah | Designation: Team Member |  Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |


| Integrated Development and Asset Management Plan (IDAMP) | | | | |
|--|---|------------------|----------------|---------------------------------------|
| Municipal Committee Burewala | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 |
| Asset Detail | | | Pictures | |
| Name | | M-Bock | | |
| Location | Latitude | 30.160647 | | |
| | Longitude | 72.685178 | | |
| Address | | M-Bock, Burewala | | |
| Area (Marla) | | 1 | | |
| Working Status | | Functional | Non-Functional | |
| Installation Year of Tube Well | | | | |
| Installation Year of Pump | | 1999 | | |
| Capital Cost of Machinery | | | | |
| Operational Hours | | 5 | | |
| Delivery Pipe | Dia | 6 | | |
| | Material | MS | | |
| Chlorinator | | Yes | No | |
| Chlorination Schedule | | Once in a Year | After 6 Months | No Schedule |
| Apron Around Pump House | | Yes | No | |
| Hoisting Girder | | Yes | No | |
| Civil Structure Condition | | Good | Fair | Bad |
| Approach to Pump House | | Good | Fair | Bad |
| Pump Details | | | | |
| Pump Type | | Turbine | | |
| Pump Make | | PECO | | |
| Discharge Capacity (Cusec) | | 1 | | |
| Rotational Speed (RPM) | | 1450 | | |
| Housing Dia (inches) | | 12" | | |
| Bore Depth (ft.) | | 450 | | |
| Head (ft.) | | 200 | | |
| Impeller Installation Depth (ft.) | | 100 | | |
| Paint of Pumping Unit | | Good | Fair | Poor |
| Number of Valves | Gate Valve | 1 | | |
| | Non-Returning Valve | 1 | | |
| Base Plate | | Yes | No | |
| Electro-Mechanical Equipment Details | | | | |
| Transformer Capacity (kVA) | | 200 (Combined) | | |
| Sanctioned Load (Kwh) | | 30 | | |
| Motor Power (HP) | | 30 | | |
| Motor Make | | PECO | | |
| MCU | | Yes | No | |
| Earthing of Motor | | Yes | No | |
| Power Wiring | | Yes | No | |
| Service Cable | | Yes | No | |
| Earthing of MCU | | Yes | No | |





| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|-------------------|--|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | Pictures | | |
| Name | | E-Block | | | |
| Location | Latitude | 30.160679 | | | |
| | Longitude | 72.683758 | | | |
| Address | | E-Block, Burewala | | | |
| Area (Marla) | | 1 | | | |
| Working Status | | Abandoned | | | |
| Installation Year of Tube Well | | | | | |
| Installation Year of Pump | | | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | | | | |
| Delivery Pipe | Dia | | | | |
| | Material | | | | |
| Chlorinator | | Yes | No | | |
| Chlorination Schedule | | Once in a Year | After 6 Months | No Schedule | |
| | | |  | | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|---|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Apron Around Pump House | Yes | | | No | |
| Hoisting Girder | Yes | | | No | |
| Civil Structure Condition | Good | Fair | Bad | | |
| Approach to Pump House | Good | Fair | Bad | | |
| Pump Details | | | | | |
| Pump Type | | | | | |
| Pump Make | | | | | |
| Discharge Capacity (Cusec) | | | | | |
| Rotational Speed (RPM) | | | | | |
| Housing Dia (inches) | | | | | |
| Bore Depth (ft.) | | | | | |
| Head (ft.) | | | | | |
| Impeller Installation Depth (ft.) | | | | | |
| Paint of Pumping Unit | | | | | |
| Number of Valves | Gate Valve | | | | |
| | Non-Returning Valve | | | | |
| Base Plate | Yes | | | No | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | | | | | |
| Sanctioned Load (Kwh) | | | | | |
| Motor Power (HP) | | | | | |
| Motor Make | | | | | |
| MCU | Yes | | | No | |
| Earthing of Motor | Yes | | | No | |
| Power Wiring | Yes | | | No | |
| Service Cable | Yes | | | No | |
| Earthing of MCU | Yes | | | No | |
| Energy Meter | Yes | | | No | |
| Water Meter | Yes | | | No | |
| PFI Equipment | Yes | | | No | |
| Generator | Yes | | | No | |
| Change Over | Yes | | | No | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> Bore choked | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |



| Integrated Development and Asset Management Plan (IDAMP) | | |
|--|---|---|
| Municipal Committee Burewala | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |


| Integrated Development and Asset Management Plan (IDAMP) | | |
|--|---|--|
| Municipal Committee Burewala | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 |
| Asset Detail | | Pictures |
| Name | | Ghalla Mandi |
| Location | Latitude | 30.157218 |
| | Longitude | 72.679596 |
| Address | | Ghalla Mandi, Burewala |
| Area (Marla) | | 1 |
| Working Status | | Abandoned |
| Installation Year of Tube Well | | |
| Installation Year of Pump | | |
| Capital Cost of Machinery | | |
| Operational Hours | | |
| Delivery Pipe | Dia | |
| | Material | |
| Chlorinator | | Yes <input type="checkbox"/> No <input type="checkbox"/> |
| Chlorination Schedule | | Once in a Year <input type="checkbox"/> After 6 Months <input type="checkbox"/> No Schedule <input type="checkbox"/> |
| Apron Around Pump House | | Yes <input type="checkbox"/> No <input type="checkbox"/> |
| Hoisting Girder | | Yes <input type="checkbox"/> No <input type="checkbox"/> |
| Civil Structure Condition | | Good <input type="checkbox"/> Fair <input type="checkbox"/> Bad <input type="checkbox"/> |
| Approach to Pump House | | Good <input type="checkbox"/> Fair <input type="checkbox"/> Bad <input type="checkbox"/> |
| Pump Details | | |
| Pump Type | | |
| Pump Make | | KSB |
| Discharge Capacity (Cusec) | | 1 |
| Rotational Speed (RPM) | | 1470 |
| Housing Dia (inches) | | |
| Bore Depth (ft.) | | 200 |
| Head (ft.) | | |
| Impeller Installation Depth (ft.) | | |
| Paint of Pumping Unit | | |
| Number of Valves | Gate Valve | |
| | Non-Returning Valve | |


| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|---|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Base Plate | Yes | No | | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | 50 | | | | |
| Sanctioned Load (Kwh) | | | | | |
| Motor Power (HP) | 30 | | | | |
| Motor Make | SIEMENS | | | | |
| MCU | Yes | No | | | |
| Earthing of Motor | Yes | No | | | |
| Power Wiring | Yes | No | | | |
| Service Cable | Yes | No | | | |
| Earthing of MCU | Yes | No | | | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> Bore Choked | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |


| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---------------------|--------------------------------------|----------------|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | | Tube Well Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | | Pictures | |
| Name | | A-Block Near Ground | | | |
| Location | Latitude | 30.160795 | | | |
| | Longitude | 72.675476 | | | |
| Address | | A Block, Burewala | | | |
| Area (Marla) | | 1 | | | |
| Working Status | | Abandoned | | | |
| Installation Year of Tube Well | | | | | |
| Installation Year of Pump | | | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | | | | |
| Delivery Pipe | Dia | | | | |
| | Material | | | | |
| Chlorinator | | Yes | No | | |
| Chlorination Schedule | | Once in a Year | After 6 Months | No Schedule | |
| Apron Around Pump House | | Yes | No | | |
| Hoisting Girder | | Yes | No | | |
| Civil Structure Condition | | Good | Fair | Bad | |
| Approach to Pump House | | Good | Fair | Bad | |
| Pump Details | | | | | |
| Pump Type | | | | | |
| Pump Make | | | | | |
| Discharge Capacity (Cusec) | | | | | |
| Rotational Speed (RPM) | | | | | |
| Housing Dia (inches) | | | | | |
| Bore Depth (ft.) | | | | | |
| Head (ft.) | | | | | |
| Impeller Installation Depth (ft.) | | | | | |
| Paint of Pumping Unit | | | | | |
| Number of Valves | Gate Valve | | | | |
| | Non-Returning Valve | | | | |
| Base Plate | | Yes | No | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | | | | | |
| Sanctioned Load (Kwh) | | | | | |
| Motor Power (HP) | | | | | |
| Motor Make | | | | | |
| MCU | | Yes | No | | |
| Earthing of Motor | | Yes | No | | |
| Power Wiring | | Yes | No | | |
| Service Cable | | Yes | No | | |
| Earthing of MCU | | Yes | No | | |
| Energy Meter | | Yes | No | | |



| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|--|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> Pumping equipment replacement required | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |



| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|------------------------------|--|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | Pictures | | |
| Name | | Ghoshala | | | |
| Location | Latitude | 30.164062 | | | |
| | Longitude | 72.674128 | | | |
| Address | | Bar Association, Burewala | | | |
| Area (Marla) | | 1 | | | |
| Working Status | | Abandoned | | | |
| Installation Year of Tube Well | | | | | |
| Installation Year of Pump | | | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | | | | |
| Delivery Pipe | Dia | | | | |
| | Material | | | | |
| Chlorinator | | Yes | No | | |
| Chlorination Schedule | | Once in a Year | After 6 Months | No Schedule | |
| | | |  | | |


| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Apron Around Pump House | Yes | | | No | |
| Hoisting Girder | Yes | | | No | |
| Civil Structure Condition | Good | Fair | Bad | | |
| Approach to Pump House | Good | Fair | Bad | | |
| Pump Details | | | | | |
| Pump Type | | | | | |
| Pump Make | | | | | |
| Discharge Capacity (Cusec) | | | | | |
| Rotational Speed (RPM) | | | | | |
| Housing Dia (inches) | | | | | |
| Bore Depth (ft.) | | | | | |
| Head (ft.) | | | | | |
| Impeller Installation Depth (ft.) | | | | | |
| Paint of Pumping Unit | | | | | |
| Number of Valves | Gate Valve | | | | |
| | Non-Returning Valve | | | | |
| Base Plate | Yes | | | No | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | | | | | |
| Sanctioned Load (Kwh) | 19 | | | | |
| Motor Power (HP) | | | | | |
| Motor Make | | | | | |
| MCU | Yes | | | No | |
| Earthing of Motor | Yes | | | No | |
| Power Wiring | Yes | | | No | |
| Service Cable | Yes | | | No | |
| Earthing of MCU | Yes | | | No | |
| Energy Meter | Yes | | | No | |
| Water Meter | Yes | | | No | |
| PFI Equipment | Yes | | | No | |
| Generator | Yes | | | No | |
| Change Over | Yes | | | No | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> • No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |


| Integrated Development and Asset Management Plan (IDAMP) | | |
|--|---|---|
| Municipal Committee Burewala | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |

| Integrated Development and Asset Management Plan (IDAMP) | | | | |
|--|---|-----------------------|----------------|---------------------------------------|
| Municipal Committee Burewala | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 |
| Asset Detail | | | Pictures | |
| Name | | Chak 437-EB | | |
| Location | Latitude | 30.163984 | | |
| | Longitude | 72.674193 | | |
| Address | | Chak 437-EB, Burewala | | |
| Area (Marla) | | 1 | | |
| Working Status | | Functional | Non-Functional | |
| Installation Year of Tube Well | | Not Available | | |
| Installation Year of Pump | | 2020 | | |
| Capital Cost of Machinery | | | | |
| Operational Hours | | 5 | | |
| Delivery Pipe | Dia | 8 | | |
| | Material | MS | | |
| Chlorinator | | Yes | No | |
| Chlorination Schedule | | Once in a Year | After 6 Months | No Schedule |
| Apron Around Pump House | | Yes | No | |
| Hoisting Girder | | Yes | No | |
| Civil Structure Condition | | Good | Fair | Bad |
| Approach to Pump House | | Good | Fair | Bad |
| Pump Details | | | | |
| Pump Type | | Turbine | | |
| Pump Make | | KSB | | |
| Discharge Capacity (Cusec) | | 1 | | |
| Rotational Speed (RPM) | | 1470 | | |
| Housing Dia (inches) | | 12" | | |
| Bore Depth (ft.) | | 450 | | |
| Head (ft.) | | 200 | | |
| Impeller Installation Depth (ft.) | | 100 | | |
| Paint of Pumping Unit | | Good | Fair | Poor |
| Number of Valves | Gate Valve | 1 | | |
| | Non-Returning Valve | 1 | | |
| Base Plate | | Yes | No | |
| Electro-Mechanical Equipment Details | | | | |
| Transformer Capacity (kVA) | | 100 (Combined) | | |
| Sanctioned Load (Kwh) | | 30 | | |
| Motor Power (HP) | | 40 | | |
| Motor Make | | Siemens | | |
| MCU | | Yes | No | |
| Earthing of Motor | | Yes | No | |
| Power Wiring | | Yes | No | |
| Service Cable | | Yes | No | |
| Earthing of MCU | | Yes | No | |




| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |



| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|-------------------------|--|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | Pictures | | |
| Name | | Stadium Canal | | | |
| Location | Latitude | 30.170839 | | | |
| | Longitude | 72.680043 | | | |
| Address | | Stadium Canal, Burewala | | | |
| Area (Marla) | | 1 | | | |
| Working Status | | Abandoned | | | |
| Installation Year of Tube Well | | | | | |
| Installation Year of Pump | | | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | | | | |
| Delivery Pipe | Dia | | | | |
| | Material | | | | |
| Chlorinator | | Yes | No | | |
| Chlorination Schedule | | | | | |
| Apron Around Pump House | | Yes | No | | |
| Hoisting Girder | | Yes | No | | |
| | | |  | | |



| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|---|---------------------|--------------------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | | Tube Well Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 | |
| Civil Structure Condition | | Good | Fair | Bad | |
| Approach to Pump House | | Good | Fair | Bad | |
| Pump Details | | | | | |
| Pump Type | | | | | |
| Pump Make | | | | | |
| Discharge Capacity (Cusec) | | | | | |
| Rotational Speed (RPM) | | | | | |
| Housing Dia (inches) | | | | | |
| Bore Depth (ft.) | | | | | |
| Head (ft.) | | | | | |
| Impeller Installation Depth (ft.) | | | | | |
| Paint of Pumping Unit | | | | | |
| Number of Valves | Gate Valve | | | | |
| | Non-Returning Valve | | | | |
| Base Plate | | Yes | No | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | | | | | |
| Sanctioned Load (Kwh) | | | | | |
| Motor Power (HP) | | | | | |
| Motor Make | | | | | |
| MCU | | Yes | No | | |
| Earthing of Motor | | Yes | No | | |
| Power Wiring | | Yes | No | | |
| Service Cable | | Yes | No | | |
| Earthing of MCU | | Yes | No | | |
| Energy Meter | | Yes | No | | |
| Water Meter | | Yes | No | | |
| PFI Equipment | | Yes | No | | |
| Generator | | Yes | No | | |
| Change Over | | Yes | No | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No Motor Bore Choked | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |




| Integrated Development and Asset Management Plan (IDAMP) | | |
|--|---|---|
| Municipal Committee Burewala | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |

| Integrated Development and Asset Management Plan (IDAMP) | | | | |
|--|---------------------|--------------------------------------|----------------|-------------------|
| Municipal Committee Burewala | | | | |
| Form: IDAMP-A1 | | Tube Well Asset Condition Assessment | | Asset Code: _____ |
| | | | | Date: 05-05-2023 |
| Asset Detail | | | Pictures | |
| Name | | Chak 435-EB | | |
| Location | Latitude | 30.178471 | | |
| | Longitude | 72.690380 | | |
| Address | | Chak 435-EB, Burewala | | |
| Area (Marla) | | 1 | | |
| Working Status | | Functional | Non-Functional | |
| Installation Year of Tube Well | | 2020 | | |
| Installation Year of Pump | | 2020 | | |
| Capital Cost of Machinery | | | | |
| Operational Hours | | 5 | | |
| Delivery Pipe | Dia | 6 | | |
| | Material | MS | | |
| Chlorinator | | Yes | No | |
| Chlorination Schedule | | Once in a Year | After 6 Months | No Schedule |
| Apron Around Pump House | | Yes | No | |
| Hoisting Girder | | Yes | No | |
| Civil Structure Condition | | Good | Fair | Bad |
| Approach to Pump House | | Good | Fair | Bad |
| Pump Details | | | | |
| Pump Type | | Turbine | | |
| Pump Make | | KSB | | |
| Discharge Capacity (Cusec) | | 1 | | |
| Rotational Speed (RPM) | | 1470 | | |
| Housing Dia (inches) | | 12" | | |
| Bore Depth (ft.) | | 450 | | |
| Head (ft.) | | 200 | | |
| Impeller Installation Depth (ft.) | | 100 | | |
| Paint of Pumping Unit | | Good | | |
| Number of Valves | Gate Valve | 1 | | |
| | Non-Returning Valve | 1 | | |
| Base Plate | | Yes | No | |
| Electro-Mechanical Equipment Details | | | | |
| Transformer Capacity (kVA) | | 50 | | |
| Sanctioned Load (Kwh) | | 19 | | |
| Motor Power (HP) | | 40 | | |
| Motor Make | | Siemens | | |
| MCU | | Yes | No | |
| Earthing of Motor | | Yes | No | |
| Power Wiring | | Yes | No | |
| Service Cable | | Yes | No | |
| Earthing of MCU | | Yes | No | |





| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| • | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |


| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|-------------------------------------|----------|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | Pictures | | |
| Name | | Khadija-tul-Kubra Park | | | |
| Location | Latitude | 30.178625 | | | |
| | Longitude | 72.690151 | | | |
| Address | | Khadija-tul-Kubra Park, Burewala | | | |
| Area (Marla) | | 1 | | | |
| Working Status | | Abandoned | | | |
| Installation Year of Tube Well | | | | | |
| Installation Year of Pump | | | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | | | | |
| Delivery Pipe | Dia | | | | |
| | Material | | | | |
| Chlorinator | | Yes | No | | |






| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|---|---|-----------------------|--------------------|---------------------------------------|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Chlorination Schedule | Once in a Year | After 6 Month s | No Schedu le | | |
| Apron Around Pump House | Yes | | No | | |
| Hoisting Girder | Yes | | No | | |
| Civil Structure Condition | Good | Fair | Bad | | |
| Approach to Pump House | Good | Fair | Bad | | |
| Pump Details | | | | | |
| Pump Type | | | | | |
| Pump Make | | | | | |
| Discharge Capacity (Cusec) | | | | | |
| Rotational Speed (RPM) | | | | | |
| Housing Dia (inches) | | | | | |
| Bore Depth (ft.) | | | | | |
| Head (ft.) | | | | | |
| Impeller Installation Depth (ft.) | | | | | |
| Paint of Pumping Unit | | | | | |
| Number of Valves | Gate Valve | | | | |
| | Non-Returning Valve | | | | |
| Base Plate | Yes | | No | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | | | | | |
| Sanctioned Load (Kwh) | | | | | |
| Motor Power (HP) | | | | | |
| Motor Make | | | | | |
| MCU | Yes | No | | | |
| Earthing of Motor | Yes | No | | | |
| Power Wiring | Yes | No | | | |
| Service Cable | Yes | No | | | |
| Earthing of MCU | Yes | No | | | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No Pump set | | | | | |

| Integrated Development and Asset Management Plan (IDAMP) | | |
|--|---|---|
| Municipal Committee Burewala | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 |
| Data Collected By: Mr. Abdullah | Designation: Team Member |  Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |

| Integrated Development and Asset Management Plan (IDAMP) | | |
|--|---|--|
| Municipal Committee Burewala | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 |
| Asset Detail | | Pictures |
| Name | | Tanki#11 P-Bolck |
| Location | Latitude | 30.171319 |
| | Longitude | 72.688386 |
| Address | | P Block, Burewala |
| Area (Marla) | | 1 |
| Working Status | | <input checked="" type="checkbox"/> Functional <input type="checkbox"/> Non-Functional |
| Installation Year of Tube Well | | |
| Installation Year of Pump | | |
| Capital Cost of Machinery | | |
| Operational Hours | | 5 |
| Delivery Pipe | Dia | 6 |
| | Material | MS |
| Chlorinator | | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No |
| Chlorination Schedule | | Once in a Year After 6 Months No Schedule |
| Apron Around Pump House | | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
| Hoisting Girder | | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No |
| Civil Structure Condition | | Good <input checked="" type="checkbox"/> Fair Bad |
| Approach to Pump House | | Good <input checked="" type="checkbox"/> Fair Bad |
| Pump Details | | |
| Pump Type | | Turbine |
| Pump Make | | BECO |
| Discharge Capacity (Cusec) | | 1 |
| Rotational Speed (RPM) | | 1470 |
| Housing Dia (inches) | | 12" |
| Bore Depth (ft.) | | 450 |
| Head (ft.) | | 200 |








| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Impeller Installation Depth (ft.) | 100 | | | | |
| Paint of Pumping Unit | Good | Fair | Poor | | |
| Number of Valves | Gate Valve | | 0 | | |
| | Non-Returning Valve | | 1 | | |
| Base Plate | Yes | No | | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | 50 | | | | |
| Sanctioned Load (Kwh) | 22 | | | | |
| Motor Power (HP) | 40 | | | | |
| Motor Make | BECO | | | | |
| MCU | Yes | No | | | |
| Earthing of Motor | Yes | No | | | |
| Power Wiring | Yes | No | | | |
| Service Cable | Yes | No | | | |
| Earthing of MCU | Yes | No | | | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|----------------------|----------------|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | | Pictures | |
| Name | | Anwar Town | | | |
| Location | Latitude | 30.173482 | | | |
| | Longitude | 72.696142 | | | |
| Address | | Anwar Town, Burewala | | | |
| Area (Marla) | | 1 | | | |
| Working Status | | Abandoned | | | |
| Installation Year of Tube Well | | | | | |
| Installation Year of Pump | | | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | | | | |
| Delivery Pipe | Dia | | | | |
| | Material | | | | |
| Chlorinator | | Yes | No | | |
| Chlorination Schedule | | Once in a Year | After 6 Months | No Schedule | |
| Apron Around Pump House | | Yes | No | | |
| Hoisting Girder | | Yes | No | | |
| Civil Structure Condition | | Good | Fair | Bad | |
| Approach to Pump House | | Good | Fair | Bad | |
| Pump Details | | | | | |
| Pump Type | | | | | |
| Pump Make | | | | | |
| Discharge Capacity (Cusec) | | | | | |
| Rotational Speed (RPM) | | | | | |
| Housing Dia (inches) | | | | | |
| Bore Depth (ft.) | | | | | |
| Head (ft.) | | | | | |
| Impeller Installation Depth (ft.) | | | | | |
| Paint of Pumping Unit | | | | | |
| Number of Valves | Gate Valve | | | | |
| | Non-Returning Valve | | | | |
| Base Plate | | Yes | No | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | | | | | |
| Sanctioned Load (Kwh) | | | | | |
| Motor Power (HP) | | | | | |
| Motor Make | | | | | |
| MCU | | Yes | No | | |
| Earthing of Motor | | Yes | No | | |
| Power Wiring | | Yes | No | | |
| Service Cable | | Yes | No | | |
| Earthing of MCU | | Yes | No | | |
| Energy Meter | | Yes | No | | |





| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No connection to distribution line No Transformer | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |




| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|------------------------|----------------|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | Pictures | | |
| Name | | Ilyas Garden | | | |
| Location | Latitude | 30.172559 | | | |
| | Longitude | 72.691920 | | | |
| Address | | Ilyas Garden, Burewala | | | |
| Area (Marla) | | 1 | | | |
| Working Status | | Functional | Non-Functional | | |
| Installation Year of Tube Well | | 2018 | | | |
| Installation Year of Pump | | 2020 | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | 5 | | | |
| Delivery Pipe | Dia | 8 | | | |
| | Material | MS | | | |
| Chlorinator | | Yes | No | | |






| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|--------------------------------------|----------------|-------------|--|------------------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ | Date: 05-05-2023 |
| Chlorination Schedule | Once in a Year | After 6 Months | No Schedule |  | |
| Apron Around Pump House | Yes | No | | | |
| Hoisting Girder | Yes | No | | | |
| Civil Structure Condition | Good | Fair | Bad | | |
| Approach to Pump House | Good | Fair | Bad | | |
| Pump Details | | | | | |
| Pump Type | Turbine | | | | |
| Pump Make | HMA | | | | |
| Discharge Capacity (Cusec) | 1 | | | | |
| Rotational Speed (RPM) | 2950 | | | | |
| Housing Dia (inches) | 12" | | | | |
| Bore Depth (ft.) | 450 | | | | |
| Head (ft.) | 200 | | | | |
| Impeller Installation Depth (ft.) | 100 | | | | |
| Paint of Pumping Unit | Good | Fair | Poor | | |
| Number of Valves | Gate Valve | 0 | | | |
| | Non-Returning Valve | 1 | | | |
| Base Plate | Yes | No | | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | 50 | | | | |
| Sanctioned Load (Kwh) | 30 | | | | |
| Motor Power (HP) | 40 | | | | |
| Motor Make | Siemens | | | | |
| MCU | Yes | No | | | |
| Earthing of Motor | Yes | No | | | |
| Power Wiring | Yes | No | | | |
| Service Cable | Yes | No | | | |
| Earthing of MCU | Yes | No | | | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |



| Integrated Development and Asset Management Plan (IDAMP) | | |
|--|---|---|
| Municipal Committee Burewala | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 |
| Data Collected By: Mr. Abdullah | Designation: Team Member |  Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |


| Integrated Development and Asset Management Plan (IDAMP) | | | |
|--|---|---------------------------------------|-------------------------------|
| Municipal Committee Burewala | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | Pictures | |
| Name | | Gulshan-e-Ghani | |
| Location | Latitude | 30.165169 | |
| | Longitude | 72.686497 | |
| Address | | Gulshan-e-Ghani, Burewala | |
| Area (Marla) | | 1 | |
| Working Status | | Functional | Non-Functional |
| Installation Year of Tube Well | | 2004 | |
| Installation Year of Pump | | 2004 | |
| Capital Cost of Machinery | | | |
| Operational Hours | | 5 | |
| Delivery Pipe | Dia | 6" | |
| | Material | MS | |
| Chlorinator | | Yes | No |
| Chlorination Schedule | | Once in a Year | After 6 Months No Schedule |
| Apron Around Pump House | | Yes | No |
| Hoisting Girder | | Yes | No |
| Civil Structure Condition | | Good | Fair |
| Approach to Pump House | | Good | Fair |
| Pump Details | | | |
| Pump Type | | Turbine | |
| Pump Make | | General Pump | |
| Discharge Capacity (Cusec) | | 1 | |
| Rotational Speed (RPM) | | 1460 | |
| Housing Dia (inches) | | 12" | |
| Bore Depth (ft.) | | 450 | |
| Head (ft.) | | 200 | |







| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | |
|--|---|--------------------------|------|---|---------|--|--|
| Municipal Committee Burewala | | | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | | | |
| Impeller Installation Depth (ft.) | 100 | | |  | | | |
| Paint of Pumping Unit | Good | Fair | Poor | | | | |
| Number of Valves | 1 | | | | | | |
| | 1 | | | | | | |
| Base Plate | Yes | No | | | | | |
| Electro-Mechanical Equipment Details | | | | | | | |
| Transformer Capacity (kVA) | 50 | | | | | | |
| Sanctioned Load (Kwh) | 41 | | | | | | |
| Motor Power (HP) | 40 | | | | | | |
| Motor Make | BECO | | | | | | |
| MCU | Yes | No | | | | | |
| Earthing of Motor | Yes | No | | | | | |
| Power Wiring | Yes | No | | | | | |
| Service Cable | Yes | No | | | | | |
| Earthing of MCU | Yes | No | | | | | |
| Energy Meter | Yes | No | | | | | |
| Water Meter | Yes | No | | | | | |
| PFI Equipment | Yes | No | | | | | |
| Generator | Yes | No | | | | | |
| Change Over | Yes | No | | | | | |
| Overall Rating | | | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 | | |
| Asset Condition | Excellent | Good | Fair | Poor | Failing | | |
| Category | A | B | C | D | E | | |
| Remarks / Requirements | | | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | | | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | | | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|-------------------|----------------|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | Pictures | | |
| Name | | Park I-Block | | |  |
| Location | Latitude | 30.164105 | | | |
| | Longitude | 72.690800 | | | |
| Address | | I Block, Burewala | | | |
| Area (Marla) | | 1 | | | |
| Working Status | | Functional | Non-Functional | | |
| Installation Year of Tube Well | | Not Available | | | |
| Installation Year of Pump | | Not Available | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | 5 | | | |
| Delivery Pipe | Dia | 8 | | | |
| | Material | MS | | | |
| Chlorinator | | Yes | No | | |
| Chlorination Schedule | | Once in a Year | After 6 Months | No Schedule | |
| Apron Around Pump House | | Yes | No | | |
| Hoisting Girder | | Yes | No | | |
| Civil Structure Condition | | Good | Fair | Bad | |
| Approach to Pump House | | Good | Fair | Bad | |
| Pump Details | | | | | |
| Pump Type | | Turbine | | | |
| Pump Make | | HMA | | | |
| Discharge Capacity (Cusec) | | 1 | | | |
| Rotational Speed (RPM) | | 2950 | | | |
| Housing Dia (inches) | | 12" | | | |
| Bore Depth (ft.) | | 450 | | | |
| Head (ft.) | | 2001 | | | |
| Impeller Installation Depth (ft.) | | 100 | | | |
| Paint of Pumping Unit | | Good | Fair | Poor | |
| Number of Valves | Gate Valve | 1 | | | |
| | Non-Returning Valve | 1 | | | |
| Base Plate | | Yes | No | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | | 50 | | | |
| Sanctioned Load (Kwh) | | 30 | | | |
| Motor Power (HP) | | 40 | | | |
| Motor Make | | Siemens | | | |
| MCU | | Yes | No | | |
| Earthing of Motor | | Yes | No | | |
| Power Wiring | | Yes | No | | |
| Service Cable | | Yes | No | | |
| Earthing of MCU | | Yes | No | | |
|  | | | | | |
|  | | | | | |
|  | | | | | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |



| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|----------------|--|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | Pictures | | |
| Name | AzeemAbad #1 | | | | |
| Location | Latitude | 30.167012 | | | |
| | Longitude | 72.692033 | | | |
| Address | AzeemAbad, Burewala | | | | |
| Area (Marla) | 1 | | | | |
| Working Status | Abandoned | | | | |
| Installation Year of Tube Well | | | | | |
| Installation Year of Pump | | | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | | | | |
| Delivery Pipe | Dia | | | | |
| | Material | | | | |
| Chlorinator | Yes | No | | | |
| Chlorination Schedule | Once in a Year | After 6 Months | No Schedule | | |
| | | |  | | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Apron Around Pump House | Yes | | | No | |
| Hoisting Girder | Yes | | | No | |
| Civil Structure Condition | Good | Fair | Bad | | |
| Approach to Pump House | Good | Fair | Bad | | |
| Pump Details | | | | | |
| Pump Type | | | | | |
| Pump Make | | | | | |
| Discharge Capacity (Cusec) | | | | | |
| Rotational Speed (RPM) | | | | | |
| Housing Dia (inches) | | | | | |
| Bore Depth (ft.) | | | | | |
| Head (ft.) | | | | | |
| Impeller Installation Depth (ft.) | | | | | |
| Paint of Pumping Unit | | | | | |
| Number of Valves | Gate Valve | | | | |
| | Non-Returning Valve | | | | |
| Base Plate | Yes | | | No | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | | | | | |
| Sanctioned Load (Kwh) | | | | | |
| Motor Power (HP) | | | | | |
| Motor Make | | | | | |
| MCU | Yes | | | No | |
| Earthing of Motor | Yes | | | No | |
| Power Wiring | Yes | | | No | |
| Service Cable | Yes | | | No | |
| Earthing of MCU | Yes | | | No | |
| Energy Meter | Yes | | | No | |
| Water Meter | Yes | | | No | |
| PFI Equipment | Yes | | | No | |
| Generator | Yes | | | No | |
| Change Over | Yes | | | No | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> • No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |


| Integrated Development and Asset Management Plan (IDAMP) | | |
|--|---|---|
| Municipal Committee Burewala | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |

| Integrated Development and Asset Management Plan (IDAMP) | | | | |
|--|---|----------------------|----------------|---------------------------------------|
| Municipal Committee Burewala | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 |
| Asset Detail | | | Pictures | |
| Name | | Azeem Abad #2 | | |
| Location | Latitude | 30.168406 | | |
| | Longitude | 72.692356 | | |
| Address | | Azeem Abad, Burewala | | |
| Area (Marla) | | 1 | | |
| Working Status | | Functional | Non-Functional | |
| Installation Year of Tube Well | | 2008 | | |
| Installation Year of Pump | | 2008 | | |
| Capital Cost of Machinery | | | | |
| Operational Hours | | 5 | | |
| Delivery Pipe | Dia | 6" | | |
| | Material | MS | | |
| Chlorinator | | Yes | No | |
| Chlorination Schedule | | Once in a Year | After 6 Months | No Schedule |
| Apron Around Pump House | | Yes | No | |
| Hoisting Girder | | Yes | No | |
| Civil Structure Condition | | Good | Fair | Bad |
| Approach to Pump House | | Good | Fair | Bad |
| Pump Details | | | | |
| Pump Type | | Turbine | | |
| Pump Make | | KSB | | |
| Discharge Capacity (Cusec) | | 1 | | |
| Rotational Speed (RPM) | | 1465 | | |
| Housing Dia (inches) | | 12" | | |
| Bore Depth (ft.) | | 450 | | |
| Head (ft.) | | 200 | | |
| Impeller Installation Depth (ft.) | | 100 | | |
| Paint of Pumping Unit | | Good | Fair | Poor |
| Number of Valves | Gate Valve | 1 | | |
| | Non-Returning Valve | 1 | | |
| Base Plate | | Yes | No | |
| Electro-Mechanical Equipment Details | | | | |
| Transformer Capacity (kVA) | | 50 | | |
| Sanctioned Load (Kwh) | | 30 | | |
| Motor Power (HP) | | 40 | | |
| Motor Make | | Siemens | | |
| MCU | | Yes | No | |
| Earthing of Motor | | Yes | No | |
| Power Wiring | | Yes | No | |
| Service Cable | | Yes | No | |
| Earthing of MCU | | Yes | No | |





| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |


| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|----------------|----------|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | Pictures | | |
| Name | Satellite Town #2 | | | | |
| Location | Latitude | 30.162951 | | | |
| | Longitude | 72.695828 | | | |
| Address | Satellite Town, Burewala | | | | |
| Area (Marla) | 1 | | | | |
| Working Status | Functional | Non-Functional | | | |
| Installation Year of Tube Well | 2017 | | | | |
| Installation Year of Pump | 2017 | | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | 5 | | | | |
| Delivery Pipe | Dia | 8" | | | |
| | Material | MS | | | |
| Chlorinator | Yes | No | | | |




| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | |
|--|---|----------------|-------------|---|---------|--|--|
| Municipal Committee Burewala | | | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | | | |
| Chlorination Schedule | Once in a Year | After 6 Months | No Schedule |  | | | |
| Apron Around Pump House | Yes | | No | | | | |
| Hoisting Girder | Yes | | No | | | | |
| Civil Structure Condition | Good | Fair | Bad | | | | |
| Approach to Pump House | Good | Fair | Bad |  | | | |
| Pump Details | | | | | | | |
| Pump Type | Turbine | | | | | | |
| Pump Make | HMA | | | | | | |
| Discharge Capacity (Cusec) | 1 | | | | | | |
| Rotational Speed (RPM) | 2950 | | | | | | |
| Housing Dia (inches) | 12" | | | | | | |
| Bore Depth (ft.) | 450 | | | | | | |
| Head (ft.) | 200 | | | | | | |
| Impeller Installation Depth (ft.) | 100 | | | | | | |
| Paint of Pumping Unit | Good | Fair | Poor |  | | | |
| Number of Valves | Gate Valve | 0 | | | | | |
| | Non-Returning Valve | 1 | | | | | |
| Base Plate | Yes | No | | | | | |
| Electro-Mechanical Equipment Details | | | | | | | |
| Transformer Capacity (kVA) | 50 | | | | | | |
| Sanctioned Load (Kwh) | 22 | | | | | | |
| Motor Power (HP) | 40 | | | | | | |
| Motor Make | Siemens | | | | | | |
| MCU | Yes | No | | | | | |
| Earthing of Motor | Yes | No | | | | | |
| Power Wiring | Yes | No | | | | | |
| Service Cable | Yes | No | | | | | |
| Earthing of MCU | Yes | No | | | | | |
| Energy Meter | Yes | No | | | | | |
| Water Meter | Yes | No | | | | | |
| PFI Equipment | Yes | No | | | | | |
| Generator | Yes | No | | | | | |
| Change Over | Yes | No | | | | | |
| Overall Rating | | | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 | | |
| Asset Condition | Excellent | Good | Fair | Poor | Failing | | |
| Category | A | B | C | D | E | | |
| Remarks / Requirements | | | | | | | |
| <ul style="list-style-type: none"> • No remarks | | | | | | | |

| Integrated Development and Asset Management Plan (IDAMP) | | |
|--|---|---|
| Municipal Committee Burewala | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 |
| Data Collected By: Mr. Abdullah | Designation: Team Member |  Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |


| Integrated Development and Asset Management Plan (IDAMP) | | | |
|--|---|---------------------------------------|-------------------------------|
| Municipal Committee Burewala | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | Pictures | |
| Name | | Satellite Town #1 | |
| Location | Latitude | 30.160899 | |
| | Longitude | 72.693570 | |
| Address | | Satellite Town Ground, Burewala | |
| Area (Marla) | | 1 | |
| Working Status | | Functional | Non-Functional |
| Installation Year of Tube Well | | 2020 | |
| Installation Year of Pump | | 2020 | |
| Capital Cost of Machinery | | | |
| Operational Hours | | 5 | |
| Delivery Pipe | Dia | 6" | |
| | Material | MS | |
| Chlorinator | | Yes | No |
| Chlorination Schedule | | Once in a Year | After 6 Months No Schedule |
| Apron Around Pump House | | Yes | No |
| Hoisting Girder | | Yes | No |
| Civil Structure Condition | | Good | Fair Bad |
| Approach to Pump House | | Good | Fair Bad |
| Pump Details | | | |
| Pump Type | | Turbine | |
| Pump Make | | KSB | |
| Discharge Capacity (Cusec) | | 1 | |
| Rotational Speed (RPM) | | 1470 | |
| Housing Dia (inches) | | 12" | |
| Bore Depth (ft.) | | 450 | |
| Head (ft.) | | 200 | |





Burewala, Punjab, Pakistan
5MBV+8JC Bilal Jolya Park, Burewala, Vehari, Punjab, Pakistan
Lat 30.160903°
Long 72.693558°
06/05/23 12:45 PM GMT +05:00




Burewala, Punjab, Pakistan
5MBV+8JC Bilal Jolya Park, Burewala, Vehari, Punjab, Pakistan
Lat 30.160899°
Long 72.69357°
06/05/23 12:45 PM GMT +05:00





Burewala, Punjab, Pakistan
5MBV+8JC Bilal Jolya Park, Burewala, Vehari, Punjab, Pakistan
Lat 30.160899°
Long 72.69357°
06/05/23 12:45 PM GMT +05:00


| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Impeller Installation Depth (ft.) | 100 | | | | |
| Paint of Pumping Unit | Good | Fair | Poor | | |
| Number of Valves | Gate Valve | 1 | | | |
| | Non-Returning Valve | 1 | | | |
| Base Plate | Yes | No | | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | 50 | | | | |
| Sanctioned Load (Kwh) | 19 | | | | |
| Motor Power (HP) | 40 | | | | |
| Motor Make | Siemens | | | | |
| MCU | Yes | No | | | |
| Earthing of Motor | Yes | No | | | |
| Power Wiring | Yes | No | | | |
| Service Cable | Yes | No | | | |
| Earthing of MCU | Yes | No | | | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|------------------------|----------------|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | | Pictures | |
| Name | | Dogar Market | | | |
| Location | Latitude | 30.160879 | | | |
| | Longitude | 72.701128 | | | |
| Address | | Dogar Market, Burewala | | | |
| Area (Marla) | | 1 | | | |
| Working Status | | Abandoned | | | |
| Installation Year of Tube Well | | | | | |
| Installation Year of Pump | | | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | | | | |
| Delivery | Dia | | | | |
| Pipe | Material | | | | |
| Chlorinator | | Yes | No | | |
| Chlorination Schedule | | Once in a Year | After 6 Months | No Schedule | |
| Apron Around Pump House | | Yes | No | | |
| Hoisting Girder | | Yes | No | | |
| Civil Structure Condition | | Good | Fair | Bad | |
| Approach to Pump House | | Good | Fair | Bad | |
| Pump Details | | | | | |
| Pump Type | | | | | |
| Pump Make | | | | | |
| Discharge Capacity (Cusec) | | | | | |
| Rotational Speed (RPM) | | | | | |
| Housing Dia (inches) | | | | | |
| Bore Depth (ft.) | | | | | |
| Head (ft.) | | | | | |
| Impeller Installation Depth (ft.) | | | | | |
| Paint of Pumping Unit | | | | | |
| Number of Valves | Gate Valve | | | | |
| | Non-Returning Valve | | | | |
| Base Plate | | Yes | No | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | | | | | |
| Sanctioned Load (Kwh) | | | | | |
| Motor Power (HP) | | | | | |
| Motor Make | | | | | |
| MCU | | Yes | No | | |
| Earthing of Motor | | Yes | No | | |
| Power Wiring | | Yes | No | | |
| Service Cable | | Yes | No | | |
| Earthing of MCU | | Yes | No | | |
| Energy Meter | | Yes | No | | |





| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No Pump-set No connection to distribution lines | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |




| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|---------------------------------|----------|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | Pictures | | |
| Name | | Shah Faisal Colony | | | |
| Location | Latitude | 30.160847 | | | |
| | Longitude | 72.701125 | | | |
| Address | | Shah Faisal Colony, Burewala | | | |
| Area (Marla) | | 1 | | | |
| Working Status | | Abandoned | | | |
| Installation Year of Tube Well | | | | | |
| Installation Year of Pump | | | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | | | | |
| Delivery Pipe | Dia | | | | |
| | Material | | | | |
| Chlorinator | | Yes | No | | |





| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|---|---|-----------------------|--------------------|---------------------------------------|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Chlorination Schedule | Once in a Year | After 6 Month s | No Schedu le | | |
| Apron Around Pump House | Yes | | No | | |
| Hoisting Girder | Yes | | No | | |
| Civil Structure Condition | Good | Fair | Bad | | |
| Approach to Pump House | Good | Fair | Bad | | |
| Pump Details | | | | | |
| Pump Type | | | | | |
| Pump Make | | | | | |
| Discharge Capacity (Cusec) | | | | | |
| Rotational Speed (RPM) | | | | | |
| Housing Dia (inches) | | | | | |
| Bore Depth (ft.) | | | | | |
| Head (ft.) | | | | | |
| Impeller Installation Depth (ft.) | | | | | |
| Paint of Pumping Unit | | | | | |
| Number of Valves | Gate Valve | | | | |
| | Non-Returning Valve | | | | |
| Base Plate | Yes | | No | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | | | | | |
| Sanctioned Load (Kwh) | | | | | |
| Motor Power (HP) | | | | | |
| Motor Make | | | | | |
| MCU | Yes | | No | | |
| Earthing of Motor | Yes | | No | | |
| Power Wiring | Yes | | No | | |
| Service Cable | Yes | | No | | |
| Earthing of MCU | Yes | | No | | |
| Energy Meter | Yes | | No | | |
| Water Meter | Yes | | No | | |
| PFI Equipment | Yes | | No | | |
| Generator | Yes | | No | | |
| Change Over | Yes | | No | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No connection to distribution line No Pump-set | | | | | |

| Integrated Development and Asset Management Plan (IDAMP) | | |
|--|---|---|
| Municipal Committee Burewala | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 |
| Data Collected By: Mr. Abdullah | Designation: Team Member |  Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |

| Integrated Development and Asset Management Plan (IDAMP) | | | |
|--|---|---------------------------------------|-------------------------------|
| Municipal Committee Burewala | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | Pictures | |
| Name | | Al abad Water Works | |
| Location | Latitude | 30.162363 | |
| | Longitude | 72.714863 | |
| Address | | Al abad, Burewala | |
| Area (Marla) | | 1 | |
| Working Status | | Functional | Non-Functional |
| Installation Year of Tube Well | | Not Available | |
| Installation Year of Pump | | Not Available | |
| Capital Cost of Machinery | | | |
| Operational Hours | | 5 | |
| Delivery Pipe | Dia | 8" | |
| | Material | MS | |
| Chlorinator | | Yes | No |
| Chlorination Schedule | | Once in a Year | After 6 Months No Schedule |
| Apron Around Pump House | | Yes | No |
| Hoisting Girder | | Yes | No |
| Civil Structure Condition | | Good | Fair Bad |
| Approach to Pump House | | Good | Fair Bad |
| Pump Details | | | |
| Pump Type | | Turbine | |
| Pump Make | | HMA | |
| Discharge Capacity (Cusec) | | 1 | |
| Rotational Speed (RPM) | | 2945 | |
| Housing Dia (inches) | | 12" | |
| Bore Depth (ft.) | | 450 | |
| Head (ft.) | | 200 | |


| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Impeller Installation Depth (ft.) | 100 | | | | |
| Paint of Pumping Unit | Good | Fair | Poor | | |
| Number of Valves | Gate Valve | | 1 | | |
| | Non-Returning Valve | | 1 | | |
| Base Plate | Yes | No | | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | 50 | | | | |
| Sanctioned Load (Kwh) | 19 | | | | |
| Motor Power (HP) | 30 | | | | |
| Motor Make | Siemens | | | | |
| MCU | Yes | No | | | |
| Earthing of Motor | Yes | No | | | |
| Power Wiring | Yes | No | | | |
| Service Cable | Yes | No | | | |
| Earthing of MCU | Yes | No | | | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|----------------|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | | Pictures | |
| Name | | Mujahid Colony Eid Gah | | | |
| Location | Latitude | 30.162299 | | | |
| | Longitude | 72.714832 | | | |
| Address | | Mujahid Colony, Burewala | | | |
| Area (Marla) | | 1 | | | |
| Working Status | | Abandoned | | | |
| Installation Year of Tube Well | | | | | |
| Installation Year of Pump | | | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | | | | |
| Delivery Pipe | Dia | | | | |
| | Material | | | | |
| Chlorinator | | Yes | No | | |
| Chlorination Schedule | | Once in a Year | After 6 Months | No Schedule | |
| Apron Around Pump House | | Yes | No | | |
| Hoisting Girder | | Yes | No | | |
| Civil Structure Condition | | Good | Fair | Bad | |
| Approach to Pump House | | Good | Fair | Bad | |
| Pump Details | | | | | |
| Pump Type | | | | | |
| Pump Make | | | | | |
| Discharge Capacity (Cusec) | | | | | |
| Rotational Speed (RPM) | | | | | |
| Housing Dia (inches) | | | | | |
| Bore Depth (ft.) | | | | | |
| Head (ft.) | | | | | |
| Impeller Installation Depth (ft.) | | | | | |
| Paint of Pumping Unit | | | | | |
| Number of Valves | Gate Valve | | | | |
| | Non-Returning Valve | | | | |
| Base Plate | | Yes | No | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | | | | | |
| Sanctioned Load (Kwh) | | | | | |
| Motor Power (HP) | | | | | |
| Motor Make | | | | | |
| MCU | | Yes | No | | |
| Earthing of Motor | | Yes | No | | |
| Power Wiring | | Yes | No | | |
| Service Cable | | Yes | No | | |
| Earthing of MCU | | Yes | No | | |
| Energy Meter | | Yes | No | | |




| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---------------------------------------|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | | Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | | Sign & Date: 30-May-2023 | |



| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|----------------|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | Pictures | | |
| Name | | Mujahid Colony #2 | | | |
| Location | Latitude | 30.160680 | | | |
| | Longitude | 72.703622 | | | |
| Address | | Mujahid Colony, Burewala | | | |
| Area (Marla) | | 1 | | | |
| Working Status | | Functional | Non-Functional | | |
| Installation Year of Tube Well | | 2020 | | | |
| Installation Year of Pump | | 2020 | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | 5 | | | |
| Delivery Pipe | Dia | 6" | | | |
| | Material | MS | | | |
| Chlorinator | | Yes | No | | |
| Chlorination Schedule | | Once in a Year | After 6 Months | No Schedule | |
| | | | | | |
| | | | | | |



| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Apron Around Pump House | Yes | | | No | |
| Hoisting Girder | Yes | | | No | |
| Civil Structure Condition | Good | Fair | Bad | | |
| Approach to Pump House | Good | Fair | Bad | | |
| Pump Details | | | | | |
| Pump Type | Turbine | | | | |
| Pump Make | KSB | | | | |
| Discharge Capacity (Cusec) | 1 | | | | |
| Rotational Speed (RPM) | 1470 | | | | |
| Housing Dia (inches) | 12" | | | | |
| Bore Depth (ft.) | 450 | | | | |
| Head (ft.) | 200 | | | | |
| Impeller Installation Depth (ft.) | 100 | | | | |
| Paint of Pumping Unit | Good | Fair | Poor | | |
| Number of Valves | Gate Valve | 1 | | | |
| | Non-Returning Valve | 1 | | | |
| Base Plate | Yes | | | No | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | 50 | | | | |
| Sanctioned Load (Kwh) | 30 | | | | |
| Motor Power (HP) | 40 | | | | |
| Motor Make | Siemens | | | | |
| MCU | Yes | | | No | |
| Earthing of Motor | Yes | | | No | |
| Power Wiring | Yes | | | No | |
| Service Cable | Yes | | | No | |
| Earthing of MCU | Yes | | | No | |
| Energy Meter | Yes | | | No | |
| Water Meter | Yes | | | No | |
| PFI Equipment | Yes | | | No | |
| Generator | Yes | | | No | |
| Change Over | Yes | | | No | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |





| Integrated Development and Asset Management Plan (IDAMP) | | |
|--|---|---|
| Municipal Committee Burewala | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |


| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|----------------|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | | Pictures | |
| Name | | Mujahid Colony #1 | | | |
| Location | Latitude | 30.159743 | | | |
| | Longitude | 72.700033 | | | |
| Address | | Mujahid Colony, Burewala | | | |
| Area (Marla) | | 12 | | | |
| Working Status | | Functional | Non-Functional | | |
| Installation Year of Tube Well | | 1989 | | | |
| Installation Year of Pump | | 1989 | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | 5 | | | |
| Delivery Pipe | Dia | 6" | | | |
| | Material | MS | | | |
| Chlorinator | | Yes | No | | |
| Chlorination Schedule | | Once in a Year | After 6 Months | No Schedule | |
| Apron Around Pump House | | Yes | No | | |
| Hoisting Girder | | Yes | No | | |
| Civil Structure Condition | | Good | Fair | Bad | |
| Approach to Pump House | | Good | Fair | Bad | |
| Pump Details | | | | | |
| Pump Type | | Turbine | | | |
| Pump Make | | PECO | | | |
| Discharge Capacity (Cusec) | | 1 | | | |
| Rotational Speed (RPM) | | 1470 | | | |
| Housing Dia (inches) | | 12" | | | |
| Bore Depth (ft.) | | 450 | | | |
| Head (ft.) | | 200 | | | |
| Impeller Installation Depth (ft.) | | 100 | | | |
| Paint of Pumping Unit | | Good | Fair | Poor | |
| Number of Valves | Gate Valve | 1 | | | |
| | Non-Returning Valve | 1 | | | |
| Base Plate | | Yes | No | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | | 50 | | | |
| Sanctioned Load (Kwh) | | 19 | | | |
| Motor Power (HP) | | 25 | | | |
| Motor Make | | PECO | | | |
| MCU | | Yes | No | | |
| Earthing of Motor | | Yes | No | | |
| Power Wiring | | Yes | No | | |
| Service Cable | | Yes | No | | |
| Earthing of MCU | | Yes | No | | |



| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |



| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|--|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | Pictures | | |
| Name | | Mujahid Colony Bairki | | | |
| Location | Latitude | 30.159784 | | | |
| | Longitude | 72.699835 | | | |
| Address | | Mujahid Colony, Burewala | | | |
| Area (Marla) | | 1 | | | |
| Working Status | | Abandoned | | | |
| Installation Year of Tube Well | | | | | |
| Installation Year of Pump | | | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | | | | |
| Delivery Pipe | Dia | | | | |
| | Material | | | | |
| Chlorinator | | Yes | No | | |
| Chlorination Schedule | | Once in a Year | After 6 Months | No Schedule | |
| | | |  | | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|---|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Apron Around Pump House | Yes | | | No | |
| Hoisting Girder | Yes | | | No | |
| Civil Structure Condition | Good | Fair | Bad | | |
| Approach to Pump House | Good | Fair | Bad | | |
| Pump Details | | | | | |
| Pump Type | | | | | |
| Pump Make | | | | | |
| Discharge Capacity (Cusec) | | | | | |
| Rotational Speed (RPM) | | | | | |
| Housing Dia (inches) | | | | | |
| Bore Depth (ft.) | | | | | |
| Head (ft.) | | | | | |
| Impeller Installation Depth (ft.) | | | | | |
| Paint of Pumping Unit | | | | | |
| Number of Valves | Gate Valve | | | | |
| | Non-Returning Valve | | | | |
| Base Plate | Yes | | | No | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | | | | | |
| Sanctioned Load (Kwh) | | | | | |
| Motor Power (HP) | | | | | |
| Motor Make | | | | | |
| MCU | Yes | | | No | |
| Earthing of Motor | Yes | | | No | |
| Power Wiring | Yes | | | No | |
| Service Cable | Yes | | | No | |
| Earthing of MCU | Yes | | | No | |
| Energy Meter | Yes | | | No | |
| Water Meter | Yes | | | No | |
| PFI Equipment | Yes | | | No | |
| Generator | Yes | | | No | |
| Change Over | Yes | | | No | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No Connection to Distribution network | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |


| Integrated Development and Asset Management Plan (IDAMP) | | |
|--|---|---|
| Municipal Committee Burewala | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|-----------------------|----------------|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | | Pictures | |
| Name | | Chak 445 EB | | | |
| Location | Latitude | 30.146768 | | | |
| | Longitude | 72.696061 | | | |
| Address | | Chak 445 EB, Burewala | | | |
| Area (Marla) | | 1 | | | |
| Working Status | | Functional | Non-Functional | | |
| Installation Year of Tube Well | | | | | |
| Installation Year of Pump | | | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | 5 | | | |
| Delivery Pipe | Dia | 6" | | | |
| | Material | MS | | | |
| Chlorinator | | Yes | No | | |
| Chlorination Schedule | | Once in a Year | After 6 Months | No Schedule | |
| Apron Around Pump House | | Yes | No | | |
| Hoisting Girder | | Yes | No | | |
| Civil Structure Condition | | Good | Fair | Bad | |
| Approach to Pump House | | Good | Fair | Bad | |
| Pump Details | | | | | |
| Pump Type | | Turbine | | | |
| Pump Make | | PECO | | | |
| Discharge Capacity (Cusec) | | 1.5 | | | |
| Rotational Speed (RPM) | | 1470 | | | |
| Housing Dia (inches) | | 12" | | | |
| Bore Depth (ft.) | | 450 | | | |
| Head (ft.) | | 200 | | | |
| Impeller Installation Depth (ft.) | | 100 | | | |
| Paint of Pumping Unit | | Good | Fair | Poor | |
| Number of Valves | Gate Valve | 1 | | | |
| | Non-Returning Valve | 1 | | | |
| Base Plate | | Yes | No | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | | 50 | | | |
| Sanctioned Load (Kwh) | | 30 | | | |
| Motor Power (HP) | | 40 | | | |
| Motor Make | | PECO | | | |
| MCU | | Yes | No | | |
| Earthing of Motor | | Yes | No | | |
| Power Wiring | | Yes | No | | |
| Service Cable | | Yes | No | | |
| Earthing of MCU | | Yes | No | | |





| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |


| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|----------------|----------|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | Pictures | | |
| Name | Chak 447 EB | | | | |
| Location | Latitude | 30.134305 | | | |
| | Longitude | 72.690148 | | | |
| Address | Chak 447 EB, Burewala | | | | |
| Area (Marla) | 1 | | | | |
| Working Status | Functional | Non-Functional | | | |
| Installation Year of Tube Well | 1991 | | | | |
| Installation Year of Pump | 1991 | | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | 5 | | | | |
| Delivery Pipe | Dia | 6" | | | |
| | Material | MS | | | |
| Chlorinator | Yes | No | | | |





| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|----------------|-------------|--|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Chlorination Schedule | Once in a Year | After 6 Months | No Schedule |  | |
| Apron Around Pump House | Yes | | No | | |
| Hoisting Girder | Yes | | No | | |
| Civil Structure Condition | Good | Fair | Bad | | |
| Approach to Pump House | Good | Fair | Bad | | |
| Pump Details | | | | | |
| Pump Type | Turbine | | |  | |
| Pump Make | Flow Pak | | | | |
| Discharge Capacity (Cusec) | 1 | | | | |
| Rotational Speed (RPM) | 1470 | | | | |
| Housing Dia (inches) | 12" | | | | |
| Bore Depth (ft.) | 450 | | | | |
| Head (ft.) | 200 | | | | |
| Impeller Installation Depth (ft.) | 100 | | | | |
| Paint of Pumping Unit | Good | Fair | Poor | | |
| Number of Valves | Gate Valve | 1 | | | |
| | Non-Returning Valve | 1 | | | |
| Base Plate | Yes | No | | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | 50 | | |  | |
| Sanctioned Load (Kwh) | 30 | | | | |
| Motor Power (HP) | 30 | | | | |
| Motor Make | Siemens | | | | |
| MCU | Yes | No | | | |
| Earthing of Motor | Yes | No | | | |
| Power Wiring | Yes | No | | | |
| Service Cable | Yes | No | | | |
| Earthing of MCU | Yes | No | | | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> • No remarks | | | | | |



| Integrated Development and Asset Management Plan (IDAMP) | | |
|--|---|---|
| Municipal Committee Burewala | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 |
| Data Collected By: Mr. Abdullah | Designation: Team Member |  Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |

| Integrated Development and Asset Management Plan (IDAMP) | | | |
|--|---|---------------------------------------|-------------------------------|
| Municipal Committee Burewala | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | Pictures | |
| Name | | P Block #02 | |
| Location | Latitude | 30.160341 | |
| | Longitude | 72.689622 | |
| Address | | P Block Burewala | |
| Area (Marla) | | 1 | |
| Working Status | | Functional | Non-Functional |
| Installation Year of Tube Well | | Not Available | |
| Installation Year of Pump | | Not Available | |
| Capital Cost of Machinery | | | |
| Operational Hours | | 5 | |
| Delivery Pipe | Dia | 8" | |
| | Material | MS | |
| Chlorinator | | Yes | No |
| Chlorination Schedule | | Once in a Year | After 6 Months No Schedule |
| Apron Around Pump House | | Yes | No |
| Hoisting Girder | | Yes | No |
| Civil Structure Condition | | Good | Fair Bad |
| Approach to Pump House | | Good | Fair Bad |
| Pump Details | | | |
| Pump Type | | Turbine | |
| Pump Make | | HMA | |
| Discharge Capacity (Cusec) | | 1 | |
| Rotational Speed (RPM) | | 2950 | |
| Housing Dia (inches) | | 12" | |
| Bore Depth (ft.) | | 450 | |
| Head (ft.) | | 200 | |











| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Impeller Installation Depth (ft.) | 100 | | | | |
| Paint of Pumping Unit | Good | Fair | Poor | | |
| Number of Valves | Gate Valve | 0 | | | |
| | Non-Returning Valve | 1 | | | |
| Base Plate | Yes | No | | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | 50 | | | | |
| Sanctioned Load (Kwh) | 30 | | | | |
| Motor Power (HP) | 40 | | | | |
| Motor Make | Siemens | | | | |
| MCU | Yes | No | | | |
| Earthing of Motor | Yes | No | | | |
| Power Wiring | Yes | No | | | |
| Service Cable | Yes | No | | | |
| Earthing of MCU | Yes | No | | | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |



| Integrated Development and Asset Management Plan (IDAMP) | | | | |
|--|---|-------------------|----------------|---------------------------------------|
| Municipal Committee Burewala | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 |
| Asset Detail | | | Pictures | |
| Name | | P Block Tanki #01 | | |
| Location | Latitude | 30.158572 | | |
| | Longitude | 72.689748 | | |
| Address | | P Block, Burewala | | |
| Area (Marla) | | 1 | | |
| Working Status | | Functional | Non-Functional | |
| Installation Year of Tube Well | | 1991 | | |
| Installation Year of Pump | | 1991 | | |
| Capital Cost of Machinery | | | | |
| Operational Hours | | 5 | | |
| Delivery Pipe | Dia | 8" | | |
| | Material | MS | | |
| Chlorinator | | Yes | No | |
| Chlorination Schedule | | Once in a Year | After 6 Months | No Schedule |
| Apron Around Pump House | | Yes | No | |
| Hoisting Girder | | Yes | No | |
| Civil Structure Condition | | Good | Fair | Bad |
| Approach to Pump House | | Good | Fair | Bad |
| Pump Details | | | | |
| Pump Type | | Turbine | | |
| Pump Make | | PECO | | |
| Discharge Capacity (Cusec) | | 1.5 | | |
| Rotational Speed (RPM) | | 1460 | | |
| Housing Dia (inches) | | 12" | | |
| Bore Depth (ft.) | | 450 | | |
| Head (ft.) | | 200 | | |
| Impeller Installation Depth (ft.) | | 100 | | |
| Paint of Pumping Unit | | Good | Fair | Poor |
| Number of Valves | Gate Valve | 1 | | |
| | Non-Returning Valve | 1 | | |
| Base Plate | | Yes | No | |
| Electro-Mechanical Equipment Details | | | | |
| Transformer Capacity (kVA) | | 50 | | |
| Sanctioned Load (Kwh) | | 30 | | |
| Motor Power (HP) | | 50 | | |
| Motor Make | | Siemens | | |
| MCU | | Yes | No | |
| Earthing of Motor | | Yes | No | |
| Power Wiring | | Yes | No | |
| Service Cable | | Yes | No | |
| Earthing of MCU | | Yes | No | |





| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|-------------------|----------------|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Asset Detail | | | Pictures | | |
| Name | | N Block | | | |
| Location | Latitude | 30.158444 | | | |
| | Longitude | 72.686797 | | | |
| Address | | N Block, Burewala | | | |
| Area (Marla) | | 1 | | | |
| Working Status | | Functional | Non-Functional | | |
| Installation Year of Tube Well | | 2009 | | | |
| Installation Year of Pump | | 2009 | | | |
| Capital Cost of Machinery | | | | | |
| Operational Hours | | 5 | | | |
| Delivery Pipe | Dia | 6" | | | |
| | Material | MS | | | |
| Chlorinator | | Yes | No | | |




| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---|----------------|-------------|--|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Chlorination Schedule | Once in a Year | After 6 Months | No Schedule |  | |
| Apron Around Pump House | Yes | | No | | |
| Hoisting Girder | Yes | | No | | |
| Civil Structure Condition | Good | Fair | Bad | | |
| Approach to Pump House | Good | Fair | Bad |  | |
| Pump Details | | | | | |
| Pump Type | Turbine | | | | |
| Pump Make | KSB | | | | |
| Discharge Capacity (Cusec) | 1 | | | | |
| Rotational Speed (RPM) | 1460 | | | | |
| Housing Dia (inches) | 12" | | | | |
| Bore Depth (ft.) | 450 | | | | |
| Head (ft.) | 200 | | | | |
| Impeller Installation Depth (ft.) | 100 | | | | |
| Paint of Pumping Unit | Good | Fair | Poor | | |
| Number of Valves | Gate Valve | 1 | | | |
| | Non-Returning Valve | 1 | | | |
| Base Plate | Yes | No | | | |
| Electro-Mechanical Equipment Details | | | | | |
| Transformer Capacity (kVA) | 50 | | | | |
| Sanctioned Load (Kwh) | 30 | | | | |
| Motor Power (HP) | 30 | | | | |
| Motor Make | Siemens | | | | |
| MCU | Yes | No | | | |
| Earthing of Motor | Yes | No | | | |
| Power Wiring | Yes | No | | | |
| Service Cable | Yes | No | | | |
| Earthing of MCU | Yes | No | | | |
| Energy Meter | Yes | No | | | |
| Water Meter | Yes | No | | | |
| PFI Equipment | Yes | No | | | |
| Generator | Yes | No | | | |
| Change Over | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> • No remarks | | | | | |





| Integrated Development and Asset Management Plan (IDAMP) | | |
|--|---|---|
| Municipal Committee Burewala | | |
| Form: IDAMP-A1 | Tube Well Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 |
| Data Collected By: Mr. Abdullah | Designation: Team Member |  Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |



B. Filtration Plant




| Sr # | Name | Age (Years) | Type | Filtration Capacity (Liters/hour) | Condition | Status | Book Value (PKR Mil) |
|------|------------------------|---------------|------|-----------------------------------|-----------|----------------|----------------------|
| 1 | Aziz Abad | 10 | RO | 1000 | Fair | Functional | 0.6 |
| 2 | Yousuf Block | Not Available | UV | 2000 | Poor | Functional | Not Available |
| 3 | Iqbal Nagar Marzipura | Not Available | UV | 2000 | Failing | Non-Functional | Not Available |
| 4 | Muhammad Nagar | 21 | UV | 2000 | Fair | Functional | 0.3 |
| 5 | Housing Colony | Not Available | UV | 2000 | Poor | Non-Functional | Not Available |
| 6 | Habib Colony | Not Available | UV | 2000 | Good | Functional | Not Available |
| 7 | Habib Colony School | 6 | UV | 2000 | Fair | Functional | 0.9 |
| 8 | H Block | Not Available | UV | 2000 | Poor | Functional | Not Available |
| 9 | E Block | Not Available | UV | 2000 | Failing | Non-Functional | Not Available |
| 10 | Ghawshala | Not Available | UV | 2000 | Failing | Non-Functional | Not Available |
| 11 | Chak 437 EB | Not Available | UV | 2000 | Fair | Functional | Not Available |
| 12 | Chak 435 EB | Not Available | UV | 2000 | Poor | Functional | Not Available |
| 13 | Khatija tul Qubra Park | Not Available | UV | 2000 | Failing | Non-Functional | Not Available |
| 14 | Yaqoob Abad | Not Available | UV | 2000 | Good | Functional | Not Available |
| 15 | Azimabad | Not Available | UV | 2000 | Fair | Functional | Not Available |
| 16 | Satellite Town Ground | Not Available | UV | 2000 | Fair | Functional | Not Available |
| 17 | Mujahid Colony # 1 | Not Available | UV | 2000 | Fair | Functional | Not Available |
| 18 | 445-EB | Not Available | UV | 2000 | Fair | Functional | Not Available |
| 19 | 447-EB | Not Available | UV | 2000 | Poor | Functional | Not Available |
| 20 | P Block Tanki | Not Available | UV | 2000 | Fair | Functional | Not Available |

| Integrated Development And Asset Management Plan (IDAMP) | | | | | |
|--|-----------|--|---------------------|---|---|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A4 | | Water Filtration Plant Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 |
| Name | | Azizabad | | | Pictures |
| Location | Latitude | 30.163845 | | |  |
| | Longitude | 72.671668 | | | |
| Address | | Azizabad, Burewala | | | |
| Installation Year | | 2013 | | | |
| Installing Agency | | Welfare Community | | | |
| O&M Agency | | MC | | | |
| Filtration (Liter/Hour) | Capacity | 1000 | | | |
| Operational Hours | | 5 | | | |
| No. of Taps | | 11 | | | |
| Effluent Test (If Available) | | Not Available | | | |
| Latest water quality analysis carried out? | | - | | | |
| If yes, which lab and parameters? | | - | | | |
| Findings of water quality analysis? | | - | | | |
| In case of any parameter above the permissible limit, which steps are taken to provide safe water? | | - | | | |
| Plant Type | | RO | UV | |  |
| Source of Water | | Local Tube Well | Public Water Supply | | |
| Working Status | | Functional | Non-Functional | | |
| Pumping Unit | | Yes | No | | |
| Control Panel | | Yes | No | | |
| Service Cable | | Yes | No | | |
| Ultraviolet Lamp/Chlorinator | | Yes | No | | |
| Takeaway Hall Condition | | Good | Fair | Poor | |
| Building Structure Condition | | Good | Fair | Poor | |
| Approach to Pump House | | Good | Fair | Poor | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |

| | | |
|------------------------------|------------------------|---|
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |
|------------------------------|------------------------|---|




| Integrated Development And Asset Management Plan (IDAMP) | | | | | |
|--|--|---------------------|-----------------------|---------------------------------------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A4 | Water Filtration Plant Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Name | | | Yusuf Block | | Pictures |
| Location | Latitude | 30.156987 | | |  <small>Burewala, Punjab, Pakistan 5M46+VM7, Burewala, Vehari, Punjab, Pakistan Lat 30.156987° Long 72.661912° 05/05/23 12:04 PM GMT +05:00</small> |
| | Longitude | 72.661912 | | | |
| Address | | | Yusuf Block, Burewala | | |
| Installation Year | | | Not Available | | |
| Installing Agency | | | MC | |  <small>Burewala, Punjab, Pakistan 5M46+MQ8, Marzi Pura Burewala, Vehari, Punjab, Pakistan Lat 30.156829° Long 72.66204° 05/05/23 12:04 PM GMT +05:00</small> |
| O&M Agency | | | MC | | |
| Filtration Capacity (Liter/Hour) | | | 2000 | | |
| Operational Hours | | | 5 | | |
| No. of Taps | | | 11 | |  <small>Burewala, Punjab, Pakistan 5M46+MQ8, Marzi Pura Burewala, Vehari, Punjab, Pakistan Lat 30.156795° Long 72.661995° 05/05/23 12:05 PM GMT +05:00</small> |
| Effluent Test (If Available) | | | Not Available | | |
| Latest water quality analysis carried out? | | | - | | |
| If yes, which lab and parameters? | | | - | | |
| Findings of water quality analysis? | | | - | |  <small>Burewala, Punjab, Pakistan 5M46+MQ8, Marzi Pura Burewala, Vehari, Punjab, Pakistan Lat 30.156808° Long 72.661909° 05/05/23 12:05 PM GMT +05:00</small> |
| In case of any parameter above the permissible limit, which steps are taken to provide safe water? | | | - | | |
| Plant Type | RO | UV | | | |
| Source of Water | Local Tube Well | Public Water Supply | | | |
| Working Status | Functional | Non-Functional | | | |
| Pumping Unit | Yes | No | | | |
| Control Panel | Yes | No | | | |
| Service Cable | Yes | No | | | |
| Ultraviolet Lamp/Chlorinator | Yes | No | | | |
| Takeaway Hall Condition | Good | Fair | Poor | | |
| Building Structure Condition | Good | Fair | Poor | | |
| Approach to Pump House | Good | Fair | Poor | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |



| | | |
|---------------------------------|--------------------------|---|
| • • • | | |
| Data Collected By: Mr. Abdullah | Designation: Team Member |  Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |



| Integrated Development And Asset Management Plan (IDAMP) | | | | |
|--|--|---------------------|------|---|
| Municipal Committee Burewala | | | | |
| Form: IDAMP-A4 | Water Filtration Plant Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 |
| Name | Iqbal Nagar Marzipura | | |    |
| Location | Latitude | 30.152340 | | |
| | Longitude | 72.657472 | | |
| Address | Iqbal Nagar Marzipura, Burewala | | | |
| Installation Year | Not Available | | | |
| Installing Agency | MC | | | |
| O&M Agency | MC | | | |
| Filtration Capacity (Liter/Hour) | 2000 | | | |
| Operational Hours | 5 | | | |
| No. of Taps | 8 | | | |
| Effluent Test (If Available) | Not Available | | | |
| Latest water quality analysis carried out? | - | | | |
| If yes, which lab and parameters? | - | | | |
| Findings of water quality analysis? | - | | | |
| In case of any parameter above the permissible limit, which steps are taken to provide safe water? | - | | | |
| Plant Type | RO | UV | | |
| Source of Water | Local Tube Well | Public Water Supply | | |
| Working Status | Abandoned | | | |
| Pumping Unit | Yes | No | | |
| Control Panel | Yes | No | | |
| Service Cable | Yes | No | | |
| Ultraviolet Lamp/Chlorinator | Yes | No | | |
| Takeaway Hall Condition | Good | Fair | Poor | |
| Building Structure Condition | Good | Fair | Poor | |


| | | | | | |
|--|-----------|--------------------------|------|--------------------------|---------|
| Approach to Pump House | Good | Fair | Poor | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | | Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | | Sign & Date: 30-May-2023 | |


| Integrated Development And Asset Management Plan (IDAMP) | | | | | |
|--|--|--------------------------|---------------------|-------------------|------------------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A4 | Water Filtration Plant Asset Condition Assessment | | | Asset Code: _____ | Date: 05-05-2023 |
| Name | | Muhammad Nagar | | Pictures | |
| Location | Latitude | 30.1526860 | | | |
| | Longitude | 72.664356 | | | |
| Address | | Muhammad Nagar, Burewala | | | |
| Installation Year | | 2002 | | | |
| Installing Agency | | MC | | | |
| O&M Agency | | MC | | | |
| Filtration (Liter/Hour) | Capacity | 2000 | | | |
| Operational Hours | | 5 | | | |
| No. of Taps | | 10 | | | |
| Effluent Test (If Available) | | Not Available | | | |
| Latest water quality analysis carried out? | | - | | | |
| If yes, which lab and parameters? | | - | | | |
| Findings of water quality analysis? | | - | | | |
| In case of any parameter above the permissible limit, which steps are taken to provide safe water? | | - | | | |
| Plant Type | | RO | UV | | |
| Source of Water | | Local Tube Well | Public Water Supply | | |
| Working Status | | Functional | Non-Functional | | |
| Pumping Unit | | Yes | No | | |



| | | | | | | |
|--|-----------|--------------------------|--|---|---------|------|
| Control Panel | Yes | No |  | | | |
| Service Cable | Yes | No | | | | |
| Ultraviolet Lamp/Chlorinator | Yes | No | | | | |
| Takeaway Hall Condition | Good | Fair | | | | Poor |
| Building Structure Condition | Good | Fair | | | | Poor |
| Approach to Pump House | Good | Fair | | | | Poor |
| Overall Rating | | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 | |
| Asset Condition | Excellent | Good | Fair | Poor | Failing | |
| Category | A | B | C | D | E | |
| Remarks / Requirements | | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | | |

| Integrated Development And Asset Management Plan (IDAMP) | | | | | |
|--|-----------|---|--|---|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A4 | | Water Filtration Plant Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 | |
| Name | | Housing Colony | | <div style="display: flex; flex-direction: column; align-items: center;"> <div style="margin-bottom: 10px;">  </div> <div>  </div> </div> | |
| Location | Latitude | 30.158892 | | | |
| | Longitude | 72.670704 | | | |
| Address | | Housing Colony, Burewala | | | |
| Installation Year | | Not Available | | | |
| Installing Agency | | MC | | | |
| O&M Agency | | MC | | | |
| Filtration (Liter/Hour) | Capacity | 2000 | | | |
| Operational Hours | | 5 | | | |
| No. of Taps | | 9 | | | |
| Effluent Test (If Available) | | Not Available | | | |
| Latest water quality analysis carried out? | | - | | | |
| If yes, which lab and parameters? | | - | | | |
| Findings of water quality analysis? | | - | | | |
| In case of any parameter above the permissible limit, | | - | | | |

| | | | | | |
|--|--------------------------|---------------------|---|------|---------|
| which steps are taken to provide safe water? | | | | | |
| Plant Type | RO | UV | | | |
| Source of Water | Local Tube Well | Public Water Supply | | | |
| Working Status | Functional | Non-Functional | | | |
| Pumping Unit | Yes | No | | | |
| Control Panel | Yes | No | | | |
| Service Cable | Yes | No | | | |
| Ultraviolet Lamp/Chlorinator | Yes | No | | | |
| Takeaway Hall Condition | Good | Fair | Poor | | |
| Building Structure Condition | Good | Fair | Poor | | |
| Approach to Pump House | Good | Fair | Poor | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| No remarks | | | | | |
| Data Collected By: Mr. Abdullah | Designation: Team Member | |  Sign & Date: 30-May-2023 | | |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead | |  Sign & Date: 30-May-2023 | | |






| Integrated Development And Asset Management Plan (IDAMP) | | | | |
|--|--|-----------|--|--|
| Municipal Committee Burewala | | | | |
| Form: IDAMP-A4 | Water Filtration Plant Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 | |
| Name | Habib Colony | | Pictures | |
| Location | Latitude | 30.151703 |  | |
| | Longitude | 72.676309 | | |
| Address | Habib Colony, Burewala | | | |
| Installation Year | Not Available | | | |
| Installing Agency | MC | | | |
| O&M Agency | MC | | | |
| Filtration Capacity (Liter/Hour) | 2000 | | | |
| Operational Hours | 5 | | | |
| No. of Taps | 4 | | | |






| | | | | | |
|--|-----------------|--------------------------|------|---|---------|
| Effluent Test (If Available) | Not Available | | | | |
| Latest water quality analysis carried out? | - | | | | |
| If yes, which lab and parameters? | - | | | | |
| Findings of water quality analysis? | - | | | | |
| In case of any parameter above the permissible limit, which steps are taken to provide safe water? | - | | | | |
| Plant Type | RO | UV | | | |
| Source of Water | Local Tube Well | Public Water Supply | | | |
| Working Status | Functional | Non-Functional | | | |
| Pumping Unit | Yes | No | | | |
| Control Panel | Yes | No | | | |
| Service Cable | Yes | No | | | |
| Ultraviolet Lamp/Chlorinator | Yes | No | | | |
| Takeaway Hall Condition | Good | Fair | Poor | | |
| Building Structure Condition | Good | Fair | Poor | | |
| Approach to Pump House | Good | Fair | Poor | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |






| | | | | | |
|---|-----------|--|--|---------------------------------------|--|
| Integrated Development And Asset Management Plan (IDAMP) | | | | | |
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A4 | | Water Filtration Plant Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 | |
| Name | | Habib Colony School | | Pictures | |
| Location | Latitude | 30.153584 | | | |
| | Longitude | 72.679245 | | | |



| | | | | |
|--|-----------------|----------------------------------|------|---|
| Address | | Habib Colony School, Burewala | | |
| Installation Year | | 2017 | | |
| Installing Agency | | MC | | |
| O&M Agency | | MC | | |
| Filtration Capacity (Liter/Hour) | 2000 | | | |
| Operational Hours | | 5 | | |
| No. of Taps | | 6 | | |
| Effluent Test (If Available) | | Not Available | | |
| Latest water quality analysis carried out? | | - | | |
| If yes, which lab and parameters? | | - | | |
| Findings of water quality analysis? | | - | | |
| In case of any parameter above the permissible limit, which steps are taken to provide safe water? | | - | | |
| Plant Type | RO | UV | | |
| Source of Water | Local Tube Well | Public Water Supply | | |
| Working Status | Functional | Non-Functional | | |
| Pumping Unit | Yes | No | | |
| Control Panel | Yes | No | | |
| Service Cable | Yes | No | | |
| Ultraviolet Lamp/Chlorinator | Yes | No | | |
| Takeaway Hall Condition | Good | Fair | Poor | |
| Building Structure Condition | Good | Fair | Poor | |
| Approach to Pump House | Good | Fair | Poor | |
| Overall Rating | | | | |
| Average Score | 1 | 2 | 3 | 4 |
| Asset Condition | Excellent | Good | Fair | Poor |
| Category | A | B | C | D |
| Remarks / Requirements | | | | |
| • No remarks | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 |




| Municipal Committee Burewala | | | | | |
|--|-----------|--|---------------------|---|---------------------------------------|
| Form: IDAMP-A4 | | Water Filtration Plant Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 |
| Name | | H-Block | | Pictures | |
| Location | Latitude | 30.159535 | |  | |
| | Longitude | 72.684071 | | | |
| Address | | H-Block, Burewala | | | |
| Installation Year | | Not Available | | | |
| Installing Agency | | MC | | | |
| O&M Agency | | MC | | | |
| Filtration (Liter/Hour) | Capacity | 2000 | | | |
| Operational Hours | | 5 | | | |
| No. of Taps | | 7 | | | |
| Effluent Test (If Available) | | Not Available | | | |
| Latest water quality analysis carried out? | | - | |  | |
| If yes, which lab and parameters? | | - | | | |
| Findings of water quality analysis? | | - | | | |
| In case of any parameter above the permissible limit, which steps are taken to provide safe water? | | - | |  | |
| Plant Type | | RO | UV | | |
| Source of Water | | Local Tube Well | Public Water Supply | | |
| Working Status | | Functional | Non-Functional | | |
| Pumping Unit | | Yes | No |  | |
| Control Panel | | Yes | No | | |
| Service Cable | | Yes | No | | |
| Ultraviolet Lamp/Chlorinator | | Yes | No | | |
| Takeaway Hall Condition | | Good | Fair | Poor | |
| Building Structure Condition | | Good | Fair | Poor | |
| Approach to Pump House | | Good | Fair | Poor | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |

| | | |
|------------------------------|------------------------|---|
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |
|------------------------------|------------------------|---|


| Integrated Development And Asset Management Plan (IDAMP) | | | | | | | |
|--|--|-------------------|---------------------|--|---------|------|---|
| Municipal Committee Burewala | | | | | | | |
| Form: IDAMP-A4 | Water Filtration Plant Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | | | |
| Name | | E-Block | | Pictures | | | |
| Location | Latitude | 30.160668 | |  | | | |
| | Longitude | 72.683780 | | | | | |
| Address | | E-Block, Burewala | | | | | |
| Installation Year | | Not Available | | | | | |
| Installing Agency | | MC | | | | | |
| O&M Agency | | MC | | | | | |
| Filtration | Capacity | | | | | | |
| Operational Hours | | | | | | | |
| No. of Taps | | | | | | | |
| Effluent Test (If Available) | | | | | | | |
| Latest water quality analysis carried out? | | | | | | | |
| If yes, which lab and parameters? | | | | | | | |
| Findings of water quality analysis? | | | | | | | |
| In case of any parameter above the permissible limit, which steps are taken to provide safe water? | | | | | | | |
| Plant Type | | RO | UV |  | | | |
| Source of Water | | Local Tube Well | Public Water Supply | | | | |
| Working Status | | Abandoned | | | | | |
| Pumping Unit | | Yes | No | | | | |
| Control Panel | | Yes | No | | | | |
| Service Cable | | Yes | No | | | | |
| Ultraviolet Lamp/Chlorinator | | Yes | No | | | | |
| Takeaway Hall Condition | | Good | Fair | | | Poor | |
| Building Structure Condition | | Good | Fair | | | Poor | |
| Approach to Pump House | | Good | Fair | | | Poor | |
| Overall Rating | | | | | | | |
| Average Score | 1 | 2 | 3 | | | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing | | |
| Category | A | B | C | D | E | | |
| Remarks / Requirements | | | | | | | |

| Integrated Development And Asset Management Plan (IDAMP) | | |
|--|--|---|
| Municipal Committee Burewala | | |
| Form: IDAMP-A4 | Water Filtration Plant Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 |
| <ul style="list-style-type: none"> No remarks | | |
| Data Collected By: Mr. Abdullah | Designation: Team Member |  Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |



| Integrated Development And Asset Management Plan (IDAMP) | | | |
|--|--|---------------------------------------|--|
| Municipal Committee Burewala | | | |
| Form: IDAMP-A4 | Water Filtration Plant Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 | |
| Name | | Goshala | |
| Location | Latitude | 30.164057 | |
| | Longitude | 72.674154 | |
| Address | | Bar Association, Burewala | |
| Installation Year | | Not Available | |
| Installing Agency | | MC | |
| O&M Agency | | MC | |
| Filtration Capacity (Liter/Hour) | | | |
| Operational Hours | | | |
| No. of Taps | | | |
| Effluent Test (If Available) | | | |
| Latest water quality analysis carried out? | | | |
| If yes, which lab and parameters? | | | |
| Findings of water quality analysis? | | | |
| In case of any parameter above the permissible limit, which steps are taken to provide safe water? | | | |
| Plant Type | RO | UV | |
| Source of Water | Local Tube Well | Public Water Supply | |
| Working Status | Abandoned | | |
| Pumping Unit | Yes | No | |
| Control Panel | Yes | No | |
| Service Cable | Yes | No | |








Burewala, Punjab, Pakistan
 5M7F+QP2, Kachehry Rd, Gao Shalla Burewala, Vehari, Punjab, Pakistan
 Lat 30.164062°
 Long 72.674147°
 06/05/23 10:35 AM GMT +05:00






Burewala, Punjab, Pakistan
 5M7F+QP2, Kachehry Rd, Gao Shalla Burewala, Vehari, Punjab, Pakistan
 Lat 30.164057°
 Long 72.674154°
 06/05/23 10:38 AM GMT +05:00


| | | | | | |
|--|-----------|--------------------------|------|---|---------|
| Ultraviolet Lamp/Chlorinator | Yes | | No | | |
| Takeaway Hall Condition | Good | Fair | Poor | | |
| Building Structure Condition | Good | Fair | Poor | | |
| Approach to Pump House | Good | Fair | Poor | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |



| Integrated Development And Asset Management Plan (IDAMP) | | | | |
|--|-----------|---|--|--|
| Municipal Committee Burewala | | | | |
| Form: IDAMP-A4 | | Water Filtration Plant Asset Condition Assessment | | Asset Code: _____ |
| | | | | Date: 05-05-2023 |
| Name | | Chak 437 EB | | Pictures |
| Location | Latitude | 30.166340 | |   |
| | Longitude | 72.676419 | | |
| Address | | Chak 437 EB, Burewala | | |
| Installation Year | | Not Available | | |
| Installing Agency | | MC | | |
| O&M Agency | | MC | | |
| Filtration (Liter/Hour) | Capacity | 2000 | | |
| Operational Hours | | 5 | | |
| No. of Taps | | 11 | | |
| Effluent Test (If Available) | | Not Available | | |
| Latest water quality analysis carried out? | | - | | |
| If yes, which lab and parameters? | | - | | |
| Findings of water quality analysis? | | - | | |
| In case of any parameter above the permissible limit, which steps are taken to provide safe water? | | - | | |

| | | | | | | |
|--|-----------------|--------------------------|--|---|---------|------|
| Plant Type | RO | UV |  | | | |
| Source of Water | Local Tube Well | Public Water Supply | | | | |
| Working Status | Functional | Non-Functional | | | | |
| Pumping Unit | Yes | No | | | | |
| Control Panel | Yes | No | | | | |
| Service Cable | Yes | No | | | | |
| Ultraviolet Lamp/Chlorinator | Yes | No | | | | |
| Takeaway Hall Condition | Good | Fair | | | | Poor |
| Building Structure Condition | Good | Fair | | | | Poor |
| Approach to Pump House | Good | Fair | | | | Poor |
| Overall Rating | | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 | |
| Asset Condition | Excellent | Good | Fair | Poor | Failing | |
| Category | A | B | C | D | E | |
| Remarks / Requirements | | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | | |





| Integrated Development And Asset Management Plan (IDAMP) | | | | |
|--|-----------|--|--|--|
| Municipal Committee Burewala | | | | |
| Form: IDAMP-A4 | | Water Filtration Plant Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 |
| Name | | Chak 435 EB | | Pictures |
| Location | Latitude | 30.178511 | |  |
| | Longitude | 72.690403 | | |
| Address | | Chak 435 EB, Burewala | | |
| Installation Year | | Not Available | | |
| Installing Agency | | MC | | |
| O&M Agency | | MC | | |
| Filtration Capacity (Liter/Hour) | 2000 | | | |
| Operational Hours | | 5 | | |
| No. of Taps | | 6 | | |
| Effluent Test (If Available) | | Not Available | | |
| Latest water quality analysis carried out? | | - | | |



| | | | | | |
|--|--------------------------|---------------------|---|------|---------|
| If yes, which lab and parameters? | - | | | | |
| Findings of water quality analysis? | - | | | | |
| In case of any parameter above the permissible limit, which steps are taken to provide safe water? | - | | | | |
| Plant Type | RO | UV | | | |
| Source of Water | Local Tube Well | Public Water Supply | | | |
| Working Status | Functional | Non-Functional | | | |
| Pumping Unit | Yes | No | | | |
| Control Panel | Yes | No | | | |
| Service Cable | Yes | No | | | |
| Ultraviolet Lamp/Chlorinator | Yes | No | | | |
| Takeaway Hall Condition | Good | Fair | Poor | | |
| Building Structure Condition | Good | Fair | Poor | | |
| Approach to Pump House | Good | Fair | Poor | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | Designation: Team Member | |  Sign & Date: 30-May-2023 | | |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead | |  Sign & Date: 30-May-2023 | | |








| Integrated Development And Asset Management Plan (IDAMP) | | | | | |
|--|-----------|--|---------------------|------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A4 | | Water Filtration Plant Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 |
| Name | | Khadija tul Kubra Park | | | Pictures |
| Location | Latitude | 30.174833 | | |  |
| | Longitude | 72.689977 | | | |
| Address | | Khadija tul Kubra Park, Burewala | | | |
| Installation Year | | Not Available | | | |
| Installing Agency | | MC | | | |
| O&M Agency | | MC | | | |
| Filtration (Liter/Hour) | Capacity | | | | |
| Operational Hours | | | | | |
| No. of Taps | | | | | |
| Effluent Test (If Available) | | | | | |
| Latest water quality analysis carried out? | | | | | |
| If yes, which lab and parameters? | | | | | |
| Findings of water quality analysis? | | | | | |
| In case of any parameter above the permissible limit, which steps are taken to provide safe water? | | | | | |
| Plant Type | | RO | UV | |  |
| Source of Water | | Local Tube Well | Public Water Supply | | |
| Working Status | | Abandoned | | | |
| Pumping Unit | | Yes | No | | |
| Control Panel | | Yes | No | | |
| Service Cable | | Yes | No | | |
| Ultraviolet Lamp/Chlorinator | | Yes | No | | |
| Takeaway Hall Condition | | Good | Fair | Poor | |
| Building Structure Condition | | Good | Fair | Poor | |
| Approach to Pump House | | Good | Fair | Poor | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |



| | | |
|---------------------------------|--------------------------|------------------------------|
| Data Collected By: Mr. Abdullah | Designation: Team Member | Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead | Sign & Date: 30-May-2023 |



| Integrated Development And Asset Management Plan (IDAMP) | | | | |
|---|--|---------------------|------|--|
| Municipal Committee Burewala | | | | |
| Form: IDAMP-A4 | Water Filtration Plant Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 |
| Name | Yaqubabad | | | Pictures |
| Location | Latitude | 30.171301 | |  |
| | Longitude | 72.688385 | | |
| Address | Yaqubabad, Burewala | | | |
| Installation Year | Not Available | | | |
| Installing Agency | MC | | | |
| O&M Agency | MC | | | |
| Filtration Capacity (Liter/Hour) | 2000 | | | |
| Operational Hours | 5 | | | |
| No. of Taps | 10 | | | |
| Effluent Test (If Available) | Not Available | | | |
| Latest water quality analysis carried out? | - | | |  |
| If yes, which lab and parameters? | - | | | |
| Findings of water quality analysis? | - | | | |
| In case of any parameter above the permissible limit, which steps are taken to provide safe water? | - | | |  |
| Plant Type | RO | UV | | |
| Source of Water | Local Tube Well | Public Water Supply | | |
| Working Status | Functional | Non-Functional | | |
| Pumping Unit | Yes | No | | |
| Control Panel | Yes | No | | |
| Service Cable | Yes | No | | |
| Ultraviolet Lamp/Chlorinator | Yes | No | | |
| Takeaway Hall Condition | Good | Fair | Poor | |
| Building Structure Condition | Good | Fair | Poor | |
| Approach to Pump House | Good | Fair | Poor |  |


| Overall Rating | | | | | |
|---------------------------------|-----------|--------------------------|------|---|---------|
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| • No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |


| Integrated Development And Asset Management Plan (IDAMP) | | | | | |
|--|-----------|--|---------------------|--|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A4 | | Water Filtration Plant Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 | |
| Name | | Azimabad | | Pictures | |
| Location | Latitude | 30.167237 | |  | |
| | Longitude | 72.692079 | | | |
| Address | | Azimabad, Burewala | | | |
| Installation Year | | Not Available | | | |
| Installing Agency | | MC | | | |
| O&M Agency | | MC | | | |
| Filtration (Liter/Hour) | Capacity | 2000 | | | |
| Operational Hours | | 5 | | | |
| No. of Taps | | 7 | | | |
| Effluent Test (If Available) | | Not Available | | | |
| Latest water quality analysis carried out? | | - | | | |
| If yes, which lab and parameters? | | - | | | |
| Findings of water quality analysis? | | - | | | |
| In case of any parameter above the permissible limit, which steps are taken to provide safe water? | | - | | | |
| Plant Type | | RO | UV |  | |
| Source of Water | | Local Tube Well | Public Water Supply | | |
| Working Status | | Functional | Non-Functional | | |
| Pumping Unit | | Yes | No | | |
|  | | | | | |






| | | | | | |
|---------------------------------|--------------------------|------|------|---|---------|
| Control Panel | Yes | No | | | |
| Service Cable | Yes | No | | | |
| Ultraviolet Lamp/Chlorinator | Yes | No | | | |
| Takeaway Hall Condition | Good | Fair | Poor | | |
| Building Structure Condition | Good | Fair | Poor | | |
| Approach to Pump House | Good | Fair | Poor | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| • No remarks | | | | | |
| Data Collected By: Mr. Abdullah | Designation: Team Member | | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead | | |  Sign & Date: 30-May-2023 | |

| Integrated Development And Asset Management Plan (IDAMP) | | | | | |
|--|--|-----------|--|--|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A4 | Water Filtration Plant Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Name | Satellite Town Ground | | | Pictures | |
| Location | Latitude | 30.160561 | | |  |
| | Longitude | 72.694312 | | | |
| Address | Satellite Town Ground, Burewala | | | | |
| Installation Year | Not Available | | | | |
| Installing Agency | MC | | | | |
| O&M Agency | MC | | | | |
| Filtration Capacity (Liter/Hour) | 2000 | | | | |
| Operational Hours | 5 | | | | |
| No. of Taps | 6 | | | | |
| Effluent Test (If Available) | Not Available | | | | |
| Latest water quality analysis carried out? | - | | |  | |
| If yes, which lab and parameters? | - | | | | |
| Findings of water quality analysis? | - | | | | |
| In case of any parameter above the permissible limit, | - | | | | |





| | | | | |
|--|--------------------------|---------------------|------|---|
| which steps are taken to provide safe water? | | | | |
| Plant Type | RO | UV | | |
| Source of Water | Local Tube Well | Public Water Supply | | |
| Working Status | Functional | Non-Functional | | |
| Pumping Unit | Yes | No | | |
| Control Panel | Yes | No | | |
| Service Cable | Yes | No | | |
| Ultraviolet Lamp/Chlorinator | Yes | No | | |
| Takeaway Hall Condition | Good | Fair | Poor | |
| Building Structure Condition | Good | Fair | Poor | |
| Approach to Pump House | Good | Fair | Poor | |
| Overall Rating | | | | |
| Average Score | 1 | 2 | 3 | 4 |
| Asset Condition | Excellent | Good | Fair | Poor |
| Category | A | B | C | D |
| Remarks / Requirements | | | | |
| <ul style="list-style-type: none"> No remarks | | | | |
| Data Collected By: Mr. Abdullah | Designation: Team Member | | |  Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead | | |  Sign & Date: 30-May-2023 |










| Integrated Development And Asset Management Plan (IDAMP) | | | |
|--|--|-----------|--|
| Municipal Committee Burewala | | | |
| Form: IDAMP-A4 | Water Filtration Plant Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 |
| Name | Mujahid Colony #01 | | Pictures  |
| Location | Latitude | 30.159763 | |
| | Longitude | 72.699886 | |
| Address | Mujahid Colony, Burewala | | |
| Installation Year | Not Available | | |
| Installing Agency | MC | | |
| O&M Agency | MC | | |
| Filtration Capacity (Liter/Hour) | 2000 | | |
| Operational Hours | 5 | | |
| No. of Taps | 7 | | |
| Effluent Test (If Available) | Not Available | | |





| | | | | | |
|--|-----------------|--------------------------|------|---|---------|
| Latest water quality analysis carried out? | - | | |  | |
| If yes, which lab and parameters? | - | | |  | |
| Findings of water quality analysis? | - | | |  | |
| In case of any parameter above the permissible limit, which steps are taken to provide safe water? | - | | | | |
| Plant Type | RO | UV | | | |
| Source of Water | Local Tube Well | Public Water Supply | | | |
| Working Status | Functional | Non-Functional | | | |
| Pumping Unit | Yes | No | | | |
| Control Panel | Yes | No | | | |
| Service Cable | Yes | No | | | |
| Ultraviolet Lamp/Chlorinator | Yes | No | | | |
| Takeaway Hall Condition | Good | Fair | Poor | | |
| Building Structure Condition | Good | Fair | Poor | | |
| Approach to Pump House | Good | Fair | Poor | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| • No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |



| | | | | | |
|---|-----------|---|--|---------------------------------------|--|
| Integrated Development And Asset Management Plan (IDAMP) | | | | | |
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A4 | | Water Filtration Plant Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 | |
| Name | | Chak 445 EB | | Pictures | |
| Location | Latitude | 30.146826 | | | |
| | Longitude | 72.696255 | | | |

| | | | | | | | |
|--|--------------------------|---------------------|------|---|--|---|---------|
| Address | Chak 445 EB Burewala | | |  | | | |
| Installation Year | Not Available | | | | | | |
| Installing Agency | MC | | | | | | |
| O&M Agency | MC | | | | | | |
| Filtration Capacity (Liter/Hour) | 2000 | | | | | | |
| Operational Hours | 5 | | | | | | |
| No. of Taps | 7 | | | | | | |
| Effluent Test (If Available) | Not Available | | | | | | |
| Latest water quality analysis carried out? | - | | | | | | |
| If yes, which lab and parameters? | - | | | | | | |
| Findings of water quality analysis? | - | | | | | | |
| In case of any parameter above the permissible limit, which steps are taken to provide safe water? | - | | | | | | |
| Plant Type | RO | UV | | | | | |
| Source of Water | Local Tube Well | Public Water Supply | | | | | |
| Working Status | Functional | Non-Functional | | | | | |
| Pumping Unit | Yes | No | | | | | |
| Control Panel | Yes | No | | | | | |
| Service Cable | Yes | No | | | | | |
| Ultraviolet Lamp/Chlorinator | Yes | No | | | | | |
| Takeaway Hall Condition | Good | Fair | Poor |  | | | |
| Building Structure Condition | Good | Fair | Poor | | | | |
| Approach to Pump House | Good | Fair | Poor | | | | |
| Overall Rating | | | | | | | |
| Average Score | 1 | 2 | 3 | | | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | | | Poor | Failing |
| Category | A | B | C | | | D | E |
| Remarks / Requirements | | | | | | | |
| • No remarks | | | | | | | |
| Data Collected By: Mr. Abdullah | Designation: Team Member | | | | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead | | | | |  Sign & Date: 30-May-2023 | |

| Municipal Committee Burewala | | | | | |
|--|-----------------|--|------|---|---------------------------------------|
| Form: IDAMP-A4 | | Water Filtration Plant Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 |
| Name | | Chak 447 EB | | Pictures | |
| Location | Latitude | 30.134181 | |  | |
| | Longitude | 72.690238 | | | |
| Address | | Chak 447 EB, Burewala | | | |
| Installation Year | | Not Available | | | |
| Installing Agency | | MC | | | |
| O&M Agency | | MC | | | |
| Filtration (Liter/Hour) | Capacity | 2000 | | | |
| Operational Hours | | 5 | | | |
| No. of Taps | | 2 | | | |
| Effluent Test (If Available) | | Not Available | | | |
| Latest water quality analysis carried out? | | - | |  | |
| If yes, which lab and parameters? | | - | | | |
| Findings of water quality analysis? | | - | | | |
| In case of any parameter above the permissible limit, which steps are taken to provide safe water? | | - | |  | |
| Plant Type | RO | UV | | | |
| Source of Water | Local Tube Well | Public Water Supply | | | |
| Working Status | Functional | Non-Functional | | | |
| Pumping Unit | Yes | No | |  | |
| Control Panel | Yes | No | | | |
| Service Cable | Yes | No | | | |
| Ultraviolet Lamp/Chlorinator | Yes | No | | | |
| Takeaway Hall Condition | Good | Fair | Poor |  | |
| Building Structure Condition | Good | Fair | Poor | | |
| Approach to Pump House | Good | Fair | Poor | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  | |

| | | |
|------------------------------|------------------------|---|
| | | Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |



| Integrated Development And Asset Management Plan (IDAMP) | | | | |
|--|---|-------------------------|------|---|
| Municipal Committee Burewala | | | | |
| Form: IDAMP-A4 | Water Filtration Plant Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 |
| Name | | P Block Tanki | | Pictures |
| Location | Latitude | 30.158724 | | |
| | Longitude | 72.689812 | | |
| Address | | P Block Tanki, Burewala | |     |
| Installation Year | | Not Available | | |
| Installing Agency | | MC | | |
| O&M Agency | | MC | | |
| Filtration (Liter/Hour) | Capacity | 2000 | | |
| Operational Hours | | 5 | | |
| No. of Taps | | 10 | | |
| Effluent Test (If Available) | | Not Available | | |
| Latest water quality analysis carried out? | | - | | |
| If yes, which lab and parameters? | | - | | |
| Findings of water quality analysis? | | - | | |
| In case of any parameter above the permissible limit, which steps are taken to provide safe water? | | - | | |
| Plant Type | RO | UV | | |
| Source of Water | Local Tube Well | Public Water Supply | | |
| Working Status | Functional | Non-Functional | | |
| Pumping Unit | Yes | No | | |
| Control Panel | Yes | No | | |
| Service Cable | Yes | No | | |
| Ultraviolet Lamp/Chlorinator | Yes | No | | |
| Takeaway Hall Condition | Good | Fair | Poor | |
| Building Structure Condition | Good | Fair | Poor | |
| Approach to Pump House | Good | Fair | Poor | |
| Overall Rating | | | | |
| Average Score | 1 | 2 | 3 | 4 |
| | | | | 5 |

| Asset Condition | Excellent | Good | Fair | Poor | Failing |
|---------------------------------|-----------|--------------------------|------|---|---------|
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| • | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |

C. OHR



| Sr # | Name | Capacity (Gallons) | Condition | Status | Book Value (PKR Mil) |
|------|------------------------|--------------------|-----------|-----------|----------------------|
| 1 | Azeem Abad | 20,000 | Failing | Abandoned | 0 |
| 2 | Chak No. 447/EB | 20,000 | Failing | Abandoned | 0 |
| 3 | Y-Block Housing Scheme | 20,000 | Failing | Abandoned | 0 |
| 4 | Marzi Pura School | 20,000 | Failing | Abandoned | 0 |
| 5 | Aziz Abad | 20,000 | Failing | Abandoned | 0 |
| 6 | Yaqoob Abad | 20,000 | Failing | Abandoned | 0 |
| 7 | Chak No. 435/EB | 20,000 | Failing | Abandoned | 0 |
| 8 | P-Block | 50,000 | Failing | Abandoned | 0 |
| 9 | Chak No. 445/EB | 20,000 | Failing | Abandoned | 0 |
| 10 | M-Block | 20,000 | Failing | Abandoned | 0 |
| 11 | MC Colony | 30,000 | Poor | Working | 0.1 |
| 12 | Habib Colony | 50,000 | Failing | Abandoned | 0 |
| 13 | Mujahid Colony | 20,000 | Failing | Abandoned | 0 |

| Integrated Development And Asset Management Plan (IDAMP) | | | | | |
|--|---|------------------------------|----------------|---------------------------------------|------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A2 | Over Head Reservoir Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Name | | MC Colony/Water Works Colony | | Pictures | |
| Location | Latitude | 30.160743 | | | |
| | Longitude | 72.673453 | | | |
| Address | | Water Works Colony, Burewala | | | |
| Year of Construction | | Before Partition | | | |
| Capacity (UK Gallons) | | 50,000 | | | |
| Cleaning Frequency (Per Year) | | 0 | | | |
| Type of Structure | | Masonry | | | |
| Structure Condition | | Good | Fair | | Poor |
| Tank Conditions | | Good | Fair | | Poor |
| Number of Valves | Sluice Valve | 1 | | | |
| | Non-Returning Valve | 1 | | | |
| Working Status | | Functiona l | Non-Functional | | |
| Rising Main | Dia | 8 | | | |
| | Material | MS | | | |
| Delivery Main | Dia | 8 | | | |


| | | | | | |
|--|---------------|--------------------------|------|---|---------|
| | Material | MS | | | |
| Overflow & Scour Pipe | Dia | 8 | | | |
| | Material | MS | | | |
| Sluice Valve | Rising Main | Yes | No | | |
| | Delivery Main | Yes | No | | |
| | Scour Pipe | Yes | No | | |
| | Overflow Pipe | Yes | No | | |
| Stair Case | | Yes | No | | |
| Apron Around OHR | | Yes | No | | |
| Tank Top Railing | | Yes | No | | |
| Top Indication Light | | Yes | No | | |
| Lightening Arrester | | Yes | No | | |
| Boundary Wall & Gate | | Yes | No | | |
| Overflow Arrangements | Disposal | Yes | No | | |
| Approach to OHR | | Good | Fair | Bad | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |






| Integrated Development And Asset Management Plan (IDAMP) | | | | |
|--|-----------|---|--|---------------------------------------|
| Municipal Committee Burewala | | | | |
| Form: IDAMP-A2 | | Over Head Reservoir Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 |
| Name | | Azizabad | | Pictures |
| Location | Latitude | 30.163816 | | |
| | Longitude | 72.671406 | | |
| Address | | Azizabad, Burewala | | |
| Year of Construction | | | | |
| Capacity (UK Gallons) | | | | |


| | | | | | |
|--|---------------------|--------------------------|------|---|---------|
| Cleaning Frequency (Per Year) | | | | | |
| Type of Structure | | Frame (RCC) | | | |
| Structure Condition | | Good | Fair | Poor | |
| Tank Conditions | | Good | Fair | Poor | |
| Number of Valves | Sluice Valve | | | | |
| | Non-Returning Valve | | | | |
| Working Status | | Abandoned | | | |
| Rising Main | Dia | | | | |
| | Material | | | | |
| Delivery Main | Dia | | | | |
| | Material | | | | |
| Overflow & Scour Pipe | Dia | | | | |
| | Material | | | | |
| Sluice Valve | Rising Main | Yes | No | | |
| | Delivery Main | Yes | No | | |
| | Scour Pipe | Yes | No | | |
| | Overflow Pipe | Yes | No | | |
| Stair Case | | Yes | No | | |
| Apron Around OHR | | Yes | No | | |
| Tank Top Railing | | Yes | No | | |
| Top Indication Light | | Yes | No | | |
| Lightening Arrester | | Yes | No | | |
| Boundary Wall & Gate | | Yes | No | | |
| Overflow Arrangements | Disposal | Yes | No | | |
| Approach to OHR | | Good | Fair | Bad | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |






| Integrated Development And Asset Management Plan (IDAMP) | | | | | |
|--|---------------------|---|------|------|---|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A2 | | Over Head Reservoir Asset Condition Assessment | | | Asset Code: _____ |
| | | | | | Date: 05-05-2023 |
| Name | | Housing Colony | | | Pictures |
| Location | Latitude | 30.159042 | | |  |
| | Longitude | 72.670330 | | | |
| Address | | Housing Colony, Burewala | | | |
| Year of Construction | | 1977 | | | |
| Capacity (UK Gallons) | | | | | |
| Cleaning Frequency (Per Year) | | | | | |
| Type of Structure | | Masonry | | | |
| Structure Condition | | Good | Fair | Poor | |
| Tank Conditions | | Good | Fair | Poor | |
| Number of Valves | Sluice Valve | | | | |
| | Non-Returning Valve | | | | |
| Working Status | | Abandoned | | | |
| Rising Main | Dia | | | | |
| | Material | | | | |
| Delivery Main | Dia | | | | |
| | Material | | | | |
| Overflow & Scour Pipe | Dia | | | | |
| | Material | | | | |
| Sluice Valve | Rising Main | Yes | No | | |
| | Delivery Main | Yes | No | | |
| | Scour Pipe | Yes | No | | |
| | Overflow Pipe | Yes | No | | |
| Stair Case | | Yes | No | | |
| Apron Around OHR | | Yes | No | | |
| Tank Top Railing | | Yes | No | | |
| Top Indication Light | | Yes | No | | |
| Lightening Arrester | | Yes | No | | |
| Boundary Wall & Gate | | Yes | No | | |
| Overflow Disposal Arrangements | | Yes | No | | |
| Approach to OHR | | Good | Fair | Bad | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |

| | | |
|---------------------------------|--------------------------|---|
| Data Collected By: Mr. Abdullah | Designation: Team Member |  Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |



| Integrated Development And Asset Management Plan (IDAMP) | | | | | |
|--|---------------------|---|------|--|------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A2 | | Over Head Reservoir Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 | |
| Name | | M Block, Burewala | | <div style="text-align: center;">Pictures</div>  | |
| Location | Latitude | 30.160466 | | | |
| | Longitude | 72.684584 | | | |
| Address | | M Block, Burewala | | | |
| Year of Construction | | | | | |
| Capacity (UK Gallons) | | | | | |
| Cleaning Frequency (Per Year) | | | | | |
| Type of Structure | | Masonry | | | |
| Structure Condition | | Good | Fair | | Poor |
| Tank Conditions | | Good | Fair | | Poor |
| Number of Valves | Sluice Valve | | | | |
| | Non-Returning Valve | | | | |
| Working Status | | Abandoned | | | |
| Rising Main | Dia | | | | |
| | Material | | | | |
| Delivery Main | Dia | | | | |
| | Material | | | | |
| Overflow & Scour Pipe | Dia | | | | |
| | Material | | | | |
| Sluice Valve | Rising Main | Yes | No | | |
| | Delivery Main | Yes | No | | |
| | Scour Pipe | Yes | No | | |
| | Overflow Pipe | Yes | No | | |
| Stair Case | | Yes | No | | |
| Apron Around OHR | | Yes | No | | |
| Tank Top Railing | | Yes | No | | |
| Top Indication Light | | Yes | No | | |
| Lightening Arrester | | Yes | No | | |
| Boundary Wall & Gate | | Yes | No | | |
| Overflow Disposal Arrangements | | Yes | No | | |
| Approach to OHR | | Good | Fair | Bad | |
| Overall Rating | | | | | |

| | | | | | |
|---------------------------------|-----------|--------------------------|------|---|---------|
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| • No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |

| Integrated Development And Asset Management Plan (IDAMP) | | | | | |
|--|---------------------|--|------|------|--|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A2 | | Over Head Reservoir Asset Condition Assessment | | | Asset Code: _____ |
| | | | | | Date: 05-05-2023 |
| Name | | Chak 435 EB | | | Pictures |
| Location | Latitude | 30.178457 | | |  |
| | Longitude | 72.690329 | | | |
| Address | | Chak 435 EB, Burewala | | | |
| Year of Construction | | | | | |
| Capacity (UK Gallons) | | | | | |
| Cleaning Frequency (Per Year) | | | | | |
| Type of Structure | | Frame (RCC) | | | |
| Structure Condition | | Good | Fair | Poor | |
| Tank Conditions | | Good | Fair | Poor | |
| Number of Valves | Sluice Valve | | | | |
| | Non-Returning Valve | | | | |
| Working Status | | Abandoned | | | |
| Rising Main | Dia | | | | |
| | Material | | | | |
| Delivery Main | Dia | | | | |
| | Material | | | | |
| Overflow & Scour Pipe | Dia | | | | |
| | Material | | | | |
| Sluice Valve | Rising Main | Yes | No | | |
| | Delivery Main | Yes | No | | |
| | Scour Pipe | Yes | No | | |
| | Overflow Pipe | Yes | No | | |
| Stair Case | | Yes | No | | |
| Apron Around OHR | | Yes | No | | |

| | | | | | |
|--|--------------------------|------|------|---|---------|
| Tank Top Railing | Yes | No | | | |
| Top Indication Light | Yes | No | | | |
| Lightening Arrester | Yes | No | | | |
| Boundary Wall & Gate | Yes | No | | | |
| Overflow Disposal Arrangements | Yes | No | | | |
| Approach to OHR | Good | Fair | Bad | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | Designation: Team Member | | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead | | |  Sign & Date: 30-May-2023 | |

| Integrated Development And Asset Management Plan (IDAMP) | | | | | | |
|--|---------------------|---|------|------|---------------------------------------|--|
| Municipal Committee Burewala | | | | | | |
| Form: IDAMP-A2 | | Over Head Reservoir Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Name | | Yaqoobabad | | | Pictures | |
| Location | Latitude | 30.171359 | | | | |
| | Longitude | 72.688410 | | | | |
| Address | | Yaqoobabad, Burewala | | | | |
| Year of Construction | | | | | | |
| Capacity (UK Gallons) | | | | | | |
| Cleaning Frequency (Per Year) | | | | | | |
| Type of Structure | | Frame (RCC) | | | | |
| Structure Condition | | Good | Fair | Poor | | |
| Tank Conditions | | Good | Fair | Poor | | |
| Number of Valves | Sluice Valve | | | | | |
| | Non-Returning Valve | | | | | |
| Working Status | | Abandoned | | | | |
| Rising Main | Dia | | | | | |
| | Material | | | | | |
| Delivery Main | Dia | | | | | |
| | Material | | | | | |

| | | | | | |
|--|---------------|--------------------------|------|---|---------|
| Overflow & Scour Pipe | Dia | | | | |
| | Material | | | | |
| Sluice Valve | Rising Main | Yes | No | | |
| | Delivery Main | Yes | No | | |
| | Scour Pipe | Yes | No | | |
| | Overflow Pipe | Yes | No | | |
| Stair Case | | Yes | No | | |
| Apron Around OHR | | Yes | No | | |
| Tank Top Railing | | Yes | No | | |
| Top Indication Light | | Yes | No | | |
| Lightening Arrester | | Yes | No | | |
| Boundary Wall & Gate | | Yes | No | | |
| Overflow Arrangements | Disposal | Yes | No | | |
| Approach to OHR | | Good | Fair | Bad | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |





| Integrated Development And Asset Management Plan (IDAMP) | | | |
|--|---|-----------|---------------------------------------|
| Municipal Committee Burewala | | | |
| Form: IDAMP-A2 | Over Head Reservoir Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 |
| Name | Azimabad | | Pictures |
| Location | Latitude | 30.167008 | |
| | Longitude | 72.692003 | |
| Address | Azimabad, Burewala | | |
| Year of Construction | | | |

| | | | | |
|--------------------------------|---------------------|------------------|------|------|
| Capacity (UK Gallons) | | 20,000 | | |
| Cleaning Frequency (Per Year) | | | | |
| Type of Structure | | Masonry | | |
| Structure Condition | | Good | Fair | Poor |
| Tank Conditions | | Good | Fair | Poor |
| Number of Valves | Sluice Valve | | | |
| | Non-Returning Valve | | | |
| Working Status | | Abandoned | | |
| Rising Main | Dia | | | |
| | Material | | | |
| Delivery Main | Dia | | | |
| | Material | | | |
| Overflow & Scour Pipe | Dia | | | |
| | Material | | | |
| Sluice Valve | Rising Main | Yes | No | |
| | Delivery Main | Yes | No | |
| | Scour Pipe | Yes | No | |
| | Overflow Pipe | Yes | No | |
| Stair Case | | Yes | No | |
| Apron Around OHR | | Yes | No | |
| Tank Top Railing | | Yes | No | |
| Top Indication Light | | Yes | No | |
| Lightening Arrester | | Yes | No | |
| Boundary Wall & Gate | | Yes | No | |
| Overflow Disposal Arrangements | | Yes | No | |
| Approach to OHR | | Good | Fair | Bad |






| Overall Rating | | | | | |
|-----------------|-----------|------|------|------|---------|
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |


| Remarks / Requirements | | |
|--|--------------------------|---|
| <ul style="list-style-type: none"> No remarks | | |
| Data Collected By: Mr. Abdullah | Designation: Team Member |  Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |



Integrated Development And Asset Management Plan (IDAMP)


Municipal Committee Burewala



| Form: IDAMP-A2 | Over Head Reservoir Asset Condition Assessment | | | Asset Code: _____ | Date: 05-05-2023 | |
|--|---|--------------------------|------|---|------------------|------|
| Name | | Chak 445 EB | | Pictures | | |
| Location | Latitude | 30.146782 | |  | | |
| | Longitude | 72.696090 | | | | |
| Address | | Chak 445 EB, Burewala | | | | |
| Year of Construction | | | | | | |
| Capacity (UK Gallons) | | | | | | |
| Cleaning Frequency (Per Year) | | | | | | |
| Type of Structure | | Frame (RCC) | | | | |
| Structure Condition | | Good | Fair | | | Poor |
| Tank Conditions | | Good | Fair | | | Poor |
| Number of Valves | Sluice Valve | | | | | |
| | Non-Returning Valve | | | | | |
| Working Status | | Abandoned | | | | |
| Rising Main | Dia | | | | | |
| | Material | | | | | |
| Delivery Main | Dia | | | | | |
| | Material | | | | | |
| Overflow & Scour Pipe | Dia | | | | | |
| | Material | | | | | |
| Sluice Valve | Rising Main | Yes | No | | | |
| | Delivery Main | Yes | No | | | |
| | Scour Pipe | Yes | No | | | |
| | Overflow Pipe | Yes | No | | | |
| Stair Case | | Yes | No | | | |
| Apron Around OHR | | Yes | No | | | |
| Tank Top Railing | | Yes | No | | | |
| Top Indication Light | | Yes | No | | | |
| Lightening Arrester | | Yes | No | | | |
| Boundary Wall & Gate | | Yes | No | | | |
| Overflow Disposal Arrangements | | Yes | No | | | |
| Approach to OHR | | Good | Fair | Bad | | |
| Overall Rating | | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 | |
| Asset Condition | Excellent | Good | Fair | Poor | Failing | |
| Category | A | B | C | D | E | |
| Remarks / Requirements | | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | | |

| | | |
|-------------------------------------|-------------------------------|--|
| <i>Data Checked By: Mr. M. Fiaz</i> | <i>Designation: Team Lead</i> |  <i>Sign & Date: 30-May-2023</i> |
|-------------------------------------|-------------------------------|--|

| Integrated Development And Asset Management Plan (IDAMP) | | | | | |
|--|---------------------|---|------|------|---|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A2 | | Over Head Reservoir Asset Condition Assessment | | | Asset Code: _____ |
| | | | | | Date: 05-05-2023 |
| Name | | Chak 447 EB | | | Pictures |
| Location | Latitude | 30.134305 | | |  |
| | Longitude | 72.690264 | | | |
| Address | | Chak 447 EB, Burewala | | | |
| Year of Construction | | | | | |
| Capacity (UK Gallons) | | | | | |
| Cleaning Frequency (Per Year) | | | | | |
| Type of Structure | | Frame (RCC) | | | |
| Structure Condition | | Good | Fair | Poor | |
| Tank Conditions | | Good | Fair | Poor | |
| Number of Valves | Sluice Valve | | | | |
| | Non-Returning Valve | | | | |
| Working Status | | Abandoned | | | |
| Rising Main | Dia | | | | |
| | Material | | | | |
| Delivery Main | Dia | | | | |
| | Material | | | | |
| Overflow & Scour Pipe | Dia | | | | |
| | Material | | | | |
| Sluice Valve | Rising Main | Yes | No | | |
| | Delivery Main | Yes | No | | |
| | Scour Pipe | Yes | No | | |
| | Overflow Pipe | Yes | No | | |
| Stair Case | | Yes | No | | |
| Apron Around OHR | | Yes | No | | |
| Tank Top Railing | | Yes | No | | |
| Top Indication Light | | Yes | No | | |
| Lightening Arrester | | Yes | No | | |
| Boundary Wall & Gate | | Yes | No | | |
| Overflow Disposal Arrangements | | Yes | No | | |
| Approach to OHR | | Good | Fair | Bad | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> • No remarks | | | | | |

| | | |
|---------------------------------|--------------------------|---|
| Data Collected By: Mr. Abdullah | Designation: Team Member |  Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |



| Integrated Development And Asset Management Plan (IDAMP) | | | | | |
|--|---|-------------------|------|--|------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A2 | Over Head Reservoir Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Name | | P Block Tanki | | <div style="text-align: center;">Pictures</div>  | |
| Location | Latitude | 30.160327 | | | |
| | Longitude | 72.689655 | | | |
| Address | | P Block, Burewala | | | |
| Year of Construction | | | | | |
| Capacity (UK Gallons) | | | | | |
| Cleaning Frequency (Per Year) | | | | | |
| Type of Structure | | Masonry | | | |
| Structure Condition | | Good | Fair | | Poor |
| Tank Conditions | | Good | Fair | | Poor |
| Number of Valves | Sluice Valve | | | | |
| | Non-Returning Valve | | | | |
| Working Status | | Abandoned | | | |
| Rising Main | Dia | | | | |
| | Material | | | | |
| Delivery Main | Dia | | | | |
| | Material | | | | |
| Overflow & Scour Pipe | Dia | | | | |
| | Material | | | | |
| Sluice Valve | Rising Main | Yes | No | | |
| | Delivery Main | Yes | No | | |
| | Scour Pipe | Yes | No | | |
| | Overflow Pipe | Yes | No | | |
| Stair Case | | Yes | No | | |
| Apron Around OHR | | Yes | No | | |
| Tank Top Railing | | Yes | No | | |
| Top Indication Light | | Yes | No | | |
| Lightening Arrester | | Yes | No | | |
| Boundary Wall & Gate | | Yes | No | | |
| Overflow Arrangements | Disposal | Yes | No | | |
| Approach to OHR | | Good | Fair | Bad | |
| Overall Rating | | | | | |

| | | | | | |
|--|-----------|--------------------------|------|---|---------|
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |

D. Water Supply Network


| Sr # | Dia | Length (meter) | Age (Years) | Condition | Material | Book Value (PKR Mil) |
|------|-----|----------------|-------------|-----------|----------|----------------------|
| 1 | 3" | 100000 | 48 | Failing | AC | 0 |
| 2 | 4" | 8604 | 48 | Failing | AC | 0 |
| 3 | 6" | 14264 | 48 | Failing | AC | 0 |
| 4 | 8" | 7930 | 48 | Failing | AC | 0 |
| 5 | 3" | 42857 | 15 | Good | UPVC | 1.41 |
| 6 | 4" | 3687 | 15 | Good | UPVC | 0.2 |
| 7 | 6" | 6113 | 15 | Good | UPVC | 0.6 |
| 8 | 8" | 3398 | 15 | Good | UPVC | 0.5 |


| Integrated Development And Asset Management Plan (IDAMP) | | | | |
|--|---|------------|---------------------------------------|-------------|
| Municipal Committee Burewala | | | | |
| Form: IDAMP-A5 | Water Supply Network Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 | |
| Description | Area (Acres) | Percentage | | |
| Served Area | 2232 | 51 | | |
| Contaminated Area | 307 | 13.75% | | |
| Water Shortage Area | 655 | 29.35% | | |
| Unserved Area | 2111 | 49 | | |
| Latest water quality analysis carried out for community network? | Yes | No | | |
| If yes, which lab and parameters? | - | | | |
| Findings of water quality analysis? | - | | | |
| In case of any parameter above the permissible limit of PEQs, which steps are taken to provide safe drinking water to the consumers? | - | | | |
| Any complaints of water contamination received from the consumers? | Yes | No | | |
| If yes, which steps were taken to resolve the complaints? | | | | |
| Pipe Dia (inches) | Pipe Material | Length (m) | Year of Laying | Age of Pipe |
| 3" | AC | 100000 | 1975 | 48 |
| 4" | AC | 8604 | 1975 | 48 |
| 6" | AC | 14264 | 1975 | 48 |
| 8" | AC | 7930 | 1975 | 48 |
| 3" | UPVC | 42857 | 2008 | 15 |
| 4" | UPVC | 3687 | 2008 | 15 |
| 6" | UPVC | 6113 | 2008 | 15 |
| 8" | UPVC | 3398 | 2008 | 15 |

| Remarks / Requirements | | |
|--|---------------------------------|--|
| <ul style="list-style-type: none"> No remarks | | |
| <p>Data Collected By: Mr. Abdullah</p> | <p>Designation: Team Member</p> |  <p>Sign & Date: 30-May-2023</p> |
| <p>Data Checked By: Mr. M. Fiaz</p> | <p>Designation: Team Lead</p> |  <p>Sign & Date: 30-May-2023</p> |

E. Vehicles/ Machinery



| Sr # | Name | Registration Number | Age (Years) | Capacity | Condition | Status | Book Value (PKR Mil) |
|------|--------------|---------------------|-------------|----------|-----------|------------|----------------------|
| 1 | Water Bowser | TMA 3 | 13 | 50 HP | Fair | Functional | 0.3 |
| 2 | Waste Loader | VRK 371 | 17 | 85 HP | Fair | Functional | 0.2 |
| 3 | Waste Loader | VRK 372 | 17 | 85 HP | Fair | Functional | 0.2 |
| 4 | Waste Loader | TMA 8 | 8 | 85 HP | Good | Functional | 0.6 |

| Integrated Development and Asset Management Plan (IDAMP) | |
|---|--|
| Municipal Committee Burewala | |
| Form: IDAMP-A16 | Moveable Asset Asset Condition Assessment |
| Asset Code: _____ Date: 05-05-2023 | |
| Type of Vehicle / Machinery | Pictures |
| Water Bowser | |
| Capacity | 500 Gallons |
| Purpose | Water Supply |
| Year of Manufacturing | 2010 |
| Model | MF 240 |
| Capital Cost | |
| Fuel Consumption (Lt) | 408 |
| Condition | Fair |
| Engine Capacity | 50 HP |
| Maintenance Cost | Not Available |
| Oiling /Fitness | Yes |
| Fitness Certificate | No |
| Registered | Not Registered |
| Overall Rating | Fair |
| Remarks / Requirements | |
| <ul style="list-style-type: none"> No remarks | |
| Data Collected By: Mr. Abdullah | Designation: Team Member |
|  Sign & Date: 30-May-2023 | |

| | | |
|-------------------------------------|-------------------------------|--|
| <i>Data Checked By: Mr. M. Fiaz</i> | <i>Designation: Team Lead</i> |  <i>Sign & Date: 30-May-2023</i> |
|-------------------------------------|-------------------------------|--|

2. Sewerage





Key Components of a Sewerage System




| | | | | | |
|--|--|--|---|---|------------------------------|
| | PROJECT: PUNJAB CITIES PROGRAM (PCP) | Map Code 0625040223 Map Version 1.4 | DISCLAIMER: INFORMATION PROVIDED BY MC, PHED & OTHER SOURCES. | Scale: 1:8,000 0 200 400 800 Meters | Date February 2023 |
|--|--|--|---|---|------------------------------|



A. Disposal Station



| Sr # | Name | Age (Years) | | Nos. of pump | Discharge Each (Cusec) | Motor hp | Pump Make | Motor Make | Condition | Status | Book Value PKR Mil |
|------|--------------------------------|-----------------|------|--------------|---------------------------------------|-------------|-------------------|------------|-----------|------------|--------------------|
| | | Civil Structure | Pump | | | | | | | | |
| 1 | 451-EB Disposal | 15 | 15 | 6 | (2x4Cusec) + (4x5cusec) | 40HP, 60 HP | KSB | KSB | Fair | Functional | 2 |
| 2 | Rehmatabad Disposal | 31 | 31 | 1 | 2.5 | 25 | KSB | PECO | Fair | Functional | 0.6 |
| 3 | Lorry Adda disposal | 93 | N.A | 3 | (2x5cusec) + (1x4cusec) | 60HP, 80HP | KSB | SIEMENS | Poor | Functional | 0.8 |
| 4 | Marzipura Multan Road Disposal | 40 | N.A | 6 | (1x2cusec) + (1x4cusec) + (4x5cusecs) | 75HP, 80HP | MECO / KSB / PECO | SIEMENS | Fair | Functional | 1.3 |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | |
|--|--------------------|--|----------------------------|-----------|------------|----------|------|---|---|---|--|
| Municipal Committee Burewala | | | | | | | | | | | |
| Form: IDAMP-A7 | | Sewerage Disposal Station Asset Condition Assessment | | | | | | Asset Code: _____ Date: 05-05-2023 | | | |
| Asset Detail | | | | | | Pictures | | | | | |
| Name | | | Marzipura Disposal Station | | | | | | | | |
| Location | | Latitude | | 30.148589 | | | | | |  | |
| | | Longitude | | 72.650961 | | | | | | | |
| Address | | | Marzipura, Multan road | | | | | | | | |
| Area (Acres) | | | 1.75 | | | | | | | | |
| Installation Year | | | 1983 | | | | | | | | |
| Capital Cost of Machinery | | | | | | | | | | | |
| Outfall Sewer | Drain | Dia | | 33" | | 42" | |  | | | |
| | | Material | | RCC | | RCC | | | | | |
| Screening Chamber | No. of Screens | | 2 | | | | | |  | | |
| | Screen Condition | | Good | | Fair | | Poor | | | | |
| | Chamber Structure | | Masonry | | | | | | | | |
| Wet Wells | Number | | 3 | | | | | |  | | |
| | Shape | | Rectangular | | Circular | | | | | | |
| | Size | | 20' | | | | | | | | |
| | Structure | | Masonry | | RCC | | | | | | |
| | Railing | | Yes | | No | | | | | | |
| Force Main | No. of force mains | | 2 | | | | | | | | |
| | Dia | | 16" | | 16" | | | | | | |
| | Material | | PVC | | PVC | | | | | | |
| | Starting Point | | Pump House | | Pump House | | | | | | |


| Integrated Development and Asset Management Plan (IDAMP) | | | | | | |
|--|---------------------------|----------------------------|---------------------------|---|---------------------------|---------------------------|
| | Ending Point | Sump PI Canal, Multan road | Broad Irrigation |  | | |
| | Length | 1800' | 500' | | | |
| Sullage Carrier | Size | No Sullage Carrier | | | | |
| | Shape | | | | | |
| | Length | | | | | |
| | Condition | | | | | |
| Delivery Pipe | Dia | 8" | | | | |
| | Material | C.I | | | | |
| Suction Pipe | Dia | 8 | | | | |
| | Material | C.I | | | | |
| Number of Valves | Sluice Valves | 12 | | | | |
| | Non-Return Valves | 6 | | | | |
| | Penstock Valves | 2 | | | | |
| Ultimate Disposal | | Sukh Bias creek | | | | |
| Civil Structure Condition | | Good | Fair | Poor | | |
| Control Room Structure | | Good | Fair | Poor | | |
| Discharge Box Structure | | Good | Fair | Poor | | |
| Approach to Pump House | | Good | Fair | Poor | | |
| Hoisting Girder | | Yes | No | | | |
| Boundary Wall & Gate | | Yes | No | | | |
| Treatment of Sewage | | Yes | No | | | |
| Wastewater daily discharge in m ³ /day? (based on available information at MC) | | 12273 | | | | |
| Ultimate disposal of wastewater? | | | | | | |
| Electro-Mechanical Equipment Details | | | | | | |
| Number of WAPDA Feeders | | 2 | | | | |
| Transformer Capacity (kVA) | | 600 | | | | |
| Number of MCU | | 6 | | | | |
| Sanctioned Load (kWh) | | 114 | | | | |
| Power Factor Improvement Equipment | | Yes | No | | | |
| Service Cable | | Yes | No | | | |
| Power Wiring | | Yes | No | | | |
| Earthing of Motor | | Yes | No | | | |
| Earthing of MCU | | Yes | No | | | |
| Generator Availability | | Yes | No | | | |
| Light Wiring of Pump House | | Yes | No | | | |
| Change Over | | Yes | No | | | |
| Pump Detail | | | | | | |
| | Pump A | Pump B | Pump C | Pump D | Pump E | Pump F |
| Pump Type | Centrifugal/ Non-Clogging | Centrifugal/ Non-Clogging | Centrifugal/ Non-Clogging | Centrifugal/ Non-Clogging | Centrifugal/ Non-Clogging | Centrifugal/ Non-Clogging |
| Pump Brand | KSB | KSB | KSB | KSB | MECO | PECO |
| Pump Paint | Poor | Poor | Poor | Poor | Poor | Poor |






| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|---------------------|--------|------------------------|----------------|----------------|----------------|--------|--------|---|--------|--------|--------|--------|----|
| Motor Brand | Siemen | Siemen | Siemen | Siemen | Siemen | Siemen | Siemen | Siemen | Siemen | Siemen | Siemen | Siemen | Siemen | |
| Installation Year of Pump | | | | | | | | | | | | | | |
| Discharge Capacity (Cusecs) | 5 | 5 | 5 | 2 | 4 | 5 | | | | | | | | |
| Rotational Speed (RPM) | 950 | 950 | 950 | 950 | 950 | 950 | | | | | | | | |
| Head (ft.) | 50 | 50 | 50 | 50 | 50 | 50 | | | | | | | | |
| Motor Power (HP) | 80 | 80 | | | | | | | | 75 | | | | |
| Pump Daily Running Time (Hours) | 12 | 12 | Non-Functional | Non-Functional | Non-Functional | Non-Functional | | | | | | | | |
| Base Plate | Yes | No | Yes | No | Yes | No | Yes | No | Yes | No | Yes | No | Yes | No |
| Number of Valves | Sluice Valve | | 12 | | | | | | | | | | | |
| | Non-Returning Valve | | 6 | | | | | | | | | | | |
| Overall Rating | | | | | | | | | | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 | | | | | | | | | |
| Asset Condition Category | Excellent | Good | Fair | Poor | Failing | | | | | | | | | |
| | A | B | C | D | E | | | | | | | | | |
| Remarks / Requirements | | | | | | | | | | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | | | | | | | | | | |
| Data Collected By: Mr. Abdullah | | | Designation: Member | | | Team | | |  Sign & Date: 30-May-2023 | | | | | |
| Data Checked By: Mr. M. Fiaz | | | Designation: Team Lead | | | | | |  Sign & Date: 30-May-2023 | | | | | |


| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|--|--------------------------|-------------|----------|------|--|--|---------------------------------------|--|--|--|--|--|--|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A7 | Sewerage Disposal Station Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | | | | | |
| Asset Detail | | | | | | | Pictures | | | | | | | |
| Name | | Chak 451 EB | | | | | | | | | | | | |
| Location | Latitude | | 30.142572 | | | | | | | | | | | |
| | Longitude | | 72.636711 | | | | | | | | | | | |
| Address | | Chak 451 EB, Multan Road | | | | | | | | | | | | |
| Area (Acres) | | 0.5 | | | | | | | | | | | | |
| Installation Year | | 2008 | | | | | | | | | | | | |
| Capital Cost of Machinery | | | | | | | | | | | | | | |
| Outfall Sewer | Drain | Dia | | 48" | | | | | | | | | | |
| | | Material | | RCC | | | | | | | | | | |
| Screening Chamber | No. of Screens | | 2 | | | | | | | | | | | |
| | Screen Condition | | Good | Fair | Poor | | | | | | | | | |
| | Chamber Structure | | Masonry | | | | | | | | | | | |
| Wet Wells | Number | | 2 | | | | | | | | | | | |
| | Shape | | Rectangular | Circular | | | | | | | | | | |
| | | | | | | |  | | | | | | | |
| | | | | | | |  | | | | | | | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | |
|--|--------------------|-----------------|------|------|
| | Size | 30' | | |
| | Structure | Masonry | RCC | |
| | Railing | Yes | No | |
| Force Main | No. of force mains | No Force Main | | |
| | Dia | | | |
| | Material | | | |
| | Starting Point | | | |
| | Ending Point | | | |
| | Length | | | |
| Sullage Carrier | Size | 4'x5' | | |
| | Shape | Rectangular | | |
| | Length | 1.5km | | |
| | Condition | Fair | | |
| Delivery Pipe | Dia | 12" | | |
| | Material | C.I | | |
| Suction Pipe | Dia | 12" | | |
| | Material | C.I | | |
| Number of Valves | Sluice Valves | 10 | | |
| | Non-Return Valves | 6 | | |
| | Penstock Valves | 2 | | |
| Ultimate Disposal | | Sukh Bias creek | | |
| Civil Structure Condition | | Good | Fair | Poor |
| Control Room Structure | | Good | Fair | Poor |
| Discharge Box Structure | | Good | Fair | Poor |
| Approach to Pump House | | Good | Fair | Poor |
| Hoisting Girder | | Yes | No | |
| Boundary Wall & Gate | | Yes | No | |
| Treatment of Sewage | | Yes | No | |
| Wastewater daily discharge in m ³ /day? (based on available information at MC) | | 12273 | | |
| Ultimate disposal of wastewater? | | | | |
| Electro-Mechanical Equipment Details | | | | |
| Number of WAPDA Feeders | | 1 | | |
| Transformer Capacity (kVA) | | 200 | | |
| Number of MCU | | 6 | | |
| Sanctioned Load (kWh) | | 198 | | |
| Power Factor Improvement Equipment | | Yes | No | |
| Service Cable | | Yes | No | |
| Power Wiring | | Yes | No | |
| Earthing of Motor | | Yes | No | |
| Earthing of MCU | | Yes | No | |
| Generator Availability | | Yes | No | |
| Light Wiring of Pump House | | Yes | No | |
| Change Over | | Yes | No | |
| Pump Detail | | | | |





| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | |
|--|---------------------|------------------|----|--------------------------|----|--------------------------|----|---|----|--------------------------|----|--------------------------|----|
| | | Pump A | | Pump B | | Pump C | | Pump D | | Pump E | | Pump F | |
| Pump Type | | Submersible Pump | | Submersible Pump | | Centrifugal/Non-Clogging | | Centrifugal/Non-Clogging | | Centrifugal/Non-Clogging | | Centrifugal/Non-Clogging | |
| Pump Brand | | KSB | | KSB | | KSB | | KSB | | KSB | | KSB | |
| Pump Paint | | Poor | | Poor | | Poor | | Poor | | Poor | | Poor | |
| Motor Brand | | KSB | | KSB | | KSB | | KSB | | KSB | | KSB | |
| Installation Year of Pump | | | | | | | | | | | | | |
| Discharge Capacity (Cusecs) | | 5 | | 5 | | 5 | | 5 | | 4 | | 4 | |
| Rotational Speed (RPM) | | 950 | | 950 | | 950 | | 950 | | 950 | | 950 | |
| Head (ft.) | | 40 | | 40 | | 40 | | 40 | | 40 | | 40 | |
| Motor Power (HP) | | 60 | | 60 | | 60 | | 60 | | 40 | | 40 | |
| Pump Daily Running Time (Hours) | | 12 | | 12 | | Non-Functional | | Non-Functional | | Non-Functional | | Non-Functional | |
| Base Plate | | Yes | No | Yes | No | Yes | No | Yes | No | Yes | No | Yes | No |
| Number of Valves | Sluice Valve | 10 | | | | | | | | | | | |
| | Non-Returning Valve | 6 | | | | | | | | | | | |
| Overall Rating | | | | | | | | | | | | | |
| Average Score | 1 | 2 | | 3 | | 4 | | 5 | | | | | |
| Asset Condition | Excellent | Good | | Fair | | Poor | | Failing | | | | | |
| Category | A | B | | C | | D | | E | | | | | |
| Remarks / Requirements | | | | | | | | | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | | | | | | | | | |
| Data Collected By: Mr. Abdullah | | | | Designation: Team Member | | | |  Sign & Date: 30-May-2023 | | | | | |
| Data Checked By: Mr. M. Fiaz | | | | Designation: Team Lead | | | |  Sign & Date: 30-May-2023 | | | | | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | |
|--|--|--|--|-----------|--|--|--|---------------------------------------|--|--|--|--|--|
| Municipal Committee Burewala | | | | | | | | | | | | | |
| Form: IDAMP-A7 | | Sewerage Disposal Station Asset Condition Assessment | | | | | | Asset Code: _____ Date: 05-05-2023 | | | | | |
| Asset Detail | | | | | | | Pictures | | | | | | |
| Name | | Rehmatabad | | | | | | | | | | | |
| Location | | Latitude | | 30.175964 | | | | | | | | | |
| | | Longitude | | 72.687052 | | | | | | | | | |
| Address | | Rehmatabad, 435 EB, Burewala | | | | | | | | | | | |
| Area (Acres) | | 0.5 | | | | | | | | | | | |
| Installation Year | | 1992 | | | | | | | | | | | |
| Capital Cost of Machinery | | | | | | | | | | | | | |
| Dia | | 12" | | | | | | | | | | | |
| | | | | | | |  | | | | | | |



| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|--------------------|------------------|----------|------|---|
| Outfall Sewer | Drain | Material | RCC | |  <p>Burewala, Punjab, Pakistan SMFP-WX7, Stadium Road, Chak No 435/EB Burewala, Vehari, Punjab, Pakistan Lat 30.175998° Long 72.887277° 06/05/23 10:52 AM GMT +05:00</p> |
| Screening Chamber | No. of Screens | 1 | | | |
| | Screen Condition | Good | Fair | Poor | |
| | Chamber Structure | Masonry | | | |
| Wet Wells | Number | 1 | | | |
| | Shape | Rectangular | Circular | | |
| | Size | 25' | | | |
| | Structure | Masonry | RCC | | |
| | Railing | Yes | No | | |
| Force Main | No. of force mains | 1 | | | |
| | Dia | 8" | | | |
| | Material | MS | | | |
| | Starting Point | Pump House | | | |
| | Ending Point | Sullage Carrier | | | |
| | Length | 500' | | | |
| Sullage Carrier | Size | 1.5'x1.5' | | | |
| | Shape | Square | | | |
| | Length | 1000' | | | |
| | Condition | Fair | | | |
| Delivery Pipe | Dia | 6" | | | |
| | Material | C.I | | | |
| Suction Pipe | Dia | 6" | | | |
| | Material | C.I | | | |
| Number of Valves | Sluice Valves | 2 | | | |
| | Non-Return Valves | 1 | | | |
| | Penstock Valves | 0 | | | |
| Ultimate Disposal | | Broad Irrigation | | | |
| Civil Structure Condition | | Good | Fair | Poor | |
| Control Room Structure | | Good | Fair | Poor | |
| Discharge Box Structure | | Good | Fair | Poor | |
| Approach to Pump House | | Good | Fair | Poor | |
| Hoisting Girder | | Yes | No | | |
| Boundary Wall & Gate | | Yes | No | | |
| Treatment of Sewage | | Yes | No | | |
| Wastewater daily discharge in m ³ /day? (based on available information at MC) | | 2300 | | | |
| Ultimate disposal of wastewater? | | | | | |
| Electro-Mechanical Equipment Details | | | | | |
| Number of WAPDA Feeders | | 1 | | | |
| Transformer Capacity (kVA) | | 25 | | | |
| Number of MCU | | 1 | | | |
| Sanctioned Load (kWh) | | 19 | | | |





| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|---------------------|---------------------------|---------------|---|---------|
| Power Factor Improvement | Equipment | Yes | No | | |
| Service Cable | | Yes | No | | |
| Power Wiring | | Yes | No | | |
| Earthing of Motor | | Yes | No | | |
| Earthing of MCU | | Yes | No | | |
| Generator Availability | | Yes | No | | |
| Light Wiring of Pump House | | Yes | No | | |
| Change Over | | Yes | No | | |
| Pump Detail | | | | | |
| | | | Pump A | | |
| Pump Type | | Centrifugal/ Non-Clogging | | | |
| Pump Brand | | KSB | | | |
| Pump Paint | | Poor | | | |
| Motor Brand | | PECO | | | |
| Installation Year of Pump | | 1992 | | | |
| Discharge Capacity (Cusecs) | | 2.5 | | | |
| Rotational Speed (RPM) | | 950 | | | |
| Head (ft.) | | 40 | | | |
| Motor Power (HP) | | 25 | | | |
| Pump Daily Running Time (Hours) | | 9 | | | |
| Base Plate | | Yes | No | | |
| Number of Valves | Sluice Valve | 2 | | | |
| | Non-Returning Valve | 1 | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Member | | Team | |
| | | | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | | | |
| | | | |  Sign & Date: 30-May-2023 | |

| Integrated Development and Asset Management Plan (IDAMP) | | |
|--|---|---------------------------------------|
| Municipal Committee Burewala | | |
| Form: IDAMP-A7 | Sewerage Disposal Station Asset Condition Assessment | Asset Code: _____ Date: 05-05-2023 |
| Asset Detail | | Pictures |
| Name | Lari Adda | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|---|--------------------|---------------------|--------------------|----------|------|
| Location | Latitude | | 30.164903 | | |
| | Longitude | | 72.685170 | | |
| Address | | Lari Adda, Burewala | | | |
| Area (Acres) | | 1.3 | | | |
| Installation Year | | 1930 | | | |
| Capital Cost of Machinery | | | | | |
| Outfall Sewer | Drain | Dia | 36" | | |
| | | Material | RCC | | |
| Screening Chamber | No. of Screens | | 2 | | |
| | Screen Condition | | Good | Fair | Poor |
| | Chamber Structure | | Masonry | | |
| Wet Wells | Number | | 3 | | |
| | Shape | | Rectangular | Circular | |
| | Size | | 2x30' | 1x35' | |
| | Structure | | Masonry | RCC | |
| | Railing | | Yes | No | |
| Force Main | No. of force mains | | 1 | | |
| | Dia | | 16" | | |
| | Material | | PVC | | |
| | Starting Point | | Pump house | | |
| | Ending Point | | Rehmatabad Road | | |
| Sullage Carrier | Length | | 2500' | | |
| | Size | | | | |
| | Shape | | | | |
| | Condition | | No Sullage Carrier | | |
| Delivery Pipe | Dia | | 16" | | |
| | Material | | C.I | | |
| Suction Pipe | Dia | | 16" | | |
| | Material | | C.I | | |
| Number of Valves | Sluice Valves | | 6 | | |
| | Non-Return Valves | | 3 | | |
| | Penstock Valves | | 1 | | |
| Ultimate Disposal | | Broad Irrigation | | | |
| Civil Structure Condition | | Good | Fair | Poor | |
| Control Room Structure | | Good | Fair | Poor | |
| Discharge Box Structure | | Good | Fair | Poor | |
| Approach to Pump House | | Good | Fair | Poor | |
| Hoisting Girder | | Yes | | No | |
| Boundary Wall & Gate | | Yes | | No | |
| Treatment of Sewage | | Yes | | No | |
| Wastewater daily discharge in m ³ /day? (based on available information at MC) | | 11045 | | | |





| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | |
|--|---------------------|---------------------------|------|---------------------------|----|---|----|
| Ultimate disposal of wastewater? | | | | | | | |
| Electro-Mechanical Equipment Details | | | | | | | |
| Number of WAPDA Feeders | | 1 | | | | | |
| Transformer Capacity (kVA) | | 200 | | | | | |
| Number of MCU | | 2 | | | | | |
| Sanctioned Load (kWh) | | 121 | | | | | |
| Power Factor Improvement Equipment | | Yes | No | | | | |
| Service Cable | | Yes | | | | | |
| Power Wiring | | Yes | | | | | |
| Earthing of Motor | | Yes | | | | | |
| Earthing of MCU | | Yes | | | | | |
| Generator Availability | | Yes | | | | | |
| Light Wiring of Pump House | | Yes | | | | | |
| Change Over | | Yes | | | | | |
| Pump Detail | | | | | | | |
| | | Pump A | | Pump B | | Pump C | |
| Pump Type | | Centrifugal/ Non-Clogging | | Centrifugal/ Non-Clogging | | Centrifugal/ Non-Clogging | |
| Pump Brand | | KSB | | KSB | | KSB | |
| Pump Paint | | Poor | | Poor | | Poor | |
| Motor Brand | | Siemens | | Siemens | | Siemens | |
| Installation Year of Pump | | Not Available | | Not Available | | Not Available | |
| Discharge Capacity (Cusecs) | | 5 | | 4 | | 5 | |
| Rotational Speed (RPM) | | 950 | | 950 | | 950 | |
| Head (ft.) | | 50 | | 50 | | | |
| Motor Power (HP) | | 80 | | 60 | | 80 | |
| Pump Daily Running Time (Hours) | | 12 | | 12 | | Non-Functional | |
| Base Plate | | Yes | No | Yes | No | Yes | No |
| Number of Valves | Sluice Valve | | 6 | | | | |
| | Non-Returning Valve | | 3 | | | | |
| Overall Rating | | | | | | | |
| Average Score | 1 | 2 | 3 | 4 | | 5 | |
| Asset Condition | Excellent | Good | Fair | Poor | | Failing | |
| Category | A | B | C | D | | E | |
| Remarks / Requirements | | | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Member | | Team | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | | | |  Sign & Date: 30-May-2023 | |



B. Sewerage Network


| Sr # | Dia | Length (meter) | Age | Condition | Material | Book Value (PKR Mil) |
|------|-----|----------------|-----|-----------|----------|----------------------|
| 1 | 8" | 180 | 33 | Failing | RCC | 0 |
| 2 | 9" | 108314 | | | | 22.79 |
| 3 | 12" | 29293 | | | | 8.34 |
| 4 | 15" | 6609 | | | | 2.38 |
| 5 | 16" | 2094 | | | | 1.24 |
| 6 | 18" | 10838 | | | | 7.63 |
| 7 | 21" | 1046 | | | | 0.98 |
| 8 | 24" | 6721 | | | | 7.8 |
| 9 | 27" | 3305 | | | | 5.3 |
| 10 | 30" | 5149 | | | | 9.4 |
| 11 | 33" | 3592 | | | | 7.38 |
| 12 | 36" | 3370 | | | | 8.94 |
| 13 | 42" | 6969 | | | | 17.44 |
| 14 | 48" | 3687 | | | | 11.48 |



| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|---|--|------------|-----------------|---------------------------------------|-------------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A6 | Sewerage Network Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Description | Area (Acres) | | Percentage | | |
| Served Area | 1938 | | 45 | | |
| Flooded Area | 471 | | 24 | | |
| Unserved Area | 2405 | | 55 | | |
| Type and number of complaints received to MC regarding sewerage system? | 26/Month | | | | |
| Steps considered by MC to resolve the complaints | | | | | |
| Pipe Dia (inches) | Pipe Material | Length (m) | No. of Manholes | Year of Laying | Age of Pipe |
| 9 | RCC | 108494 | 7117 | 1991 | 32 Years |
| 12 | RCC | 29293 | 961 | 1991 | 32 Years |
| 15 | RCC | 8703 | 190 | 1991 | 32 Years |
| 18 | RCC | 10838 | 178 | 1991 | 32 Years |
| 21 | RCC | 1046 | 14 | 1991 | 32 Years |
| 24 | RCC | 6721 | 88 | 1991 | 32 Years |
| 27 | RCC | 3305 | 36 | 1991 | 32 Years |
| 30 | RCC | 5149 | 56 | 1991 | 32 Years |
| 33 | RCC | 3592 | 39 | 1991 | 32 Years |
| 36 | RCC | 3370 | 37 | 1991 | 32 Years |

| | | | | | |
|--|-----|--------------------------|----|---|----------|
| 42 | RCC | 6969 | 76 | 1991 | 32 Years |
| 48 | RCC | 3687 | 30 | 1991 | 32 Years |
| | | | | | |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |

C. Vehicles/ Machinery



| Sr # | Name | Registration Number | Age (Years) | Capacity | Condition | Status | Book Value (PKR Mil) |
|------|--------------------------------|---------------------|---------------|---------------|-----------|------------|----------------------|
| 1 | HINO-300 | TMA 11 | 14 | 4500 CC | Fair | Functional | 0.8 |
| 2 | De Watering Sets (4 Nos) | Not Available | Not Available | Not Available | Good | Functional | N.A |
| 3 | Shoulder Foggers (2 Nos) | Not Applicable | 10 | Not Available | Fair | Functional | Not Available |
| 4 | Spray Pumps (6 Nos) | Not Applicable | 10 | Not Available | Fair | Functional | Not Available |
| 5 | Safety Gear (1 Nos) | Not Applicable | 10 | Not Available | Fair | Functional | Not Available |
| 6 | Sewer Safety Equipment (2 Nos) | Not Applicable | 10 | Not Available | Fair | Functional | Not Available |

| Integrated Development and Asset Management Plan (IDAMP) | |
|--|--|
| Municipal Committee Burewala | |
| Form: IDAMP-A16 | Moveable Asset Asset Condition Assessment |
| Asset Code: _____ Date: 05-05-2023 | |
| Type of Vehicle / Machinery | Pictures |
| Suction & Jetting Machine |  |
| | Suction & Jetting Machine |
| Capacity | 4500 liters |
| Purpose | Suction & Jetting |
| Year of Manufacturing | 2009 |
| Model | Hino 300 |
| Capital Cost | |

| | | |
|---------------------------------|--------------------------|---|
| Fuel Consumption (Lt) | 752 | |
| Condition | Fair | |
| Engine Capacity | 4500 CC | |
| Maintenance Cost | Not Available | |
| Oiling /Fitness | Yes | |
| Fitness Certificate | No | |
| Registered | No Registration | |
| Overall Rating | Fair | |
| Remarks / Requirements | | |
| No remarks | | |
| Data Collected By: Mr. Abdullah | Designation: Team Member |  Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |

3. Solid Waste Management




Key Components of Solid Waste Management System





A. Dumping Site



| Sr # | Name | Age (Years) | Area | Condition | Status | Book Value (PKR Mil) |
|------|----------------------------|-------------|------|-----------|------------|----------------------|
| 1 | Chak 435 EB | 6 | 6 | Fair | Functional | 432 |
| 2 | Multan Road, Near Disposal | 9 | 12.5 | Poor | Closed | |
| 3 | Fawara Chowk, Lahore Road | 28 | 6 | Poor | Closed | |

| Integrated Development And Asset Management Plan (IDAMP) | | | | |
|--|---|-----------|---------------------------------------|--|
| Municipal Committee Burewala | | | | |
| Form: IDAMP-A11 | Solid Waste Dumping Site Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 | |
| Name | Chak 435 EB | | Pictures | |
| Location | Latitude | 30.193037 | | |
| | Longitude | 72.683876 | | |
| Address | Chak 423 Road | | | |
| Area (Acres) | 6 | | | |
| Distance from urban area | 4 km | | | |
| Year the site started for dumping service | 2017 | | | |
| Average waste dumped daily (based on information provided by MC) | Not Available | | | |
| EHS SOPs for waste handlers | No | | | |
| Availability of PPEs for waste collectors/handlers | Yes | No | | |
| Expected Life (Years) | 15 | | | |
| Land Ownership | Private (Leased by MC) | | | |
| Site Accessibility | Good | Fair | Poor | |
| Surface Type | Flat | Depressed | | |
| Approach Road Condition | Good | Fair | Poor | |
| Parking Shed | Yes | No | | |
| Boundary Wall | Yes | No | | |
| Gate | Yes | No | | |
| Ramps | Yes | No | | |
| Any Building at Site | Yes | No | | |
| Weigh Bridge | Yes | No | | |
| Earth Cover Arrangements | Yes | No | | |
| Compaction Equipment | Yes | No | | |
| Plantation Around Site | Yes | No | | |







| | | | | | |
|--|--------------------------|------|------|---|---------|
| Any illegal occupants or encroachments observed-if yes, type | No | | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| • No remarks | | | | | |
| Data Collected By: Mr. Abdullah | Designation: Team Member | | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead | | |  Sign & Date: 30-May-2023 | |

| Integrated Development And Asset Management Plan (IDAMP) | | | | | | |
|--|-----------|---|-----------|----------|---------------------------------------|--|
| Municipal Committee Burewala | | | | | | |
| Form: IDAMP-A11 | | Solid Waste Dumping Site Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Name | | Multan Road | | Pictures | | |
| Location | Latitude | 30.148074 | | | | |
| | Longitude | 72.650434 | | | | |
| Address | | Multan Road, Near Disposal | | | | |
| Area (Acres) | | 12.5 | | | | |
| Distance from urban area | | 2 km | | | | |
| Year the site started for dumping service | | 2014 | | | | |
| Average waste dumped daily (based on information provided by MC) | | Not Available | | | | |
| EHS SOPs for waste handlers | | No | | | | |
| Availability of PPEs for waste collectors/handlers | | Yes | No | | | |
| Expected Life (Years) | | Closed | | | | |
| Land Ownership | | Treasury Department | | | | |
| Site Accessibility | | Good | Fair | Poor | | |
| Surface Type | | Flat | Depressed | | | |
| Approach Road Condition | | Good | Fair | Poor | | |

| | | | | | |
|--|-----------|--------------------------|------|---|---------|
| Parking Shed | Yes | No | | | |
| Boundary Wall | Yes | No | | | |
| Gate | Yes | No | | | |
| Ramps | Yes | No | | | |
| Any Building at Site | Yes | No | | | |
| Weigh Bridge | Yes | No | | | |
| Earth Cover Arrangements | Yes | No | | | |
| Compaction Equipment | Yes | No | | | |
| Plantation Around Site | Yes | No | | | |
| Any illegal occupants or encroachments observed-if yes, type | No | | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |




| Integrated Development And Asset Management Plan (IDAMP) | | | | | |
|--|-----------|--|-----------|----------|---------------------------------------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A11 | | Solid Waste Dumping Site Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 |
| Name | | Fawara Chowk | | Pictures | |
| Location | Latitude | 30.157936 | | | |
| | Longitude | 72.693126 | | | |
| Address | | Fawara Chowk, Lahore Road | | | |
| Area (Acres) | | 6 | | | |
| Distance from urban area | | 1.5 | | | |
| Year the site started for dumping service | | 1995 | | | |
| Average waste dumped daily (based on information provided by MC) | | Not Available | | | |
| EHS SOPs for waste handlers | | No | | | |
| Availability of PPEs for waste collectors/handlers | | Yes | No | | |
| Expected Life (Years) | | Closed | | | |
| Land Ownership | | Private (Leased by MC) | | | |
| Site Accessibility | | Good | Fair | Poor | |
| Surface Type | | Flat | Depressed | | |
| Approach Road Condition | | Good | Fair | Poor | |
| Parking Shed | | Yes | No | | |
| Boundary Wall | | Yes | No | | |
| Gate | | Yes | No | | |
| Ramps | | Yes | No | | |
| Any Building at Site | | Yes | No | | |
| Weigh Bridge | | Yes | No | | |
| Earth Cover Arrangements | | Yes | No | | |
| Compaction Equipment | | Yes | No | | |
| Plantation Around Site | | Yes | No | | |
| Any illegal occupants or encroachments observed-if yes, type | | | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> • No remarks | | | | | |




| | | |
|--|---------------------------------|--|
| <i>Data Collected By: Mr. Abdullah</i> | <i>Designation: Team Member</i> |  <i>Sign & Date: 30-May-2023</i> |
| <i>Data Checked By: Mr. M. Fiaz</i> | <i>Designation: Team Lead</i> |  <i>Sign & Date: 30-May-2023</i> |




B. Vehicles/ Machinery




| Sr # | Name | No. | Registration Number | Age (Years) | Capacity | Condition | Status | Book Value (PKR Mil) |
|------|---|-----|---------------------|---------------|-----------------|-----------|------------------------------|----------------------|
| 1 | MF 240 | 1 | TMA 1 | 13 | 50 HP | Fair | Functional | 0.3 |
| 2 | MF 240 | 1 | TMA 2 | 13 | 50 HP | Fair | Functional | 0.3 |
| 3 | MF 240 | 1 | TMA 4 | 8 | 50 HP | Good | Functional | 0.5 |
| 4 | MF 135 | 1 | TMA 5 | 55 | 35 HP | Poor | Functional | 0.1 |
| 5 | MF 240 | 1 | TMA 6 | 43 | 50 HP | Poor | Functional | 0.1 |
| 6 | MF 375 | 1 | TMA 7 | 8 | 75 HP | Good | Functional | 0.5 |
| 7 | MF 385 | 1 | TMA 8 | 8 | 85 HP | Good | Functional | |
| 8 | MF 385 | 1 | Not Registered | 8 | 85 HP | Good | Functional | |
| 9 | Fiat NH640 | 1 | Not Registered | 17 | 85 HP | Fair | Functional | |
| 10 | Fiat NH640 | 1 | Not Registered | 17 | 85 HP | Fair | Functional | |
| 11 | Mechanical Sweeper | 1 | Not Registered | 03 | 50 HP | Good | Functional | |
| 12 | Front End Loader-1 | 1 | Not Registered | 3 | 85 HP | Good | Functional | |
| 13 | Front End Loader-2 | 1 | Not Registered | 3 | 85 HP | Good | Functional | |
| 14 | Front End Loader-3 | 1 | Not Registered | 3 | 85 HP | Good | Functional | |
| 15 | Front End Loader-4 | 1 | Not Registered | 7 | 50 HP | Good | Functional | |
| 16 | Front End Loader-5 | 1 | Not Registered | 17 | 50 HP | Fair | Functional | |
| 17 | Front Blade Tractor-1 | 1 | Not Registered | 3 | 75 HP | Good | Functional | |
| 18 | Front Blade Tractor-2 | 1 | Not Registered | 3 | 75 HP | Good | Functional | |
| 19 | Front Blade Tractor-3 | 1 | Not Registered | 3 | 75 HP | Good | Functional | |
| 20 | Front Blade Tractor-4 | 1 | VRK-372 | 17 | 85 HP | Fair | Functional | |
| 21 | HINO-300 | 1 | TMA 9 | 11 | 4500 CC | Fair | Functional | 0.2 |
| 22 | Containers 5 m3 | 23 | Not Available | Not Available | 5 Cubic Meter | Good | Functional | N.A |
| 23 | Containers 3 m3 | 17 | Not Available | Not Available | 3 Cubic Meter | Good | Total 17 (7 Requires Repair) | |
| 24 | Garbage container 0.8 cubic meters capacity | 423 | Not Available | 1 | 0.8 Cubic Meter | Excellent | Functional | 0.0702 |




| Sr # | Name | No. | Registration Number | Age (Years) | Capacity | Condition | Status | Book Value (PKR Mil) |
|------|---|-----|---------------------|-------------|-----------------|-----------|------------|----------------------|
| 25 | Garbage compactor 8.0 cubic meter capacity | 4 | Not Available | 1 | 8 Cubic Meter | Excellent | Functional | 9.45 |
| 26 | Three wheeled handcarts with adjustable height compatible with 0.8 cubic meter containers | 27 | Not Available | 1 | .08 Cubic Meter | Excellent | Functional | 0.0675 |
| 27 | Three wheeled conventional handcarts | 100 | Not Available | 1 | Not Available | Excellent | Functional | 0.0675 |
| 28 | Mini tipper 1.0 cubic meter | 3 | Not Available | 1 | 1.0 Cubic Meter | Excellent | Functional | 1.6578 |
| 29 | 200 cc Hydraulic Motor cycle Rickshaw | 12 | Not Available | 1 | 200cc | Excellent | Functional | 0.36 |
| 30 | Garbage container 5 cubic | 30 | Not Available | 1 | 5 Cubic Meter | Excellent | Functional | s0.4275 |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | |
|--|--|--------------------------|-------------------------|-------------------------|---|-------------------------|-------------------------|
| Municipal Committee Burewala | | | | | | | |
| Form: IDAMP-A16 | Moveable Asset Asset Condition Assessment | | | | Asset Code: _____ Date: 05-05-2023 | | |
| Type of Vehicle / Machinery | Pictures | | | | | | |
| Tractor-Millat |  | | | | | | |
| | Tractor -Millat 1 | Tractor -Millat 2 | Tractor -Millat 3 | Tractor -Millat 4 | Tractor -Millat 5 | Tractor -Millat 6 | Tractor -Millat 7 |
| Capacity | 50 HP | 50 HP | 50 HP | 35 HP | 50 HP | 75 HP | 85 HP |
| Purpose | SWM | SWM | SWM | SWM | SWM | SWM | SWM |
| Year of Manufacturing | 2010 | 2010 | 2015 | 1968 | 1980 | 2015 | 2015 |
| Model | MF240 | MF240 | MF240 | MF135 | MF240 | MF375 | MF385 |
| Capital Cost | | | | | | | |
| Fuel Consumption (Lt) | Non- Function al | Non- Function al | Non- Function al | 507 | 549 | 510 | 531 |
| Condition | Fair | Fair | Good | Poor | Poor | Good | Good |
| Engine Capacity | 50 HP | 50 HP | 50 HP | 35 HP | 50 HP | 75 HP | 85 HP |
| Maintenance Cost | Not Availab le | Not Availab le | Not Availab le | Not Availab le | Not Availab le | Not Availab le | Not Availab le |
| Oiling /Fitness | Yes | Yes | Yes | Yes | Yes | Yes | Yes |
| Fitness Certificate | No | No | No | No | No | No | No |
| Registered | Not Registe red | Not Registe red | Not Registe red | Not Registe red | Not Registe red | Not Registe red | Not Registe red |
| Overall Rating | Fair | Fair | Good | Poor | Poor | Good | Good |
| Remarks / Requirements | | | | | | | |
| <ul style="list-style-type: none"> • No remarks | | | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | | |  Sign & Date: 30-May-2023 | | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | | |  Sign & Date: 30-May-2023 | | |

| Integrated Development and Asset Management Plan (IDAMP) | | | |
|--|--|---|---------------------------------------|
| Municipal Committee Burewala | | | |
| Form: IDAMP-A16 | Moveable Asset Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 |
| Type of Vehicle / Machinery | Pictures | | |
| Tractor |  | | |
| | Tractor-Millat 8 | Tractor-FIAT 1 | Tractor-FIAT 2 |
| Capacity | 85 HP | 85HP | 85HP |
| Purpose | SWM | SWM | SWM |
| Year of Manufacturing | 2015 | 2006 | 2006 |
| Model | MF385 | Fiat NH640 | Fiat NH640 |
| Capital Cost | | | |
| Fuel Consumption (Lt) | 287 | 468 | 507 |
| Condition | Good | Fair | Fair |
| Engine Capacity | 85 HP | 85HP | 85HP |
| Maintenance Cost | Not Available | Not Available | Not Available |
| Oiling /Fitness | Yes | Yes | Yes |
| Fitness Certificate | No | No | No |
| Registered | Not Registered | VRK 371 | VRK 372 |
| Overall Rating | Good | Fair | Fair |
| Remarks / Requirements | | | |
| <ul style="list-style-type: none"> No remarks | | | |
| Data Collected By: Mr. Abdullah | Designation: Team Member |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|--|-----------------------|-----------------------|---|-----------------------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A16 | Moveable Asset Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Type of Vehicle / Machinery | Pictures | | | | |
| Tractor |  | | | | |
| | Front End Loader-1 | Front End Loader-2 | Front End Loader-3 | Front End Loader-4 | Front End Loader-5 |
| Capacity | 85 HP | 85 HP | 85 HP | 50 HP | 50 HP |
| Purpose | SWM | SWM | SWM | SWM | SWM |
| Year of Manufacturing | 2020 | 2020 | 2020 | 2015 | 2006 |
| Model | MF385 | MF385 | MF385 | MF240 | MF240 |
| Capital Cost | | | | | |
| Fuel Consumption (Lt) | 214 | 211 | 224 | 198 | 191 |
| Condition | Good | Good | Good | Fair | Fair |
| Engine Capacity | 85 HP | 85HP | 85 HP | 50 HP | 50 HP |
| Maintenance Cost | Not Available | Not Available | Not Available | Not Available | Not Available |
| Oiling /Fitness | Yes | Yes | Yes | Yes | Yes |
| Fitness Certificate | No | No | No | No | No |
| Registered | Not Registered | Not Registered | Not Registered | Not Registered | Not Registered |
| Overall Rating | Good | Good | Good | Fair | Fair |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> | | | | | |
| Data Collected By: Mr. Abdullah | Designation: Team Member | | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead | | |  Sign & Date: 30-May-2023 | |





| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|--|--------------------------|--------------------------|---|-----------------------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A16 | Moveable Asset Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Type of Vehicle / Machinery | Pictures | | | | |
| Tractor |  | | | | |
| | Front Blade Tractor-1 | Front Blade Tractor-2 | Front Blade Tractor-3 | Front Blade Tractor-4 | Mechanical Sweeper |
| Capacity | 75 HP | 75 HP | 75 HP | 85 HP | 50 HP |
| Purpose | SWM | SWM | SWM | SWM | SWM |
| Year of Manufacturing | 2020 | 2020 | 2020 | 2006 | 2020 |
| Model | MF375 | MF375 | MF375 | FIAT NH640 | MF240 |
| Capital Cost | | | | | |
| Fuel Consumption (Lt) | 210 | 221 | 215 | 298 | 231 |
| Condition | Good | Good | Good | Fair | Good |
| Engine Capacity | 85 HP | 85HP | 85 HP | 50 HP | 50 HP |
| Maintenance Cost | Not Available | Not Available | Not Available | Not Available | Not Available |
| Oiling /Fitness | Yes | Yes | Yes | Yes | Yes |
| Fitness Certificate | No | No | No | No | No |
| Registered | Not Registered | Not Registered | Not Registered | VRK-372 | Not Registered |
| Overall Rating | Good | Good | Good | Fair | Good |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |



| Integrated Development and Asset Management Plan (IDAMP) | | | |
|--|--|----------------|---|
| Municipal Committee Burewala | | | |
| Form: IDAMP-A16 | Moveable Asset Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 |
| Type of Vehicle / Machinery | Pictures | | |
| Truck |  | | |
| | Truck- Hino 1 | Truck- Hino 2 | Mini Tipper |
| Capacity | 4500 CC | 4500 CC | 4500 CC |
| Purpose | SWM | SWM | SWM |
| Year of Manufacturing | 2010 | 2012 | 2012 |
| Model | Hino 300 | Hino 300 | Hino 300 |
| Capital Cost | | | |
| Fuel Consumption (Lt) | 314 | 489 | 380 |
| Condition | Fair | Fair | Fair |
| Engine Capacity | 4500 CC | 4500 CC | 4500 CC |
| Maintenance Cost | Not Available | Not Available | Not Available |
| Oiling /Fitness | Yes | Yes | Yes |
| Fitness Certificate | No | No | No |
| Registered | Not Registered | Not Registered | Not Registered |
| Overall Rating | Fair | Fair | Fair |
| Remarks / Requirements | | | |
| <ul style="list-style-type: none"> No remarks | | | |
| Data Collected By: Mr. Abdullah | Designation: Team Member | |  Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead | |  Sign & Date: 30-May-2023 |

4. Building

A. Offices





| Sr # | Name | Age (Years) | Area (Acre) | Condition | Status | Book Value (PKR Mil) |
|------|-----------|-------------|-------------|-----------|------------|----------------------|
| 1 | MC Office | 76 | 1.61 | Good | Functional | 231 |



| Integrated Development and Asset Management Plan (IDAMP) | | | |
|---|-------------------------------------|--|---------------------------------------|
| Municipal Committee Burewala | | | |
| Form: IDAMP-A14 | Building Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 |
| Name | | MC Office | |
| Location | Latitude | 30.159768 | |
| | Longitude | 72.682088 | |
| Address | | College Road, Gol Chowk, Burewala | |
| Year of Construction | | Before Partition | |
| Land Area (Acres) | | 1.5 | |
| No. of Stories | | 2 | |
| Condition | | Fair | |
| Purpose | | Admin Affairs | |
| No. of Staff | | 153 | |
| No. of Rooms | | 31 | |
| Conference/Meeting Room | | Yes | No |
| Store Room | | Yes | No |
| Study Room/Book Shelf | | Yes | No |
| Boundary Wall | | Yes | No |
| Heating & Cooling Arrangement | | Yes | No |
| Parking Lots | | Yes | No |
| Drinking Water Facilities | | Yes | No |
| Availability and quality of water (based on available water quality test reports) | | Yes | No |
| Washrooms / Sewerage System | | Yes | No |
| Separate Washroom for Ladies | | Yes | No |
| Prayers Area/room | | Yes | No |
| Furniture | | Yes | No |
| Electric Appliances (Fans Etc.) | | Yes | No |
| Machinery & Equipment | | Yes | No |
| Sports Club | | Yes | No |
| Staff Attendance System | | Yes | No |
| Emergency Alarm System | | Yes | No |
| Fire Fighting System / Equipment | | Yes | No |
| Ramps for wheel chairs at entry gate | | Yes | No |
| | | Pictures | |
| | |  | |
| | |  | |
| | |  | |
| | |  | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|--|--------------------------|------|---|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A14 | Building Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Security Guard | Yes | No | | | |
| Park/lawn plantation | Yes | No | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> Different Renovations in different years | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | |  Sign & Date: 30-May-2023 | |

B. Library

| Sr # | Name | Age (Years) | Area (Acre) | Condition | Status | Book Value (PKR Mil) |
|------|------------|-------------|-------------|-----------|------------|----------------------|
| 1 | MC Library | 66 | 0.15 | Fair | Functional | 21.6 |

| Integrated Development and Asset Management Plan (IDAMP) | | | |
|---|-------------------------------------|--|---------------------------------------|
| Municipal Committee Burewala | | | |
| Form: IDAMP-A14 | Building Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 |
| Name | | MC Library | |
| Location | Latitude | 30.160706 | |
| | Longitude | 72.681047 | |
| Address | | College Road, Near DPS, Burewala | |
| Year of Construction | | Not Available | |
| Land Area (Acres) | | 0.12 | |
| No. of Stories | | 1 | |
| Condition | | Fair | |
| Purpose | | Library | |
| No. of Staff | | 3 | |
| No. of Rooms | | 3 rooms + 1 Hall | |
| Conference/Meeting Room | | Yes | No |
| Store Room | | Yes | No |
| Study Room/Book Shelf | | Yes | No |
| Boundary Wall | | Yes | No |
| Heating & Cooling Arrangement | | Yes | No |
| Parking Lots | | Yes | No |
| Drinking Water Facilities | | Yes | No |
| Availability and quality of water (based on available water quality test reports) | | Yes | No |
| Washrooms / Sewerage System | | Yes | No |
| Separate Washroom for Ladies | | Yes | No |
| Prayers Area/room | | Yes | No |
| Furniture | | Yes | No |
| Electric Appliances (Fans Etc.) | | Yes | No |
| Machinery & Equipment | | Yes | No |
| Sports Club | | Yes | No |
| Staff Attendance System | | Yes | No |
| Emergency Alarm System | | Yes | No |
| Fire Fighting System / Equipment | | Yes | No |
| Ramps for wheel chairs at entry gate | | Yes | No |
| | | Pictures | |
| | |  | |
| | |  | |
| | |  | |
| | |  | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|--|------|---|---------------------------------------|---------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A14 | Building Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Security Guard | Yes | No | | | |
| Park/lawn plantations | outdoor/indoor | Yes | No | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | Designation: Team Member | |  Sign & Date: 30-May-2023 | | |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead | |  Sign & Date: 30-May-2023 | | |

C. Shops

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|------------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|---------------|----------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 1 | | Cloth Market Joyia Road | 30.15722833 | 72.68239333 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Zaheer ahmed | |
| 2 | | Cloth Market Joyia Road | 30.15726167 | 72.68247667 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | maqsood Ahmed | |
| 3 | | Cloth Market Joyia Road | 30.15726667 | 72.68244167 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m saleem | |
| 4 | | Cloth Market Joyia Road | 30.15725833 | 72.68250333 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | zaffer ahmed | |
| 5 | | Cloth Market Joyia Road | 30.15717 | 72.68253667 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m aslam | |
| 6 | | Cloth Market Joyia Road | 30.15701167 | 72.68248667 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m aslam | |
| 7 | | Cloth Market Joyia Road | 30.15701667 | 72.68254333 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m aslam | |
| 8 | | Cloth Market Joyia Road | 30.15698333 | 72.682475 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m sadiq | |
| 9 | | Cloth Market Joyia Road | 30.15696833 | 72.68249667 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m sadeeq | |
| 10 | | Cloth Market Joyia Road | 30.15722333 | 72.68252833 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Rajan bibi | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|---------------|----------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 11 | | Cloth Market Joyia Road | 30.15712667 | 72.68239667 | 120 | 1 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Abdul qadir | |
| 12 | | Cloth Market Joyia Road | 30.15711167 | 72.682325 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | atta muhammad | |
| 13 | | Cloth Market Joyia Road | 30.1571 | 72.682335 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | zaffer ahmed | |
| 14 | | Cloth Market Joyia Road | 30.15714667 | 72.68233167 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Riaz ahmed | |
| 15 | | Cloth Market Joyia Road | 30.15727667 | 72.68233833 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m yaseen | |
| 16 | | Cloth Market Joyia Road | 30.15706833 | 72.68218667 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Qazi Ahmed | |
| 17 | | Cloth Market Joyia Road | 30.15728333 | 72.68237667 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | roshan din | |
| 18 | | Cloth Market Joyia Road | 30.15719 | 72.6823 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m Rafiq | |
| 19 | | Cloth Market Joyia Road | 30.15738 | 72.68236833 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | mango khan | |
| 20 | | Cloth Market Joyia Road | 30.157295 | 72.68229667 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | nawab din | |
| 21 | | Cloth Market Joyia Road | 30.15727833 | 72.68220833 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m aslam | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------|----------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 22 | | Cloth Market Joyia Road | 30.157265 | 72.68226167 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m waryam | |
| 23 | | Cloth Market Joyia Road | 30.157265 | 72.68239667 | 120 | 1 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | m irfan | |
| 24 | | Cloth Market Joyia Road | 30.15729833 | 72.68230833 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Anwar nisar | |
| 25 | | Cloth Market Joyia Road | 30.15739667 | 72.68237333 | 120 | 1 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Bashir Ahmed | |
| 26 | | Cloth Market Joyia Road | 30.15722333 | 72.68239 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m hanif | |
| 27 | | Cloth Market Joyia Road | 30.15718333 | 72.68246 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Anwar nisar | |
| 28 | | Cloth Market Joyia Road | 30.15725333 | 72.68243667 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Sajjad Ahmed | |
| 29 | | Cloth Market Joyia Road | 30.15696 | 72.68229833 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m mukhtar Ahmed | |
| 30 | | Cloth Market Joyia Road | 30.156935 | 72.68252 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m rafiq | |
| 31 | | Cloth Market Joyia Road | 30.15706667 | 72.68243333 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m habib | |
| 32 | | Cloth Market Joyia Road | 30.15697333 | 72.682335 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m habib | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|---------------|----------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 33 | | Cloth Market Joyia Road | 30.15699 | 72.68235833 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Allah dita | |
| 34 | | Cloth Market Joyia Road | 30.15711333 | 72.682165 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m ramzan | |
| 35 | | Cloth Market Joyia Road | 30.15716833 | 72.68219667 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m ramzan | |
| 36 | | Cloth Market Joyia Road | 30.15712333 | 72.68215 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m aslam | |
| 37 | | Cloth Market Joyia Road | 30.157065 | 72.682405 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Nazir hussain | |
| 38 | | Cloth Market Joyia Road | 30.15716833 | 72.682385 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m hanif | |
| 39 | | Cloth Market Joyia Road | 30.15718667 | 72.68207333 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m Ashraf | |
| 40 | | Cloth Market Joyia Road | 30.157185 | 72.68209167 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m sharif | |
| 41 | | Cloth Market Joyia Road | 30.157185 | 72.68209167 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Niaz Hussain | |
| 42 | | Cloth Market Joyia Road | 30.15719333 | 72.68213167 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m anwer | |
| 43 | | Cloth Market Joyia Road | 30.15708333 | 72.68223667 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m awais | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|------------------|----------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 44 | | Cloth Market Joyia Road | 30.15704833 | 72.68202833 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m jamil | |
| 45 | | Cloth Market Joyia Road | 30.15709833 | 72.68235667 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Tariq Mehmood | |
| 46 | | Cloth Market Joyia Road | 30.15706667 | 72.68241 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Akbar ali | |
| 47 | | Cloth Market Joyia Road | 30.15707167 | 72.68235833 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | mubashir Hussain | |
| 48 | | Cloth Market Joyia Road | 30.157205 | 72.68218833 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m ashiq | |
| 49 | | Cloth Market Joyia Road | 30.156845 | 72.68226 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Ali ahmed | |
| 50 | | Cloth Market Joyia Road | 30.15692333 | 72.68242167 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | m iqbal | |
| 51 | | Cloth Market Joyia Road | 30.15676667 | 72.68239167 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m iqbal | |
| 52 | | Cloth Market Joyia Road | 30.15694833 | 72.6823 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhamma d ishaq | |
| 53 | | Cloth Market Joyia Road | 30.156925 | 72.68227833 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | manzoor | |
| 54 | | Cloth Market Joyia Road | 30.156925 | 72.68227833 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Haq nawaz | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------|----------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 55 | | Cloth Market Joyia Road | 30.15702 | 72.68193 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | mumtaz hussain | |
| 56 | | Cloth Market Joyia Road | 30.15704833 | 72.68208167 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m ashraf | |
| 57 | | Cloth Market Joyia Road | 30.15708167 | 72.68224667 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m ismail | |
| 58 | | Cloth Market Joyia Road | 30.15707167 | 72.68227833 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m sadique | |
| 59 | | Cloth Market Joyia Road | 30.15714833 | 72.68228833 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Khushi muhammad | |
| 60 | | Cloth Market Joyia Road | 30.1572 | 72.681905 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | falak share | |
| 61 | | Cloth Market Joyia Road | 30.15719167 | 72.68195333 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Hakim ali | |
| 62 | | Cloth Market Joyia Road | 30.15729167 | 72.682005 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Abdul rehman | |
| 63 | | Cloth Market Joyia Road | 30.15722167 | 72.68208833 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Abdul rehman | |
| 64 | | Cloth Market Joyia Road | 30.15722 | 72.68216167 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m ali | |
| 65 | | Cloth Market Joyia Road | 30.15723333 | 72.68219333 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Abdul aziz | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|---------------|----------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 66 | | Cloth Market Joyia Road | 30.15739333 | 72.68226667 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m haneef | |
| 67 | | Cloth Market Joyia Road | 30.15722333 | 72.68221833 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m waryam | |
| 68 | | Cloth Market Joyia Road | 30.1571 | 72.68221667 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | barkat ali | |
| 69 | | Cloth Market Joyia Road | 30.15697833 | 72.682235 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m ashraf | |
| 70 | | Cloth Market Joyia Road | 30.157045 | 72.68219 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m ali | |
| 71 | | Cloth Market Joyia Road | 30.157125 | 72.68236833 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m iqbal | |
| 72 | | Cloth Market Joyia Road | 30.15691833 | 72.68219167 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Abdul Aziz | |
| 73 | | Cloth Market Joyia Road | 30.15687833 | 72.682225 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m ali | |
| 74 | | Cloth Market Joyia Road | 30.15688333 | 72.68229 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Abdul shakoor | |
| 75 | | Cloth Market Joyia Road | 30.157045 | 72.68214167 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m akram | |
| 76 | | Cloth Market Joyia Road | 30.15698167 | 72.68204667 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | hadayat ullah | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|---------------|----------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 77 | | Cloth Market Joyia Road | 30.15709 | 72.68206667 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Nazir Ahmed | |
| 78 | | Cloth Market Joyia Road | 30.15694667 | 72.68209167 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Talib Hussain | |
| 79 | | Cloth Market Joyia Road | 30.15706167 | 72.68211833 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Rashid Ahmed | |
| 80 | | Cloth Market Joyia Road | 30.15705833 | 72.68213667 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | zakir hussain | |
| 81 | | Cloth Market Joyia Road | 30.15704333 | 72.68195333 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m hanif | |
| 82 | | Cloth Market Joyia Road | 30.15706833 | 72.681945 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m ameen | |
| 83 | | Cloth Market Joyia Road | 30.15717833 | 72.68181167 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | safadr ali | |
| 84 | | Cloth Market Joyia Road | 30.157305 | 72.68188333 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m asgar | |
| 85 | | Cloth Market Joyia Road | 30.15694167 | 72.682115 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m rashid | |
| 86 | | Cloth Market Joyia Road | 30.15696333 | 72.68200167 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m anawar | |
| 87 | | Cloth Market Joyia Road | 30.15715 | 72.68185667 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m sadique | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|---------------|----------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 88 | | Cloth Market Joyia Road | 30.15717833 | 72.68186167 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Nazir ali | |
| 89 | | Cloth Market Joyia Road | 30.1572 | 72.681915 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | zulifqar Ali | |
| 90 | | Cloth Market Joyia Road | 30.15719 | 72.68191333 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Abdul rasheed | |
| 91 | | Cloth Market Joyia Road | 30.15707667 | 72.68192833 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Masood ahmed | |
| 92 | | Cloth Market Joyia Road | 30.15703667 | 72.68194333 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | akbar ali | |
| 93 | | Cloth Market Joyia Road | 30.15706 | 72.68196667 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | ghulam qadir | |
| 94 | | Cloth Market Joyia Road | 30.15708333 | 72.68190167 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Abdul Rafiq | |
| 95 | | Cloth Market Joyia Road | 30.15703 | 72.681945 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | saif rehman | |
| 96 | | Cloth Market Joyia Road | 30.15735167 | 72.681815 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | m ramzan | |
| 97 | | Cloth Market Joyia Road | 30.15763333 | 72.68195833 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | ghulam nabi | |
| 98 | | Cloth Market Joiya Road | 30.15752667 | 72.68157833 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ahmed din | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------|-------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 99 | | Cloth Market Joiya Road | 30.15741167 | 72.68179333 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Abdul Latif | |
| 100 | | Cloth Market Joiya Road | 30.15746667 | 72.68173 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | sardar muhammad | |
| 101 | | Cloth Market Joiya Road | 30.15720333 | 72.681875 | 64 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | maqsood ahmed | |
| 102 | | Cloth Market Joiya Road | 30.15749667 | 72.681875 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | jalal din | |
| 103 | | Cloth Market Joiya Road | 30.15729333 | 72.68199667 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | m khushi | |
| 104 | | Cloth Market Joyia Road | 30.15702667 | 72.68211833 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m younus | |
| 105 | 16070 | Joiya Road | 30.15726333 | 72.683445 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Fayaz | A1 Electronic s |
| 106 | 27032 | Wapda Daftar | 30.15884833 | 72.67745333 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Aamir | aamir qasab |
| 107 | | Food Grain Dokanat | 30.15678 | 72.67935667 | 60 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Adnan | Aari works |
| 108 | 21028 | Androon Sabaz Mandi | 30.159015 | 72.68178333 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Hamza | abaiya collection |
| 109 | 23017 | Tehsil Council | 30.15952667 | 72.68230833 | 56 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Abbas | Abbas Jewelers |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------------|----------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 110 | 23018 | Tehsil Council | 30.15947 | 72.682355 | 56 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Abbas | Abbas Jewelers |
| 111 | | Cloth Market Joyia Road | 30.15737833 | 72.68174167 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | abbas | abbas tailors |
| 112 | 6003 | Chongi dukanaat | 30.15682833 | 72.68118333 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Shamas ul Haq(2shops) | Abdul haq karyana store |
| 113 | | Cloth Market Joyia Road | 30.15756667 | 72.68246333 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Abdul kareem | Abdul kareem general store |
| 114 | 12039 | Food Grain Road | 30.15633167 | 72.679825 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Abdul Majeed | Abdul majeed bans shop |
| 115 | | Cloth Market Joyia Road | 30.1574 | 72.681865 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhamma d abdulah | abdulah ashla shop |
| 116 | | Cloth Market Joyia Road | 30.15779333 | 72.68197833 | 64 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | zulfiqar ali | abdullah cloth house |
| 117 | 27027 | Wapda Daftar | 30.158835 | 72.67765667 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | abdul hameed | abdullah welding store |
| 118 | 1052 | arif bazar | 30.16164833 | 72.685005 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Ramzan | Abid electronics |
| 119 | 23012 | Tehsil Council | 30.15952167 | 72.68216667 | 56 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Usman | Abid Jewelers |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|----------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|----------------|-----------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 120 | 16002 | Joiya Road | 30.15771 | 72.68561667 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Adnan | adnan autos |
| 121 | 19015 | Purani Tehsil | 30.156915 | 72.68173333 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Adnan | adnan karyana store |
| 122 | 3004 | Barshian Gass Vehari Bazar | 30.15952333 | 72.675465 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | adnan | Adnan nazeer electric store |
| 123 | 16042 | Joiya Road | 30.15753667 | 72.68451333 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Shabir | adnan number plate |
| 124 | 21013 | Sabaz Mandi Gol Chowk | 30.15915167 | 72.68207833 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | ghulam murtaza | Adnan shoping center |
| 125 | 10011 | Fire Brigade | 30.16105333 | 72.67192333 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Afzal | afzal autos |
| 126 | | Cloth Market Joyia Road | 30.15754667 | 72.68182 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | afzal | afzal gold smith |
| 127 | | Cloth Market Joyia Road | 30.15757 | 72.682155 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | afzal | afzal gold smith |
| 128 | 2019 | Barlab Nehar Vehari Bazar | 30.16049167 | 72.67395167 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ahmad | ahmad autos |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|------------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|----------------|---------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 129 | 9061 | Dokanat Vehari Bazar | 30.158755 | 72.679115 | 48 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Waqar Ahmad | ahmad jewelers |
| 130 | | Cloth Market Joyia Road | 30.15755667 | 72.68231167 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | ahmad | ahmad jewelers |
| 131 | 8051 | Deewar High School | 30.16283667 | 72.68599167 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | tayyab | ahmad medical store |
| 132 | 8052 | Deewar High School | 30.162845 | 72.68601667 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | tayyab | ahmad medical store |
| 133 | 8053 | Deewar High School | 30.16271 | 72.68597333 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | tayyab hussain | ahmad medical store |
| 134 | 18001 | Near Gate Ghala Mandi | 30.157295 | 72.67914 | 70 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ahmad Ali | ahmad pan shop |
| 135 | 15078 | Joiya Market Dokanaat | 30.15714833 | 72.683155 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | ahsaan | ahsaan electric |
| 136 | 22023 | Joiya Road | 30.15643 | 72.67991833 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ahsan | Ahsan joiya traders |
| 137 | | Cloth Market Joyia Road | 30.15752833 | 72.68249667 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | ahsan | ahsan store |
| 138 | | Cloth Market Joyia Road | 30.15761667 | 72.68221333 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | waseem | ak fabrics |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------|-------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 139 | 16094 | Joiya Road | 30.15717833 | 72.68333 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Asghar | akber brother sangar |
| 140 | 16093 | Joiya Road | 30.157245 | 72.68331167 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Asghar ameen | akber brothers |
| 141 | 12014 | Food Grain Road | 30.15649167 | 72.6805 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Abid Hussain | akber gujjar chara tall |
| 142 | 15060 | Joiya Market Dokanaat | 30.15706667 | 72.68277167 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Alyas | akber sangar |
| 143 | 1034 | arif bazar | 30.161095 | 72.684685 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Akhtar | akhter watch house |
| 144 | | Cloth Market Joyia Road | 30.15735 | 72.68246167 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Akmal | akmal cloth house |
| 145 | 15035 | Joiya Market Dokanaat | 30.156915 | 72.681785 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Akram | akram karyana store |
| 146 | | Cloth Market Joyia Road | 30.15776333 | 72.68199833 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m akram | akram kasheda kari |
| 147 | 16075 | Joiya Road | 30.15725833 | 72.683745 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M SHafi | akram store |
| 148 | 6002 | Chongi dukanaat | 30.1568 | 72.68126333 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ghulam Rasool | al aziz traders |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-----------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|----------------------|-------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 149 | 15039 | Joiya Market Dokanaat | 30.15673667 | 72.68171833 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Munawar Hussain | al fareed general store |
| 150 | 9023 | Dokanat Vehari Bazar | 30.15894 | 72.68002167 | 48 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Sultan begh | al habib wan store |
| 151 | 10031 | Fire Brigade | 30.16114333 | 72.67152667 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | muzaffar hussain | al harmain composin g |
| 152 | 8011 | Deewar High School | 30.1622 | 72.68549 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Sadeeqa Bibi | al kareem mobiles |
| 153 | 15013 | Joiya Market Dokanaat | 30.15700167 | 72.68237667 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Shaukat Ali | Al masoom jewelers |
| 154 | 15082 | Joiya Market Dokanaat | 30.15720333 | 72.683205 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Nawaz | al mudassir |
| 155 | 16001 | Joiya Road | 30.15770667 | 72.685805 | 98 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhamma d Naem Akram | al noor iron store |
| 156 | 1008 | arif bazar | 30.160515 | 72.68411333 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Farhan | Al qaim mobiles |
| 157 | 15038 | Joiya Market Dokanaat | 30.15688333 | 72.68168833 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Munawar Hussain | Alfareed general store |
| 158 | 1053 | Arif Bazar | 30.16045667 | 72.68406833 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Sajid Ali | Ali barbar |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-----------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|----------------|--------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 159 | | Cloth Market Joyia Road | 30.15766167 | 72.68168833 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Ali raza | Ali cloth house |
| 160 | | Cloth Market Joyia Road | 30.15766167 | 72.68168833 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | ali | Ali cloth house |
| 161 | | Cloth Market Joyia Road | 30.15766167 | 72.68168833 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Ali | Ali cloth house |
| 162 | 8034 | Deewar High School | 30.162535 | 72.68576667 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Imran | ali imran electronics |
| 163 | 23003 | Tehsil Council | 30.15912667 | 72.68236667 | 56 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Tariq | Ali jewelers |
| 164 | 10017 | Fire Brigade | 30.161005 | 72.671785 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Asif | Ali raza photo state |
| 165 | 10016 | Fire Brigade | 30.16090667 | 72.67189667 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | adnan | ali raza photostate |
| 166 | 4001 | Cantine Park Housing Scheme | 30.15824667 | 72.67112333 | 36 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Aftab Nazir | Ali super karyana store |
| 167 | 9010 | Dokanat Vehari Bazar | 30.15896833 | 72.68037333 | 96 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Javed Khan | Ali wan store |
| 168 | 22021 | Joiya Road | 30.15642 | 72.67998167 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Sadiq | Allah hoo comission shop |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|----------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|--------------------------|------------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 169 | 13010 | General Bus Stand | 30.16378167 | 72.68574667 | 112 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Rana Sajjad/Hammad Ahmad | Allah tawakal motor workshop |
| 170 | | Cloth Market Joyia Road | 30.15757333 | 72.68185833 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Fair | Abdul Rehman | Almeer Mobile shop |
| 171 | 22017 | Joiya Road | 30.15650167 | 72.68017167 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | altaf | altaf wooden works |
| 172 | 9043 | Dokanat Vehari Bazar | 30.15889667 | 72.67954167 | 48 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M waseem | alvi mobile |
| 173 | 7010 | Darbaar Vehari Bazar | 30.16054333 | 72.672735 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Ashraf Alwi | alwi mobiles |
| 174 | 7011 | Darbaar Vehari Bazar | 30.16056333 | 72.672735 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Ashraf Alwi | alwi mobiles |
| 175 | 15019 | Joiya Market Dokanaat | 30.15695833 | 72.68221167 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Ameen | ameen coil house |
| 176 | | Water Works Collony | 30.16041667 | 72.67354667 | 60 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M ameen | ameen honda service |
| 177 | 3001 | Barshian Gass Vehari Bazar | 30.15947 | 72.67553 | 98 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Tahir | ameen karyana store |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|--------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|---------------|---------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 178 | 22016 | Joiya Road | 30.15650833 | 72.68020833 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | iqbal | ameen motors |
| 179 | 8005 | Deewar High School | 30.16177833 | 72.68507833 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Imran Waheed | amir book center |
| 180 | 10010 | Fire Brigade | 30.16099167 | 72.67192667 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | nayamat ali | amir paint house |
| 181 | 9069 | Dokanat Vehari Bazar | 30.15862167 | 72.678955 | 48 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Amjid | amjad iron store |
| 182 | 8058 | Deewar High School | 30.16286 | 72.68598167 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Azhar Behzaad | amjad medical store |
| 183 | 18002 | Near Gate Ghala Mandi | 30.15724333 | 72.67921333 | 60 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Amjid | amjad pan shop |
| 184 | 24001 | Tharra Jaat Lakkar mandi | 30.156895 | 72.67830333 | 108 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Abdul Ghafoor | ara 1 |
| 185 | 24002 | Tharra Jaat Lakkar mandi | 30.15693833 | 72.67829667 | 55.5 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Â Abdul Aziz | ara 2 |
| 186 | 24003 | Tharra Jaat Lakkar mandi | 30.156925 | 72.67834 | 55.5 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Â Abdul Aziz | ara 3 |
| 187 | 24004 | Tharra Jaat Lakkar mandi | 30.15694167 | 72.67843 | 108 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | liaqat ali | ara shop |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|--------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-------------------------------------|----------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 188 | 24005 | Tharra Jaat Lakkar mandi | 30.15694667 | 72.67846333 | 108 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | shahid | ara shop |
| 189 | 24006 | Tharra Jaat Lakkar mandi | 30.15691333 | 72.67861 | 141.3 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhamma d Akram / Muhamma d Shabire | ara shop |
| 190 | 24007 | Tharra Jaat Lakkar mandi | 30.156905 | 72.67862 | 137 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | liaqat | ara shop |
| 191 | 24008 | Tharra Jaat Lakkar mandi | 30.156925 | 72.67874833 | 211 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Saint shah | ara shop |
| 192 | 24009 | Tharra Jaat Lakkar mandi | 30.15686 | 72.67902667 | 105 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | shamshad ahmad | ara shop |
| 193 | 24010 | Tharra Jaat Lakkar mandi | 30.1569 | 72.67908833 | 105 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | shamshad | ara shop |
| 194 | 24026 | Tharra Jaat Lakkar mandi | 30.156825 | 72.67923667 | 211 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | mirza mukhtar | ara shop |
| 195 | 24021 | Tharra Jaat Lakkar mandi | 30.15677667 | 72.679235 | 600 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | waris | ara shop |
| 196 | 24020 | Tharra Jaat Lakkar mandi | 30.15676667 | 72.67920333 | 600 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | mirza ahmad ali | ara shop |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|--------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|--|----------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 197 | 24019 | Tharra Jaat Lakkar mandi | 30.15677667 | 72.679025 | 600 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | sadeeq | ara shop |
| 198 | 24018 | Tharra Jaat Lakkar mandi | 30.15669 | 72.679015 | 600 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Â Nasar Ahamd /Iftikhar Ahmad/ Mehmoood Tariq /Musht | ara shop |
| 199 | 24017 | Tharra Jaat Lakkar mandi | 30.15666 | 72.67896 | 600 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Sardar Muhammad /Muhammad Ali | ara shop |
| 200 | 24016 | Tharra Jaat Lakkar mandi | 30.15664833 | 72.67887833 | 600 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | iqbal | ara shop |
| 201 | 24015 | Tharra Jaat Lakkar mandi | 30.156615 | 72.67882667 | 73.6 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Â Muhammad Shafi | ara shop |
| 202 | 24013 | Tharra Jaat Lakkar mandi | 30.156615 | 72.678865 | 73.6 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Jamal Din | ara shop |
| 203 | 24012 | Tharra Jaat Lakkar mandi | 30.15656333 | 72.678755 | 73.6 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | rafeeq | ara shop |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|--------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|---|----------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 204 | 24011 | Tharra Jaat Lakkar mandi | 30.156565 | 72.678735 | 73.6 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Gulzar / Muhammad Wakeel/Naik Muhammad | ara shop |
| 205 | 24014 | Tharra Jaat Lakkar mandi | 30.15669667 | 72.67885833 | 73.6 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Â Khushi Muhammad | ara shop |
| 206 | 24022 | Tharra Jaat Lakkar mandi | 30.15676 | 72.678885 | 600 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Â Muhammad Jameel /Hanif Habib/Muhammad Saeed Qamer | ara shop |
| 207 | 24023 | Tharra Jaat Lakkar mandi | 30.15684 | 72.67884333 | 600 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | ramzan | ara shop |
| 208 | 24025 | Tharra Jaat Lakkar mandi | 30.15687833 | 72.67855 | 600 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Â Muhammad Rafique | ara shop |
| 209 | 24024 | Tharra Jaat Lakkar mandi | 30.15689167 | 72.67851667 | 600 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | ijaz | ara shop |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|------------------|----------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 210 | | Cloth Market Joyia Road | 30.15792667 | 72.68176167 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | zakir habib | araiz jewelers |
| 211 | 16022 | Joiya Road | 30.157615 | 72.68505167 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Ahsan | Arshad autos |
| 212 | | Cloth Market Joyia Road | 30.1574 | 72.68239 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | arshad | Arshad gold smith |
| 213 | 27028 | Wapda Daftar | 30.15884667 | 72.677665 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | arслан | arslam qasab |
| 214 | 8012 | Deewar High School | 30.16217333 | 72.685515 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Arslan Rasool | arslan general store |
| 215 | 8013 | Deewar High School | 30.162245 | 72.68551333 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Arslan | Arslan general store |
| 216 | 9002 | Dokanat Vehari Bazar | 30.15914667 | 72.68055667 | 48 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Arslan | Arslan Iron Store |
| 217 | 9003 | Dokanat Vehari Bazar | 30.15910333 | 72.68054167 | 48 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Anwar | Arslan Iron Store |
| 218 | | Cloth Market Joyia Road | 30.15746167 | 72.682 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhamma d sageer | arslan jewelry |
| 218 | 27007 | Wapda Daftar | 30.15865333 | 72.67816333 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Arslan | arslan works |
| 219 | | Cloth Market Joyia Road | 30.15736 | 72.68241 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | saif | Asad gold smith |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------|------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 220 | | Cloth Market Joyia Road | 30.15736333 | 72.68239667 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | saif | Asad gold smith |
| 221 | 9028 | Dokanat Vehari Bazar | 30.15895 | 72.6799 | 96 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Asad | asad rang walay |
| 222 | 22024 | Joiya Road | 30.15638833 | 72.67988667 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Asif | asaif cotton store |
| 223 | 27017 | Wapda Daftar | 30.15880833 | 72.67785333 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Asghar Ali | asghar alluminium shop |
| 224 | 27019 | Wapda Daftar | 30.15876833 | 72.67780167 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Shahid Ghafoor | asghar and sons |
| 225 | | Cloth Market Joyia Road | 30.157585 | 72.68219667 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | asghar | asghar cloth house |
| 226 | | Cloth Market Joyia Road | 30.15760833 | 72.68219833 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | asghar | asghar cloth house |
| 227 | 12061 | Food Grain Road | 30.15673833 | 72.68106333 | 144 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Waqar Asghar | asghar karyana store |
| 228 | 13006 | General Bus Stand | 30.163835 | 72.68576667 | 112 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ashiq Hussain | ashiq autos |
| 229 | 27023 | Wapda Daftar | 30.15884333 | 72.67776 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Ashraf | ashraf cycle works |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|------------------|-------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 230 | 9011 | Dokanat Vehari Bazar | 30.15916167 | 72.68039667 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m ashraf | Ashraf iron store |
| 231 | 9007 | Dokanat Vehari Bazar | 30.15910167 | 72.68041667 | 32 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Adnan Ashraf | Ashraf iron store |
| 232 | 9070 | Dokanat Vehari Bazar | 30.15866833 | 72.67896833 | 48 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | jawad | ashraf iron store |
| 233 | 9071 | Dokanat Vehari Bazar | 30.15865 | 72.67891333 | 48 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhamma d Ashraf | Ashraf iron store |
| 234 | | Cloth Market Joyia Road | 30.15766167 | 72.68168833 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | ashraf | ashraf jewelers |
| 235 | | Cloth Market Joyia Road | 30.15766167 | 72.68168833 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | ashraf | AsHraf jewelers |
| 236 | 16085 | Joiya Road | 30.15727 | 72.683505 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Ashraf | ashraf kabariyaa |
| 237 | 12059 | Food Grain Road | 30.15673333 | 72.68127 | 144 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M ashraf | ashraf pan shop |
| 238 | 23013 | Tehsil Council | 30.15952 | 72.68232 | 56 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Kamran | Asia Jewelers |
| 239 | 8030 | Deewar High School | 30.162445 | 72.68576 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Abdul Khaliq | Asif mobiles |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|----------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------|-----------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 240 | 7008 | Darbaar Vehari Bazar | 30.16056333 | 72.67278833 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Saleem Akhtar | Asif opticle |
| 241 | 12025 | Food Grain Road | 30.15644833 | 72.68032 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Asif | asif wood works |
| 242 | 3009 | Barshian Gass Vehari Bazar | 30.15969833 | 72.67517667 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Aslam | aslam cooler pas shop |
| 243 | 1042 | arif bazar | 30.161395 | 72.68476833 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Aslam | Aslam desi mithai |
| 244 | 9072 | Dokanat Vehari Bazar | 30.15865167 | 72.67886 | 70 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Aslam | aslam fruit shop |
| 245 | | Cloth Market Joyia Road | 30.156755 | 72.68224833 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Aslam | Aslam jewelry |
| 246 | 22004 | Joiya Road | 30.15675167 | 72.68116667 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Aslam | atari karyana store |
| 247 | 22005 | Joiya Road | 30.15673167 | 72.681195 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Faryad Ahmad | atari karyana store |
| 248 | 12032 | Food Grain Road | 30.15643333 | 72.67983667 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Sabir Ali | Atta chakki |
| 249 | 12033 | Food Grain Road | 30.15638333 | 72.67981833 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Sabir Ali | Atta chakki |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|--------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|------------------|-------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 250 | 12034 | Food Grain Road | 30.15633333 | 72.67989333 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Sabir Ali | Atta chakki |
| 251 | 12035 | Food Grain Road | 30.156365 | 72.67992 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Sabir Ali | Atta chakki |
| 252 | 12036 | Food Grain Road | 30.156315 | 72.67991667 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M yameen Sajid | atta chakki |
| 253 | 12037 | Food Grain Road | 30.15632167 | 72.67992667 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Sabir Ali | Atta chakki |
| 254 | 16053 | Joiya Road | 30.157435 | 72.68429 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | ashfaaq | attar wala motors |
| 255 | 2009 | Barlab Nehar Vehari Baza | 30.16049 | 72.674055 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | m shareef | awais autos |
| 256 | 1038 | arif bazar | 30.16121333 | 72.68469333 | 36 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Shafiq Shahzad | Awais cycle store |
| 257 | 23014 | Tehsil Council | 30.15954833 | 72.68228167 | 56 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Abdul Malik | Awais Jewelers |
| 258 | 1039 | arif bazar | 30.161265 | 72.68474833 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | waseem jutt | awais mobile |
| 259 | 8010 | Deewar High School | 30.16218 | 72.68547167 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Awais | Awais mobiles |
| 260 | 16059 | Joiya Road | 30.15758333 | 72.68437333 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | shahbaz ahmad | awais motors |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-----------------------|-------------|------------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|----------------|-------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 261 | 8041 | Deewar High School | 30.16268833 | 72.68592167 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Akram | awami band |
| 262 | 15024 | Joiya Market Dokanaat | 30.15695333 | 72.68210667 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Shahid | azan traders |
| 263 | 19012 | Purani Tehsil | 30.15688667 | 72.68179833 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Azeem | azeem gurr shop |
| 264 | 8024 | Deewar High School | 30.16241167 | 72.685695 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Azeem | azeem optical |
| 265 | 6001 | Chongi dukanaat | 30.15684333 | 72.68123167 | 48 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ghulam Rasool | Azeez traders |
| 266 | 27008 | Wapda Daftar | 30.15870667 | 72.67811833 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Shahid | azhar tea stall |
| 267 | 9056 | Dokanat Vehari Bazar | 30.15872833 | 72.67918667 | 48 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Azhar Khan | azhar wan shop |
| 268 | 15043 | Joiya Market Dokanaat | 30.15677167 | 72.68167167 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ilam Din | baba boota store |
| 269 | 15042 | Joiya Market Dokanaat | 30.15677333 | 72.68168 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ilam Din | baba bota dry fruit |
| 270 | 8042 | Deewar High School | 30.16257833 | 72.68589 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Ijaz | baba fareed electronics |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|----------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|----------------|------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 271 | 11006 | Food Grain Dokanat | 30.15659833 | 72.67941667 | 238 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Imtiaz ali | baba fareed iron store |
| 272 | 11005 | Food Grain Dokanat | 30.15666667 | 72.67940667 | 224 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ahmad Ali | baba fareed iron store |
| 273 | 8043 | Deewar High School | 30.16269167 | 72.68594167 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhamma d Ijaz | baba farid electronics |
| 274 | 22003 | Joiya Road | 30.156735 | 72.68129667 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Anwar | baba golden dry fruit |
| 275 | 16064 | Joiya Road | 30.15734333 | 72.68398167 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Yameen | badar electronics |
| 276 | 9015 | Dokanat Vehari Bazar | 30.15862333 | 72.67909333 | 48 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Zulifqar Ali | badar watch house |
| 277 | 9064 | Dokanat Vehari Bazar | 30.15861 | 72.67902333 | 48 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Iftikhar Ali | badar watch house |
| 278 | 23022 | Tehsil Council | 30.15949833 | 72.68229833 | 56 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Shabir | Bag shop |
| 279 | 23023 | Tehsil Council | 30.159475 | 72.68241167 | 56 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Aslam | Bag shop |
| 280 | 16073 | Joiya Road | 30.15721 | 72.683235 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Rashid | baho electric |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|--------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|----------------------|----------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 281 | 21021 | Androon Sabaz Mandi | 30.15931667 | 72.68208333 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Shafiq Ahmad | bangle shop |
| 282 | 12040 | Food Grain Road | 30.15632333 | 72.67983 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Abdul Majeed | bans shop |
| 283 | 12017 | Food Grain Road | 30.15645833 | 72.68036333 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Aleem Khan | bans store |
| 284 | 26006 | Vehari Bazar Water Works | 30.16061833 | 72.67302833 | 96 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ishtaq Ahmad | bao ishtiaq store |
| 285 | 15083 | Joiya Market Dokanaat | 30.15720333 | 72.683265 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Imran | bao sangar |
| 286 | 12027 | Food Grain Road | 30.15641667 | 72.68011667 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Shahid Bari | Bari motors |
| 287 | 12028 | Food Grain Road | 30.156365 | 72.68012667 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Majid Bari | Bari motors |
| 288 | 12029 | Food Grain Road | 30.15640667 | 72.68013167 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Majid Bari | bari motors |
| 289 | | Cloth Market Joyia Road | 30.15733167 | 72.68216167 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Ali raza | barkat ali jewelers |
| 290 | 10029 | Fire Brigade | 30.16120667 | 72.67158333 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Ramzan | barkat karyana store |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|--------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------|-----------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 291 | 10030 | Fire Brigade | 30.161115 | 72.671625 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Ramzan | barkat karyana store |
| 292 | 16028 | Joiya Road | 30.15761333 | 72.68474 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Nadeem bhatti | barkat motors |
| 293 | 2016 | Barlab Nehar Vehari Baza | 30.16050833 | 72.67430833 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | rizwan bhatti | barkat rent a car |
| 294 | 8056 | Deewar High School | 30.162865 | 72.68605333 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | m naseer | basheer karyana store |
| 295 | 10045 | Fire Brigade | 30.16142 | 72.67187833 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Bashir | bashir and company |
| 296 | 27036 | Wapda Daftar | 30.15890667 | 72.67738833 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Ibadat Ali | bashir dawakhan a |
| 297 | 15002 | Joiya Market Dokanaat | 30.15708833 | 72.68257833 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ali Raza Akram | bashir khalil works |
| 298 | 27035 | Wapda Daftar | 30.15897 | 72.677445 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Raiz Ahmad | bashir pansar store |
| 299 | 16020 | Joiya Road | 30.15763333 | 72.684855 | 81 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Mouzzam | bhutta autos |
| 300 | 16021 | Joiya Road | 30.15767667 | 72.68508 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muazzam bhutta | bhutta autos |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|--------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|------------------|--------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 301 | 9004 | Dokanat Vehari Bazar | 30.15917333 | 72.68048833 | 64 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Bilal Ashraf | Bilal Iron store |
| 302 | 8048 | Deewar High School | 30.16275333 | 72.68601833 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ghulam Nabi | bilal medical store |
| 303 | 22022 | Joiya Road | 30.15638333 | 72.67997667 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Bilal | Bilal super store |
| 304 | 28005 | Water Works Collony | 30.16044167 | 72.67352333 | 60 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Ishaq | bismillah autos |
| 305 | 2001 | Barlab Nehar Vehari Baza | 30.16041167 | 72.67383667 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Saleem | bismillah hotel |
| 306 | 2002 | Barlab Nehar Vehari Baza | 30.16039667 | 72.67385333 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | saleem | bismillah hotel |
| 307 | 16016 | Joiya Road | 30.15764833 | 72.68521833 | 98 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhamma d Nadeem | Bismillah Motors |
| 308 | 16044 | Joiya Road | 30.15747 | 72.684495 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhamma d Anwar | bismillah number plate |
| 309 | 22025 | Joiya Road | 30.15639 | 72.67988 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Qurban Zafar | Bismillah pakwaan center |
| 310 | 22027 | Joiya Road | 30.15638167 | 72.67984333 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Numan Sarwar | Bismillah pakwaan store |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------|-----------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 311 | 27012 | Wapda Daftar | 30.158715 | 72.67809667 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Maqsood Ahmad | bismillah steel works |
| 312 | | Food Grain Dokanat | 30.15684333 | 72.67931167 | 144 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Bashir Ahmad | bismillah wood works |
| 313 | 15027 | Joiya Market Dokanaat | 30.15701 | 72.681965 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Hasnain Parveez | bobi photo studio |
| 314 | | Cloth Market Joyia Road | 30.15728667 | 72.68186333 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Nazir ahmed | book shop |
| 315 | | Cloth Market Joyia Road | 30.15741 | 72.68191 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muneeb | book shop |
| 316 | | Cloth Market Joyia Road | 30.15737833 | 72.68182833 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Khalid | Book Store |
| 317 | 28015 | Water Works Collony | 30.16050333 | 72.67329333 | 60 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Malik javed | boota honda service |
| 318 | 28019 | Water Works Collony | 30.160545 | 72.67321167 | 60 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Aslam | boots autos |
| 319 | 10002 | Fire Brigade | 30.16097333 | 72.67212167 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ali haider | burewala number plate |
| 320 | 9032 | Dokanat Vehari Bazar | 30.15904833 | 72.67984667 | 96 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Sajjad | butt bartan shop |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-----------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|----------------|---------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 321 | 1031 | arif bazar | 30.16109333 | 72.68456667 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Waseem Sadiq | butt electric store |
| 322 | 15056 | Joiya Market Dokanaat | 30.15709833 | 72.68268 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Abdul Rehman | Ch hotel |
| 323 | 15055 | Joiya Market Dokanaat | 30.15715667 | 72.68265333 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ali Ahmad | Ch hotel |
| 324 | 15054 | Joiya Market Dokanaat | 30.15710167 | 72.68269333 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Noor Ahmad | ch hotel |
| 325 | 6008 | Chongi dukanaat | 30.15669833 | 72.68111667 | 200 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Aslam | chahat sweets |
| 326 | 10032 | Fire Brigade | 30.16118 | 72.671595 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Arshad Ahmad | chamman food point |
| 327 | 10040 | Fire Brigade | 30.16143 | 72.67178833 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Awar | chand auto store |
| 328 | 28011 | Water Works Collony | 30.16050667 | 72.673405 | 60 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M farooq | chand autos |
| 329 | 8036 | Deewar High School | 30.162585 | 72.685935 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Chand | Chand electronics |
| 330 | 8037 | Deewar High School | 30.16257667 | 72.68584333 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | chand | chand electronics |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|----------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|----------------------|-------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 331 | 16045 | Joiya Road | 30.15746667 | 72.68447167 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Sultan | cheema motors |
| 332 | 8039 | Deewar High School | 30.16264667 | 72.685955 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | chand | close shop |
| 333 | | Cloth Market Joyia Road | 30.15777167 | 72.68176 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Saji Mehmood | cloth depot |
| 334 | 21003 | Sabaz Mandi Gol Chowk | 30.15878833 | 72.68186333 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Aslam+ M Ashraf | cousins bootique |
| 335 | 16019 | Joiya Road | 30.15753833 | 72.68521333 | 98 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Asif shehzad | Dastageer number plates |
| 336 | 16060 | Joiya Road | 30.157375 | 72.68406167 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Mohsin Zahoor Bhatti | dastgeer motors |
| 337 | 16061 | Joiya Road | 30.15737333 | 72.684065 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Mohsin Zahoor | dastgeer motors |
| 338 | 3006 | Barshian Gass Vehari Bazar | 30.15952 | 72.67539167 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Imran kashif | data burger store |
| 339 | 16012 | Joiya Road | 30.15769667 | 72.68527833 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Barkat ali | Data motors |
| 340 | 12003 | Food Grain Road | 30.15658667 | 72.68074667 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Latif | data walay goods |
| 341 | 16063 | Joiya Road | 30.15737333 | 72.68404333 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | majeed | deewan motors |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|---------------------------------|-----------------|-----------------|------------------------------------|---------------|--------------------------|-------------------|---------------------|------------------|-------------------|---------------------------------------|-------------------|------------------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 342 | 27001 | Wapda Daftar | 30.158636 67 | 72.67829 | 49 | 2 | Commercial | Owned/ Managed | No | No | Rented/ Leased | Good | Maqbool | delta power solar company |
| 343 | 1017 | arif bazar | 30.16072 | 72.68427 | 36 | 2 | Commercial | Owned/ Managed | No | No | Rented/ Leased | Good | Sadiq Maqsood | diamond jewelers |
| 344 | 1055 | arif bazar | 30.160925 | 72.684433 33 | 84 | 2 | Commercial | Owned/ Managed | No | No | Rented/ Leased | Good | dilbar hussain | dilbar foam house |
| 345 | 7005 | Darbaar Vehari Bazar | 30.160526 67 | 72.672866 67 | 80 | 2 | Commercial | Owned/ Managed | No | No | Rented/ Leased | Good | Iqbal Hussain | dish sale point |
| 346 | 2008 | Barlab Nehar Vehari Baza | 30.160446 67 | 72.674086 67 | 80 | 2 | Commercial | Owned/ Managed | No | No | Rented/ Leased | Good | M Shareef | dress care dry clean |
| 347 | 14005 | Goal Chowk Phari Haye | 30.159098 33 | 72.681788 33 | 90 | 2 | Commercial | Owned/ Managed | No | No | Rented/ Leased | Good | Rao amir | Dubai shoes |
| 348 | 21018 | Androon Sabaz Mandi | 30.159228 33 | 72.682066 67 | 480 | 2 | Commercial | Owned/ Managed | No | No | Rented/ Leased | Good | Haji ashraf | dubai shoes |
| 349 | 2018 | Barlab Nehar Vehari bazar | 30.16045 | 72.67394 | 80 | 2 | Commercial | Owned/ Managed | No | Yes | Rented/ Leased | Good | Faisal Rehman | faisal motors |
| 350 | 14003 | Goal Chowk Phari Haye | 30.159091 67 | 72.68172 | 90 | 2 | Commercial | Owned/ Managed | No | No | Rented/ Leased | Good | Faiz Ahmad | Faiz shoes |
| 351 | | Cloth Market Joyia Road | 30.157288 33 | 72.682063 33 | 64 | 2 | Commercial | Owned/ Managed | No | Yes | Rented/ Leased | Good | Muhamma d Amin | Faizan jewelry |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-----------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|----------------|--------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 352 | 1018 | arif bazar | 30.16076167 | 72.68424 | 36 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Excellent | Ahsan Saddique | fancy jewelers |
| 353 | 28008 | Water Works Collony | 30.16045833 | 72.67347333 | 60 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Farooq | fareed autos |
| 354 | 13003 | General Bus Stand | 30.16355167 | 72.68605667 | 112 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Ather Saed | fareed coch |
| 355 | 22028 | Joiya Road | 30.15639167 | 72.67976 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ashfaq Ahmad | Fareed cycle store |
| 356 | 16051 | Joiya Road | 30.15743667 | 72.68434833 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | ashfaaq | fareed naan shop |
| 357 | 16052 | Joiya Road | 30.15744167 | 72.6843 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | ashfaaq | fareed naan shop |
| 358 | 16049 | Joiya Road | 30.157445 | 72.68431833 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | ashfaq | fareed nan shop |
| 359 | 16050 | Joiya Road | 30.15744667 | 72.68437333 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | ashfaaq | fareed nan shop |
| 360 | 12047 | Food Grain Road | 30.15630833 | 72.67970167 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | ishfaq goga | fareed steel works |
| 361 | 15005 | Joiya Market Dokanaat | 30.15713 | 72.68260167 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Shafiq | fareed tea stall |
| 362 | 14011 | Goal Chowk Phari Haye | 30.159415 | 72.68182333 | 50 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Ikram | farhan javed shoes |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|--------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------|----------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 363 | 9012 | Dokanat Vehari Bazar | 30.159005 | 72.68029333 | 96 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Umar Farooq | farooq wan store |
| 364 | 9013 | Dokanat Vehari Bazar | 30.15904167 | 72.680305 | 96 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Farooq Ahmad | farooq wan store |
| 365 | 27018 | Wapda Daftar | 30.15884333 | 72.67786667 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | faryad | faryad autos |
| 366 | 16090 | Joiya Road | 30.15727167 | 72.683385 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | muzamil | farzam autos store |
| 367 | 16089 | Joiya Road | 30.15719167 | 72.68316833 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muzamma I | farzan autos |
| 368 | 21008 | Sabaz Mandi Gol Chowk | 30.15902833 | 72.682055 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Faqeer Muhammad | fashion jewelers |
| 369 | 2010 | Barlab Nehar Vehari Baza | 30.16046833 | 72.67407333 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | umer | fatafat number plate |
| 370 | | Cloth Market Joyia Road | 30.15716667 | 72.68268167 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m asharf | food point |
| 371 | 16058 | Joiya Road | 30.15737333 | 72.68413833 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Hamid ali | friend motors |
| 372 | 23024 | Tehsil Council | 30.15953333 | 72.68252333 | 56 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Saeed Ahmad | Fruit shop |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|----------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------------|------------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 373 | 27005 | Wapda Daftar | 30.15857333 | 72.678185 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | muhammad ashraf anjum | gezer wooden shop |
| 374 | 3003 | Barshian Gass Vehari Bazar | 30.15960167 | 72.67552833 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Abdul hanan | ghazi electronics |
| 375 | 6007 | Chongi dukanaat | 30.15678667 | 72.68111833 | 200 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Sabir Hussain | ghousia auto service |
| 376 | 7009 | Darbaar Vehari Bazar | 30.16053167 | 72.67276333 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Basharat ali | ghousia autos |
| 377 | 10038 | Fire Brigade | 30.16140333 | 72.67172 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Khalil Amjid | ghousia milk point |
| 378 | 22018 | Joiya Road | 30.15646833 | 72.68012 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Aslam | Ghousia tailors |
| 379 | 12019 | Food Grain Road | 30.15643667 | 72.680285 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Aslam | ghousia tailors |
| 380 | 15036 | Joiya Market Dokanaat | 30.15676833 | 72.6818 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ghulam Mustafa | ghulam mustafa karyana store |
| 381 | 15037 | Joiya Market Dokanaat | 30.15695167 | 72.68178167 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ghulam Mustafa | ghulam mustafa karyana store |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-----------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|---------------|------------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 382 | | Joiya Market Dokanaat | 30.15691 | 72.681855 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | ghulam rasool | ghulam rasool karyana store |
| 383 | 15030 | Joiya Market Dokanaat | 30.15690167 | 72.68193 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ghulam Rasool | ghulam rasool karyana store |
| 384 | 15031 | Joiya Market Dokanaat | 30.15686833 | 72.681915 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ghulam Rasool | ghulam rasool karyana store |
| 385 | 15033 | Joiya Market Dokanaat | 30.15688 | 72.68187667 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ghulam Rasool | ghulam rasool karyana store |
| 386 | 15032 | Joiya Market Dokanaat | 30.156875 | 72.68190167 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ghulam Rasool | ghulam rassool karyana store |
| 387 | 28010 | Water Works Collony | 30.16051333 | 72.67342833 | 60 | 12 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Anwar | gilani motors |
| 388 | 16082 | Joiya Road | 30.15730167 | 72.683475 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Abdul ghaffar | GM Electrician |
| 389 | 12058 | Food Grain Road | 30.15629167 | 72.67938333 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Bashir Ahmad | gujjar bans store |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------------|----------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 390 | 1020 | arif bazar | 30.16079167 | 72.68431 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Bilal | gulshan mobile |
| 391 | | Cloth Market Joyia Road | 30.15743833 | 72.682345 | 120 | 1 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | gulzar | gulzar jewelers |
| 392 | 8015 | Deewar High School | 30.16218 | 72.68553667 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhamma d Amjad Saeed | habib electric works |
| 393 | 15007 | Joiya Market Dokanaat | 30.15699833 | 72.68249 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Waqas | habib motors |
| 394 | 15008 | Joiya Market Dokanaat | 30.15705833 | 72.682485 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Waqas | habib motors |
| 395 | 10003 | Fire Brigade | 30.16102333 | 72.67213333 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | hafiz umair | hafiz autos |
| 396 | 25004 | Vehari Bazar 1-A | 30.16018333 | 72.67404667 | 40 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Jamsheed | hafiz chicken broast |
| 397 | 15073 | Joiya Market Dokanaat | 30.15714333 | 72.68303833 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Hafiz Maqsood Ahmad | hafiz electric |
| 398 | 28006 | Water Works Collony | 30.16028833 | 72.67360833 | 60 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Iftikhar Hussain | hafiz electric works |
| 399 | 9052 | Dokanat Vehari Bazar | 30.15880333 | 72.67928167 | 48 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Taimoor | Hafiz Mobile |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|----------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|------------------|-----------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 400 | 1045 | arif bazar | 30.16140667 | 72.68487833 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Orangzaib Atif | hafiz mobiles |
| 401 | 9018 | Dokanat Vehari Bazar | 30.15899333 | 72.680175 | 48 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Israr Khan | hafiz seed shop |
| 402 | 16065 | Joiya Road | 30.15732 | 72.68393167 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Ashraf | haider motors |
| 403 | 9008 | Dokanat Vehari Bazar | 30.15911833 | 72.68033833 | 48 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Maqbool Ahmad | Haji anayat iron store |
| 404 | 9009 | Dokanat Vehari Bazar | 30.15915333 | 72.68038833 | 48 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Saqib Maqbool | Haji Anayat Iron store |
| 405 | 10044 | Fire Brigade | 30.16133833 | 72.67183167 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Bashir | haji bashir and company |
| 406 | 22014 | Joiya Road | 30.15658667 | 72.68056 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Shahbaz Shekh | haji faqeer ghee |
| 407 | 22013 | Joiya Road | 30.15658167 | 72.68056167 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Zabair | Haji faqeer ghee industries |
| 408 | 22015 | Joiya Road | 30.15659167 | 72.68058333 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Umair ahmed khan | haji faqeer ghee industries |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-----------------------|-----------------|-----------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------|-------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 409 | 15052 | Joiya Market Dokanaat | 30.15671 | 72.68128 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Kashif Riaz | haji riaz oil traders |
| 410 | 7003 | Darbaar Vehari Bazar | 30.160535 | 72.672945 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | mudassir iqbal | hajveri electric store |
| 411 | 1033 | arif bazar | 30.161126 67 | 72.684681 67 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Asghar Ali | hakeem asghar |
| 412 | 27029 | Wapda Daftar | 30.158855 | 72.677588 33 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Abdul Hameed | hameed and sons |
| 413 | 27030 | Wapda Daftar | 30.158903 33 | 72.677615 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | hameed | hameed and sons welding |
| 414 | 22009 | Joiya Road | 30.156688 33 | 72.680825 | 98 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Abdul hameed | hameed traders |
| 415 | 10013 | Fire Brigade | 30.16107 | 72.671896 67 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | hamza | hamza autos |
| 416 | 12001 | Food Grain Road | 30.156573 33 | 72.680818 33 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Tajamal Shahzad | hamza motors |
| 417 | 15009 | Joiya Market Dokanaat | 30.157016 67 | 72.68245 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Akbar | haneef electric store |
| 418 | 15045 | Joiya Market Dokanaat | 30.1568 | 72.681638 33 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Naem Abbas | hanif karyana |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|--------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-------------------------------|-------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 419 | 9053 | Dokanat Vehari Bazar | 30.15874167 | 72.67930667 | 32 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Hanif | Hanif pan shop |
| 420 | 9054 | Dokanat Vehari Bazar | 30.15873667 | 72.67931667 | 32 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Hanif khan (brother of owner) | hanif pan shop |
| 421 | | Joiya Market Dokanaat | 30.15693 | 72.68218333 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhamma d Hanif | hanif tobaco store |
| 422 | 11007 | Food Grain Dokanat | 30.15654333 | 72.679435 | 140 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Shafqat Ali | haq bahoo goods |
| 423 | 16056 | Joiya Road | 30.15737 | 72.68416833 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Malik razzaq awan | haq bahoo motors |
| 424 | 9074 | Dokanat Vehari Bazar | 30.15863167 | 72.678875 | 100 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Amjid | haq fareed juice corner |
| 425 | 2007 | Barlab Nehar Vehari Baza | 30.16046667 | 72.674075 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Bashir Ahmad | haq shahbaz shop |
| 426 | 15076 | Joiya Market Dokanaat | 30.15725667 | 72.683035 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | israr bhatti | haroon motors |
| 427 | 15075 | Joiya Market Dokanaat | 30.15713833 | 72.68308 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | israr bhatti | haroon motors |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|--------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|----------------------------|-------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 428 | 1016 | arif bazar | 30.16077 | 72.684165 | 36 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Hasnain | Hasnain Mobile |
| 429 | 21025 | Androon Sabaz Mandi | 30.15894167 | 72.681965 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Mukhtar Ahmad | hasnain shopping center |
| 430 | | Cloth Market Joyia Road | 30.15720167 | 72.68221 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | haneef | hassan jewelers |
| 431 | 26001 | Vehari Bazar Water Works | 30.160705 | 72.672835 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Safdar | hassan steel works |
| 432 | 26007 | Vehari Bazar Water Works | 30.16064333 | 72.67293 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Asghar Ali | hassan steel works |
| 433 | 1049 | arif bazar | 30.161525 | 72.684895 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Aslam | hassan travels |
| 434 | 1050 | arif bazar | 30.16159667 | 72.68488833 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ch M Aslam | hassan travels |
| 435 | | Cloth Market Joyia Road | 30.15770333 | 72.682325 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | tariq javed | heera sweets |
| 436 | 16017 | Joiya Road | 30.15769333 | 72.68517333 | 98 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Saleem | Hero autos |
| 437 | 1025 | arif bazar | 30.160895 | 72.68444167 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Hakeem javed Iqbal rehmani | hikmat shop |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|------------------|-------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 438 | 1004 | arif bazar | 30.16048833 | 72.68410833 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Javeed Iqbal | Holly wood electronics |
| 439 | 1005 | arif bazar | 30.16051333 | 72.684145 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Kamran Aziz | Holly wood electronics |
| 440 | 1006 | arif bazar | 30.16049667 | 72.68412833 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | sheikh imran | holly wood electronics |
| 441 | 19023 | Purani Tehsil | 30.156855 | 72.68152833 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Hukam Din | hukam din karyana store |
| 442 | 19020 | Purani Tehsil | 30.15684333 | 72.68159667 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Imran | hukam din karyana store |
| 443 | 16057 | Joiya Road | 30.157375 | 72.68414167 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | ghulam hussain | husnani dental supply |
| 444 | 23009 | Tehsil Council | 30.15951167 | 72.68214333 | 56 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Rashid Hussain | Hussain Jewelers |
| 445 | | Cloth Market Joyia Road | 30.15750167 | 72.682185 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | tufail | hussain jewelers |
| 446 | 28026 | Water Works Collony | 30.160535 | 72.67303667 | 60 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Bilal Ishtiaq | ibrahim autos |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|------------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|------------------|-----------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 447 | 19013 | Purani Tehsil | 30.15688833 | 72.68177333 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Ibrahim | ibrahim karyana store |
| 448 | 9021 | Dokanat Vehari Bazar | 30.158975 | 72.68013833 | 48 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Arshad | ibrahim samosa shop |
| 449 | 9020 | Dokanat Vehari Bazar | 30.15898667 | 72.68015333 | 48 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Arshad | ibrahim smosa wala |
| 450 | | Cloth Market Joyia Road | 30.15742333 | 72.68205667 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | sheraz | idrees jewelers |
| 451 | 8019 | Deewar High School | 30.16234833 | 72.68567167 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | ijaz | ijaz sound |
| 452 | 6009 | Chongi dukanaat | 30.15672167 | 72.68110167 | 200 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ikram Ullah khan | ikram churi store |
| 453 | 27025 | Wapda Daftar | 30.15882333 | 72.67771 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Ikram | ikram traders |
| 454 | 27026 | Wapda Daftar | 30.15885333 | 72.67764833 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | ikram | ikram traders |
| 455 | 16048 | Joiya Road | 30.157455 | 72.684395 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Ilyas | Ilyas autos |
| 456 | 19019 | Purani Tehsil | 30.15686667 | 72.68166167 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Alyas | ilyas karyana |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|--------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|--------------------|------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 457 | 19018 | Purani Tehsil | 30.15686667 | 72.681645 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Alyas | ilyas karyana store |
| 458 | 13001 | General Bus Stand | 30.163585 | 72.68608 | 112 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ilyas | ilyas mechanical works |
| 459 | 2014 | Barlab Nehar Vehari Baza | 30.16047167 | 72.67422167 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | imran | imran auto boring |
| 460 | 28009 | Water Works Collony | 30.16044167 | 72.67342833 | 60 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Imran | imran autos |
| 461 | 15074 | Joiya Market Dokanaat | 30.15721333 | 72.68301833 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Imran | imran brothers |
| 462 | 21009 | Sabaz Mandi Gol Chowk | 30.15904833 | 72.68189833 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Rizwan | imran collection |
| 463 | 13002 | General Bus Stand | 30.16354667 | 72.68605833 | 112 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Imran Mehmood Khan | imran diesel lab |
| 464 | 21024 | Androon Sabaz Mandi | 30.15898333 | 72.681955 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Imran | Imran fabrics |
| 465 | 1003 | arif bazar | 30.16049333 | 72.684125 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Imran Aziz | Imran repairing center |
| 466 | 21014 | Sabaz Mandi Gol Chowk | 30.15918 | 72.682085 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Imtiaz Ahmad | imtiaz cloth house |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|---------------------------------|-------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------|----------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | Shop Asset Condition Assessment | | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 467 | 27015 | Wapda Daftar | 30.15874667 | 72.67792833 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Iqbal | iqbal and sons |
| 468 | 28023 | Water Works Collony | 30.160565 | 72.67310667 | 60 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ali Shan | iqbal autos |
| 469 | 19004 | Purani Tehsil | 30.15692167 | 72.681955 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Iqbal | iqbal bhatti karyana store |
| 470 | 19003 | Purani Tehsil | 30.15695333 | 72.68199 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Iqbal | iqbal bhatti karyana store |
| 471 | | Cloth Market Joyia Road | 30.15752333 | 72.68177667 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Ramzan | iqbal book store |
| 472 | 9065 | Dokanat Vehari Bazar | 30.15862167 | 72.67902167 | 48 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Iqbal | iqbal iron store |
| 473 | | Cloth Market Joyia Road | 30.15743667 | 72.682405 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | iqbal | iqbal tailors |
| 474 | 22011 | Joiya Road | 30.15664667 | 72.68069667 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Irfan | irfan autos |
| 475 | 8050 | Deewar High School | 30.16279167 | 72.68604333 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | irfan | irfan electronics |
| 476 | 1026 | arif bazar | 30.160935 | 72.684505 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Irfan Ullah Ch. | irfan glass house |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-----------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------|---------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 477 | 12041 | Food Grain Road | 30.15632667 | 72.67981167 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Irfan | irfan iron store |
| 478 | 8057 | Deewar High School | 30.16288667 | 72.68615833 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | tahir sethi | irfan medical |
| 479 | 8059 | Deewar High School | 30.16256667 | 72.68587333 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M younas | irfan medical |
| 480 | 15006 | Joiya Market Dokanaat | 30.15709167 | 72.68247833 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | sheikh zulfiqar | irfan motors |
| 481 | 9040 | Dokanat Vehari Bazar | 30.15889 | 72.679505 | 96 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Irfan | irfan wan house |
| 482 | 9044 | Dokanat Vehari Bazar | 30.15881667 | 72.67944333 | 48 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Irshad Khan | Irhad Wan House |
| 483 | 12048 | Food Grain Road | 30.15629833 | 72.67962333 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Ghulam Rasool | iron store |
| 484 | 9046 | Dokanat Vehari Bazar | 30.15881333 | 72.679425 | 48 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Irshad Khan | irshad wan house |
| 485 | 21005 | Sabaz Mandi Gol Chowk | 30.15888833 | 72.68195833 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Ishaq | ishaq dupatta house |
| 486 | 23011 | Tehsil Council | 30.15955 | 72.682135 | 56 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Ishaq | Ishaq Jewelers |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-----------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|----------------|-------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 487 | 28016 | Water Works Collony | 30.16048167 | 72.673225 | 60 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M ishfaq | ishfaq wheel balance |
| 488 | 28027 | Water Works Collony | 30.16054 | 72.672985 | 60 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Javeed Ishtiaq | ishtiaq autos |
| 489 | 1029 | arif bazar | 30.16102833 | 72.68444333 | 36 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Ishtaiq Ahmad | ishtiaq cycle store |
| 490 | 1030 | arif bazar | 30.16101333 | 72.68451833 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Asghar | ishtiaq cycle store |
| 491 | 15061 | Joiya Market Dokanaat | 30.15702833 | 72.68279333 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Mushtaq | islaah zulf barbar shop |
| 492 | 15003 | Joiya Market Dokanaat | 30.15704667 | 72.68257833 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Islam | islam motors |
| 493 | 15004 | Joiya Market Dokanaat | 30.157015 | 72.68255 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Islam | islam motors |
| 494 | 9041 | Dokanat Vehari Bazar | 30.15894667 | 72.67962 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Adnan ismaeel | ismaeel cloth house |
| 495 | 15058 | Joiya Market Dokanaat | 30.15705667 | 72.68275167 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Sajid Majeed | ittehad electric |
| 496 | 15057 | Joiya Market Dokanaat | 30.15711167 | 72.68266167 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Sajid Majeed | ittehad electric store |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-----------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------|-------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 497 | 1013 | arif bazar | 30.160665 | 72.68424333 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Abdul Hafiz | ittifaq cycle store |
| 498 | 1014 | arif bazar | 30.160665 | 72.684235 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Saleem | ittifaq cycle store |
| 499 | 15059 | Joiya Market Dokanaat | 30.15716667 | 72.68273333 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Akram Naseem | ittihad electric store |
| 500 | 10014 | Fire Brigade | 30.161135 | 72.67191 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Abdul Jabar | jabbar auto electrician |
| 501 | 8028 | Deewar High School | 30.16244667 | 72.68569667 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Zubair | jabbar cloth house |
| 502 | 8049 | Deewar High School | 30.16279167 | 72.68601667 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Abdul Jabbar | jabbar sweets |
| 503 | 7012 | Darbaar Vehari Bazar | 30.16044833 | 72.67295833 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Ishaq | jaddah electric store |
| 504 | 7001 | Darbaar Vehari Bazar | 30.16048333 | 72.67297833 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Ishaq | jaddah electric works |
| 505 | 16034 | Joiya Road | 30.157565 | 72.68472333 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Jaffar Ali | jaffar number plate |
| 506 | 5001 | Chok Qasaab Vehari | 30.15848167 | 72.67876 | 24 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Rao jamal | jamal pan shop |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|----------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|----------------|-------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| | | Bazar Dokanat | | | | | | | | | | | | |
| 507 | 3007 | Barshian Gass Vehari Bazar | 30.15955833 | 72.67541333 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Anwar | jameel pakwan |
| 508 | 1044 | arif bazar | 30.16139167 | 72.68474 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Saleem Aslam | japan electronics |
| 509 | 1027 | arif bazar | 30.16091667 | 72.68448 | 36 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Munir Ahmad | javed bakery |
| 510 | | Cloth Market Joyia Road | 30.15773667 | 72.68202167 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | javed | javed cloth house |
| 511 | | Cloth Market Joyia Road | 30.157715 | 72.68211833 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | rafeeq | javed cloth house |
| 512 | 21006 | Sabaz Mandi Gol Chowk | 30.15886167 | 72.68202167 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Aslam | javed collection |
| 513 | 1043 | arif bazar | 30.16135 | 72.68477667 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Nadeem Aslam | javed electronics |
| 514 | 28014 | Water Works Collony | 30.1605 | 72.67332167 | 60 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | javed | javed poshish |
| 515 | 16010 | Joiya Road | 30.157695 | 72.68537333 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Ali asghar | Jholay laal cycle |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-----------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|----------------|------------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 516 | | General Bus stand | 30.163595 | 72.686245 | 112 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | raja bhatti | jhollay laal canteen |
| 517 | 16011 | Joiya Road | 30.15769333 | 72.68539167 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Ali asghar | jhollay laal cycle |
| 518 | 11001 | Food Grain Dokanat | 30.15697 | 72.67928833 | 144 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Rana shahid | jhollay laal marchant |
| 519 | 11002 | Food Grain Dokanat | 30.15697667 | 72.67927667 | 144 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Zahid | jhollay laal timber marchant |
| 520 | 23026 | Tehsil Council | 30.159785 | 72.682435 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Waris Ali | Jutt Jewelers |
| 521 | 12046 | Food Grain Road | 30.15631 | 72.67969667 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Abdul Latif | karachi biryani |
| 522 | 8027 | Deewar High School | 30.16243833 | 72.68580333 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ghulam mustafa | karam din hukkah frosh |
| 523 | 21012 | Sabaz Mandi Gol Chowk | 30.15915333 | 72.68211 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ahmad | karam garments |
| 524 | 27037 | Wapda Daftar | 30.15887 | 72.677545 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Abdul kareem | kareem welding store |
| 525 | 25003 | Vehari Bazar 1-A | 30.16016833 | 72.67406833 | 40 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Haji nadeem | karim chaska point |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------|------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 526 | 22031 | Joiya Road | 30.156355 | 72.679675 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Fareed Ahmad | karman walay autos |
| 527 | 8008 | Deewar High School | 30.16208167 | 72.68545667 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Zahid iqbal | karmanwala juice point |
| 528 | 12030 | Food Grain Road | 30.15633 | 72.68007833 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Abdul razzaq | karmanwalay food point |
| 529 | | Cloth Market Joyia Road | 30.15743833 | 72.68226167 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Kashif | Kashif cloth house |
| 530 | 9005 | Dokanat Vehari Bazar | 30.159215 | 72.68046667 | 96 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Masood Ahmad | Kashif iron store |
| 531 | 9019 | Dokanat Vehari Bazar | 30.15888833 | 72.68017833 | 48 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Amjid Khan | Kashif seeds |
| 532 | 9039 | Dokanat Vehari Bazar | 30.15882 | 72.67966333 | 48 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Kashif Khan | kashif wan store |
| 533 | 1021 | arif bazar | 30.16073333 | 72.68433 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Abdul Latif | kausar book dipo |
| 534 | 1022 | arif bazar | 30.16076667 | 72.68432667 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Aamir | khaleeq electronics |
| 535 | 28020 | Water Works Collony | 30.16054667 | 72.67319 | 60 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | khalid mehmoood | khalid auto parts |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|----------------------------|-------------|------------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|--------------------|--------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 536 | 28017 | Water Works Collony | 30.16054667 | 72.67325833 | 60 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | khalid mehmoood | khalid autos |
| 537 | 3010 | Barshian Gass Vehari Bazar | 30.15943333 | 72.67542333 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Abid farooq | khalid gas company |
| 538 | 9038 | Dokanat Vehari Bazar | 30.15899 | 72.67963833 | 96 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Khalid Mehmoood | khalid general store |
| 539 | | Cloth Market Joyia Road | 30.15744833 | 72.68237167 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | khalid | khalid gold smith |
| 540 | 12015 | Food Grain Road | 30.156445 | 72.680365 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Naem ahmad | khalil electric store |
| 541 | 12016 | Food Grain Road | 30.15620667 | 72.679315 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Nadeem Ahmad | khalil electric works |
| 542 | 15016 | Joiya Market Dokanaat | 30.156925 | 72.68231333 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Khalil Ahmad | khalil tobaco corner |
| 543 | 12050 | Food Grain Road | 30.15638667 | 72.67943667 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Sabir Hussain Khan | khan brothers iron store |
| 544 | 12053 | Food Grain Road | 30.15642333 | 72.67941167 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Yousaf | khan brothers iron store |
| 545 | | Cloth Market Joyia Road | 30.15766167 | 72.68168833 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | nizam khan | khan cloth house |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|--------------------|--------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 546 | | Cloth Market Joyia Road | 30.15766167 | 72.68168833 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | saab khan | khan cloth house |
| 547 | 12051 | Food Grain Road | 30.15632 | 72.67956333 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Zain ul Abdain | khan iron store |
| 548 | 12052 | Food Grain Road | 30.156305 | 72.67952 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Zain ul Abdain | khan iron store |
| 549 | 12054 | Food Grain Road | 30.156345 | 72.67952833 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Yousaf | khan iron store |
| 550 | 12055 | Food Grain Road | 30.15627333 | 72.67949333 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Younas | khan iron store |
| 551 | 12056 | Food Grain Road | 30.15624167 | 72.679455 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Younas | khan iron store |
| 552 | | Cloth Market Joyia Road | 30.157865 | 72.682195 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | wahid | khan tailors |
| 553 | 1037 | arif bazar | 30.16121167 | 72.68469333 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Yousaf khan | khan watch |
| 554 | 1036 | arif bazar | 30.16117833 | 72.68469167 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Iqbal, M Sadique | khan watch/shama plastic |
| 555 | 15070 | Joiya Market Dokanaat | 30.157125 | 72.68296667 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | tariq aziz | khawar electric |
| 556 | 27011 | Wapda Daftar | 30.1587 | 72.678095 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | afzal ahmad | khushi electric |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-------------------|---------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 557 | | Cloth Market Joyia Road | 30.15757333 | 72.68215167 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | mujahid ali | khushi tailors |
| 558 | 21029 | Androon Sabaz Mandi | 30.15902 | 72.68167667 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Saleem | kisan seed store |
| 559 | 16024 | Joiya Road | 30.15758667 | 72.68501 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Abdul khaliq | laal shahbaz motors |
| 560 | | Cloth Market Joyia Road | 30.15729833 | 72.68241333 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad sadeeq | labek jewelry shop |
| 561 | 16091 | Joiya Road | 30.15721833 | 72.68335167 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Saeed Ahmad | lasani motors |
| 562 | 16092 | Joiya Road | 30.15722333 | 72.683315 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | saeed | lasani motors |
| 563 | 15010 | Joiya Market Dokanaat | 30.15699833 | 72.68255667 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Sohail Ahmad | lasani motors |
| 564 | | Cloth Market Joyia Road | 30.15757 | 72.68167167 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | usama | lateef jewelers |
| 565 | 21019 | Androon Sabaz Mandi | 30.159225 | 72.68205167 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Shafique | lateef shoes |
| 566 | 10035 | Fire Brigade | 30.16135167 | 72.67164667 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Latif | latif autos |
| 567 | 1057 | arif bazar | 30.16163167 | 72.68498333 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Abdul Latif | latif electronics |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-----------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|----------------|-----------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 568 | 8014 | Deewar High School | 30.16235 | 72.68549167 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Latif | latif electronics |
| 569 | | Joiya Road | 30.15657833 | 72.680625 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | liaqat ali | liaqat ali phari wala |
| 570 | 22012 | Joiya Road | 30.15663333 | 72.68058 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Liaqat Ali | liaqat ali phari wala |
| 571 | 15047 | Joiya Market Dokanaat | 30.15679833 | 72.681545 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Liaqat ALi | Liaqat dry fruits |
| 572 | 14006 | Goal Chowk Phari Haye | 30.15917167 | 72.6818 | 90 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Arshad | M Alam shoes |
| 573 | 23001 | Tehsil Council | 30.15939833 | 72.68207167 | 56 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Atif Aslam | M Aslam Lock house |
| 574 | 23010 | Tehsil Council | 30.15958833 | 72.68224167 | 56 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Bilal | M Zubair Jewelers |
| 575 | 15072 | Joiya Market Dokanaat | 30.15724667 | 72.68301667 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Allao Din | maan electric |
| 576 | 15064 | Joiya Market Dokanaat | 30.15710667 | 72.68285167 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | jaffar | madina autos |
| 577 | 10042 | Fire Brigade | 30.16137333 | 72.67182167 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Amjid Ali | madina gas |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|---------------|--------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 578 | 10043 | Fire Brigade | 30.161415 | 72.67185833 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Aman ullah | madina gas center |
| 579 | 10041 | Fire Brigade | 30.16132167 | 72.671705 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Jamil Ahmad | Madina gas point |
| 580 | 10039 | Fire Brigade | 30.16145167 | 72.67177167 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M aslam | madina gas store |
| 581 | | Cloth Market Joyia Road | 30.15746833 | 72.681445 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | talib hussain | madina jewelers |
| 582 | 9031 | Dokanat Vehari Bazar | 30.158975 | 72.67982167 | 96 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Imran | madina mobiles |
| 583 | 12004 | Food Grain Road | 30.156545 | 72.680725 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | irfan bhatti | madina motors |
| 584 | 10026 | Fire Brigade | 30.161165 | 72.67162667 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Abdul Sattar | madina paint house |
| 585 | 10027 | Fire Brigade | 30.16114667 | 72.67161 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | abdul sattar | madina paint house |
| 586 | 19006 | Purani Tehsil | 30.156945 | 72.681915 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Akram | madina sale point |
| 587 | 21004 | Sabaz Mandi Gol Chowk | 30.158845 | 72.68190833 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Saeed | Madina shaal store |
| 588 | 8044 | Deewar High School | 30.16270667 | 72.68595 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Arslan Hayyat | madina sound |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|--------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|--------------|---------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 589 | 9026 | Dokanat Vehari Bazar | 30.15901333 | 72.67992833 | 96 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Sultan Baig | madina wan store |
| 590 | 9027 | Dokanat Vehari Bazar | 30.15898667 | 72.67996167 | 48 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Sultan Baig | Madina wan store |
| 591 | 15053 | Joiya Market Dokanaat | 30.15714 | 72.68263167 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Zubair | mahboob pan shop |
| 592 | | Cloth Market Joyia Road | 30.15762333 | 72.68222333 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | rasheed | majeed cloth house |
| 593 | 2004 | Barlab Nehar Vehari Baza | 30.16041667 | 72.67389667 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Aslam | Makkah baring store |
| 594 | 23016 | Tehsil Council | 30.159545 | 72.68224333 | 56 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Ali | Makkah Jewelers |
| 595 | 1046 | arif bazar | 30.161505 | 72.684945 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Akram | makkah mobiles |
| 596 | 22020 | Joiya Road | 30.15644333 | 72.68007 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | sufyan | makkah motors |
| 597 | 22019 | Joiya Road | 30.15646333 | 72.680105 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Safeer Ahmad | makkah motors |
| 598 | 16027 | Joiya Road | 30.15758333 | 72.68489833 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M shareef | makkah motors+c haye shop |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|--------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|--------------------|-------------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 599 | 2011 | Barlab Nehar Vehari Baza | 30.16053667 | 72.67412833 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Arshad | makkah steel works |
| 600 | 2012 | Barlab Nehar Vehari Baza | 30.16056167 | 72.674125 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Arshad | makkah steel works |
| 601 | 2013 | Barlab Nehar Vehari Baza | 30.16045667 | 72.67416333 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Awais S/O Arshad | makkah steel works |
| 602 | 15015 | Joiya Market Dokanaat | 30.157005 | 72.68230167 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Sarfraz Ahmad | malik ahmad ali karyana store |
| 603 | 15017 | Joiya Market Dokanaat | 30.156975 | 72.68224333 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Shahzad Ahmad | malik ahmad sons store |
| 604 | 15014 | Joiya Market Dokanaat | 30.15708 | 72.682275 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Sarfraz Ahmad | malik ahmad store |
| 605 | 12062 | Food Grain Road | 30.156675 | 72.681065 | 240 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Naveed Anwar | Malik anwar karyana store |
| 606 | 12063 | Food Grain Road | 30.15670167 | 72.68103833 | 144 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Qasim anwar | malik anwer karyana store |
| 607 | | Joiya Road | 30.156705 | 72.68107167 | 24.5 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | waqas asghar | malik asghar |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-----------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-------------------|----------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| | | | | | | | | | | | | | | karyana store |
| 608 | 15049 | Joiya Market Dokanaat | 30.15676167 | 72.68152333 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Iqbal Hanif | malik haneef ghee |
| 609 | 15025 | Joiya Market Dokanaat | 30.156925 | 72.682065 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Awais | malik karyana store |
| 610 | 15026 | Joiya Market Dokanaat | 30.156935 | 72.682045 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Awais | malik karyana store |
| 611 | 19001 | Purani Tehsil | 30.15694833 | 72.68201667 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Faisal imran | malik karyana store |
| 612 | 8007 | Deewar High School | 30.16214833 | 72.68533667 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ghulam Hussain | Malik M Shareef Mobiles |
| 613 | | Joiya Road | 30.15672667 | 72.681045 | 98 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Malik naveed | Malik naveed karyana store |
| 614 | 19011 | Purani Tehsil | 30.156925 | 72.68179333 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhamma d Rafique | malik ramzan karyana store |
| 615 | 15028 | Joiya Market Dokanaat | 30.156965 | 72.681975 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Ajmal | malik ramzan store |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|------------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|--------------|--------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 616 | 15029 | Joiya Market Dokanaat | 30.15695333 | 72.68199 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Asawar Rafiq | malik ramzan store |
| 617 | 15041 | Joiya Market Dokanaat | 30.15680667 | 72.68171667 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Sakhi Sarwar | malik sakhi sarwar store |
| 618 | 19002 | Purani Tehsil | 30.156955 | 72.68202 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | javed iqbal | malik shareef karyana |
| 619 | | Joiya Road | 30.15640333 | 72.67981333 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Malik shokat | Malik welding store |
| 620 | | Cloth Market Joyia Road | 30.15745 | 72.68190667 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | waqar | manan jewelers |
| 621 | 9060 | Dokanat Vehari Bazar | 30.15875167 | 72.679135 | 48 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Manzoor ali | manzoor tobacco |
| 622 | 9059 | Dokanat Vehari Bazar | 30.15874 | 72.67912 | 48 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Maqsood ALi | maqsood tobacco |
| 623 | 10019 | Fire Brigade | 30.16096 | 72.67170833 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | abdul khaliq | marhaba photostate |
| 624 | 10018 | Fire Brigade | 30.161035 | 72.67177667 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | nazeer | marhaba photostate |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------------|-------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 625 | 10020 | Fire Brigade | 30.161045 | 72.671725 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Nazir Ahmad | marhaba photostate |
| 626 | 22008 | Joiya Road | 30.156655 | 72.680825 | 70 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Sarwar Bashir | maru hotel wala |
| 627 | 16007 | Joiya Road | 30.15782 | 72.68541333 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Raiz | MashaAllah autos |
| 628 | 12044 | Food Grain Road | 30.15633333 | 72.67972833 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Mushtaq Abid | MashaAllah rice traders |
| 629 | 15084 | Joiya Market Dokanaat | 30.15713667 | 72.68325 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Adnan Ahmad | masoom mobiles |
| 630 | 15001 | Joiya Market Dokanaat | 30.15721167 | 72.68325 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Noor Ahmad | massom mobiles |
| 631 | 16081 | Joiya Road | 30.15724833 | 72.68358333 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Ahsan | master electric |
| 632 | | Cloth Market Joyia Road | 30.15734 | 72.68248333 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | abdul Razzaq | matching center |
| 633 | | Cloth Market Joyia Road | 30.15734 | 72.68248333 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | abdul razzaq | matching center |
| 634 | | Cloth Market Joyia Road | 30.15734 | 72.68248333 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | abdul razzaq | matching center |
| 635 | 8045 | Deewar High School | 30.16277 | 72.68587833 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Ali Saqib | MD Mobiles |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|----------------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|---------------------|---------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 636 | 5003 | Chok Qasaab Vehari Bazar Dokanat | 30.15844833 | 72.678795 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Shabir | meat shop |
| 637 | 5004 | Chok Qasaab Vehari Bazar Dokanat | 30.15870167 | 72.67864667 | 96 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Munir Ahmad | meat shop |
| 638 | 6006 | Chongi dukanaat | 30.1568 | 72.681125 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Rana Mazher Mukhtar | mechanical workshop |
| 639 | 9047 | Dokanat Vehari Bazar | 30.15888167 | 72.679415 | 48 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | mehar ban khan | mehrban wan house |
| 640 | 9048 | Dokanat Vehari Bazar | 30.15892167 | 72.679425 | 48 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | mehar ban khan | mehrban wan house |
| 641 | 9049 | Dokanat Vehari Bazar | 30.15877333 | 72.67932833 | 48 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | mehar ban khan | mehrban wan house |
| 642 | 14010 | Goal Chowk Phari Haye | 30.15926333 | 72.681895 | 72 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Shahbaz | Metro shoes |
| 643 | 16088 | Joiya Road | 30.15723 | 72.68344167 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Ibrahim | MH electric |
| 644 | 19014 | Purani Tehsil | 30.156835 | 72.68172167 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | munawar hussain | minawar gurr shop |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|---------------------|--------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 645 | 23015 | Tehsil Council | 30.15949667 | 72.68218333 | 56 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Aftab | Minsa Jewelers |
| 646 | 12009 | Food Grain Road | 30.15650333 | 72.68059 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Rao Ghulam Muhammad | mirch store |
| 647 | 12008 | Food Grain Road | 30.15652333 | 72.68063333 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Ameer Ahmad | mirch store |
| 648 | 9006 | Dokanat Vehari Bazar | 30.15905667 | 72.68046833 | 96 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Noor Hassain | Mirza abdul ghafoor shop |
| 649 | 12002 | Food Grain Road | 30.156575 | 72.68080167 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Jamil | mirza auto boring |
| 650 | 25002 | Vehari Bazar 1-A | 30.16017333 | 72.67415333 | 200 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Amir Farooq | mirza welding house |
| 651 | 25001 | Vehari Bazar 1-A | 30.16017 | 72.67407833 | 140 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Idrees | mirza welding store |
| 652 | 27002 | Wapda Daftar | 30.158675 | 72.67826667 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Allah Ditta | Mistri Allah ditta |
| 653 | | Cloth Market Joyia Road | 30.15748 | 72.68219167 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | afzal | moon jewelers |
| 654 | 25005 | Vehari Bazar 1-A | 30.16022833 | 72.67397333 | 70 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Abdullah | Mubarak hotel |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-------------------|----------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 655 | 15023 | Joiya Market Dokanaat | 30.15697 | 72.68213667 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Mubashir | mubashar super store |
| 656 | 15020 | Joiya Market Dokanaat | 30.1569 | 72.68222167 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Mubashir Ali | mubashir tobacco |
| 657 | | Cloth Market Joyia Road | 30.15736 | 72.68221667 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | mudassir | mudassir cloth house |
| 658 | 8031 | Deewar High School | 30.16244667 | 72.68577667 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Mudassir | mudassir printers |
| 659 | 9024 | Dokanat Vehari Bazar | 30.15895 | 72.67998667 | 48 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Mudassir | mudassir wan house |
| 660 | 9051 | Dokanat Vehari Bazar | 30.15879 | 72.67932 | 50 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Mudassir | Mudassir wan house |
| 661 | 9025 | Dokanat Vehari Bazar | 30.15892833 | 72.679975 | 48 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Mudassir | Mudassir wan store |
| 662 | 12043 | Food Grain Road | 30.15619833 | 72.67975 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Irfan | mughal ari spot |
| 663 | 27009 | Wapda Daftar | 30.15874 | 72.678135 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Riaz | mughal engineering |
| 664 | 27010 | Wapda Daftar | 30.158645 | 72.67810333 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M iqbal | mughal engineering |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|----------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-------------------------|-------------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 665 | 23002 | Tehsil Council | 30.159505 | 72.68207333 | 56 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Haji Ijaz | Muhamma d Ali Jewelers |
| 666 | 16077 | Joiya Road | 30.15724833 | 72.68367167 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | haji mukhtar | mukhtar sanitary store |
| 667 | 16078 | Joiya Road | 30.15724833 | 72.68366333 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | haji mukhtar | mukhtar sanitary store |
| 668 | 10046 | Fire Brigade | 30.16093333 | 72.67199 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M faizan | Multani burger(do ouble shop) |
| 669 | | Joiya Road | 30.15649667 | 72.680205 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | ahsaan | mumtaz motors |
| 670 | 16005 | Joiya Road | 30.157695 | 72.685445 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Asad Munir | Munir Autos |
| 671 | 7004 | Darbaar Vehari Bazar | 30.16052667 | 72.67289167 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | munir bhatti | munir honda autos |
| 672 | 1041 | arif bazar | 30.161305 | 72.68481667 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Tanveer Ahmad | munir karyana |
| 673 | 10023 | Fire Brigade | 30.16112667 | 72.67169 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Mubashir Munir | munir paint house |
| 674 | 10024 | Fire Brigade | 30.16111833 | 72.67165667 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhamma d Muzamil Munir | munir paint house |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|--------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|----------------|-----------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 675 | 11004 | Food Grain Dokanat | 30.15672833 | 72.67938167 | 91 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Munir Ahmad | munir wood works |
| 676 | 9037 | Dokanat Vehari Bazar | 30.158795 | 72.67967667 | 96 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Mushtaq Khan | mushtaq wan store |
| 677 | 1059 | arif bazar | 30.161665 | 72.684935 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ijaz | music in mobile |
| 678 | 16087 | Joiya Road | 30.15719167 | 72.68334333 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | adeel | muslim electric |
| 679 | 16086 | Joiya Road | 30.15734833 | 72.68328 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Adeel | Muslim electric |
| 680 | 21007 | Sabaz Mandi Gol Chowk | 30.15897667 | 72.68205167 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Ameen | Mustafa cloth house |
| 681 | 21002 | Sabaz Mandi Gol Chowk | 30.15890833 | 72.68179833 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ghulam Mustafa | Mustafa dupatta house |
| 682 | 2015 | Barlab Nehar Vehari Baza | 30.16047167 | 72.67427 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | mateen bajwa | mustafa paint house |
| 683 | 15063 | Joiya Market Dokanaat | 30.15708333 | 72.68283167 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Ahmad | muzamma I sangar |
| 684 | 15062 | Joiya Market Dokanaat | 30.15711 | 72.6828 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Ahmad | muzamma I sangar |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-----------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|----------------|----------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 685 | 21011 | Sabaz Mandi Gol Chowk | 30.15901 | 72.68193333 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Nawaz | muzammil cloth house |
| 686 | 8038 | Deewar High School | 30.162655 | 72.685905 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Rehan | muzammil electronics |
| 687 | 15077 | Joiya Market Dokanaat | 30.15723333 | 72.6831 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | nabeel | nabeel sangar |
| 688 | 1032 | arif bazar | 30.16112667 | 72.68461833 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Iqbal | nadeem digital photostudio |
| 689 | 23020 | Tehsil Council | 30.15944167 | 72.682345 | 56 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Nadeem | Nadeem landa House |
| 690 | 15021 | Joiya Market Dokanaat | 30.157155 | 72.68273833 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Nadeem AHmad | nadeem store |
| 691 | 15022 | Joiya Market Dokanaat | 30.15707833 | 72.68231667 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Nadeem AHmad | nadeem store |
| 692 | 12007 | Food Grain Road | 30.15653333 | 72.6806 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Naeem Asghar | naeem asghar sanitary |
| 693 | 12006 | Food Grain Road | 30.15656667 | 72.68066 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Asghar Ali | naeem asghar store |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-----------------------------|-----------------|-----------------|---------------------------------|---------------|--------------------------|-------------------|---------------------|------------------|-------------------|---------------------------------------|-------------------|--------------------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 694 | 12018 | Food Grain Road | 30.156466 67 | 72.68034 | 120 | 3 | Commercial | Owned/ Managed | No | Yes | Rented/ Leased | Good | Naem Khan | Naeem khan bans store |
| 695 | 15011 | Joiya Market Dokanaat | 30.156998 33 | 72.682401 67 | 120 | 2 | Commercial | Owned/ Managed | No | No | Rented/ Leased | Good | Abdul Rasheed | naqshban dia electric store |
| 696 | 15012 | Joiya Market Dokanaat | 30.157001 67 | 72.682376 67 | 120 | 2 | Commercial | Owned/ Managed | No | No | Rented/ Leased | Good | Abdul Rasheed | naqshban dia electric store |
| 697 | 13011 | General Bus Stand | 30.163648 33 | 72.686031 67 | 112 | 2 | Commercial | Owned/ Managed | No | No | Rented/ Leased | Good | M Murtaza | naseer and company |
| 698 | 16037 | Joiya Road | 30.157513 33 | 72.684646 67 | 49 | 2 | Commercial | Owned/ Managed | No | Yes | Rented/ Leased | Good | Huzaiifa Ali | nasir autos |
| 699 | 9073 | Dokanat Vehari Bazar | 30.158645 | 72.678833 33 | 49 | 2 | Commercial | Owned/ Managed | No | No | Rented/ Leased | Good | Nasir | nasir meet shop |
| 700 | 28025 | Water Works Collony | 30.16053 | 72.673043 33 | 60 | 20 | Commercial | Owned/ Managed | No | No | Rented/ Leased | Good | Iftikhar Ahmad | national autos |
| 701 | 16006 | Joiya Road | 30.157733 33 | 72.685475 | 49 | 2 | Commercial | Owned/ Managed | No | Yes | Rented/ Leased | Good | Naveed | Naveed Electrician |
| 702 | 9062 | Dokanat Vehari Bazar | 30.15873 | 72.679063 33 | 48 | 2 | Commercial | Owned/ Managed | No | No | Rented/ Leased | Good | Naveed Ahmad | naveed iron store |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|----------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|----------------|-----------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 703 | 12013 | Food Grain Road | 30.15648833 | 72.68050333 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Naveed Anwar | naveed super store |
| 704 | 12031 | Food Grain Road | 30.15638667 | 72.680035 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Yasin | nawab din oil traders |
| 705 | 14001 | Goal Chowk Phari Haye | 30.15906667 | 72.68172 | 72 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Majid Farooq | Nawab medical store |
| 706 | 3002 | Barshian Gass Vehari Bazar | 30.15947167 | 72.67549333 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Khalid Nadeem | nazeer ahmad electric store |
| 707 | | Cloth Market Joyia Road | 30.15779333 | 72.681985 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | nazeer | nazeer cloth house |
| 708 | | Cloth Market Joyia Road | 30.15776 | 72.68165333 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | nazeer | nazeer cloth house |
| 709 | 16004 | Joiya Road | 30.157865 | 72.68546 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Hanan | nazir rasheed karyana store |
| 710 | 1051 | arif bazar | 30.16162 | 72.68484 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Waseem Asghar | new hafiz electronics |
| 711 | 10007 | Fire Brigade | 30.16100333 | 72.67201833 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Ayoob | new waqar autos |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|---------------------|---------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 712 | 10008 | Fire Brigade | 30.16095833 | 72.67196 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | haji ayub | new waqar autos |
| 713 | 23021 | Tehsil Council | 30.15947833 | 72.68241833 | 56 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Naseem ul Din | No Name |
| 714 | 22026 | Joiya Road | 30.15638167 | 72.67978333 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Noman | Noman mirch shop |
| 715 | 8025 | Deewar High School | 30.16239333 | 72.68565333 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Naveed Ahmad Shabir | noman mobiles |
| 716 | 20001 | Rail Bazar Pakka Tharra | 30.15892833 | 72.68155667 | 208 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | zulifqar | Noor cloth house |
| 717 | 1019 | arif bazar | 30.16073833 | 72.68421167 | 36 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | waseem | noor mobiles |
| 718 | 16003 | Joiya Road | 30.15765333 | 72.68558333 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhamma d Afzal | Noor nabi autos |
| 719 | 9055 | Dokanat Vehari Bazar | 30.158735 | 72.679275 | 48 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Noshad | Noshad drink corner |
| 720 | 16076 | Joiya Road | 30.15731833 | 72.68368833 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Asghar Hussain | Pak electronics |
| 721 | 16039 | Joiya Road | 30.15748833 | 72.68463833 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Mubarak ali cheema | pakistan autos |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-----------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|--------------------|-------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 722 | 28003 | Water Works Collony | 30.16036833 | 72.67358 | 60 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Anwar | Pakistan autos |
| 723 | 28004 | Water Works Collony | 30.16036833 | 72.673585 | 60 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Aqeel Ahmad | pakistan autos |
| 724 | 16055 | Joiya Road | 30.15733167 | 72.6842 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Rasheed | pakistan electric store |
| 725 | 16038 | Joiya Road | 30.15739833 | 72.68464833 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Mubarak ali cheema | pakistan motors |
| 726 | 16068 | Joiya Road | 30.15731333 | 72.68391167 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | tahir mehmoood | pakistan motors |
| 727 | 16069 | Joiya Road | 30.15731667 | 72.68387333 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | tahir mehmoood | pakistan motors |
| 728 | 10001 | Fire Brigade | 30.16081 | 72.67221167 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Abdul Jabar | pakistan studio |
| 729 | 9033 | Dokanat Vehari Bazar | 30.15889167 | 72.67978667 | 96 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Shahrukh Begh | pakistan wan store |
| 730 | 27003 | Wapda Daftar | 30.15867667 | 72.67821333 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Manzoor | papu air cooler |
| 731 | 27004 | Wapda Daftar | 30.15864167 | 72.67822 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Raja M Sarwar | papu air cooler |
| 732 | 21001 | Sabaz Mandi Gol Chowk | 30.15893333 | 72.68166667 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Pervaiz Akhter | paras cloth house |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|--------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|--------------------------|----------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 733 | 27014 | Wapda Daftar | 30.15875167 | 72.67801167 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Khalid Ahmad | photocopy shop |
| 734 | | Vehari Bazar Water Works | 30.16062333 | 72.67300667 | 72 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Sajid | pmln office |
| 735 | 12049 | Food Grain Road | 30.15637667 | 72.67951667 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Arshad | popular iron store |
| 736 | 16018 | Joiya Road | 30.157835 | 72.68500667 | 70 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Nawab Din/Ghulam Hussain | Punjab dental lab |
| 737 | 28012 | Water Works Collony | 30.16046 | 72.67336 | 60 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Aqeel | punjab motors |
| 738 | 28013 | Water Works Collony | 30.16045 | 72.67333667 | 60 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Aqeel | punjab motors |
| 739 | 1015 | arif bazar | 30.16069333 | 72.684255 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Munir Ahmad | qaifi pan shop |
| 740 | 8004 | Deewar High School | 30.16174833 | 72.68514667 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Abdul Qayum | qayyum mobiles |
| 741 | 10033 | Fire Brigade | 30.16137833 | 72.671645 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | rafee ilyas | rafee honda service |
| 742 | 19005 | Purani Tehsil | 30.15694333 | 72.68194833 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Rafique | rafeeq karyana store |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-----------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------|----------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 743 | 15066 | Joiya Market Dokanaat | 30.15713167 | 72.68287333 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Rafiq | rafiq mochi shop |
| 744 | 8054 | Deewar High School | 30.162835 | 72.68605333 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Anees Shehzad | raheel mobiles |
| 745 | 16008 | Joiya Road | 30.15766333 | 72.685405 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Idrees | raheem motors |
| 746 | 28018 | Water Works Collony | 30.16046 | 72.6732 | 60 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Abdul Raheem | raheem opticle house |
| 747 | 21027 | Androon Sabaz Mandi | 30.15937167 | 72.68197833 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Mohsin | raja rani shoes |
| 748 | 14007 | Goal Chowk Phari Haye | 30.15921333 | 72.68181833 | 72 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Hassan | Rajpoot shoes |
| 749 | 15044 | Joiya Market Dokanaat | 30.15680167 | 72.68163833 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Rameez Hanif | rameez hanif karyana store |
| 750 | 27034 | Wapda Daftar | 30.15891 | 72.67742833 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Ramzan | ramzan brothers nalka |
| 751 | 16047 | Joiya Road | 30.15747167 | 72.68442333 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Bao ramzan | ramzan electric |
| 752 | 8016 | Deewar High School | 30.16228 | 72.68570333 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ramzan | ramzan electronics |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|--------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|--------------------------------|-----------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 753 | 8017 | Deewar High School | 30.16225667 | 72.6857 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | ramzan | ramzan electronics |
| 754 | 19010 | Purani Tehsil | 30.15690833 | 72.68182833 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Asawar Rafiq | ramzan karyana store |
| 755 | 19009 | Purani Tehsil | 30.15694167 | 72.68181167 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Nabeel Rafique | ramzan karyana store |
| 756 | 19008 | Purani Tehsil | 30.15693 | 72.68190167 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Ramzan | ramzan karyana store |
| 757 | 27006 | Wapda Daftar | 30.158645 | 72.67818667 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Ramzan | ramzan mechanical works |
| 758 | 1010 | arif bazar | 30.16058167 | 72.68419167 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Javeed | rana brothers cycle store |
| 759 | 1056 | Arif Bazar | 30.16066667 | 72.68424333 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Rana M Zain ul Abdeen | rana brothers cycle store |
| 760 | 1011 | arif bazar | 30.16060167 | 72.68426 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Javid / Muhammad Azam | rana brothers general store |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|---------------------|-----------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 761 | 1012 | arif bazar | 30.16061 | 72.68425333 | 36 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Raay khuram shahzad | rana brothers general store |
| 762 | | Cloth Market Joyia Road | 30.15811167 | 72.68210833 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | zain | Rana general store |
| 763 | | Cloth Market Joyia Road | 30.15797 | 72.68215833 | 64 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | zaid | Rana general store |
| 764 | 12067 | Food Grain Road | 30.15655 | 72.68038667 | 224 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Rao Noor Muhammad | rao brothers marchant |
| 765 | 12068 | Food Grain Road | 30.156555 | 72.6804 | 238 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Rao Noor Muhammad | rao brothers marchant |
| 766 | | Cloth Market Joyia Road | 30.15734 | 72.68248333 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | khalid | rasheed cloth house |
| 767 | | Cloth Market Joyia Road | 30.157725 | 72.68214 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | khalid | rasheed cloth house |
| 768 | 1047 | arif bazar | 30.161505 | 72.68491333 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Rasheed Ahmad | rasheed electronics |
| 769 | 15068 | Joiya Market Dokanaat | 30.15719333 | 72.68291167 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Rasheed | rasheed shoes shop |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-----------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|----------------------------|-----------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 770 | 15018 | Joiya Market Dokanaat | 30.15711 | 72.68212333 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Rashid ALi | rashid churi makers |
| 771 | 16079 | Joiya Road | 30.15720167 | 72.68364667 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Ali | rauf autos |
| 772 | 10015 | Fire Brigade | 30.16110333 | 72.67188833 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Ameen | rauf book stall |
| 773 | 1058 | Arif Bazar | 30.16151167 | 72.684865 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | abdul rauf | rauf cycle store |
| 774 | 16026 | Joiya Road | 30.15759 | 72.68492167 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhamma d Aslam/Abdul Aziz | Raza motors |
| 775 | 10025 | Fire Brigade | 30.16111667 | 72.67163833 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Abdul Sattar | rehman associate |
| 776 | 15034 | Joiya Market Dokanaat | 30.15688 | 72.68186 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Sohail Ahmad | rehman electric store |
| 777 | 23006 | Tehsil Council | 30.15949833 | 72.68211 | 56 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Faisel Azeem | Rehman Jewelers |
| 778 | 23007 | Tehsil Council | 30.15944667 | 72.68220167 | 56 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhamma d Tariq | Rehman Jewelers |
| 779 | 8009 | Deewar High School | 30.16213667 | 72.6855 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Faqeer Hussain | rehman mobiles |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|--------------------|----------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 780 | 8033 | Deewar High School | 30.16247667 | 72.68579667 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Abdul Sattar | rehman mobiles |
| 781 | 19007 | Purani Tehsil | 30.15692833 | 72.68193333 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Hafiz Zohaib Latif | rehmat karyana store |
| 782 | 12012 | Food Grain Road | 30.15648167 | 72.68051833 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Riaz | riaz starch agency |
| 783 | 22029 | Joiya Road | 30.15637667 | 72.67966667 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Riaz ul Haq | riaz welding store |
| 784 | 22030 | Joiya Road | 30.15641167 | 72.67968667 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Riaz | riaz welding store |
| 785 | | Cloth Market Joyia Road | 30.15733 | 72.68249167 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | rizwan | rizwan gold smith |
| 786 | 19017 | Purani Tehsil | 30.156875 | 72.68168 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Sakhi Sarwar | rizwan karayana |
| 787 | 19016 | Purani Tehsil | 30.15687 | 72.68170833 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Rizwan | rizwan karyana |
| 788 | 23008 | Tehsil Council | 30.15944333 | 72.68205667 | 56 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Arshad | Robi Jewelers |
| 789 | 10012 | Fire Brigade | 30.16104833 | 72.671905 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Ashraf | rustam tea stall |
| 790 | 23004 | Tehsil Council | 30.15927167 | 72.68222833 | 56 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Abdul Mutlib | Sabir Ali Hukah shop |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|--------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|---------------------|----------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 791 | | Cloth Market Joyia Road | 30.15752167 | 72.682205 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Niaz | saddar tailors |
| 792 | | Cloth Market Joyia Road | 30.15753833 | 72.68229833 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | niaz | saddar tailors |
| 793 | 1054 | arif bazar | 30.16085333 | 72.68423833 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Zubaida | saddique bans store |
| 794 | | Cloth Market Joyia Road | 30.15844167 | 72.68256333 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad shareef | sadeeq jewelry |
| 795 | 9034 | Dokanat Vehari Bazar | 30.15899667 | 72.679725 | 48 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Sadique | sadiq bartan store |
| 796 | | Cloth Market Joyia Road | 30.15752833 | 72.68223833 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | hamza sadiq | sadiq cloth house |
| 797 | 15046 | Joiya Market Dokanaat | 30.15665333 | 72.68108 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Rana Muhammad Sadiq | sadiq karyana store |
| 798 | 26005 | Vehari Bazar Water Works | 30.16062 | 72.67294833 | 150 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Ashraf | sadiq works |
| 799 | 9035 | Dokanat Vehari Bazar | 30.15893833 | 72.67970333 | 48 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Afzal | sadique bartan store |
| 800 | 16023 | Joiya Road | 30.157605 | 72.685025 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muzaam bhutta | saeed autos |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|----------------|------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 801 | 14002 | Goal Chowk Phari Haye | 30.15907167 | 72.68173833 | 72 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Sajid | saeed karyana marchant |
| 802 | 27024 | Wapda Daftar | 30.15882333 | 72.6777 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Saeed ahmad | saeed paint house |
| 803 | 16083 | Joiya Road | 30.157255 | 72.68356667 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Shakeel ahmad | saeed sewing machine |
| 804 | 16084 | Joiya Road | 30.15726667 | 72.683535 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | shakeel | saeed sewing machine |
| 805 | 15081 | Joiya Market Dokanaat | 30.15713667 | 72.68321167 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Malik Saeed | saeed traders |
| 806 | 12023 | Food Grain Road | 30.15643333 | 72.68020167 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | bukhtyar ahmad | safa marwa motors |
| 807 | 12024 | Food Grain Road | 30.15643333 | 72.68022333 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | bakhtyar ahmad | saffa marwa motors |
| 808 | | Cloth Market Joyia Road | 30.157495 | 72.68227833 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | saif ullah | saif gold smith |
| 809 | 9067 | Dokanat Vehari Bazar | 30.158735 | 72.67896667 | 48 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | sajid | sajid gold smith |
| 810 | 9068 | Dokanat Vehari Bazar | 30.15867833 | 72.67899333 | 48 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | sajid | sajid gold smith |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-----------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------|------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 811 | 16015 | Joiya Road | 30.15768833 | 72.685265 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Nadee. | Sajjad Electro store |
| 812 | 16013 | Joiya Road | 30.15763667 | 72.68528333 | 24 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Habib | sajjad haider tarpal |
| 813 | 16014 | Joiya Road | 30.15769167 | 72.68528667 | 24 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Sajjad | Sajjad tarpal house |
| 814 | | Cloth Market Joyia Road | 30.15780833 | 72.68198 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | ghulam mustafa | sakhi lal jewelry |
| 815 | | Cloth Market Joyia Road | 30.15760333 | 72.68195 | 64 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | ghulam nabi | sakhi lal jewelry |
| 816 | 27016 | Wapda Daftar | 30.158745 | 72.67788333 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Saleem | saleem cycle store |
| 817 | 17001 | Municipal Giraje joyia road | 30.15667167 | 72.68118333 | 312 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Haroon | saleem dry fruits |
| 818 | | Cloth Market Joyia Road | 30.15761167 | 72.68217 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | khan muhammad | saleem general store |
| 819 | 8060 | Deewar High School | 30.16292833 | 72.686155 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Saleem | saleem medical store |
| 820 | 15050 | Joiya Market Dokanaat | 30.156755 | 72.68150333 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Saeem Raza | saleem raza dry fruits |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|---------------|------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 821 | 15051 | Joiya Market Dokanaat | 30.15666667 | 72.681115 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Aftaab Ahmad | saleem raza dry fruits |
| 822 | 28021 | Water Works Collony | 30.16052667 | 72.673155 | 60 | 13 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | raees khan | salman autos |
| 823 | 16009 | Joiya Road | 30.15773 | 72.68538 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Haider | Salman motors |
| 824 | | Cloth Market Joyia Road | 30.15773333 | 72.68235 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m sardar | sardar super store |
| 825 | | Cloth Market Joyia Road | 30.157705 | 72.682375 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Gulzar ahmed | sardar super store |
| 826 | 12022 | Food Grain Road | 30.15643 | 72.68026667 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Haji M sarwar | sarwar sanitary store |
| 827 | 12021 | Food Grain Road | 30.15643333 | 72.68023167 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Sarwar | Sarwar sanitary store |
| 828 | 12020 | Food Grain Road | 30.15644833 | 72.68021833 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Sarwar | Sarwar sanitary store |
| 829 | | Joiya Market Dokanaat | 30.156935 | 72.68212167 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Sarwar | sarwar sweets |
| 830 | 10028 | Fire Brigade | 30.16113667 | 72.671575 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Abdul Sattar | sattar paint house |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|------------------------|-------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 831 | 8026 | Deewar High School | 30.16239167 | 72.68570333 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Talat Mehmood Saddique | saudia tibbi foundation |
| 832 | 9017 | Dokanat Vehari Bazar | 30.15901167 | 72.68021167 | 48 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Ibraheem khalil | seed shop |
| 833 | | Cloth Market Joyia Road | 30.157165 | 72.68168333 | 128 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Farooq Ahmed | servay |
| 834 | | Cloth Market Joyia Road | 30.157185 | 72.68181333 | 128 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Rafiq | servay |
| 835 | | Cloth Market Joyia Road | 30.15725833 | 72.68187333 | 128 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Younis | servay |
| 836 | | Cloth Market Joyia Road | 30.15728167 | 72.68182167 | 128 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Abdul Ghafoor | servay |
| 837 | | Cloth Market Joyia Road | 30.15728833 | 72.68180667 | 128 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Fair | Muhammad Ashraf | servay |
| 838 | | Cloth Market Joyia Road | 30.15734833 | 72.681765 | 128 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Fair | Mehmood Ahmed | servay |
| 839 | | Cloth Market Joyia Road | 30.15725333 | 72.68169167 | 128 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Fair | Nazir Ahmed | servay |
| 840 | | Cloth Market Joyia Road | 30.15733667 | 72.68168667 | 128 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Tehsin Ahmed | servay |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-------------------|------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 841 | 22032 | Joiya Road | 30.156385 | 72.67962167 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | shabir ahmad | shabir wooden works |
| 842 | 10037 | Fire Brigade | 30.16114333 | 72.671675 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | imtiazhahmed shah | shah g gas |
| 843 | 10036 | Fire Brigade | 30.16123 | 72.67159 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | imtiazhahmed shah | shah g gas point |
| 844 | | Cloth Market Joyia Road | 30.157395 | 72.68175333 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | shah jahan | shah jahan jewelers |
| 845 | | Cloth Market Joyia Road | 30.15775833 | 72.68186667 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | shah muhammad | shah muhammad jewelers |
| 846 | | Cloth Market Joyia Road | 30.15775167 | 72.68199 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Arbaz hussain | shahbaz jewelers |
| 847 | 1028 | arif bazar | 30.161 | 72.68439 | 36 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Mushtaq | shahbaz mobile |
| 848 | 27013 | Wapda Daftar | 30.15873167 | 72.67804833 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | rana inaam | shahbaz photostate |
| 849 | 15065 | Joiya Market Dokanaat | 30.15709667 | 72.68286333 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Sadeeq | shahbaz sangar |
| 850 | 1035 | arif bazar | 30.16119667 | 72.68469167 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | saqlain ahmed | shahbaz tailors |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-----------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|----------------|----------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 851 | 8020 | Deewar High School | 30.16227333 | 72.685605 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Sughraan Bibi | shahid boot house |
| 852 | 8022 | Deewar High School | 30.162365 | 72.68570333 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Shahid | shahid electronics |
| 853 | 8023 | Deewar High School | 30.16231167 | 72.68568 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Shahid | shahid electronics |
| 854 | 27033 | Wapda Daftar | 30.15889333 | 72.67745167 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | shahid | shahid karyana store |
| 855 | 8021 | Deewar High School | 30.16230667 | 72.68561333 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Sughraan Bibi | shahid mobiles |
| 856 | 15048 | Joiya Market Dokanaat | 30.15680333 | 72.68152333 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Irfan | shahid sweets |
| 857 | 1024 | arif bazar | 30.160905 | 72.68446167 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | iqbal khan | shahid watch |
| 858 | 13007 | General Bus Stand | 30.16383333 | 72.68577167 | 112 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Shahid | shahid workshop |
| 859 | 22010 | Joiya Road | 30.15666167 | 72.68077333 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Ali | shakeel electronics |
| 860 | 15067 | Joiya Market Dokanaat | 30.15718 | 72.6829 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Shakeel Khan | shakeel wan |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|--------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------|----------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 861 | 27031 | Wapda Daftar | 30.15890333 | 72.677475 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhamma d Akram | shalimar electronics |
| 862 | | Cloth Market Joyia Road | 30.157145 | 72.682655 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Farooq siddique | Shalimar hotel |
| 863 | 1007 | arif bazar | 30.160605 | 72.68419167 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Riaz | shalimar mobiles |
| 864 | 27020 | Wapda Daftar | 30.158745 | 72.67779667 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | shamas | shamas tubewells |
| 865 | 27021 | Wapda Daftar | 30.158765 | 72.677775 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | shamas | shamas tubewells |
| 866 | 27022 | Wapda Daftar | 30.15885833 | 72.677835 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Shamas | Shamas tubewells |
| 867 | 1040 | arif bazar | 30.16128333 | 72.68467 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Shahid Mehmood | shams foam |
| 868 | 10009 | Fire Brigade | 30.16106833 | 72.67199 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Naseem akhter | shan lafafa house |
| 869 | 2005 | Barlab Nehar Vehari Baza | 30.160445 | 72.673985 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Iqbal Hussain | shan motors |
| 870 | 2006 | Barlab Nehar Vehari Baza | 30.16046833 | 72.674035 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | saith iqbal | shan motors |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|------------------|-----------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 871 | | Cloth Market Joyia Road | 30.15730833 | 72.68183667 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad shareef | shareef cloth depot |
| 872 | 9030 | Dokanat Vehari Bazar | 30.15893167 | 72.67985333 | 96 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Sharif | shareef cloth house |
| 873 | 28022 | Water Works Collony | 30.16057 | 72.67316167 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Sharif | shareef welding shop |
| 874 | | Cloth Market Joyia Road | 30.15788167 | 72.682125 | 64 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | shehbaz hussain | shehbaz jewelers |
| 875 | 12066 | Food Grain Road | 30.15663833 | 72.68064667 | 91 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Sher Zaman | shehzad autos |
| 876 | 12060 | Food Grain Road | 30.15658667 | 72.680745 | 144 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Shehzad akber | shehzad autos |
| 877 | 21023 | Androon Sabaz Mandi | 30.15905833 | 72.68211167 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Saleem | shehzad botique |
| 878 | | Cloth Market Joyia Road | 30.157395 | 72.68175333 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | shehzad | shehzad gold smith |
| 879 | 16074 | Joiya Road | 30.15727 | 72.68357167 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Akram | sheikh akram karyana store |
| 880 | 15040 | Joiya Market Dokanaat | 30.15685167 | 72.68175833 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | abdullah | sheikh haneef karyana store |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------|---------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 881 | 8006 | Deewar High School | 30.16176667 | 72.68506 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Aslam | sheikh sports |
| 882 | 12042 | Food Grain Road | 30.15632333 | 72.679785 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Sheikh shahid | sheikh steel works |
| 883 | | Cloth Market Joyia Road | 30.15745333 | 72.68207833 | 64 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | sheikh fayyaz | sheikh wazeer cloth house |
| 884 | | Cloth Market Joyia Road | 30.15735 | 72.682255 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | sheraz | sheraz gold smith |
| 885 | 8055 | Deewar High School | 30.16255333 | 72.68586333 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Iqbal | shokat karyana store |
| 886 | 1009 | arif bazar | 30.16059333 | 72.68414167 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | farhan | shop |
| 887 | | Cloth Market Joyia Road | 30.15736 | 72.68203167 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Shoukat Ali | shop |
| 888 | | Cloth Market Joyia Road | 30.15723 | 72.68226833 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Sadeeq | shop |
| 889 | | Cloth Market Joyia Road | 30.15735833 | 72.682035 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad sadeeq | shop |
| 890 | | Cloth Market Joyia Road | 30.15751 | 72.68250833 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m irshad | shop |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|---------------|----------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 891 | | Cloth Market Joyia Road | 30.15750167 | 72.682515 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Dr manzoor | shop |
| 892 | | Cloth Market Joyia Road | 30.15745667 | 72.68255833 | 120 | 1 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | m ramzan | shop |
| 893 | | Cloth Market Joyia Road | 30.15745 | 72.68255167 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m iqbal | shop |
| 894 | | Cloth Market Joyia Road | 30.15741833 | 72.68253333 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m shareef | shop |
| 895 | | Cloth Market Joyia Road | 30.15739 | 72.68255333 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | javaid iqbal | shop |
| 896 | | Cloth Market Joyia Road | 30.15739167 | 72.68256 | 120 | 1 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Habibulah | shop |
| 897 | | Cloth Market Joyia Road | 30.15743833 | 72.68250167 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Abdulustar | shop |
| 898 | | Cloth Market Joyia Road | 30.15737167 | 72.68259333 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | younus | shop |
| 899 | | Cloth Market Joyia Road | 30.15738833 | 72.68250333 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m yasin | shop |
| 900 | | Cloth Market Joyia Road | 30.15729167 | 72.68257 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Talib Hussain | shop |
| 901 | | Cloth Market Joyia Road | 30.157255 | 72.68253333 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m din | shop |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|---------------|----------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 902 | | Cloth Market Joyia Road | 30.15725167 | 72.68258833 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | shoukat ali | shop |
| 903 | | Cloth Market Joyia Road | 30.15724667 | 72.68261667 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m akram | shop |
| 904 | | Cloth Market Joyia Road | 30.15726333 | 72.682625 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Gulam Rubani | shop |
| 905 | | Cloth Market Joyia Road | 30.15722667 | 72.68262167 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Rashid nisar | shop |
| 906 | | Cloth Market Joyia Road | 30.15716667 | 72.68267833 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Umer Farooq | shop |
| 907 | | Cloth Market Joyia Road | 30.15729333 | 72.68240833 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m ishtiaq | shop |
| 908 | | Cloth Market Joyia Road | 30.15723333 | 72.68237833 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m iqbal | shop |
| 909 | | Cloth Market Joyia Road | 30.15717333 | 72.68235167 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | m mustafa | shop |
| 910 | 12005 | Food Grain Road | 30.15656667 | 72.68072333 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Abdul Rasheed | shreef crokery store |
| 911 | 1023 | arif bazar | 30.16073167 | 72.68426333 | 84 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Saddique | siddique bans store |
| 912 | | Cloth Market Joyia Road | 30.15755667 | 72.68219833 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | waseem | sk fabrics |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|----------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------|-----------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 913 | 3008 | Barshian Gass Vehari Bazar | 30.15956833 | 72.67537 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Saleem | sky star store |
| 914 | 9042 | Dokanat Vehari Bazar | 30.15887167 | 72.67952667 | 48 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Sohaib Ismail | sohaib cloth house |
| 915 | 15080 | Joiya Market Dokanaat | 30.15717333 | 72.683175 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Khalil Ahmad | split master |
| 916 | 8001 | Deewar High School | 30.161675 | 72.685085 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | khurram shehzad | ss mobiles |
| 917 | 12011 | Food Grain Road | 30.156375 | 72.680515 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Alyas | starch shop |
| 918 | 16054 | Joiya Road | 30.15755167 | 72.68450333 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | mukhtar | store warehouse |
| 919 | | Cloth Market Joyia Road | 30.15746167 | 72.68184667 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | abdul rehman | subha jewelers |
| 920 | 8032 | Deewar High School | 30.16250833 | 72.68583167 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Amjad | suhail toys |
| 921 | 3005 | Barshian Gass Vehari Bazar | 30.15953667 | 72.67544167 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Sultan Ahamd | sultan sound |
| 922 | 13004 | General Bus Stand | 30.16343667 | 72.686015 | 112 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ayaz | sunny drink corner+gu |

Integrated Development and Asset Management Plan (IDAMP)

Municipal Committee Burewala

| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
|-----------------|-----------|--------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|------------------|---------------------------|
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| | | | | | | | | | | | | | | jjar pan shop |
| 923 | 28001 | Water Works Collony | 30.16039833 | 72.67367667 | 60 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Baniyameen | Sunny motors |
| 924 | 28002 | Water Works Collony | 30.16038833 | 72.67364333 | 60 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Binyameen | sunny motors |
| 925 | 14008 | Goal Chowk Phari Haye | 30.15926167 | 72.68174833 | 72 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | zahid | super fashion shoes |
| 926 | 12065 | Food Grain Road | 30.15664833 | 72.68069833 | 60 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Abdul Majeed | super tailors |
| 927 | 9063 | Dokanat Vehari Bazar | 30.15874833 | 72.67908 | 48 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Mudasar Afzal | tahir electric |
| 928 | 21022 | Androon Sabaz Mandi | 30.15918167 | 72.682205 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Naveed ghouri | tahir jewelers |
| 929 | 10022 | Fire Brigade | 30.16109667 | 72.67171167 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | munir ahmad | tahir photostate |
| 930 | 2017 | Barlab Nehar Vehari Baza | 30.16050667 | 72.67423333 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | m Zahid | tahir shehzad parda house |
| 931 | 16025 | Joiya Road | 30.15760667 | 72.68497833 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Ashfaq ali anjum | Taj Autos |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|----------------------------------|-------------|------------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|--------------------|---------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 932 | 5002 | Chok Qasaab Vehari Bazar Dokanat | 30.15847833 | 72.678795 | 96 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Gulzar | talab mutton shop |
| 933 | 9050 | Dokanat Vehari Bazar | 30.158925 | 72.67940167 | 50 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Tanveer Ahmad khan | tanveer wan house |
| 934 | 7002 | Darbaar Vehari Bazar | 30.16049833 | 72.67291333 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Tanveer | tanveer welding |
| 935 | 15079 | Joiya Market Dokanaat | 30.15722833 | 72.68314 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | majeed | taqwa silai machine |
| 936 | 12010 | Food Grain Road | 30.15649667 | 72.68057 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M tariq | tariq store |
| 937 | | Cloth Market Joyia Road | 30.15736 | 72.68191167 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhamma d Farooq | tawakal fabrics |
| 938 | | Cloth Market Joyia Road | 30.15721667 | 72.681885 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Farooq | tawakal fabrics |
| 939 | | Cloth Market Joyia Road | 30.157235 | 72.682025 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Farooq | tawakal fabrics |
| 940 | 12057 | Food Grain Road | 30.15630333 | 72.67942667 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Ghulam Farid | til shop |
| 941 | 26002 | Vehari Bazar Water Works | 30.16066667 | 72.672885 | 105 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Shabir Ahmad | tube well shop |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|--------------------------|-------------|-------------|---------------------------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-------------------------------|-----------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 942 | 26003 | Vehari Bazar Water Works | 30.16065333 | 72.67293167 | 105 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Shabir Ahmad | tubewell shop |
| 943 | 26004 | Vehari Bazar Water Works | 30.16067667 | 72.67292167 | 105 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Shabir Ahmad | tubewell turbine shop |
| 944 | 10034 | Fire Brigade | 30.16111833 | 72.67162667 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | hafiz zubair | umair autos |
| 945 | | Cloth Market Joyia Road | 30.157325 | 72.68207667 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | umair | umair jewelers |
| 946 | 16043 | Joiya Road | 30.15753833 | 72.68455667 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Akram/Faryad Hussain | umair traders |
| 947 | 13009 | General Bus Stand | 30.16382 | 72.685735 | 112 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Umer Farooq | Umer Dogar Transport Office |
| 948 | 21015 | Sabaz Mandi Gol Chowk | 30.15901 | 72.68190667 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Saleem | umer saleem bed sheet |
| 949 | 21010 | Sabaz Mandi Gol Chowk | 30.15900167 | 72.68189833 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Saleem | umer saleem bed sheet |
| 950 | 14004 | Goal Chowk Phari Haye | 30.15909167 | 72.68179667 | 90 | 2 | Non Commercial | Owned/Managed | No | No | Rented/Leased | Good | Umer saleem | Umer saleem fabrics |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------------|------------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 951 | 21026 | Androon Sabaz Mandi | 30.15912167 | 72.68183667 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Saleem | Umer saleem fabrics |
| 952 | | Food Grain Road | 30.156485 | 72.68038833 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ghulam mustafa | umer steel works |
| 953 | 8003 | Deewar High School | 30.16168167 | 72.68504 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Murtaza+qayum | usama book dipo+qayum mobile |
| 954 | 8002 | Deewar High School | 30.16165667 | 72.68505667 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ghulam Murtaza Bhatti | usama book dipot |
| 955 | 10021 | Fire Brigade | 30.16110333 | 72.671735 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Rizwan Rafiq | usama electric store |
| 956 | | Cloth Market Joyia Road | 30.15755667 | 72.68231167 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | saleem | usama gold smith |
| 957 | | Cloth Market Joyia Road | 30.15718167 | 72.68232 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | tufail | vacant shop |
| 958 | 8040 | Deewar High School | 30.16266 | 72.68593 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | chand | vaccant shop |
| 959 | 16046 | Joiya Road | 30.15752833 | 72.68453667 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Latif | vaccant shop |
| 960 | 21016 | Sabaz Mandi Gol Chowk | 30.15898833 | 72.68161 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Sajid Farooq | vegetable shop |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------|---------------------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 961 | | Cloth Market Joyia Road | 30.15749 | 72.68197333 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Fazal Rehman | Vegetable shop |
| 962 | | Cloth Market Joyia Road | 30.15735833 | 72.68200833 | 64 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Shoukat Ali | vegetable shop |
| 963 | 26008 | Cloth market Joiya Road | 30.15742333 | 72.681835 | 128 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Ishtiaq Ahmad | Vegetable s shop |
| 964 | | Cloth Market Joyia Road | 30.15737 | 72.68173 | 128 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhamma d sadiq | Vegetable s shop |
| 965 | 9022 | Dokanat Vehari Bazar | 30.15901333 | 72.67999667 | 48 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M moosa | wahab karyana |
| 966 | 19022 | Purani Tehsil | 30.15685667 | 72.68155167 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Wali Muhammad | wal muhamma d karyana |
| 967 | 16071 | Joiya Road | 30.15734167 | 72.68384167 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Saleem | waleed brothers electric |
| 968 | 16072 | Joiya Road | 30.15725667 | 72.68351 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Rashid | waleed brothers+ bahoo electric |
| 969 | | Cloth Market Joyia Road | 30.15757 | 72.681805 | 64 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | awais | wali jewelers |
| 970 | 19021 | Purani Tehsil | 30.156845 | 72.68156 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Wali Muhammad | wali karyana store |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-----------------------|-----------------|------------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|------------------|-------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 971 | 10004 | Fire Brigade | 30.160985 | 72.672055 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Bilawal Yaqoob | waqar autos |
| 972 | 10005 | Fire Brigade | 30.160928 33 | 72.67197 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Sajawal Ahmad | waqar autos |
| 973 | 10006 | Fire Brigade | 30.16093 | 72.671965 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhamma d Yaqoob | waqar autos |
| 974 | 8035 | Deewar High School | 30.162585 | 72.685871 67 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Waqar | waqar electronics |
| 975 | 23005 | Tehsil Council | 30.159375 | 72.682328 33 | 56 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Irfan Ahmad | Waqar Jewelers |
| 976 | 22001 | Joiya Road | 30.156731 67 | 72.681303 33 | 98 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Waqas | waqas meat shop |
| 977 | 8018 | Deewar High School | 30.162301 67 | 72.685601 67 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | waqas | waqas mobiles |
| 978 | 9001 | Dokanat Vehari Bazar | 30.159123 33 | 72.680603 33 | 48 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Imran Khan | Wasee Mobiles |
| 979 | 13005 | General Bus Stand | 30.163828 33 | 72.68578 | 112 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Waseem | waseem kharadia |
| 980 | 15071 | Joiya Market Dokanaat | 30.157143 33 | 72.682996 67 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Anwar | waseem mobiles |
| 981 | 7006 | Darbaar Vehari Bazar | 30.160506 67 | 72.67284 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Excellent | Sajjad Ali | waseer dairy farm |



| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-----------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|------------------|-----------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 982 | 7007 | Darbaar Vehari Bazar | 30.16056167 | 72.67290333 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Sajjad Ali | waseer dairy farm |
| 983 | 22006 | Joiya Road | 30.15676167 | 72.68105667 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Abu Bakar | Welcome autos |
| 984 | | Joiya Road | 30.15672833 | 72.68114333 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | rana mazhar | welcome autos |
| 985 | | Joiya Road | 30.15669 | 72.68111333 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Rana mazhar | welcome autos |
| 986 | 23019 | Tehsil Council | 30.15947167 | 72.682275 | 56 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Qurban Ali | Welcome Dry Fruit |
| 987 | 14013 | Goal chowk | 30.15937667 | 72.68199167 | 41 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M sharif | welcome garments |
| 988 | 14012 | Goal Chowk Phari Haye | 30.159395 | 72.68198667 | 41 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Muhammad Sharif | welcome garments |
| 989 | 8046 | Deewar High School | 30.162735 | 72.68603333 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Sheikh irshaad | welcome medical store |
| 990 | 8047 | Deewar High School | 30.162705 | 72.68608333 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | danish | welcome medical store |
| 991 | 9057 | Dokanat Vehari Bazar | 30.15870833 | 72.67915667 | 48 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Riaz | welcome mobile |
| 992 | 6004 | Chongi dukanaat | 30.156745 | 72.68120333 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Hafiz Ali Sardar | welcome motors |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|--------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|-----------------|----------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 993 | 6005 | Chongi dukanaat | 30.1567 | 72.68126333 | 80 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Abu Bakar | welcome motors |
| 994 | 8061 | Deewar High School | 30.16303333 | 72.68612667 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | waseem shehzad | welcome sweets |
| 995 | 16066 | Joiya Road | 30.15737833 | 72.68392833 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhamma d Iqbal | welcome traders |
| 996 | 16067 | Joiya Road | 30.15731333 | 72.68391667 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Fatah Muhamma d | welcome traders |
| 997 | 12038 | Food Grain Road | 30.156335 | 72.67984333 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Abdul majeed | Wood works shop |
| 998 | | Food Grain Dokanat | 30.156915 | 72.67930667 | 144 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Baba noor din | wooden works |
| 999 | | Food Grain Dokanat | 30.15687167 | 72.67932333 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Nazar din | wooden works |
| 1000 | 11003 | Food Grain Dokanat | 30.15684 | 72.67934833 | 168 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Abdul Majeed | wooden works |
| 1001 | 22007 | Joiya Road | 30.15665833 | 72.68089667 | 98 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M yameen Sajid | yameen karyana store |
| 1002 | 12045 | Food Grain Road | 30.156315 | 72.679745 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Suleman | Yaqoob steel works |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|-------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|---------------|-----------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 1003 | 15069 | Joiya Market Dokanaat | 30.15713833 | 72.68291667 | 120 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Ahmad Ameen | yaseen sangar |
| 1004 | 9014 | Dokanat Vehari Bazar | 30.15897833 | 72.68028333 | 32 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | M Yasin | yaseen seeds |
| 1005 | 9016 | Dokanat Vehari Bazar | 30.15907167 | 72.68024833 | 56 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Naveed Ahmad | yaseen seeds |
| 1006 | 9058 | Dokanat Vehari Bazar | 30.15878 | 72.67917667 | 48 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Liaqat Ali | yasir mobiles |
| 1007 | 16040 | Joiya Road | 30.15751167 | 72.68457833 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Yasir | yasir traders |
| 1008 | 16041 | Joiya Road | 30.15749667 | 72.68457667 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | yasir | yasir traders |
| 1009 | 8029 | Deewar High School | 30.16240333 | 72.68571667 | 216 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Younas | younas electronics |
| 1010 | | Cloth Market Joyia Road | 30.15734 | 72.68248333 | 120 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | younas | younas gold smith |
| 1011 | 28024 | Water Works Collony | 30.16056333 | 72.67306833 | 60 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Yousaf | yousaf honda workshop |
| 1012 | 22002 | Joiya Road | 30.15668333 | 72.68136167 | 49 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Yousaf | yousaf karyana store |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|---------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|------------------|--------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 1013 | 1048 | arif bazar | 30.16153333 | 72.68487667 | 84 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Gulnaz Bibi | zaffar electronics |
| 1014 | 21017 | Androon Sabaz Mandi | 30.15920333 | 72.68209167 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Imran Saleem | zahid jewelers |
| 1015 | 16080 | Joiya Road | 30.15736 | 72.68365 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Shareef | zahid traders |
| 1016 | 13008 | General Bus Stand | 30.16385333 | 72.685775 | 112 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Zahid | zahid works |
| 1017 | 16032 | Joiya Road | 30.15759667 | 72.68474333 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Sardar Ali | zaibi autos |
| 1018 | 16033 | Joiya Road | 30.15756833 | 72.68474167 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Latif | zaibi autos |
| 1019 | 16035 | Joiya Road | 30.15754 | 72.68467333 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Anser | zaibi number plate |
| 1020 | 16036 | Joiya Road | 30.15753833 | 72.68467 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | anser | zaibi number plate |
| 1021 | 16062 | Joiya Road | 30.15731833 | 72.683905 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | mangoo | zaibi number plate |
| 1022 | 16029 | Joiya Road | 30.15759167 | 72.684845 | 49 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Abdul Majeed | Zaidi autos |
| 1023 | 16030 | Joiya Road | 30.15753833 | 72.68486167 | 90 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Muhammad Iqbal | zaidi autos |


| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | |
|--|-----------|--------------------------|-------------|---------------------------------|-------------|---------------|--------------------------|------------------|---------------------|------------------|----------------|---------------------------------------|----------------|-----------------------|
| Municipal Committee Burewala | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | Shop Asset Condition Assessment | | | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business |
| 1024 | 16031 | Joiya Road | 30.15755 | 72.68481667 | 90 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Farooq Ahmad | zaidi autos new |
| 1025 | | Cloth Market Joyia Road | 30.15735167 | 72.68246 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | ansar | zain gold smith |
| 1026 | | Cloth Market Joyia Road | 30.15735167 | 72.68247833 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | ansar | zain gold smith |
| 1027 | 21020 | Androon Sabaz Mandi | 30.15923 | 72.68203167 | 480 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | Hafiz Abdullah | zaman collection |
| 1028 | 9029 | Dokanat Vehari Bazar | 30.15885667 | 72.67987833 | 96 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Mudasar Khan | zeeshan general store |
| 1029 | 23025 | Tehsil Council | 30.15956167 | 72.68263 | 56 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Zia-ud-Din | zia bag house |
| 1030 | 12064 | Food Grain Road | 30.15672167 | 72.68099667 | 168 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Qasid | zia karyana store |
| 1031 | 2003 | Barlab Nehar Vehari Baza | 30.16044333 | 72.67384333 | 80 | 2 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | zia | zia number plate |
| 1032 | 28007 | Water Works Collony | 30.16045333 | 72.67345833 | 60 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M zia | zia number plate |
| 1033 | 14009 | Goal Chowk Phari Haye | 30.15922333 | 72.68185667 | 72 | 2 | Commercial | Owned/Managed | No | No | Rented/Leased | Good | M Ashraf | ziml collection |
| 1034 | | Cloth Market Joyia Road | 30.15722833 | 72.68239333 | 120 | 1 | Commercial | Owned/Managed | No | Yes | Rented/Leased | Good | Zaheer ahmed | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | | | | | | | |
|--|-----------|------------------|----------|-----------|---------------------------------|---------------|--------------------------|------------------|---------------------|--|----------------|---------------------------------------|-------------|----------|--|
| Municipal Committee Burewala | | | | | | | | | | | | | | | |
| Form: IDAMP-A17 | | | | | Shop Asset Condition Assessment | | | | | | | Asset Code: _____ Date: 05-05-2023 | | | |
| SR | Shop Code | Property Address | Latitude | Longitude | Area (Sqft) | No of Stories | Property Location Status | Ownership Status | Encroachment Status | Litigation Exist | Current Status | Condition | Tenant Name | Business | |
| Average Score | | 1 | | | 2 | | | 3 | | | 4 | | 5 | | |
| Asset Condition | | Excellent | | | Good | | | Fair | | | Poor | | Failing | | |
| Category | | A | | | B | | | C | | | D | | E | | |
| Data Collected By: Mr. Abdullah | | | | | Designation: Team Member | | | | |  Sign & Date: 30-May-2023 | | | | | |
| Data Checked By: Mr. M. Fiaz | | | | | Designation: Team Lead | | | | |  Sign & Date: 30-May-2023 | | | | | |

5. Public Places**A. Slaughter House**


| Sr # | Name | Area (Acre) | Condition | Status | Book Value (PKR Mil) |
|------|-----------------|-------------|-----------|------------|----------------------|
| 1 | Slaughter House | 0.76 | Fair | Functional | 133 |




| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | |
|--|-----------------|---|------|---------------------------------------|---------|--|--|
| Municipal Committee Burewala | | | | | | | |
| Form: IDAMP-A15 | | Slaughterhouse Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 | | | |
| Name | | P.I Link Canal | | Pictures | | | |
| Location | Latitude | 30.145890 | | | | | |
| | Longitude | 72.646758 | | | | | |
| Address | | P.I Link Canal, Multan Road | | | | | |
| Year of Construction | | 2007 | | | | | |
| Total Area (Acres) | | 0.5 | | | | | |
| Ownership | | MC | | | | | |
| Slaughter Capacity (Per Day) | Larger Animals | 30 | | | | | |
| | Smaller Animals | 50 | | | | | |
| Supervisor | | Yes | No | | | | |
| Doctor's Room | | Yes | No | | | | |
| Inhabitation Facility | | Yes | No | | | | |
| Slaughtering Hall | | Yes | No | | | | |
| Evisceration Hall | | Yes | No | | | | |
| Meat Cutting Room | | Yes | No | | | | |
| Blood Collection Arrangements | | Yes | No | | | | |
| Skin Storage Room | | Yes | No | | | | |
| Tools Disinfectant System | | Yes | No | | | | |
| Health and Hygiene SOPs | | Yes | No | | | | |
| Refrigeration / Storage System | | Yes | No | | | | |
| Separate Facility for Sick Animals | | Yes | No | | | | |
| Water Supply System | | Yes | No | | | | |
| Drainage & Disposal Facility | | Yes | No | | | | |
| Solid Waste Collection Facility | | Yes | No | | | | |
| Boundary Wall & Gate | | Yes | No | | | | |
| Approach Road Condition | | Good | Fair | Poor | | | |
| Civil Structure Condition | | Good | Fair | Poor | | | |
| Overall Rating | | | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 | | |
| Asset Condition | Excellent | Good | Fair | Poor | Failing | | |
| Category | A | B | C | D | E | | |
| Remarks / Requirements | | | | | | | |
| No remarks | | | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | | Sign & Date: 30-May-2023 | | | |

| | | |
|------------------------------|------------------------|---|
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |
|------------------------------|------------------------|---|


B. Bus Stand

| Sr # | Name | Area (Acre) | Condition | Status | Book Value (PKR Mil) |
|------|-------------------|-------------|-----------|---------|----------------------|
| 1 | General Bus Stand | 0.5 | Fair | Working | 72 |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | |
|--|---|---|----|---|--|---|---|
| Municipal Committee Burewala | | | | | | | |
| Form: IDAMP-A12 | Bus Stand Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | | | |
| Name | | General Bus Stand Burewala | | Pictures | | | |
| Location | Latitude | 30.163273 | |  | | | |
| | Longitude | 72.685867 | | | | | |
| Address | | Lari ada chowk, Multan Road, Burewala | | | | | |
| Year of Construction | | Not Available | | | | | |
| Last Major Renovation | | Not Available | | | | | |
| Area (Acres) | | 0.45 | | | | | |
| Ownership | | MC | | | | | |
| Class | | A | B | | | C | D |
| Designed Capacity of Vehicles | Buses | Not Available | | | | | |
| | Coasters | Not Available | | | | | |
| | Wagons | Not Available | | | | | |
| Daily parking of vehicles (based on information provided by MC) | Buses | 20-25 | | | | | |
| | Coasters | 0 | | | | | |
| | Wagons | 0 | | | | | |
| | Rickshaws | 0 | | | | | |
| Distance from the urban area | | 1.5 km | | | | | |
| Security | At Entry | Yes | No | | | | |
| | At Exit | Yes | No | | | | |
| Gate | At Entry | Yes | No | | | | |
| | At Exit | Yes | No | | | | |
| Waiting Area | Men | Yes | No | | | | |
| | Families | Yes | No | | | | |
| | Male | Yes | No | | | | |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|--|-----------|---|------|------|---|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A12 | | Bus Stand Asset Condition Assessment | | | Asset Code: _____ |
| | | | | | Date: 05-05-2023 |
| Washroom | Female | Yes | No | |   |
| Prayer Room | Male | Yes | No | | |
| | Female | Yes | No | | |
| Administration Office | | Yes | No | | |
| Parking Stand | Rickshaw | Yes | No | | |
| | Cars | Yes | No | | |
| Fuel Outlets | | Yes | No | | |
| Reception Desk | | Yes | No | | |
| Ticketing System | | Yes | No | | |
| Tuck Shop | | Yes | No | | |
| Workshop | | Yes | No | | |
| Ablution Area | | Yes | No | | |
| Pedestrian | | Yes | No | | |
| Green Spaces | | Yes | No | | |
| Water Arrangement | Drinking | Yes | No | | |
| Water Arrangement | Disposal | Yes | No | | |
| Boarding Shed | | Yes | No | | |
| Workshops | | Yes | No | | |
| Lighting | | Yes | No | | |
| Boundary Wall | | Yes | No | | |
| Flooring & Pavement | Type | Brick soling | | | |
| | Condition | Good | Fair | Poor | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | | |  Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | | Designation: Team Lead | | |  Sign & Date: 30-May-2023 |

C. Parks



| Sr # | Name | Area (Acre) | Condition | Status | Book Value (PKR Mil) |
|------|-------------------------------|-------------|-----------|------------|----------------------|
| 1 | Ladies & Children Park | 1.63 | Good | Functional | 182 |
| 2 | Family Park Chungi # 5 | 3.75 | Fair | Functional | 420 |
| 3 | Khadija Tul Qubra | 1.10 | Fair | Functional | 123 |
| 4 | Satellite Town / Jamia Hanifa | 3.90 | Poor | Functional | 374 |


| Integrated Development and Asset Management Plan (IDAMP) | | | | |
|---|------------------------------------|------------------------|------|---------------------------------------|
| Municipal Committee Burewala | | | | |
| Form: IDAMP-A10 | Park Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 |
| Name | | Ladies & Children Park | | Pictures |
| Location | Latitude | 30.158332 | | |
| | Longitude | 72.670945 | | |
| Area In Acres | | 1.63 | | |
| Ownership-Owned by MC or possession allocated to MC by any other department (documents available) | | MC | | |
| Turfing Condition | | Good | Fair | Poor |
| Approach Road | | Good | Fair | Poor |
| Parking Lots | | Yes | No | |
| Canteen Availability | | Yes | No | |
| Average number of daily visitors (based on the assessment of MC staff) | | 300 | | |
| Any illegal occupants or encroachments observed-if yes, type | | No | | |
| Security system | | Yes | No | |
| Watering & Irrigation | | | | |
| Tube Well | | Yes | No | |
| Water Supply from Municipal System | | Yes | No | |
| Water Tank | | Yes | No | |
| Pumping Unit | | Yes | No | |
| Distribution Pipe Lines | | Yes | No | |
| Valves | | Yes | No | |
| Sprinkler System | | Yes | No | |
| Ground water storage reservoirs/ponds | | Yes | No | |
| Landscaping & Plantation | | | | |
| Grass Beds | | Yes | No | |
| Flower Beds | | Yes | No | |
| Hedges | | Yes | No | |
| Plants | | Yes | No | |
| Number of trees and species (based on readily available information at MC) | | 50 | | |
| Lights | | | | |
| Total Number | | 13 | | |
| Poles | | Yes | No | |
| Cables | | Yes | No | |
| Brackets And Lights | | Yes | No | |
| Bulbs And Tubes | | Yes | No | |
| Control Units | | Yes | No | |







Pictures



| Structures | | | | | | |
|--|-----------|--------------------------|------|------|---|---------|
| No. of Toilets | Gents | 01 | | | | |
| | Ladies | 01 | | | | |
| Condition of Toilets | Gents | Good | Fair | Poor | | |
| | Ladies | Good | Fair | Poor | | |
| Buildings | | Yes | No | | | |
| Fountains & Water Fall Structure | | Yes | No | | | |
| Walkways | | Yes | No | | | |
| Jogging tracks | | Yes | No | | | |
| Ramps at entry gates for wheel chairs | | Yes | No | | | |
| Bridges & Culverts | | Yes | No | | | |
| Play Area | | Yes | No | | | |
| Gazebos | | Yes | No | | | |
| Benches/ sitting arrangements | | Yes | No | | | |
| Boundary Wall & Gate | | Yes | No | | | |
| Toilets | | Yes | No | | | |
| Lakes & Brooks | | Yes | No | | | |
| Mechanical Equipment | | | | | | |
| Pumping Units | | Yes | No | | | |
| Swings | | Yes | No | | | |
| Children Games | | Yes | No | | | |
| Fixtures | | Yes | No | | | |
| Benches | | Yes | No | | | |
| Sanitation & Water Supply | | | | | | |
| Litter Bins | | Yes | No | | | |
| Condition of SWM | | Good | Fair | Poor | | |
| Toilet Fixtures | | Yes | No | | | |
| Sewerage System | | Yes | No | | | |
| Vegetation Cuttings & Disposal | | Yes | No | | | |
| Drinking water availability and quality (based on availability of water quality test reports) | | Not Available | | | | |
| Water Pipes | | Yes | No | | | |
| HR | | | | | | |
| Security Guards | | Yes | No | | | |
| Landscape Experts | | Yes | No | | | |
| Mali / Beldaar (Number) | | 2 | | | | |
| Overall Rating | | | | | | |
| Average Score | 1 | 2 | | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | | Fair | Poor | Failing |
| Category | A | B | | C | D | E |
| Remarks / Requirements | | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | | |
| Data Collected By: Mr. Abdullah | | Designation: Team Member | | |  Sign & Date: 30-May-2023 | |



| | | |
|------------------------------|------------------------|---|
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |
|------------------------------|------------------------|---|

| Integrated Development and Asset Management Plan (IDAMP) | | | | |
|---|------------------------------------|-------------------------|------|---------------------------------------|
| Municipal Committee Burewala | | | | |
| Form: IDAMP-A10 | Park Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 |
| Name | | Family Park, Chungi #05 | | Pictures |
| Location | Latitude | 30.161962 | | |
| | Longitude | 72.671628 | | |
| Area In Acres | | 3.75 | | |
| Ownership-Owned by MC or possession allocated to MC by any other department (documents available) | | MC | | |
| Turfing Condition | | Good | Fair | Poor |
| Approach Road | | Good | Fair | Poor |
| Parking Lots | | Yes | | No |
| Canteen Availability | | Yes | No | |
| Average number of daily visitors (based on the assessment of MC staff) | | 500 | | |
| Any illegal occupants or encroachments observed-if yes, type | | No | | |
| Security system | | Yes | No | |
| Watering & Irrigation | | | | |
| Tube Well | | Yes | No | |
| Water Supply from Municipal System | | Yes | No | |
| Water Tank | | Yes | No | |
| Pumping Unit | | Yes | No | |
| Distribution Pipe Lines | | Yes | No | |
| Valves | | Yes | No | |
| Sprinkler System | | Yes | No | |
| Ground water storage reservoirs/ponds | | Yes | No | |
| Landscaping & Plantation | | | | |
| Grass Beds | | Yes | No | |
| Flower Beds | | Yes | No | |
| Hedges | | Yes | No | |
| Plants | | Yes | No | |
| Number of trees and species (based on readily available information at MC) | | 35 | | |
| Lights | | | | |









| | | | | | |
|---|---------------|------|------|------|---------|
| Total Number | 28 | | | | |
| Poles | Yes | No | | | |
| Cables | Yes | No | | | |
| Brackets And Lights | Yes | No | | | |
| Bulbs And Tubes | Yes | No | | | |
| Control Units | Yes | No | | | |
| Structures | | | | | |
| No. of Toilets | Gents | 2 | | | |
| | Ladies | 2 | | | |
| Condition of Toilets | Gents | Good | Fair | Poor | |
| | Ladies | Good | Fair | Poor | |
| Buildings | Yes | No | | | |
| Fountains & Water Fall Structure | Yes | No | | | |
| Walkways | Yes | No | | | |
| Jogging tracks | Yes | No | | | |
| Ramps at entry gates for wheel chairs | Yes | No | | | |
| Bridges & Culverts | Yes | No | | | |
| Play Area | Yes | No | | | |
| Gazebos | Yes | No | | | |
| Benches/ sitting arrangements | Yes | No | | | |
| Boundary Wall & Gate | Yes | No | | | |
| Toilets | Yes | No | | | |
| Lakes & Brooks | Yes | No | | | |
| Mechanical Equipment | | | | | |
| Pumping Units | Yes | No | | | |
| Swings | Yes | No | | | |
| Children Games | Yes | No | | | |
| Fixtures | Yes | No | | | |
| Benches | Yes | No | | | |
| Sanitation & Water Supply | | | | | |
| Litter Bins | Yes | No | | | |
| Condition of SWM | Good | Fair | Poor | | |
| Toilet Fixtures | Yes | No | | | |
| Sewerage System | Yes | No | | | |
| Vegetation Cuttings & Disposal | Yes | No | | | |
| Drinking water availability and quality (based on availability of water quality test reports) | Not Available | | | | |
| Water Pipes | Yes | No | | | |
| HR | | | | | |
| Security Guards | Yes | No | | | |
| Landscape Experts | Yes | No | | | |
| Mali / Beldaar (Number) | 03 | | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | |


| | | |
|---------------------------------|--------------------------|---|
| Data Collected By: Mr. Abdullah | Designation: Team Member |  Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |


| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|---|------------------------------------|------------------------|------|--|------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A10 | Park Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Name | | Khadija Tul Qubra Park | |   | |
| Location | Latitude | 30.174738 | | | |
| | Longitude | 72.689408 | | | |
| Area In Acres | | 1.1 | | | |
| Ownership-Owned by MC or possession allocated to MC by any other department (documents available) | | MC | | | |
| Turfing Condition | | Good | Fair | | Poor |
| Approach Road | | Good | Fair | | Poor |
| Parking Lots | | Yes | No | | |
| Canteen Availability | | Yes | No | | |
| Average number of daily visitors (based on the assessment of MC staff) | | 100 | | | |
| Any illegal occupants or encroachments observed-if yes, type | | No | | | |
| Security system | | Yes | No | | |
| Watering & Irrigation | | | | | |
| Tube Well | | Yes | No | | |
| Water Supply from Municipal System | | Yes | No | | |
| Water Tank | | Yes | No | | |
| Pumping Unit | | Yes | No | | |
| Distribution Pipe Lines | | Yes | No | | |
| Valves | | Yes | No | | |
| Sprinkler System | | Yes | No | | |
| Ground water storage reservoirs/ponds | | Yes | No | | |
| Landscaping & Plantation | | | | | |
| Grass Beds | | Yes | No | | |
| Flower Beds | | Yes | No | | |
| Hedges | | Yes | No | | |

| | | | | | |
|--|----------------|-----------|-----------|-----------|--------------|
| Plants | Yes | No | | | |
| Number of trees and species (based on readily available information at MC) | 5 | | | | |
| Lights | | | | | |
| Total Number | 18 | | | | |
| Poles | Yes | No | | | |
| Cables | Yes | No | | | |
| Brackets And Lights | Yes | No | | | |
| Bulbs And Tubes | Yes | No | | | |
| Control Units | Yes | No | | | |
| Structures | | | | | |
| No. of Toilets | Gents | 0 | | | |
| | Ladies | 0 | | | |
| Condition of Toilets | Gents | - | | | |
| | Ladies | - | | | |
| Buildings | Yes | No | | | |
| Fountains & Water Fall Structure | Yes | No | | | |
| Walkways | Yes | No | | | |
| Jogging tracks | Yes | No | | | |
| Ramps at entry gates for wheel chairs | Yes | No | | | |
| Bridges & Culverts | Yes | No | | | |
| Play Area | Yes | No | | | |
| Gazebos | Yes | No | | | |
| Benches/ sitting arrangements | Yes | No | | | |
| Boundary Wall & Gate | Yes | No | | | |
| Toilets | Yes | No | | | |
| Lakes & Brooks | Yes | No | | | |
| Mechanical Equipment | | | | | |
| Pumping Units | Yes | No | | | |
| Swings | Yes | No | | | |
| Children Games | Yes | No | | | |
| Fixtures | Yes | No | | | |
| Benches | Yes | No | | | |
| Sanitation & Water Supply | | | | | |
| Litter Bins | Yes | No | | | |
| Condition of SWM | Good | Fair | Poor | | |
| Toilet Fixtures | Yes | No | | | |
| Sewerage System | Yes | No | | | |
| Vegetation Cuttings & Disposal | Yes | No | | | |
| Drinking water availability and quality (based on availability of water quality test reports) | Not Available | | | | |
| Water Pipes | Yes | No | | | |
| HR | | | | | |
| Security Guards | Yes | No | | | |
| Landscape Experts | Yes | No | | | |
| Mali / Beldaar (Number) | 01 | | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition Category | Excellent A | Good B | Fair C | Poor D | Failing E |
| Remarks / Requirements | | | | | |

| | | |
|---------------------------------|--------------------------|---|
| • No remarks | | |
| Data Collected By: Mr. Abdullah | Designation: Team Member |  Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |


| Integrated Development and Asset Management Plan (IDAMP) | | | | | |
|---|------------------------------------|--------------------------------------|------|---|------|
| Municipal Committee Burewala | | | | | |
| Form: IDAMP-A10 | Park Asset Condition Assessment | | | Asset Code: _____ Date: 05-05-2023 | |
| Name | | Jamia Hanfia Park, Satellite Town | | Pictures     | |
| Location | Latitude | 30.164538 | | | |
| | Longitude | 72.692196 | | | |
| Area In Acres | | 3.9 | | | |
| Ownership-Owned by MC or possession allocated to MC by any other department (documents available) | | MC | | | |
| Turfing Condition | | Good | Fair | | Poor |
| Approach Road | | Good | Fair | | Poor |
| Parking Lots | | Yes | No | | |
| Canteen Availability | | Yes | No | | |
| Average number of daily visitors (based on the assessment of MC staff) | | 350 | | | |
| Any illegal occupants or encroachments observed-if yes, type | | No | | | |
| Security system | | Yes | No | | |
| Watering & Irrigation | | | | | |
| Tube Well | | Yes | No | | |
| Water Supply from Municipal System | | Yes | No | | |
| Water Tank | | Yes | No | | |
| Pumping Unit | | Yes | No | | |
| Distribution Pipe Lines | | Yes | No | | |
| Valves | | Yes | No | | |
| Sprinkler System | | Yes | No | | |
| Ground water storage reservoirs/ponds | | Yes | No | | |
| Landscaping & Plantation | | | | | |
| Grass Beds | | Yes | No | | |
| Flower Beds | | Yes | No | | |
| Hedges | | Yes | No | | |
| Plants | | Yes | No | | |
| Number of trees and species (based on readily available information at MC) | | 50 | | | |
| Lights | | | | | |
| Total Number | | 28 | | | |
| Poles | | Yes | No | | |
| Cables | | Yes | No | | |
| Brackets And Lights | | Yes | No | | |
| Bulbs And Tubes | | Yes | No | | |
| Control Units | | Yes | No | | |



| Structures | | | | | |
|---|--------------------------|------|------|---|---------|
| No. of Toilets | Gents | 0 | | | |
| | Ladies | 0 | | | |
| Condition of Toilets | Gents | - | | | |
| | Ladies | - | | | |
| Buildings | Yes | No | | | |
| Fountains & Water Fall Structure | Yes | No | | | |
| Walkways | Yes | No | | | |
| Jogging tracks | Yes | No | | | |
| Ramps at entry gates for wheel chairs | Yes | No | | | |
| Bridges & Culverts | Yes | No | | | |
| Play Area | Yes | No | | | |
| Gazebos | Yes | No | | | |
| Benches/ sitting arrangements | Yes | No | | | |
| Boundary Wall & Gate | Yes | No | | | |
| Toilets | Yes | No | | | |
| Lakes & Brooks | Yes | No | | | |
| Mechanical Equipment | | | | | |
| Pumping Units | Yes | No | | | |
| Swings | Yes | No | | | |
| Children Games | Yes | No | | | |
| Fixtures | Yes | No | | | |
| Benches | Yes | No | | | |
| Sanitation & Water Supply | | | | | |
| Litter Bins | Yes | No | | | |
| Condition of SWM | Good | Fair | Poor | | |
| Toilet Fixtures | Yes | No | | | |
| Sewerage System | Yes | No | | | |
| Vegetation Cuttings & Disposal | Yes | No | | | |
| Drinking water availability and quality (based on availability of water quality test reports) | Not Available | | | | |
| Water Pipes | Yes | No | | | |
| HR | | | | | |
| Security Guards | Yes | No | | | |
| Landscape Experts | Yes | No | | | |
| Mali / Beldaar (Number) | 02 | | | | |
| Overall Rating | | | | | |
| Average Score | 1 | 2 | 3 | 4 | 5 |
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |
| Remarks / Requirements | | | | | |
| • No remarks | | | | | |
| Data Collected By: Mr. Abdullah | Designation: Team Member | | |  Sign & Date: 30-May-2023 | |

| | | |
|------------------------------|------------------------|---|
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 |
|------------------------------|------------------------|---|


6. Office Vehicles

| Sr # | Name | Registration Number | Age (Years) | Capacity | Condition | Status | Book Value (PKR Mil) |
|------|----------------|---------------------|-------------|----------|-----------|------------|----------------------|
| 1 | Cultus | VRG 37 | 21 | 1000 CC | Fair | Functional | 0.4 |
| 2 | Potohar SJ-410 | VRK 37 | 17 | 970 CC | Fair | Functional | 0.3 |
| 3 | Khyber | VRC 3371 | N/A | 993 CC | Poor | Functional | 0.2 |

| Integrated Development and Asset Management Plan (IDAMP) | | | |
|--|--|---------------|---------------------------------------|
| Municipal Committee Burewala | | | |
| Form: IDAMP-A16 | Moveable Asset Asset Condition Assessment | | Asset Code: _____ Date: 05-05-2023 |
| Type of Vehicle / Machinery | Pictures | | |
| Cars |  | | |
| | Suzuki 1 | Suzuki 2 | Suzuki 3 |
| Capacity | 1000 CC | 1000 CC | 1000 CC |
| Purpose | Staff | Staff | Staff |
| Year of Manufacturing | 2002 | 2006 | Not Available |
| Model | Cultus | Potohar | Khyber |
| Capital Cost | | | |
| Fuel Consumption (Lt) | 365 | 365 | 325 |
| Condition | Fair | Fair | Poor |
| Engine Capacity | 1000 CC | 970 CC | 993 CC |
| Maintenance Cost | Not Available | Not Available | Not Available |
| Oiling /Fitness | Yes | Yes | Yes |
| Fitness Certificate | No | No | No |
| Registered | VRG 37 | VRK 37 | VRC 3371 |






| Overall Rating | Fair | Fair | Poor |
|--|--------------------------|------|---|
| Remarks / Requirements | | | |
| <ul style="list-style-type: none"> No remarks | | | |
| Data Collected By: Mr. Abdullah | Designation: Team Member | |  Sign & Date: 30-May-2023 |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead | |  Sign & Date: 30-May-2023 |

7. Street Lights



| | Streetlights | MC Operated | Privately Operated |
|-------------------------------|--------------|-------------|--------------------|
| Operational Street Lights | 191 | 191 | |
| Non-Operational Street Lights | 12 | 12 | |
| Faulty Meter / Line | 6 | 6 | |
| Total | 209 | 209 | 0 |


| Operated by | Precast Concrete | Steel Structure | Tubular Steel | Pillars | Grand Total |
|-------------|------------------|-----------------|---------------|---------|-------------|
| MC | 47 | 58 | 47 | 17 | 169 |
| Private | | | | | 0 |

| Integrated Development and Asset Management Plan (IDAMP) | | | |
|---|---|---|-----------------------------------|
| Municipal Committee Burewala | | | |
| Form: IDAMP-A9 | Street Lights Asset Condition Assessment | Asset Code: _____ | Date: 05-05-2023 |
| Pictures | | | |
|  |  |  | |
| Area | Total | Operational Status | Poles Type (WAPDA Pole / MC Pole) |
| Gol Chowk | 28 | Not Available | Not Available |
| Machli Bazar | 12 | Not Available | Not Available |
| Vehari Bazar | 47 | Not Available | Not Available |
| Water Works Colony | 36 | Not Available | Not Available |
| Ladies and Children Park | 16 | Not Available | Not Available |
| Habib Colony Road | 13 | Not Available | Not Available |
| City Graveyard | 10 | Not Available | Not Available |
| Fawarah Chowk | 19 | Not Available | Not Available |
| Stadium Road | 22 | Not Available | Not Available |
| Multan Road | 6 | Not Available | Not Available |
| Remarks / Requirements | | | |
| No remarks | | | |
| Data Collected By: Mr. Abdullah | Designation: Team Member |  Sign & Date: 30-May-2023 | |
| Data Checked By: Mr. M. Fiaz | Designation: Team Lead |  Sign & Date: 30-May-2023 | |

Out of the 209 lights in the MC, 191 lights are operational. Details are given in the following table:

| Equipment Type | Wattage of Lighting Fixture | Quantity | | Daily Operational Hours |
|----------------|-----------------------------|----------|---------|-------------------------|
| | | MC | Private | |
| LED | 120 | 182 | - | 12.0 |
| LED | 100 | 9 | - | 12.0 |
| Total | | | | |

8. Roads




| Sr # | Road Name | R.O.W (ft) | Existing Type | Length (km) |
|------|----------------------|------------|---------------|-------------|
| 1 | Joyia Road | 40 | T.S.T | 2 |
| 2 | Mujahid colony road | 30 | T.S.T | 2 |
| 3 | Dr. Irfan Ali road | 30 | T.S.T | 1 |
| 4 | Iqbal nagar road | 30 | T.S.T | 1.5 |
| 5 | Fruit Mandi road | 25 | T.S.T | 1 |
| 6 | Barki road | 28 | T.S.T | 3 |
| 7 | Disposal road | 22 | T.S.T | 1 |
| 8 | Shabir Town road | 25 | T.S.T | 0.75 |
| 9 | Imam Bargha road | 30 | T.S.T | 2 |
| 10 | Adda Dewan link road | 30 | T.S.T | 1.5 |
| 11 | Sadiq town road | 24 | T.S.T | 2.5 |
| 12 | Sharif town road | 20 | T.S.T | 3 |
| 13 | Akhtar Town road | 20 | T.S.T | 1.5 |
| 14 | New Barki road | 32 | T.S.T | 2 |

| Sr # | Road Name | R.O.W (ft) | Existing Type | Length (km) |
|------|--------------------|------------|---------------|-------------|
| 15 | Afaq Khan Road | 30 | T.S.T | 1.5 |
| 16 | Arif Bazar | 53 | Asphalt | 0.6 |
| 17 | College Road | 48 | Asphalt | 0.46 |
| 18 | Fish Bazar | 30 | TST | 0.25 |
| 19 | Rail Bazar | 50 | Asphalt | 0.15 |
| 20 | Vehari Bazar | 49 | Asphalt | 0.24 |
| 21 | Vehari Bazar | 70 | Asphalt | 0.83 |
| 22 | Goal Chowk | 60 | Asphalt | 0.167 |
| 23 | Anwar Town | 25 | TST | 0.35 |
| 24 | Shah Faiz Park | 20 | TST | 0.88 |
| 25 | Shah Faisal colony | 20 | TST | 0.97 |
| 26 | Dumping Point | 24 | TST | 2.32 |
| 27 | Lat Bhattian | 20 | TST | 0.37 |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | |
|--|------------------------------------|-----------------------|---------------------|--------------|---------------------------------|----------|---------------------------------------|---------------------|-----------|
| Municipal Committee Burewala | | | | | | | | | |
| Form: IDAMP-A8 | Road Asset Condition Assessment | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| Pictures | | | | | | | | | |
| Sr. No. | Road Name | From | to | Ownership | TST, Asphalt Or Concrete Pavers | Row (Ft) | Paved Width (Ft) | Approx. Length (Km) | Condition |
| 1 | Joyia Road | Chowk Qasian | Chamra Mandi (Pump) | MC, Burewala | T.S.T | 40 | 16 | 2 | Poor |
| 2 | Mujahid colony road | Phatic Mujahid Colony | Canal | MC, Burewala | T.S.T | 30 | 10 | 2 | Poor |
| 3 | Dr. Irfan Ali road | Nadeem Iron Store | Office Agriculture | MC, Burewala | T.S.T | 30 | 16 | 1 | Poor |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | |
|--|------------------------------------|-------------------------|--------------------------------|--------------|---------|----|---------------------------------------|------|------|
| Municipal Committee Burewala | | | | | | | | | |
| Form: IDAMP-A8 | Road Asset Condition Assessment | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| 4 | Iqbal nagar road | Multan Road | Iqbal Nagar | MC, Burewala | T.S.T | 30 | 10 | 1.5 | Poor |
| 5 | Fruit Mandi road | Lat Bhattian | Ishtiq Nagar | MC, Burewala | T.S.T | 25 | 10 | 1 | Poor |
| 6 | Barki road | Shah Faiz Park | Chak No. 445/EB Along BTM | MC, Burewala | T.S.T | 28 | 16 | 3 | Poor |
| 7 | Disposal road | Graveyard Shah Zakrai | Chak No. 435/EB near UC office | MC, Burewala | T.S.T | 22 | 10 | 1 | Poor |
| 8 | Shabir Town road | Chichawatni Road | Shabir Town | MC, Burewala | T.S.T | 25 | 12 | 0.75 | Poor |
| 9 | Imam Bargha road | Fountain Chowk | Imam Bargha | MC, Burewala | T.S.T | 30 | 10 | 2 | Poor |
| 10 | Adda Dewan link road | Adda Dewan Sahib | Habib Colony Link Luddun Road | MC, Burewala | T.S.T | 30 | 10 | 1.5 | Poor |
| 11 | Sadiq town road | Sadiq town | Chichawatni Road | MC, Burewala | T.S.T | 24 | 10 | 2.5 | Poor |
| 12 | Sharif town road | Sharif Town | Fareed Town | MC, Burewala | T.S.T | 20 | 10 | 3 | Poor |
| 13 | Akhtar Town road | Street No. 1 Marzi Pura | Akhtar Town | MC, Burewala | T.S.T | 20 | 10 | 1.5 | Poor |
| 14 | New Barki road | Mujahid Colony | Barki Link Canal | MC, Burewala | T.S.T | 32 | 20 | 2 | Poor |
| 15 | Afaq Khan Road | Afaq Khan Chowk | Multan Road | MC, Burewala | T.S.T | 30 | 10 | 1.5 | Fair |
| 16 | Arif Bazar | Arif Bazar | Lorry Adda chowk | MC, Burewala | Asphalt | 53 | 53 | 0.6 | Poor |

| Integrated Development and Asset Management Plan (IDAMP) | | | | | | | | | |
|--|------------------------------------|------------------|--------------------------|--------------|---------|---|---------------------------------------|-------|------|
| Municipal Committee Burewala | | | | | | | | | |
| Form: IDAMP-A8 | Road Asset Condition Assessment | | | | | | Asset Code: _____ Date: 05-05-2023 | | |
| 17 | College Road | Goal Chowk | Multan Road | MC, Burewala | Asphalt | 48 | 48 | 0.46 | Poor |
| 18 | Fish Bazar | Vehari Bazar | Joiya Road | MC, Burewala | TST | 30 | 16 | 0.25 | Poor |
| 19 | Rail Bazar | Goal Chowk | Joiya road | MC, Burewala | Asphalt | 50 | 43 | 0.15 | Poor |
| 20 | Vehari Bazar | Goal Chowk | Chowk Qasian | MC, Burewala | Asphalt | 49 | 40 | 0.24 | Poor |
| 21 | Vehari Bazar | Chowk Qasian | Choungi No. 5 | MC, Burewala | Asphalt | 70 | 30 | 0.83 | Poor |
| 22 | Goal Chowk | Goal Chowk | Office M.C | MC, Burewala | Asphalt | 60 | 49 | 0.167 | Poor |
| 23 | Anwar Town | Main Road | | MC, Burewala | TST | 25 | 10 | 0.35 | Poor |
| 24 | Shah Faiz Park | BTM | Barki Road | MC, Burewala | TST | 20 | 10 | 0.88 | Poor |
| 25 | Shah Faisal colony | Doctor Majid | Meezan Super Store | MC, Burewala | TST | 20 | 10 | 0.97 | Poor |
| 26 | Dumping Point | Pull Rehmat Abad | Chak 423/EB | MC, Burewala | TST | 24 | 24 | 2.32 | Poor |
| 27 | Lat Bhattian | Multan Road | Graveyard | MC, Burewala | TST | 20 | 10 | 0.37 | Poor |
| Remarks / Requirements | | | | | | | | | |
| <ul style="list-style-type: none"> No remarks | | | | | | | | | |
| Data Collected By: Mr. Abdullah | | | Designation: Team Member | | |  Sign & Date: 30-May-2023 | | | |
| Data Checked By: Mr. M. Fiaz | | | Designation: Team Lead | | |  Sign & Date: 30-May-2023 | | | |

Annexure B. Projects Coding Scheme:

| Region Name | Region Code | MC | MC Code | Property Types | Property Type Code | Sub Property Types | Sub Property Type Code | Unique Codes |
|-----------------|-------------|----------------|---------|-------------------------------|--------------------|---------------------------|------------------------|----------------|
| Southern Punjab | 03 | Burewala | 13 | Water Supply System | 01 | Tube wells | 01 | 03-13-01-01-XX |
| | | | | | | Water Supply Network (ft) | 02 | 03-13-01-02-XX |
| | | | | | | OHR | 03 | 03-13-01-03-XX |
| | | | | | | Filtration Plants | 04 | 03-13-01-04-XX |
| | | | | | | Vehicles | 05 | 03-13-01-05-XX |
| | | | | | | GST | 06 | 03-13-01-06-XX |
| | | | | Sewerage System | 02 | Sewerage Network (ft) | 01 | 03-13-02-01-XX |
| | | | | | | Disposal Stations | 02 | 03-13-02-02-XX |
| | | | | | | Vehicles | 03 | 03-13-02-03-XX |
| | | | | Solid Waste Management System | 03 | Dumping site | 01 | 03-13-03-01-XX |
| | | | | | | Vehicles | 02 | 03-13-03-02-XX |
| | | | | | | Parking Shed | 03 | 03-13-03-03-XX |
| | | | | Roads and Streets | 04 | Roads | 01 | 03-13-04-01-XX |
| | | | | | | Street | 02 | 03-13-04-02-XX |
| | | | | | | Street light | 03 | 03-13-04-03-XX |
| | | | | Public Places | 05 | Parks | 01 | 03-13-05-01-XX |
| | | | | | | Playgrounds | 02 | 03-13-05-02-XX |
| | | | | | | Open Spaces / Plots | 03 | 03-13-05-03-XX |
| | | | | | | Bus Stand | 04 | 03-13-05-04-XX |
| | | | | | | Library | 05 | 03-13-05-05-XX |
| | | | | | | Slaughter Houses | 06 | 03-13-05-06-XX |
| Graveyards | 07 | 03-13-05-07-XX | | | | | | |

| Region Name | Region Code | MC | MC Code | Property Types | Property Type Code | Sub Property Types | Sub Property Type Code | Unique Codes |
|-------------|-------------|----|---------|----------------|--------------------|----------------------|------------------------|----------------|
| | | | | | | Masjid/ Imam bargah | 08 | 03-13-05-08-XX |
| | | | | | | Shops | 09 | 03-13-05-09-XX |
| | | | | Others | 06 | Office buildings | 01 | 03-13-06-01-XX |
| | | | | | | Office vehicles | 02 | 03-13-06-02-XX |
| | | | | | | Residential building | 03 | 03-13-06-03-XX |

Annexure C. Project Screening and Phasing

Project ID: 03-13-01-02-01
 Project Description : Improvement & Rehabilitation of Water Supply system in Burewala City

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score | | |
|--|---|--------------|-----------------|------------|--------------------------|---|---|------------------------------|----|
| 1. Project Purpose & Service Delivery Improvement | | | | | | | | | |
| 1.1 | Does the project fill a gap in a wider system of service delivery? | 30 | 10 | 2.5 | Minor contribution | Significant contribution | 10 | | |
| | | | | 7.5 | Major contribution | | | | |
| | | | | 10 | Significant contribution | | | | |
| 1.2 | Whether the project will contribute to Sectoral Plan / City Master Plan? | | 30 | 10 | 0 | No contribution. | Major contribution to key development goal. | 10 | |
| | | | | | 2.5 | Indirect contribution. | | | |
| | | | | | 7.5 | Minor direct contribution | | | |
| | | | | | 10 | Major contribution to key development goal. | | | |
| 1.3 | Whether the deference/ delay of the project is going to affect citizens' health, safety, property, prosperity etc.? | | | 30 | 10 | 0 | No consequences | Major immediate consequences | 10 |
| | | | | | | 2.5 | Minor consequences | | |
| | | 7.5 | | | | Major future consequences | | | |
| | | 10 | | | | Major immediate consequences | | | |
| 2. Public Response | | | | | | | | | |
| 2.1 | Population served by the project. | 15 | 7.5 | | 1 | Less than 10% | Greater than 20% | 7.5 | |
| | | | | | 5 | Between 10% to 20% | | | |
| | | | | | 7.5 | Greater than 20% | | | |

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score |
|---------------------------------|---|--------------|-----------------|------------|--|---|----------------|
| 2.2 | Is there support or opposition for the project from NGO's, community groups, network, media or business organizations? | | 5 | 0 | Majority opposition | Majority support | 5 |
| | | | | 1 | Minority opposition | | |
| | | | | 5 | Majority support | | |
| | | | | 2.5 | Minority support | | |
| 2.3 | Is there support or opposition from residents in the immediate vicinity of the new facility? | | 2.5 | 0 | Majority opposition | Majority support | 2.5 |
| | | | | 0.5 | Minority opposition | | |
| | | | | 2.5 | Majority support | | |
| | | | | 1.5 | Minority support | | |
| 3. Environmental Impact | | | | | | | |
| 3.1 | The impact of the proposed project on the quality of local environment (e.g. Air quality, Water pollution, Waste reduction, etc. | 10 | 10 | 0 | Negative effects on quality of the local environment | Positive effects on the quality of the local environment | 10 |
| | | | | 5 | Neutral | | |
| | | | | 10 | Positive effects on the quality of the local environment | | |
| 4. Socio-Economic Impact | | | | | | | |
| 4.1 | Will the project bring in direct revenue? | 15 | 7.5 | 0 | No direct revenue | Direct revenue is not sufficient to meet O&M costs | 2.5 |
| | | | | 2.5 | Direct revenue is not sufficient to meet O&M costs | | |
| | | | | 5 | Revenue meets O&M costs | | |
| | | | | 7.5 | Revenue exceeds O&M costs | | |
| 4.2 | Are there indirect economic benefits from this project in the long term, e.g. employment creation, investment generation, increase in land/property | | 7.5 | 0 | Negative impact on the local economy | Additional investment in the area and increased wealth for citizens | 5 |
| | | | | 2.5 | Little or no long term economic development benefits | | |

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score | |
|----------------------------------|---|--------------|-----------------|------------|--|--|----------------|-----|
| | prices, reduction in citizens' expenditures, etc.? | | | 5 | Additional investment in the area and increased wealth for citizens | | | |
| | | | | 7.5 | Significant competitive advantage to industry and boost to the local economy | | | |
| 5. Ease of Implementation | | | | | | | | |
| 5.1 | Has land been acquired for the project (If required)? | 30 | 10 | 10 | Yes | Yes | 10 | |
| | | | | 0 | No | | | |
| 5.2 | Has funding been secured/allocated within the Local Government budget or whether the external sources of funding have been secured? | | 5 | 5 | Yes | Yes | 5 | |
| | | | | 0 | No | | | |
| 5.3 | Will the project get approval from higher levels of Government? | | 5 | 5 | 1 | Difficult | Standard | 2.5 |
| | | | | | 2.5 | Standard | | |
| | | | | | 5 | Easy | | |
| 5.4 | Ease of implementation of project in respect of technical design? | | 5 | 5 | 1 | Difficult | Standard | 3 |
| | | | | | 3 | Standard | | |
| | | | | | 5 | Easy | | |
| 5.5 | Is there a capable system in place to implement and operate this project or is external support needed? | 5 | 5 | 0 | Outside expertise needed for construction, O&M | Outside expertise needed for construction phase only | 1 | |
| | | | | 1 | Outside expertise needed for construction phase only | | | |
| | | | | 3 | Outside expertise needed for preparation phase i.e. feasibility studies | | | |
| | | | | 5 | No outside expertise needed | | | |
| Total Achieved Score | | | | | | | 84 | |

Project ID:

03-13-01-06-01

Project Description :

Construction of Underground Water Storage Tank

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score | | |
|--|---|--------------|-----------------|------------|--------------------------|---------------------------|---|------------------------------|-----|
| 1. Project Purpose & Service Delivery Improvement | | | | | | | | | |
| 1.1 | Does the project fill a gap in a wider system of service delivery? | 30 | 10 | 2.5 | Minor contribution | Significant contribution | 10 | | |
| | | | | 7.5 | Major contribution | | | | |
| | | | | 10 | Significant contribution | | | | |
| 1.2 | Whether the project will contribute to Sectoral Plan / City Master Plan? | | 30 | 10 | 0 | No contribution. | Major contribution to key development goal. | 10 | |
| | | | | | 2.5 | Indirect contribution. | | | |
| | | | | | 7.5 | Minor direct contribution | | | |
| 1.3 | Whether the deference/ delay of the project is going to affect citizens' health, safety, property, prosperity etc.? | | | 30 | 10 | 10 | Major contribution to key development goal. | Major immediate consequences | 10 |
| | | | | | | 0 | No consequences | | |
| | | | | | | 2.5 | Minor consequences | | |
| | | 7.5 | | | | Major future consequences | | | |
| 10 | Major immediate consequences | 30 | | | 10 | 10 | Major immediate consequences | Major immediate consequences | 10 |
| | | | | | | 0 | No consequences | | |
| | | | 2.5 | | | Minor consequences | | | |
| 2. Public Response | | | | | | | | | |
| 2.1 | Population served by the project. | | 15 | | 7.5 | 1 | Less than 10% | Greater than 20% | 7.5 |
| | | | | 5 | | Between 10% to 20% | | | |
| | | | | 7.5 | | Greater than 20% | | | |
| 2.2 | Is there support or opposition for the project from NGO's, community groups, | | | 15 | 5 | 0 | Majority opposition | Majority support | 5 |
| | | | | | | 1 | Minority opposition | | |
| | | 5 | | | | Majority support | | | |

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score |
|---------------------------------|--|--------------|-----------------|------------|--|---|----------------|
| | network, media or business organizations? | | 2.5 | 2.5 | Minority support | Majority support | 2.5 |
| 2.3 | Is there support or opposition from residents in the immediate vicinity of the new facility? | | | 0 | Majority opposition | | |
| | | | | 0.5 | Minority opposition | | |
| | | | | 2.5 | Majority support | | |
| | | | | 1.5 | Minority support | | |
| 3. Environmental Impact | | | | | | | |
| 3.1 | The impact of the proposed project on the quality of local environment (e.g. Air quality, Water pollution, Waste reduction, etc. | 10 | 10 | 0 | Negative effects on quality of the local environment | Positive effects on the quality of the local environment | 10 |
| | | | | 5 | Neutral | | |
| | | | | 10 | Positive effects on the quality of the local environment | | |
| 4. Socio-Economic Impact | | | | | | | |
| 4.1 | Will the project bring in direct revenue? | 15 | 7.5 | 0 | No direct revenue | Direct revenue is not sufficient to meet O&M costs | 2.5 |
| | | | | 2.5 | Direct revenue is not sufficient to meet O&M costs | | |
| | | | | 5 | Revenue meets O&M costs | | |
| | | | | 7.5 | Revenue exceeds O&M costs | | |
| 4.2 | Are there indirect economic benefits from this project in the long term, e.g. employment creation, investment generation, increase in land/property prices, reduction in citizens' expenditures, etc.? | | 7.5 | 0 | Negative impact on the local economy | Additional investment in the area and increased wealth for citizens | 5 |
| | | | | 2.5 | Little or no long term economic development benefits | | |
| | | | | 5 | Additional investment in the area and increased wealth for citizens | | |
| | | | | 7.5 | Significant competitive advantage to industry and boost to the local economy | | |

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score |
|----------------------------------|---|--------------|-----------------|------------|---|---|----------------|
| 5. Ease of Implementation | | | | | | | |
| 5.1 | Has land been acquired for the project (If required)? | 30 | 10 | 10 | Yes | Yes | 10 |
| | | | | 0 | No | | |
| 5.2 | Has funding been secured/allocated within the Local Government budget or whether the external sources of funding have been secured? | | 5 | 5 | Yes | Yes | 5 |
| | | | | 0 | No | | |
| 5.3 | Will the project get approval from higher levels of Government? | | 5 | 1 | Difficult | Standard | 2.5 |
| | | | | 2.5 | Standard | | |
| | | | | 5 | Easy | | |
| 5.4 | Ease of implementation of project in respect of technical design? | | 5 | 1 | Difficult | Standard | 3 |
| | | | | 3 | Standard | | |
| | | | | 5 | Easy | | |
| 5.5 | Is there a capable system in place to implement and operate this project or is external support needed? | | 5 | 0 | Outside expertise needed for construction, O&M | Outside expertise needed for or construction phase only | 1 |
| | | | | 1 | Outside expertise needed for construction phase only | | |
| | | | | 3 | Outside expertise needed for preparation phase i.e. feasibility studies | | |
| | | | | 5 | No outside expertise needed | | |
| Total Achieved Score | | | | | | | 84 |

Project ID: 03-13-02-01-01

Project Description : Improvement of Existing Sewerage System and Disposal Stations for Burewala City

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score |
|--|--|--------------|-----------------|------------|---|---|----------------|
| 1. Project Purpose & Service Delivery Improvement | | | | | | | |
| 1.1 | Does the project fill a gap in a wider system of service delivery? | 30 | 10 | 2.5 | Minor contribution | Significant contribution | 10 |
| | | | | 7.5 | Major contribution | | |
| | | | | 10 | Significant contribution | | |
| 1.2 | Whether the project will contribute to Sectoral Plan / City Master Plan? | 30 | 10 | 0 | No contribution. | Major contribution to key development goal. | 10 |
| | | | | 2.5 | Indirect contribution. | | |
| | | | | 7.5 | Minor direct contribution | | |
| | | | | 10 | Major contribution to key development goal. | | |
| 1.3 | Whether the deference/ delay of the project is going to affect citizens' health, safety, property, prosperity etc.? | 30 | 10 | 0 | No consequences | Major immediate consequences | 10 |
| | | | | 2.5 | Minor consequences | | |
| | | | | 7.5 | Major future consequences | | |
| | | | | 10 | Major immediate consequences | | |
| 2. Public Response | | | | | | | |
| 2.1 | Population served by the project. | 15 | 7.5 | 1 | Less than 10% | Greater than 20% | 7.5 |
| | | | | 5 | Between 10% to 20% | | |
| | | | | 7.5 | Greater than 20% | | |
| 2.2 | Is there support or opposition for the project from NGO's, community groups, network, media or business organizations? | 15 | 5 | 0 | Majority opposition | Majority support | 5 |
| | | | | 1 | Minority opposition | | |
| | | | | 5 | Majority support | | |
| | | | | 2.5 | Minority support | | |
| 2.3 | | | 2.5 | 0 | Majority opposition | Majority support | 2.5 |

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score |
|----------------------------------|--|--------------|-----------------|------------|--|---|----------------|
| | Is there support or opposition from residents in the immediate vicinity of the new facility? | | | 0.5 | Minority opposition | | |
| | | | | 2.5 | Majority support | | |
| | | | | 1.5 | Minority support | | |
| 3. Environmental Impact | | | | | | | |
| 3.1 | The impact of the proposed project on the quality of local environment (e.g. Air quality, Water pollution, Waste reduction, etc. | 10 | 10 | 0 | Negative effects on quality of the local environment | Positive effects on the quality of the local environment | 10 |
| | | | | 5 | Neutral | | |
| | | | | 10 | Positive effects on the quality of the local environment | | |
| 4. Socio-Economic Impact | | | | | | | |
| 4.1 | Will the project bring in direct revenue? | | 7.5 | 0 | No direct revenue | No direct revenue | 0 |
| | | | | 2.5 | Direct revenue is not sufficient to meet O&M costs | | |
| | | | | 5 | Revenue meets O&M costs | | |
| | | | | 7.5 | Revenue exceeds O&M costs | | |
| 4.2 | Are there indirect economic benefits from this project in the long term, e.g. employment creation, investment generation, increase in land/property prices, reduction in citizens' expenditures, etc.? | 15 | 7.5 | 0 | Negative impact on the local economy | Additional investment in the area and increased wealth for citizens | 5 |
| | | | | 2.5 | Little or no long term economic development benefits | | |
| | | | | 5 | Additional investment in the area and increased wealth for citizens | | |
| | | | | 7.5 | Significant competitive advantage to industry and boost to the local economy | | |
| 5. Ease of Implementation | | | | | | | |
| 5.1 | Has land been acquired for the project (If required)? | | 10 | 10 | Yes | Yes | 10 |
| | | | | 0 | No | | |
| 5.2 | Has funding been secured/allocated within the Local Government budget or whether the external sources of funding have been secured? | 30 | 5 | 5 | Yes | Yes | 5 |
| | | | | 0 | No | | |

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score | |
|-----------------------------|---|--------------|-----------------|------------|-----------------------------|---|--|---|
| 5.3 | Will the project get approval from higher levels of Government? | | 5 | 1 | Difficult | Standard | 2.5 | |
| | | | | 2.5 | Standard | | | |
| | | | | 5 | Easy | | | |
| 5.4 | Ease of implementation of project in respect of technical design? | | 5 | 5 | 1 | Difficult | Standard | 3 |
| | | | | | 3 | Standard | | |
| | | | | | 5 | Easy | | |
| 5.5 | Is there a capable system in place to implement and operate this project or is external support needed? | | 5 | 5 | 0 | Outside expertise needed for construction, O&M | Outside expertise needed for construction phase only | 1 |
| | | | | | 1 | Outside expertise needed for construction phase only | | |
| | | | | | 3 | Outside expertise needed for preparation phase i.e. feasibility studies | | |
| | | 5 | | | No outside expertise needed | | | |
| Total Achieved Score | | | | | | | 81.5 | |

Project ID: 03-13-05-01-01

Project Description : Improvement and Rehabilitation of Parks in Burewala City

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score | | |
|--|--|--------------|-----------------|------------|--------------------------|------------------------------|---------------------------|---------------------------|-----|
| 1. Project Purpose & Service Delivery Improvement | | | | | | | | | |
| 1.1 | Does the project fill a gap in a wider system of service delivery? | 30 | 10 | 2.5 | Minor contribution | Major contribution | 7.5 | | |
| | | | | 7.5 | Major contribution | | | | |
| | | | | 10 | Significant contribution | | | | |
| 1.2 | Whether the project will contribute to Sectoral Plan / City Master Plan? | | 30 | 10 | 0 | No contribution. | Minor direct contribution | 7.5 | |
| | | | | | 2.5 | Indirect contribution. | | | |
| | | | | | 7.5 | Minor direct contribution | | | |
| 1.3 | Whether the deference/ delay of the project is going to affect citizens' health, safety, property, prosperity etc.? | | | 30 | 10 | 0 | No consequences | Major future consequences | 7.5 |
| | | | | | | 2.5 | Minor consequences | | |
| | | | | | | 7.5 | Major future consequences | | |
| | | 10 | | | | Major immediate consequences | | | |
| 2. Public Response | | | | | | | | | |
| 2.1 | Population served by the project. | 15 | | | 7.5 | 1 | Less than 10% | Between 10% to 20% | 5 |
| | | | 5 | | | Between 10% to 20% | | | |
| | | | 7.5 | | | Greater than 20% | | | |
| 2.2 | Is there support or opposition for the project from NGO's, community groups, network, media or business organizations? | | 15 | | 5 | 0 | Majority opposition | Majority support | 5 |
| | | | | 1 | | Minority opposition | | | |
| | | | | 5 | | Majority support | | | |
| | | | | 2.5 | | Minority support | | | |
| 2.3 | Is there support or opposition from residents in the immediate vicinity of | | | 15 | 2.5 | 0 | Majority opposition | Majority support | 2.5 |
| | | | | | | 0.5 | Minority opposition | | |
| | | 2.5 | | | | Majority support | | | |

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score |
|----------------------------------|--|--------------|-----------------|------------|--|--|----------------|
| | the new facility? | | | 1.5 | Minority support | | |
| 3. Environmental Impact | | | | | | | |
| 3.1 | The impact of the proposed project on the quality of local environment (e.g. Air quality, Water pollution, Waste reduction, etc. | 10 | 10 | 0 | Negative effects on quality of the local environment | Positive effects on the quality of the local environment | 10 |
| | | | | 5 | Neutral | | |
| | | | | 10 | Positive effects on the quality of the local environment | | |
| 4. Socio-Economic Impact | | | | | | | |
| 4.1 | Will the project bring in direct revenue? | 15 | 7.5 | 0 | No direct revenue | No direct revenue | 0 |
| | | | | 2.5 | Direct revenue is not sufficient to meet O&M costs | | |
| | | | | 5 | Revenue meets O&M costs | | |
| | | | | 7.5 | Revenue exceeds O&M costs | | |
| 4.2 | Are there indirect economic benefits from this project in the long term, e.g. employment creation, investment generation, increase in land/property prices, reduction in citizens' expenditures, etc.? | 15 | 7.5 | 0 | Negative impact on the local economy | Little or no long term economic development benefits | 2.5 |
| | | | | 2.5 | Little or no long term economic development benefits | | |
| | | | | 5 | Additional investment in the area and increased wealth for citizens | | |
| | | | | 7.5 | Significant competitive advantage to industry and boost to the local economy | | |
| 5. Ease of Implementation | | | | | | | |
| 5.1 | Has land been acquired for the project (If required)? | 30 | 10 | 10 | Yes | Yes | 10 |
| | | | | 0 | No | | |
| 5.2 | Has funding been secured/allocated within the Local Government budget or whether the external sources of funding have been secured? | 30 | 5 | 5 | Yes | Yes | 5 |
| | | | | 0 | No | | |
| 5.3 | Will the project get approval from higher levels of Government? | 30 | 5 | 1 | Difficult | Standard | 2.5 |
| | | | | 2.5 | Standard | | |

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score | |
|-----------------------------|---|--------------|-----------------|------------|---|--|----------------|--|
| | | | | 5 | Easy | | | |
| 5.4 | Ease of implementation of project in respect of technical design? | | 5 | 1 | Difficult | Standard | 3 | |
| | | | | 3 | Standard | | | |
| | | | | 5 | Easy | | | |
| 5.5 | Is there a capable system in place to implement and operate this project or is external support needed? | | 5 | 0 | Outside expertise needed for construction, O &M | Outside expertise needed for construction phase only | 1 | |
| | | | | 1 | Outside expertise needed for construction phase only | | | |
| | | | | 3 | Outside expertise needed for preparation phase i.e. feasibility studies | | | |
| | | | | 5 | No outside expertise needed | | | |
| Total Achieved Score | | | | | | | 69 | |

Project ID: 03-13-05-04-01

Project Description : Construction of General Bus Stand (GSB) in Burewala City

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score |
|--|--|--------------|------------------|---|---------------------------|---------------------------|----------------|
| 1. Project Purpose & Service Delivery Improvement | | | | | | | |
| 1.1 | Does the project fill a gap in a wider system of service delivery? | 30 | 10 | 2.5 | Minor contribution | Major contribution | 7.5 |
| | | | | 7.5 | Major contribution | | |
| | | | | 10 | Significant contribution | | |
| 1.2 | Whether the project will contribute to Sectoral Plan / City Master Plan? | | 10 | 0 | No contribution. | Minor direct contribution | 7.5 |
| | | | | 2.5 | Indirect contribution. | | |
| | | | | 7.5 | Minor direct contribution | | |
| | | | 10 | Major contribution to key development goal. | | | |
| 1.3 | Whether the deference/ delay of the project is going to affect citizens' health, safety, property, prosperity etc.? | | 10 | 0 | No consequences | Major future consequences | 7.5 |
| | | | | 2.5 | Minor consequences | | |
| | | 7.5 | | Major future consequences | | | |
| | | 10 | | Major immediate consequences | | | |
| 2. Public Response | | | | | | | |
| 2.1 | Population served by the project. | 15 | 7.5 | 1 | Less than 10% | Greater than 20% | 7.5 |
| | | | | 5 | Between 10% to 20% | | |
| | | | | 7.5 | Greater than 20% | | |
| 2.2 | Is there support or opposition for the project from NGO's, community groups, network, media or business organizations? | | 5 | 0 | Majority opposition | Majority support | 5 |
| | | | | 1 | Minority opposition | | |
| | | | | 5 | Majority support | | |
| | | 2.5 | Minority support | | | | |
| 2.3 | Is there support or opposition from residents in the immediate vicinity of | 2.5 | 0 | Majority opposition | Majority support | 2.5 | |
| | | | 0.5 | Minority opposition | | | |
| | | | 2.5 | Majority support | | | |

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score |
|----------------------------------|--|--------------|-----------------|------------|--|---|----------------|
| | the new facility? | | | 1.5 | Minority support | | |
| 3. Environmental Impact | | | | | | | |
| 3.1 | The impact of the proposed project on the quality of local environment (e.g. Air quality, Water pollution, Waste reduction, etc. | 10 | 10 | 0 | Negative effects on quality of the local environment | Positive effects on the quality of the local environment | 10 |
| | | | | 5 | Neutral | | |
| | | | | 10 | Positive effects on the quality of the local environment | | |
| 4. Socio-Economic Impact | | | | | | | |
| 4.1 | Will the project bring in direct revenue? | 15 | 7.5 | 0 | No direct revenue | Direct revenue is not sufficient to meet O&M costs | 2.5 |
| | | | | 2.5 | Direct revenue is not sufficient to meet O&M costs | | |
| | | | | 5 | Revenue meets O&M costs | | |
| | | | | 7.5 | Revenue exceeds O&M costs | | |
| 4.2 | Are there indirect economic benefits from this project in the long term, e.g. employment creation, investment generation, increase in land/property prices, reduction in citizens' expenditures, etc.? | 15 | 7.5 | 0 | Negative impact on the local economy | Additional investment in the area and increased wealth for citizens | 5 |
| | | | | 2.5 | Little or no long term economic development benefits | | |
| | | | | 5 | Additional investment in the area and increased wealth for citizens | | |
| | | | | 7.5 | Significant competitive advantage to industry and boost to the local economy | | |
| 5. Ease of Implementation | | | | | | | |
| 5.1 | Has land been acquired for the project (If required)? | 30 | 10 | 10 | Yes | Yes | 10 |
| | | | | 0 | No | | |
| 5.2 | Has funding been secured/allocated within the Local Government budget or whether the external sources of funding have been secured? | 30 | 5 | 5 | Yes | Yes | 5 |
| | | | | 0 | No | | |
| 5.3 | Will the project get approval from higher levels of Government? | 30 | 5 | 1 | Difficult | Standard | 2.5 |
| | | | | 2.5 | Standard | | |

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score |
|-----------------------------|---|--------------|-----------------|-----------------------------|---|--|----------------|
| | | | | 5 | Easy | | |
| 5.4 | Ease of implementation of project in respect of technical design? | | 5 | 1 | Difficult | standard | 3 |
| | | | | 3 | Standard | | |
| | | | | 5 | Easy | | |
| 5.5 | Is there a capable system in place to implement and operate this project or is external support needed? | | 5 | 0 | Outside expertise needed for construction, O &M | Outside expertise needed for construction phase only | 1 |
| | | | | 1 | Outside expertise needed for construction phase only | | |
| | | | | 3 | Outside expertise needed for preparation phase i.e. feasibility studies | | |
| | | | 5 | No outside expertise needed | | | |
| Total Achieved Score | | | | | | | 76.5 |

Project ID: 03-13-05-06-01

Project Description : Rehabilitation of slaughter house

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score | |
|--|--|--------------|-----------------|------------------|------------------------------|---|---------------------------|-----|
| 1. Project Purpose & Service Delivery Improvement | | | | | | | | |
| 1.1 | Does the project fill a gap in a wider system of service delivery? | 30 | 10 | 2.5 | Minor contribution | Major contribution | 7.5 | |
| | | | | 7.5 | Major contribution | | | |
| | | | | 10 | Significant contribution | | | |
| 1.2 | Whether the project will contribute to Sectoral Plan / City Master Plan? | | 10 | 10 | 0 | No contribution. | Minor direct contribution | 7.5 |
| | | | | | 2.5 | Indirect contribution. | | |
| | | | | | 7.5 | Minor direct contribution | | |
| | | | | 10 | 10 | Major contribution to key development goal. | | |
| 1.3 | Whether the deference/ delay of the project is going to affect citizens' health, safety, property, prosperity etc.? | | 10 | 10 | 0 | No consequences | Major future consequences | 7.5 |
| | | | | | 2.5 | Minor consequences | | |
| | | 7.5 | | | Major future consequences | | | |
| | | 10 | | | Major immediate consequences | | | |
| 2. Public Response | | | | | | | | |
| 2.1 | Population served by the project. | 15 | 7.5 | 1 | Less than 10% | Greater than 20% | 7.5 | |
| | | | | 5 | Between 10% to 20% | | | |
| | | | | 7.5 | Greater than 20% | | | |
| 2.2 | Is there support or opposition for the project from NGO's, community groups, network, media or business organizations? | | 5 | 5 | 0 | Majority opposition | Majority support | 5 |
| | | | | | 1 | Minority opposition | | |
| | | | | | 5 | Majority support | | |
| | | | 2.5 | Minority support | | | | |
| 2.3 | Is there support or opposition from residents in the immediate vicinity of the new facility? | 2.5 | 2.5 | 0 | Majority opposition | Majority support | 2.5 | |
| | | | | 0.5 | Minority opposition | | | |
| | | | | 2.5 | Majority support | | | |

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score | | |
|----------------------------------|--|--------------|-----------------|------------|--|--|----------------|-----|--|
| | | | | 1.5 | Minority support | | | | |
| 3. Environmental Impact | | | | | | | | | |
| 3.1 | The impact of the proposed project on the quality of local environment (e.g. Air quality, Water pollution, Waste reduction, etc. | 10 | 10 | 0 | Negative effects on quality of the local environment | Neutral | 5 | | |
| | | | | 5 | Neutral | | | | |
| | | | | 10 | Positive effects on the quality of the local environment | | | | |
| 4. Socio-Economic Impact | | | | | | | | | |
| 4.1 | Will the project bring in direct revenue? | 15 | 7.5 | 0 | No direct revenue | Direct revenue is not sufficient to meet O&M costs | 2.5 | | |
| | | | | | | | | 2.5 | Direct revenue is not sufficient to meet O&M costs |
| | | | | | | | | 5 | Revenue meets O&M costs |
| | | | | | | | | 7.5 | Revenue exceeds O&M costs |
| 4.2 | Are there indirect economic benefits from this project in the long term, e.g. employment creation, investment generation, increase in land/property prices, reduction in citizens' expenditures, etc.? | 15 | 7.5 | 0 | Negative impact on the local economy | Little or no long term economic development benefits | 2.5 | | |
| | | | | | | | | 2.5 | Little or no long term economic development benefits |
| | | | | | | | | 5 | Additional investment in the area and increased wealth for citizens |
| | | | | | | | | 7.5 | Significant competitive advantage to industry and boost to the local economy |
| 5. Ease of Implementation | | | | | | | | | |
| 5.1 | Has land been acquired for the project (If required)? | 30 | 10 | 10 | Yes | Yes | 10 | | |
| | | | | | | | | 0 | No |
| 5.2 | Has funding been secured/allocated within the Local Government budget or whether the external sources of funding have been secured? | | 5 | 5 | 5 | Yes | Yes | 5 | |
| | | | | | | | | | 0 |
| 5.3 | Will the project get approval from higher levels of Government? | | 5 | 5 | 1 | Difficult | Standard | 2.5 | |
| | | | | | | | | | 2.5 |

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score | |
|-----------------------------|---|--------------|-----------------|------------|-----------------------------|---|--|---|
| | | | | 5 | Easy | | | |
| 5.4 | Ease of implementation of project in respect of technical design? | | | 5 | 1 | Difficult | Standard | 3 |
| | | | | | 3 | Standard | | |
| | | | | | 5 | Easy | | |
| 5.5 | Is there a capable system in place to implement and operate this project or is external support needed? | | | 5 | 0 | Outside expertise needed for construction, O &M | Outside expertise needed for construction phase only | 1 |
| | | | | | 1 | Outside expertise needed for construction phase only | | |
| | | | | | 3 | Outside expertise needed for preparation phase i.e. feasibility studies | | |
| | | 5 | | | No outside expertise needed | | | |
| Total Achieved Score | | | | | | | 69 | |

Project ID: 03-13-06-01-01

Project Description : Solarization of the municipal buildings

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score |
|--|--|--------------|-----------------|------------------------------|---|---|----------------|
| 1. Project Purpose & Service Delivery Improvement | | | | | | | |
| 1.1 | Does the project fill a gap in a wider system of service delivery? | 30 | 10 | 2.5 | Minor contribution | Major contribution | 7.5 |
| | | | | 7.5 | Major contribution | | |
| | | | | 10 | Significant contribution | | |
| 1.2 | Whether the project will contribute to Sectoral Plan / City Master Plan? | | 10 | 0 | No contribution. | Major contribution to key development goal. | 10 |
| | | | | 2.5 | Indirect contribution. | | |
| | | | | 7.5 | Minor direct contribution | | |
| 1.3 | Whether the deference/ delay of the project is going to affect citizens' health, safety, property, prosperity etc.? | | 10 | 10 | Major contribution to key development goal. | Minor consequences | 2.5 |
| | | | | 0 | No consequences | | |
| | | | | 2.5 | Minor consequences | | |
| | | | 7.5 | Major future consequences | | | |
| | | | 10 | Major immediate consequences | | | |
| 2. Public Response | | | | | | | |
| 2.1 | Population served by the project. | 15 | 7.5 | 1 | Less than 10% | Less than 10% | 1 |
| | | | | 5 | Between 10% to 20% | | |
| | | | | 7.5 | Greater than 20% | | |
| 2.2 | Is there support or opposition for the project from NGO's, community groups, network, media or business organizations? | | 5 | 0 | Majority opposition | Majority support | 5 |
| | | | | 1 | Minority opposition | | |
| | | | | 5 | Majority support | | |
| | | | 2.5 | Minority support | | | |
| 2.3 | | | 2.5 | 0 | Majority opposition | Majority support | 2.5 |

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score |
|----------------------------------|--|--------------|-----------------|------------|--|--|----------------|
| | Is there support or opposition from residents in the immediate vicinity of the new facility? | | | 0.5 | Minority opposition | | |
| | | | | 2.5 | Majority support | | |
| | | | | 1.5 | Minority support | | |
| 3. Environmental Impact | | | | | | | |
| 3.1 | The impact of the proposed project on the quality of local environment (e.g. Air quality, Water pollution, Waste reduction, etc. | 10 | 10 | 0 | Negative effects on quality of the local environment | Positive effects on the quality of the local environment | 10 |
| | | | | 5 | Neutral | | |
| | | | | 10 | Positive effects on the quality of the local environment | | |
| 4. Socio-Economic Impact | | | | | | | |
| 4.1 | Will the project bring in direct revenue? | | 7.5 | 0 | No direct revenue | Revenue exceeds O&M costs | 7.5 |
| | | | | 2.5 | Direct revenue is not sufficient to meet O&M costs | | |
| | | | | 5 | Revenue meets O&M costs | | |
| | | | | 7.5 | Revenue exceeds O&M costs | | |
| 4.2 | Are there indirect economic benefits from this project in the long term, e.g. employment creation, investment generation, increase in land/property prices, reduction in citizens' expenditures, etc.? | 15 | 7.5 | 0 | Negative impact on the local economy | Significant competitive advantage to industry and boost to the local economy | 7.5 |
| | | | | 2.5 | Little or no long term economic development benefits | | |
| | | | | 5 | Additional investment in the area and increased wealth for citizens | | |
| | | | | 7.5 | Significant competitive advantage to industry and boost to the local economy | | |
| 5. Ease of Implementation | | | | | | | |
| 5.1 | Has land been acquired for the project (If required)? | 30 | 10 | 10 | Yes | Yes | 10 |
| | | | | 0 | No | | |
| 5.2 | Has funding been secured/allocated within the Local | | 5 | 5 | Yes | Yes | 5 |
| | | | | 0 | No | | |

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score | |
|-----------------------------|---|--------------|-----------------|------------|---|--|----------------|--|
| | Government budget or whether the external sources of funding have been secured? | | | | | | | |
| 5.3 | Will the project get approval from higher levels of Government? | | 5 | 1 | Difficult | Easy | 5 | |
| | | | | 2.5 | Standard | | | |
| | | | | 5 | Easy | | | |
| 5.4 | Ease of implementation of project in respect of technical design? | | 5 | 1 | Difficult | Easy | 5 | |
| | | | | 3 | Standard | | | |
| | | | | 5 | Easy | | | |
| 5.5 | Is there a capable system in place to implement and operate this project or is external support needed? | | 5 | 0 | Outside expertise needed for construction, O&M | Outside expertise needed for construction phase only | 1 | |
| | | | | 1 | Outside expertise needed for construction phase only | | | |
| | | | | 3 | Outside expertise needed for preparation phase i.e. feasibility studies | | | |
| | | | | 5 | No outside expertise needed | | | |
| Total Achieved Score | | | | | | | 79.5 | |

Project ID: 03-13-01-01-01

Project Description : Solarization of Tube wells and Water Supply System

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score | |
|--|--|--------------|-----------------|------------------|------------------------------|---------------------------|---|-----|
| 1. Project Purpose & Service Delivery Improvement | | | | | | | | |
| 1.1 | Does the project fill a gap in a wider system of service delivery? | 30 | 10 | 2.5 | Minor contribution | Major contribution | 7.5 | |
| | | | | 7.5 | Major contribution | | | |
| | | | | 10 | Significant contribution | | | |
| 1.2 | Whether the project will contribute to Sectoral Plan / City Master Plan? | | 10 | 10 | 0 | No contribution. | Major contribution to key development goal. | 10 |
| | | | | | 2.5 | Indirect contribution. | | |
| | | | | | 7.5 | Minor direct contribution | | |
| 1.3 | Whether the deference/ delay of the project is going to affect citizens' health, safety, property, prosperity etc.? | | 10 | 10 | 0 | No consequences | Minor consequences | 2.5 |
| | | | | | 2.5 | Minor consequences | | |
| | | | | | 7.5 | Major future consequences | | |
| | | 10 | | | Major immediate consequences | | | |
| 2. Public Response | | | | | | | | |
| 2.1 | Population served by the project. | 15 | 7.5 | 1 | Less than 10% | Less than 10% | 1 | |
| | | | | 5 | Between 10% to 20% | | | |
| | | | | 7.5 | Greater than 20% | | | |
| 2.2 | Is there support or opposition for the project from NGO's, community groups, network, media or business organizations? | | 5 | 5 | 0 | Majority opposition | Majority support | 5 |
| | | | | | 1 | Minority opposition | | |
| | | | | | 5 | Majority support | | |
| 2.3 | | 2.5 | 0 | Majority support | Minority support | Majority support | 2.5 | |

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score | | |
|---------------------------------|--|--------------|-----------------|------------|---|--|----------------|-----|--|
| | Is there support or opposition from residents in the immediate vicinity of the new facility? | | | 0.5 | Minority opposition | | | | |
| | | | | 2.5 | Majority support | | | | |
| | | | | 1.5 | Minority support | | | | |
| 3. Environmental Impact | | | | | | | | | |
| 3.1 | The impact of the proposed project on the quality of local environment (e.g. Air quality, Water pollution, Waste reduction, etc. | 10 | 10 | 0 | Negative effects on quality of the local environment | Positive effects on the quality of the local environment | 10 | | |
| | | | | 5 | Neutral | | | | |
| | | | | 10 | Positive effects on the quality of the local environment | | | | |
| 4. Socio-Economic Impact | | | | | | | | | |
| 4.1 | Will the project bring in direct revenue? | 15 | 7.5 | 0 | No direct revenue | Revenue exceeds O&M costs | 7.5 | | |
| | | | | | | | | 2.5 | Direct revenue is not sufficient to meet O&M costs |
| | | | | | | | | 5 | Revenue meets O&M costs |
| | | | | | | | | 7.5 | Revenue exceeds O&M costs |
| 4.2 | Are there indirect economic benefits from this project in the long term, e.g. employment creation, investment generation, increase in land/property prices, reduction in citizens' expenditures, etc.? | | 7.5 | 0 | Negative impact on the local economy | Significant competitive advantage to industry and boost to the local economy | 7.5 | | |
| | | | | 2.5 | Little or no long term economic development benefits | | | | |
| | | | | 5 | Additional investment in the area and increased wealth for citizens | | | | |

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score |
|----------------------------------|---|--------------|-----------------|--|--|-------------------|----------------|
| | | | | 7.5 | Significant competitive advantage to industry and boost to the local economy | | |
| 5. Ease of Implementation | | | | | | | |
| 5.1 | Has land been acquired for the project (If required)? | 30 | 10 | 10 | Yes | Yes | 10 |
| | | | | 0 | No | | |
| 5.2 | Has funding been secured/allocated within the Local Government budget or whether the external sources of funding have been secured? | | 5 | 5 | Yes | Yes | 5 |
| | | | | 0 | No | | |
| 5.3 | Will the project get approval from higher levels of Government? | | 5 | 1 | Difficult | Easy | 5 |
| | | | | 2.5 | Standard | | |
| | | | | 5 | Easy | | |
| 5.4 | Ease of implementation of project in respect of technical design? | | 5 | 1 | Difficult | Easy | 5 |
| | | | | 3 | Standard | | |
| | | | | 5 | Easy | | |
| 5.5 | Is there a capable system in place to implement and operate this project or is external support needed? | 5 | 0 | Outside expertise needed for construction, O&M | Outside expertise needed for construction phase only | 1 | |
| | | | 1 | Outside expertise needed for construction phase only | | | |
| | | | 3 | Outside expertise needed for preparation phase i.e . feasibility studies | | | |
| | | | 5 | No outside expertise needed | | | |
| Total Achieved Score | | | | | | | 79.5 |

Project ID: 03-13-04-01-01

Project Description : Improvement & Rehabilitation of Roads

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score |
|--|--|--------------|-----------------|------------------------------|---|---|----------------|
| 1. Project Purpose & Service Delivery Improvement | | | | | | | |
| 1.1 | Does the project fill a gap in a wider system of service delivery? | 30 | 10 | 2.5 | Minor contribution | Major contribution | 7.5 |
| | | | | 7.5 | Major contribution | | |
| | | | | 10 | Significant contribution | | |
| 1.2 | Whether the project will contribute to Sectoral Plan / City Master Plan? | | 10 | 0 | No contribution. | Major contribution to key development goal. | 10 |
| | | | | 2.5 | Indirect contribution. | | |
| | | | | 7.5 | Minor direct contribution | | |
| 1.3 | Whether the deference/ delay of the project is going to affect citizens' health, safety, property, prosperity etc.? | | 10 | 10 | Major contribution to key development goal. | Minor consequences | 2.5 |
| | | | | 0 | No consequences | | |
| | | | | 2.5 | Minor consequences | | |
| | | | 7.5 | Major future consequences | | | |
| | | | 10 | Major immediate consequences | | | |
| 2. Public Response | | | | | | | |
| 2.1 | Population served by the project. | 15 | 7.5 | 1 | Less than 10% | Less than 10% | 1 |
| | | | | 5 | Between 10% to 20% | | |
| | | | | 7.5 | Greater than 20% | | |
| 2.2 | Is there support or opposition for the project from NGO's, community groups, network, media or business organizations? | | 5 | 0 | Majority opposition | Majority support | 5 |
| | | | | 1 | Minority opposition | | |
| | | | | 5 | Majority support | | |
| | | | 2.5 | Minority support | | | |
| 2.3 | | | 2.5 | 0 | Majority opposition | Majority support | 2.5 |

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score |
|----------------------------------|--|--------------|-----------------|------------|--|--|----------------|
| | Is there support or opposition from residents in the immediate vicinity of the new facility? | | | 0.5 | Minority opposition | | |
| | | | | 2.5 | Majority support | | |
| | | | | 1.5 | Minority support | | |
| 3. Environmental Impact | | | | | | | |
| 3.1 | The impact of the proposed project on the quality of local environment (e.g. Air quality, Water pollution, Waste reduction, etc. | 10 | 10 | 0 | Negative effects on quality of the local environment | Positive effects on the quality of the local environment | 10 |
| | | | | 5 | Neutral | | |
| | | | | 10 | Positive effects on the quality of the local environment | | |
| 4. Socio-Economic Impact | | | | | | | |
| 4.1 | Will the project bring in direct revenue? | | 7.5 | 0 | No direct revenue | Revenue exceeds O&M costs | 7.5 |
| | | | | 2.5 | Direct revenue is not sufficient to meet O&M costs | | |
| | | | | 5 | Revenue meets O&M costs | | |
| | | | | 7.5 | Revenue exceeds O&M costs | | |
| 4.2 | Are there indirect economic benefits from this project in the long term, e.g. employment creation, investment generation, increase in land/property prices, reduction in citizens' expenditures, etc.? | 15 | 7.5 | 0 | Negative impact on the local economy | Significant competitive advantage to industry and boost to the local economy | 7.5 |
| | | | | 2.5 | Little or no long term economic development benefits | | |
| | | | | 5 | Additional investment in the area and increased wealth for citizens | | |
| | | | | 7.5 | Significant competitive advantage to industry and boost to the local economy | | |
| 5. Ease of Implementation | | | | | | | |
| 5.1 | Has land been acquired for the project (If required)? | 30 | 10 | 10 | Yes | Yes | 10 |
| | | | | 0 | No | | |
| 5.2 | Has funding been secured/allocated within the Local | | 5 | 5 | Yes | Yes | 5 |
| | | | | 0 | No | | |

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score | |
|-----------------------------|---|--------------|-----------------|------------|---|--|----------------|--|
| | Government budget or whether the external sources of funding have been secured? | | | | | | | |
| 5.3 | Will the project get approval from higher levels of Government? | | 5 | 1 | Difficult | Easy | 5 | |
| | | | | 2.5 | Standard | | | |
| | | | | 5 | Easy | | | |
| 5.4 | Ease of implementation of project in respect of technical design? | | 5 | 1 | Difficult | Easy | 5 | |
| | | | | 3 | Standard | | | |
| | | | | 5 | Easy | | | |
| 5.5 | Is there a capable system in place to implement and operate this project or is external support needed? | | 5 | 0 | Outside expertise needed for construction, O&M | Outside expertise needed for construction phase only | 1 | |
| | | | | 1 | Outside expertise needed for construction phase only | | | |
| | | | | 3 | Outside expertise needed for preparation phase i.e. feasibility studies | | | |
| | | | | 5 | No outside expertise needed | | | |
| Total Achieved Score | | | | | | | 79.5 | |

Project ID: 03-13-06-01-02

Project Description : Improvement & Rehabilitation of Roads

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score |
|--|--|--------------|-----------------|------------------------------|---|---|----------------|
| 1. Project Purpose & Service Delivery Improvement | | | | | | | |
| 1.1 | Does the project fill a gap in a wider system of service delivery? | 30 | 10 | 2.5 | Minor contribution | Major contribution | 7.5 |
| | | | | 7.5 | Major contribution | | |
| | | | | 10 | Significant contribution | | |
| 1.2 | Whether the project will contribute to Sectoral Plan / City Master Plan? | | 10 | 0 | No contribution. | Major contribution to key development goal. | 10 |
| | | | | 2.5 | Indirect contribution. | | |
| | | | | 7.5 | Minor direct contribution | | |
| 1.3 | Whether the deference/ delay of the project is going to affect citizens' health, safety, property, prosperity etc.? | | 10 | 10 | Major contribution to key development goal. | Minor consequences | 2.5 |
| | | | | 0 | No consequences | | |
| | | | | 2.5 | Minor consequences | | |
| | | | 7.5 | Major future consequences | | | |
| | | | 10 | Major immediate consequences | | | |
| 2. Public Response | | | | | | | |
| 2.1 | Population served by the project. | 15 | 7.5 | 1 | Less than 10% | Less than 10% | 1 |
| | | | | 5 | Between 10% to 20% | | |
| | | | | 7.5 | Greater than 20% | | |
| 2.2 | Is there support or opposition for the project from NGO's, community groups, network, media or business organizations? | | 5 | 0 | Majority opposition | Majority support | 5 |
| | | | | 1 | Minority opposition | | |
| | | | | 5 | Majority support | | |
| | | | 2.5 | Minority support | | | |
| 2.3 | | | 2.5 | 0 | Majority opposition | Majority support | 2.5 |

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score |
|----------------------------------|--|--------------|-----------------|------------|--|--|----------------|
| | Is there support or opposition from residents in the immediate vicinity of the new facility? | | | 0.5 | Minority opposition | | |
| | | | | 2.5 | Majority support | | |
| | | | | 1.5 | Minority support | | |
| 3. Environmental Impact | | | | | | | |
| 3.1 | The impact of the proposed project on the quality of local environment (e.g. Air quality, Water pollution, Waste reduction, etc. | 10 | 10 | 0 | Negative effects on quality of the local environment | Positive effects on the quality of the local environment | 10 |
| | | | | 5 | Neutral | | |
| | | | | 10 | Positive effects on the quality of the local environment | | |
| 4. Socio-Economic Impact | | | | | | | |
| 4.1 | Will the project bring in direct revenue? | | 7.5 | 0 | No direct revenue | Revenue exceeds O&M costs | 7.5 |
| | | | | 2.5 | Direct revenue is not sufficient to meet O&M costs | | |
| | | | | 5 | Revenue meets O&M costs | | |
| | | | | 7.5 | Revenue exceeds O&M costs | | |
| 4.2 | Are there indirect economic benefits from this project in the long term, e.g. employment creation, investment generation, increase in land/property prices, reduction in citizens' expenditures, etc.? | 15 | 7.5 | 0 | Negative impact on the local economy | Significant competitive advantage to industry and boost to the local economy | 7.5 |
| | | | | 2.5 | Little or no long term economic development benefits | | |
| | | | | 5 | Additional investment in the area and increased wealth for citizens | | |
| | | | | 7.5 | Significant competitive advantage to industry and boost to the local economy | | |
| 5. Ease of Implementation | | | | | | | |
| 5.1 | Has land been acquired for the project (If required)? | 30 | 10 | 10 | Yes | Yes | 10 |
| | | | | 0 | No | | |
| 5.2 | Has funding been secured/allocated within the Local | | 5 | 5 | Yes | Yes | 5 |
| | | | | 0 | No | | |

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score | |
|-----------------------------|---|--------------|-----------------|------------|---|--|----------------|--|
| | Government budget or whether the external sources of funding have been secured? | | | | | | | |
| 5.3 | Will the project get approval from higher levels of Government? | | 5 | 1 | Difficult | Easy | 5 | |
| | | | | 2.5 | Standard | | | |
| | | | | 5 | Easy | | | |
| 5.4 | Ease of implementation of project in respect of technical design? | | 5 | 1 | Difficult | Easy | 5 | |
| | | | | 3 | Standard | | | |
| | | | | 5 | Easy | | | |
| 5.5 | Is there a capable system in place to implement and operate this project or is external support needed? | | 5 | 0 | Outside expertise needed for construction, O&M | Outside expertise needed for construction phase only | 1 | |
| | | | | 1 | Outside expertise needed for construction phase only | | | |
| | | | | 3 | Outside expertise needed for preparation phase i.e. feasibility studies | | | |
| | | | | 5 | No outside expertise needed | | | |
| Total Achieved Score | | | | | | | 79.5 | |

Project ID: 03-13-02-01-02

Project Description : Solarization of disposal stations

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score |
|--|--|--------------|-----------------|------------------------------|---|---|----------------|
| 1. Project Purpose & Service Delivery Improvement | | | | | | | |
| 1.1 | Does the project fill a gap in a wider system of service delivery? | 30 | 10 | 2.5 | Minor contribution | Major contribution | 7.5 |
| | | | | 7.5 | Major contribution | | |
| | | | | 10 | Significant contribution | | |
| 1.2 | Whether the project will contribute to Sectoral Plan / City Master Plan? | | 10 | 0 | No contribution. | Major contribution to key development goal. | 10 |
| | | | | 2.5 | Indirect contribution. | | |
| | | | | 7.5 | Minor direct contribution | | |
| 1.3 | Whether the deference/ delay of the project is going to affect citizens' health, safety, property, prosperity etc.? | | 10 | 10 | Major contribution to key development goal. | Minor consequences | 2.5 |
| | | | | 0 | No consequences | | |
| | | | | 2.5 | Minor consequences | | |
| | | | 7.5 | Major future consequences | | | |
| | | | 10 | Major immediate consequences | | | |
| 2. Public Response | | | | | | | |
| 2.1 | Population served by the project. | 15 | 7.5 | 1 | Less than 10% | Less than 10% | 1 |
| | | | | 5 | Between 10% to 20% | | |
| | | | | 7.5 | Greater than 20% | | |
| 2.2 | Is there support or opposition for the project from NGO's, community groups, network, media or business organizations? | | 5 | 0 | Majority opposition | Majority support | 5 |
| | | | | 1 | Minority opposition | | |
| | | | | 5 | Majority support | | |
| | | | 2.5 | Minority support | | | |
| 2.3 | | | 2.5 | 0 | Majority opposition | Majority support | 2.5 |

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score |
|----------------------------------|--|--------------|-----------------|------------|--|--|----------------|
| | Is there support or opposition from residents in the immediate vicinity of the new facility? | | | 0.5 | Minority opposition | | |
| | | | | 2.5 | Majority support | | |
| | | | | 1.5 | Minority support | | |
| 3. Environmental Impact | | | | | | | |
| 3.1 | The impact of the proposed project on the quality of local environment (e.g. Air quality, Water pollution, Waste reduction, etc. | 10 | 10 | 0 | Negative effects on quality of the local environment | Positive effects on the quality of the local environment | 10 |
| | | | | 5 | Neutral | | |
| | | | | 10 | Positive effects on the quality of the local environment | | |
| 4. Socio-Economic Impact | | | | | | | |
| 4.1 | Will the project bring in direct revenue? | | 7.5 | 0 | No direct revenue | Revenue exceeds O&M costs | 7.5 |
| | | | | 2.5 | Direct revenue is not sufficient to meet O&M costs | | |
| | | | | 5 | Revenue meets O&M costs | | |
| | | | | 7.5 | Revenue exceeds O&M costs | | |
| 4.2 | Are there indirect economic benefits from this project in the long term, e.g. employment creation, investment generation, increase in land/property prices, reduction in citizens' expenditures, etc.? | 15 | 7.5 | 0 | Negative impact on the local economy | Significant competitive advantage to industry and boost to the local economy | 7.5 |
| | | | | 2.5 | Little or no long term economic development benefits | | |
| | | | | 5 | Additional investment in the area and increased wealth for citizens | | |
| | | | | 7.5 | Significant competitive advantage to industry and boost to the local economy | | |
| 5. Ease of Implementation | | | | | | | |
| 5.1 | Has land been acquired for the project (If required)? | 30 | 10 | 10 | Yes | Yes | 10 |
| | | | | 0 | No | | |
| 5.2 | Has funding been secured/allocated within the Local | | 5 | 5 | Yes | Yes | 5 |
| | | | | 0 | No | | |

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score | |
|-----------------------------|---|--------------|-----------------|------------|---|--|----------------|--|
| | Government budget or whether the external sources of funding have been secured? | | | | | | | |
| 5.3 | Will the project get approval from higher levels of Government? | | 5 | 1 | Difficult | Easy | 5 | |
| | | | | 2.5 | Standard | | | |
| | | | | 5 | Easy | | | |
| 5.4 | Ease of implementation of project in respect of technical design? | | 5 | 1 | Difficult | Easy | 5 | |
| | | | | 3 | Standard | | | |
| | | | | 5 | Easy | | | |
| 5.5 | Is there a capable system in place to implement and operate this project or is external support needed? | | 5 | 0 | Outside expertise needed for construction, O&M | Outside expertise needed for construction phase only | 1 | |
| | | | | 1 | Outside expertise needed for construction phase only | | | |
| | | | | 3 | Outside expertise needed for preparation phase i.e. feasibility studies | | | |
| | | | | 5 | No outside expertise needed | | | |
| Total Achieved Score | | | | | | | 79.5 | |

Project ID: 03-13-01-01-02

Project Description : SCADA system for tube wells and disposal stations

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score |
|--|--|--------------|-----------------|------------------------------|---|---|----------------|
| 1. Project Purpose & Service Delivery Improvement | | | | | | | |
| 1.1 | Does the project fill a gap in a wider system of service delivery? | 30 | 10 | 2.5 | Minor contribution | Major contribution | 7.5 |
| | | | | 7.5 | Major contribution | | |
| | | | | 10 | Significant contribution | | |
| 1.2 | Whether the project will contribute to Sectoral Plan / City Master Plan? | | 10 | 0 | No contribution. | Major contribution to key development goal. | 10 |
| | | | | 2.5 | Indirect contribution. | | |
| | | | | 7.5 | Minor direct contribution | | |
| 1.3 | Whether the deference/ delay of the project is going to affect citizens' health, safety, property, prosperity etc.? | | 10 | 10 | Major contribution to key development goal. | Minor consequences | 2.5 |
| | | | | 0 | No consequences | | |
| | | | | 2.5 | Minor consequences | | |
| | | | 7.5 | Major future consequences | | | |
| | | | 10 | Major immediate consequences | | | |
| 2. Public Response | | | | | | | |
| 2.1 | Population served by the project. | 15 | 7.5 | 1 | Less than 10% | Less than 10% | 1 |
| | | | | 5 | Between 10% to 20% | | |
| | | | | 7.5 | Greater than 20% | | |
| 2.2 | Is there support or opposition for the project from NGO's, community groups, network, media or business organizations? | | 5 | 0 | Majority opposition | Majority support | 5 |
| | | | | 1 | Minority opposition | | |
| | | | | 5 | Majority support | | |
| | | | 2.5 | Minority support | | | |
| 2.3 | | | 2.5 | 0 | Majority opposition | Majority support | 2.5 |

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score |
|----------------------------------|--|--------------|-----------------|------------|--|--|----------------|
| | Is there support or opposition from residents in the immediate vicinity of the new facility? | | | 0.5 | Minority opposition | | |
| | | | | 2.5 | Majority support | | |
| | | | | 1.5 | Minority support | | |
| 3. Environmental Impact | | | | | | | |
| 3.1 | The impact of the proposed project on the quality of local environment (e.g. Air quality, Water pollution, Waste reduction, etc. | 10 | 10 | 0 | Negative effects on quality of the local environment | Positive effects on the quality of the local environment | 10 |
| | | | | 5 | Neutral | | |
| | | | | 10 | Positive effects on the quality of the local environment | | |
| 4. Socio-Economic Impact | | | | | | | |
| 4.1 | Will the project bring in direct revenue? | | 7.5 | 0 | No direct revenue | Revenue exceeds O&M costs | 7.5 |
| | | | | 2.5 | Direct revenue is not sufficient to meet O&M costs | | |
| | | | | 5 | Revenue meets O&M costs | | |
| | | | | 7.5 | Revenue exceeds O&M costs | | |
| 4.2 | Are there indirect economic benefits from this project in the long term, e.g. employment creation, investment generation, increase in land/property prices, reduction in citizens' expenditures, etc.? | 15 | 7.5 | 0 | Negative impact on the local economy | Significant competitive advantage to industry and boost to the local economy | 7.5 |
| | | | | 2.5 | Little or no long term economic development benefits | | |
| | | | | 5 | Additional investment in the area and increased wealth for citizens | | |
| | | | | 7.5 | Significant competitive advantage to industry and boost to the local economy | | |
| 5. Ease of Implementation | | | | | | | |
| 5.1 | Has land been acquired for the project (If required)? | 30 | 10 | 10 | Yes | Yes | 10 |
| | | | | 0 | No | | |
| 5.2 | Has funding been secured/allocated within the Local | | 5 | 5 | Yes | Yes | 5 |
| | | | | 0 | No | | |

| Index | Question | Index Weight | Question Weight | Sub Weight | Possible Responses | Selected Response | Achieved Score | |
|-----------------------------|---|--------------|-----------------|------------|---|--|----------------|--|
| | Government budget or whether the external sources of funding have been secured? | | | | | | | |
| 5.3 | Will the project get approval from higher levels of Government? | | 5 | 1 | Difficult | Easy | 5 | |
| | | | | 2.5 | Standard | | | |
| | | | | 5 | Easy | | | |
| 5.4 | Ease of implementation of project in respect of technical design? | | 5 | 1 | Difficult | Easy | 5 | |
| | | | | 3 | Standard | | | |
| | | | | 5 | Easy | | | |
| 5.5 | Is there a capable system in place to implement and operate this project or is external support needed? | | 5 | 0 | Outside expertise needed for construction, O&M | Outside expertise needed for construction phase only | 1 | |
| | | | | 1 | Outside expertise needed for construction phase only | | | |
| | | | | 3 | Outside expertise needed for preparation phase i.e. feasibility studies | | | |
| | | | | 5 | No outside expertise needed | | | |
| Total Achieved Score | | | | | | | 79.5 | |

Annexure D. Environmental and Social Considerations in IDAMP³

Section 1: Policy, Legal and Administrative Framework

This section provides an overview of the policy framework and national legislation that applies to the proposed project. The project is expected to comply with all national/provincial legislation regulations, EPA guidelines, World Bank Operational Policies and guidelines which are relevant and applicable to the sub-project.

1.1. Punjab Environment Protection Act 1997 (Amended 2012 & 2017)

Under Section 12 (and subsequent amendment in 2012 and then in 2017) of the PEPA (1997):

“a project falling under any category specified in Schedule I of the IEE/EIA Regulations 2022 requires the proponent of the project to file an IEE with the concerned provincial EPA while projects falling under any category specified in Schedule II require the proponent to file an EIA with the provincial agency, which is responsible for its review and accordance of approval or request any additional information deemed necessary”

In compliance of local legal framework, development of IEE/EIA reports and subsequent approval from the competent forums shall be mandatory for all new infrastructure projects.

Regulatory Clearances, Punjab EPA

In accordance with provincial regulatory requirements, an IEE/EIA satisfying the requirements of the Punjab Environmental Protection Act (amended 2012&2017) will be marked cleared by Punjab-EPA and No Objection Certificate (NOC) will be issued for it. MCs will ensure to obtain NOCs/approval from the competent forums before the execution of new infrastructure development projects.

³ The Environmental & Social Considerations have been provided by the Environment & Social Management (E&SM) team of PMDFC.

1.2. Guidelines for Environmental Assessment, Pakistan EPA

The Pak-EPA has published a set of environmental guidelines for conducting environmental assessments and the environmental management of different types of development projects. The guidelines that are relevant to the proposed projects are listed below:

- Guidelines for the Preparation and Review of Environmental Reports, Pakistan, EPA 1997.
- Guidelines for Public Consultations; Pakistan EPA May 1997

These guidelines have been adopted by the Punjab Environment Protection Agency after 18th amendment.

1.3. Punjab Environmental Quality Standards (PEQS)

The Punjab Environmental Quality Standards (PEQS), 2016 specify the following standards:

1. Punjab Environment Quality Standards for Drinking Water, 2016
2. Punjab Environment Quality Standards for Ambient Air, 2016
3. Punjab Environment Quality Standards for Noise, 2016
4. Punjab Environment Quality Standards for Municipal and Liquid Industrial Effluents, 2016

32 parameters of PEQs for drinking water shall be applicable to all water supply schemes/ projects/ subprojects (rehabilitation and new). PEQs for ambient air shall be applicable during rehabilitation or new construction of infrastructure development projects to analyze the emissions that may emerge from construction work machinery/equipment's. PEQs for noise shall also be applicable during rehabilitation or new construction of infrastructure development projects to analyze the emissions that may emerge from construction work machinery/equipment. PEQs for municipal and liquid waste shall be applicable to determine the quality of municipal wastewater where wastewater is to be treated.

1.4. Other Environment Related Legislations:

| Sr. # | Act | Description | Applicability to sub-project |
|-------|--|---|--|
| 1. | Punjab Environment Protection Act, 1997 (as amended up to 2017) | The Act establishes the Environmental Protection Agency that deals with the preparation of national environmental policies, prepare & publish national environment report, ensure the enforcement of National Environmental Quality Standards, establishment of ambient air, water and land quality standards, measures to control environmental pollution. Additionally, under this Act, no proponent of a project shall commence construction or operation unless he has filed with the Provincial Agency an initial environmental examination or, where the project is likely to cause an adverse environmental effect, an Environmental Impact Assessment (EIA/ESIA), and has obtained from the approval in respect thereof. | Section 11,12,13 and 14 of PEPA, 2012 shall be applicable to all the new infrastructure projects. |
| 2. | Punjab Environment Protection Review of | Provided that the proponent shall file an Initial Environmental Examination or Environmental | <ul style="list-style-type: none"> These regulations have two schedules I & II. As per schedule I the subprojects require submission of IEE report have to be prepared and as per |

| Sr. # | Act | Description | Applicability to sub-project | | | | | | | | | | | | | | | |
|------------|--------------------------|---|---|----------|--------|--------|------------|---------------------|---|--|--------------|---|--|-------|---|--|-------|---|
| | IEE/EIA Regulations 2022 | Impact Assessment, if the project is likely to cause an adverse environmental impact | <p>schedule II the EIA of Subproject will be carried out.</p> <p>The sector wise screening of MCs subprojects as per Punjab Environment protection review of IEE/EIA regulations 2000 are given below in Table.</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="background-color: #FFD700;">Schedule</th> <th style="background-color: #FFD700;">Sector</th> <th style="background-color: #FFD700;">Clause</th> </tr> </thead> <tbody> <tr> <td>Schedule I</td> <td>Stormwater Drainage</td> <td>F. Water management, dams, irrigation and flood protection 1. Small Dams and reservoirs 2. Irrigation and drainage projects</td> </tr> <tr> <td></td> <td>Water supply</td> <td>G. Water Supply and Treatment Water supply schemes and treatment plants with total cost less than Rs. 50 million</td> </tr> <tr> <td></td> <td>Parks</td> <td>I. Urban development and tourism 5. Urban development projects</td> </tr> <tr> <td></td> <td>Waste</td> <td>H. Waste disposal Non-hazardous scrap yard / warehouse</td> </tr> </tbody> </table> | Schedule | Sector | Clause | Schedule I | Stormwater Drainage | F. Water management, dams, irrigation and flood protection 1. Small Dams and reservoirs 2. Irrigation and drainage projects | | Water supply | G. Water Supply and Treatment Water supply schemes and treatment plants with total cost less than Rs. 50 million | | Parks | I. Urban development and tourism 5. Urban development projects | | Waste | H. Waste disposal Non-hazardous scrap yard / warehouse |
| Schedule | Sector | Clause | | | | | | | | | | | | | | | | |
| Schedule I | Stormwater Drainage | F. Water management, dams, irrigation and flood protection 1. Small Dams and reservoirs 2. Irrigation and drainage projects | | | | | | | | | | | | | | | | |
| | Water supply | G. Water Supply and Treatment Water supply schemes and treatment plants with total cost less than Rs. 50 million | | | | | | | | | | | | | | | | |
| | Parks | I. Urban development and tourism 5. Urban development projects | | | | | | | | | | | | | | | | |
| | Waste | H. Waste disposal Non-hazardous scrap yard / warehouse | | | | | | | | | | | | | | | | |

| Sr. # | Act | Description | Applicability to sub-project | | |
|-------|-----|-------------|------------------------------|---|--|
| | | | Schedule II | Water supply, Sewerage System and treatment | F. Water supply, Sewerage System and treatment Water supply schemes and treatment plants (excluding the Reverse Osmosis, Ultra filtration and such like) with total cost more than Rs. 50 million 2. Wastewater channels / Sewerage System Schemes 3. Combined Wastewater Treatment Plants with treatment capacity greater than 100m ³ /hr |
| | | | | Waste Storage and Disposal | G. Waste Storage and Disposal 1. Landfill sites 2. Waste Incinerators and autoclaves 3. Hazardous substance or waste storage warehouse |

| Sr. # | Act | Description | Applicability to sub-project |
|-------|--|--|--|
| 3. | Delegations of power for Environment Approvals Rule 2017 | According to these rules the powers of environmental approval are delegated to commissioner for specific types of projects | <ul style="list-style-type: none"> • Under PCP the clause of h, n and o are applicable. • clause h Construction of roads fallings within the jurisdiction of a district, expecting highways, expressways and motorways • Clause o solid waste management excepting landfills • Clause p water supply schemes /water purifications plants costing upto Rs. 20,000/- |
| 4. | Notification No. SOG/EPD/5-86/2019 delegation of powers to Deputy Commissioner | According to this notification the powers of environmental approval are delegated to deputy commissioner for specific types of projects | Under PCP clause g is applicable Bus and Wagon stands od category C with area upto 8 kanal. |
| 3. | Pakistan Penal Code, 1860 | The Code deals with the offences where public or private property or human lives are affected due to intentional or accidental misconduct of an individual or organization. The Code also addresses control of noise, noxious emissions and disposal of effluents. | The provisions of the Penal Code, 1860 are applicable to the project in terms of penalties for effecting human lives and public property. It also addresses the control of noise, air emissions and effluent disposal. |
| 4. | Motor Vehicle Rules, 1969 | It defines powers and responsibilities of Motor Vehicle Examiners (MVEs). The establishment of | This act is applicable to the gaseous emission that will be released from the vehicles in operation phase |

| Sr. # | Act | Description | Applicability to sub-project |
|-------|---|--|--|
| | | MVE inspection system is one of the regulatory measures that can be taken to tackle the ambient air quality problems associated with the vehicular emissions during operation phase. | at machinery used during construction phase of this subproject. |
| 5. | The Land Acquisition Act, 1894 | The Land Acquisition Act, 1894, is a “law for the acquisition of land needed for public purposes and for companies and for determining the amount of compensation to be paid on account of such acquisition”. | This act will not be triggered as no land acquisition is required. |
| 6. | The Punjab Land Acquisition Rules, 1983, | It describes the land acquisition procedure for public purposes or for a company. | This act will be triggered as wherever land to be acquired for subproject. Such as in Swerage project, Construction of Wastewater treatment plants, installation of new tube wells etc. |
| 7. | Pakistan Antiquities Act 1975 and Punjab Antiquities Amendment Act 2012 | The Punjab Antiquities Amendment Act, 2012 is adopted from the Pakistan Antiquities Act of 1975 with a few minor changes. The Antiquities Act, 1975 (amended in 1990) states the following: <ul style="list-style-type: none"> • “Ancient” is any object that is at least 75 years old; | The law will be applicable to the project due to its provision that if any accidental archaeological discoveries may occur during the excavation works for the construction of sub-projects. |

| Sr. # | Act | Description | Applicability to sub-project |
|-------|--|---|---|
| | | <ul style="list-style-type: none"> • All accidental discoveries of artifacts must be reported to the Federal Department of Archaeology; • The Government is the owner of all buried antiquities discovered on any site, whether protected or otherwise; • All new construction within a distance of 200 feet from protected antiquities is forbidden; • No changes or repairs can be made to a protected monument, even if it is owned privately, without approval of the responsible authorities; and <p>The cultural heritage laws of Pakistan are uniformly applicable to all categories of sites regardless of their state of preservation and classification as monuments of national or world heritage.</p> | |
| 8. | Punjab Restriction of Employment of Children Act, 2016 | According to the sub-section 11(a) of this Act, an occupier who employs or permits a child (person under the age of 15 years) to work in an establishment shall be liable to punishment with imprisonment for a term which may extend to six | The relevance of this act to the project will be to prohibit child employment for construction related activities of the proposed sub- project and it will be applicable throughout the construction activities related to subprojects. |

| Sr. # | Act | Description | Applicability to sub-project |
|-------|---|--|---|
| | | months, but which shall not be less than seven days, and a mandatory fine between 10,000 and 50,000 rupees. | |
| 9. | The Punjab Occupational Safety and Health Act, 2019 | <p>The Punjab Occupational Safety and Health Act, 2019 (IV of 2019) An Act to provide for occupational safety and health at workplace.</p> <p>It is necessary to make and consolidate the law for the occupational safety and health of the persons at workplace and to protect them against risks arising out of the occupational hazards; to promote safe and healthy working environment catering to the physiological and psychological needs of the employees at workplace and to provide for matters connected therewith or ancillary thereto.</p> | <p>The Punjab Occupational Safety and Health Act, 2019 relevant sections to the proposed projects are:</p> <p>8. Safety and Health, 10. Consultation 13. Notification and investigation of accidents, dangerous occurrences and occupational illness. Adopting this Act, PMDFC has developed SOPs for health and safety of the labor (including women workers) and communities which will be applicable for all the infrastructure related activities of new or rehabilitation subprojects.</p> |
| 10 | National Hazardous Waste Management Policy, 2022 | A policy to facilitate the implementation of international treaties & Conventions on a national level to improve the definition & implementation of Hazardous Waste Management (HWM) for better environmental management, clarify institutional | Policy measures shall be applicable whereas there is any risk of usage or generation of hazardous waste. |

| Sr. # | Act | Description | Applicability to sub-project |
|-------|---|---|---|
| | | responsibilities related to HWM, and strengthen the management of hazardous & other wastes. | |
| 11 | Protection Against Harassment of Women at the Workplace (Amended) Act, 2014 | In this act major and minor penalties are mentioned. | This act is applicable for all the employees of MCs, LG&CDD and women labor (if involved for infrastructure development activities) |
| 12 | Punjab Labor Policy, 2018 | Punjab Labor Policy, 2018 presents a policy document which directly addresses the child labor, bonded labor, gender discrimination, gender mainstreaming, labor protection, out of school children and lack of health facilities for the workers etc. Labor Policy of 2018 incorporates the key thematic areas regarding effective implementation of labor standards, social dialogue, improvements in workplace safety, living wages, awareness raising, excellence in labor inspections regime, imparting quality technical trainings through well-improved Training Centers, simplification of labor laws, medical facilities for secured workers even after retirement, establishment of labor colonies and schools for workers' children, improvement in | This act is applicable for all the employees of MCs, LG&CDD and women labor (if involved for infrastructure development activities) |

| Sr. # | Act | Description | Applicability to sub-project |
|-------|-----------------------------------|--|--|
| | | the wage fixation process and strengthening the role of Punjab Minimum Wages Board, efficient disbursement of welfare grants and gradual extension of labor protection frame-work. | |
| 13 | Punjab Local Government Act, 2019 | <p>As per PLGA 2019 Functions of a Metropolitan Corporation, Municipal Corporation and Municipal Committee:</p> <p>Part I</p> <p>(g) Solid waste collection and disposal;</p> <p>(h) Sewerage collection and disposal including water management and treatment;</p> <p>(i) Building control and land use;</p> <p>(j) Births, deaths, marriages and divorce registration;</p> <p>(k) Museums and art galleries;</p> <p>(l) Open markets;</p> <p>(m) Livestock and agriculture markets;</p> <p>(n) Public parking facilities;</p> <p>(o) City roads and traffic management;</p> <p>(p) Public transport;</p> | All the related clauses of this Act shall be applicable for MCs. |

| Sr. # | Act | Description | Applicability to sub-project |
|-------|-----|--|------------------------------|
| | | <p>(q) Abstraction of water for industrial and commercial purposes;</p> <p>(r) Emergency planning and relief;</p> <p>(s) Support to provincial agencies in prevention of crime and maintenance of public order; and</p> <p>(t) Regulatory enforcement in the functions assigned under Part 1 and 2 of this Schedule;</p> <p>Part 2</p> <p>(u) Establishment and management of pre-schools;</p> <p>(v) Libraries;</p> <p>(w) Drinking water supply;</p> <p>(x) Public convenances;</p> <p>(z) Children's services;</p> <p>(aa) Community safety;</p> <p>(bb) Arts and recreation;</p> <p>(cc) Public fairs and ceremonies;</p> <p>(dd) Sports;</p> <p>(ee) Environmental health, awareness and services;</p> <p>(ff) Parks and landscape development;</p> <p>(gg) Slaughtering of animals;</p> <p>(hh) Street lights; and</p> | |

| Sr. # | Act | Description | Applicability to sub-project |
|-------|--|---|--|
| | | (ii) Sign boards and street advertisements. | |
| 14 | Guidelines for Preparation and Review of Environment Reports, 1997 | Guidelines for preparation and Review of Environmental Reports were issued by Pak EPA in 1997 under Pakistan Environment Protection Act, 1997 and are adopted by Punjab Environment protection Agency after 18 th Amendment. These guidelines describe the steps in IEE Preparation, format of IEE Reports, assessing impacts, mitigation and impact management, reporting, reviewing and decision making, monitoring and auditing and project management. | These guidelines shall be applicable during preparation and review of IEEs/EIAs of new infrastructure development projects. |
| 15 | Guidelines for Public Consultation, 1997 | These guidelines address possible approaches to public consultation and techniques for designing an effective program of consultation that reaches all major stakeholders and ensures the incorporation of their concerns in any impact assessment study. The guidelines cover consultation, involvement, and participation of stakeholders; effective public consultation (planning, stages of an EIA where | Public consultation and citizens engagement is mandatory at projects planning and design phase and these guidelines shall be applicable for public consultation. |

| Sr. # | Act | Description | Applicability to sub-project |
|-------|--|--|---|
| | | consultation is appropriate); and facilitation of involvement (including the poor, women, and NGOs). | |
| 16 | Guidelines for Regulation of Disclosure of Environmental Information & Citizen Engagement 2020 | <p>These guidelines give details about disclosure of environmental information. These guidelines have 2 parts:</p> <p>First part deals with Public Disclosure instructions regarding arrangement of public disclosure of environment information and maintenance of record in indexed form</p> <p>Second part is regarding Citizen Engagement, and it gives detailed information regarding citizen engagement and Grievance redress mechanism.</p> | <p>These guidelines will be applicable for public disclosure of environment related information of IEEs/EIAs or any other interventions that may cause any harm to the environment.</p> |
| 17 | Canal and Drainage Act 1873 and Amendment Act 2016 | <p>The CDA focuses on construction and maintenance of drainage channels and defines powers to prohibit obstruction or order their removal. It also covers issues related to canal navigation. It briefly addresses issues relating to environmental pollution.</p> <p>Section 70(5) of the CDA clearly states that no one is allowed to "corrupt or foul the water of any canal</p> | <p>This act shall be applicable for all the subprojects of MCs where untreated wastewater is being dispose off to the irrigation canals.</p> |

| Sr. # | Act | Description | Applicability to sub-project |
|-------|---|---|---|
| | | <p>so as to render it less fit for the purposes for which it is ordinarily used.”</p> <p>In addition, Section 73 of the CDA gives power to arrest without warrant or to be taken before the magistrate a person who has willfully damaged or obstructed the canal or “rendered it less useful.”</p> | |
| 18 | Punjab Wildlife Protection, Conservation and Management Act, 1974 | The Act requires the protection of wildlife species declared as endangered/threatened and rare. It gives protection to these species by declaring their natural living environment as protected and reserved, which includes areas such as national parks, wildlife sanctuaries, and game reserves. | This act shall be applicable in case any harm to wildlife is assessed at the stage of early screening or if there is any potential risk identified to the wildlife during or after execution of the subprojects/projects related to infrastructure development and municipal service delivery. |
| 19 | Guidelines and Checklists adopted by GOP after 18th Amendment | <p>Punjab EPA has also designed the following Guidelines/Checklists for IEE/EIA Projects:</p> <p>Check List for IEE (updated September 2020)</p> <p>Check List for EIA (updated September 2020)</p> <p>After 18th Amendment, Punjab EPA has adopted the following sectoral Guidelines that were prepared by other provinces and were earlier adopted by Pak EPA:</p> <ul style="list-style-type: none"> ✓ Poultry Farms | <p>Checklists for IEE and EIA shall be applicable to all the new infrastructure development projects.</p> <p>Following Guidelines shall be applicable for MC’s municipal service delivery projects:</p> <ul style="list-style-type: none"> ✓ Urban Roads ✓ Water Supply ✓ Sanitation Schemes ✓ Major Sewerage Schemes |

| Sr. # | Act | Description | Applicability to sub-project |
|-------|-----|---|------------------------------|
| | | <ul style="list-style-type: none"> ✓ Urban Roads ✓ Rural Schools ✓ Housing Schemes ✓ Petrol & CNG ✓ Forest Road ✓ Forest Harvesting ✓ Water Supply ✓ Tourist Facilities ✓ Sanitation Schemes ✓ Major Chemicals and Manufacturing Plants ✓ Flour Mills ✓ Carpet Manufacturing ✓ Housing Estates and New Town Development ✓ Industrial Estate ✓ Major Roads ✓ Major Sewerage Schemes ✓ Stone Crushers ✓ Marble Units ✓ Oil & Gas Exploration | |

Section 2: Environmental & Social Categorization

2.1. Environmental Screening and Categorization of Sub-Projects

Based upon the Screening Checklists, following table will be used to for environmental screening of the identified sub-projects/projects and further documentation requirements. This classification is preliminary and will be finalized when the exact locations and scale of the sub-projects are identified, and screening checklist will be filled in for each of the sub-project/project.

| Sr. # | Project Categories | Type of Sub-projects | Nature of Environmental Issues | Env. Category | Social Category | Instruments Required |
|-------|--|--|---|---------------|--|---|
| 1. | Waste Management | | | | | |
| | Solid Waste | Collection Equipment, Collection Bins | Negligible environmental impacts | E3 | S3 | Applicability of PMDFC EHS SOPs for SWM Machinery/Equipment |
| | Liquid Waste | Sludge ponds | May have some negative but localized environmental and social impacts | E2 | S2 | ESMP |
| | | Community septic tanks | May have some negative but localized environmental and social impacts | E2 | S2 | ESMP |
| | | Vacuum Trucks, Vacuum Handcarts and others | Negligible environmental impacts | E3 | S3 | NA |
| | Construction of Waste Water Treatment Plants | May have significant environmental impacts | E1 | S2/S1 | IEE/EIA as per nature of impacts and Schedule I and II of PEPA Review of IEE/EIA Regulations 2022. | |

| Sr. # | Project Categories | Type of Sub-projects | Nature of Environmental Issues | Env. Category | Social Category | Instruments Required |
|-------|--|-----------------------------------|---|---------------|-----------------|---|
| 2. | Water Supply | | | | | |
| | | Water supply pumps / tube wells | May have negligible environmental impacts | E3 | S3 | NA |
| | | Overhead reservoirs (OHRs) | May have negligible environmental impacts | E2 | S2 | ESMP |
| | | Water Supply distribution network | May have some negative to significant environmental and social impacts depending upon the scope of work | E1 or E2 | S1 or S2 | ESMP for repair and maintenance of existing network or IEE/EIA for new sub-projects as per scope of work and environmental impacts and categorization given in Schedule I and II of PEPA Review of IEE/EIA Regulations 2000 |
| 3. | Storm Water Drainage | | | | | |
| | Urban drainage systems Open Drainage System Covered Drains | | May have some negative to significant environmental and social impacts depending upon the scope of work | E1 or E2 | S1 or S2 | ESMP for repair and maintenance of existing systems or IEE/EIA for new sub-projects as per scope of work and environmental impacts and categorization given in Schedule I and II of PEPA Review of IEE/EIA Regulations 2000 |

| Sr. # | Project Categories | Type of Sub-projects | Nature of Environmental Issues | Env. Category | Social Category | Instruments Required |
|-----------|--|-----------------------|---|---------------|-----------------|---|
| | | Flood control systems | May have some negative to significant environmental and social impacts depending upon the scope of work | E1 or E2 | S2 | ESMP for repair and maintenance of existing system or IEE/EIA for new sub-project as per scope of work and environmental impacts and categorization given in Schedule I and II of PEPA Review of IEE/EIA Regulations 2000 |
| 4. | Connectivity | | | | | |
| | Rehabilitation and maintenance of urban roads ⁴ | | May have some negative but localized environmental and social impacts | E2 | S2S | ESMP |
| | Pedestrian walkways, Bicycle paths | | May have negligible environmental impacts | E2 | S2 | ESMP |
| | Streets and security lights, and road signs | | May have negligible environmental impacts | E3 | S3 | NA |
| | Construction of Bus Workshops | | May have some negative but localized environmental and social impacts | E2 | S2 | ESMP |
| | Rehabilitation of Bus Stands/Terminals ⁵ | | May have negligible environmental impacts | E2 | E2 | ESMP |
| 5. | Social and Livability Infrastructure | | | | | |

4 After 18th Amendment, Punjab EPA has adopted the Checklists/Guidelines adopted by the Pakistan EPA (as it is). Punjab EPA has adopted Checklists/Guidelines developed by KPK and Balochistan for Small to medium water supply schemes, sanitation schemes, small and medium sized road construction and expansion in urban areas and construction and expansion of bus terminals. These Checklists/Guidelines will be used for the mentioned subprojects of PCP adopted by Punjab EPA

5 According to a notification by Punjab EPA vide No. Dir (EIA)/01/2017 dated 29-05-2017, Bus and Wagon stands of Category C with area upto 8 kanals, are exempted from IEE/EIA

| Sr. # | Project Categories | Type of Sub-projects | Nature of Environmental Issues | Env. Category | Social Category | Instruments Required |
|-------|--|----------------------|---|---------------|-----------------|----------------------|
| | Urban greenery and public spaces | | May have negligible environmental impacts | E2 | S2 | ESMP |
| | Construction of Community Parks ⁶ | | May have some negative but localized environmental and social impacts | E2/E1 | S2/S1 | ESMP/IEE/EIA |
| | Rehabilitation /Maintenance of Community Parks | | May have negligible environmental impacts | E2 | S2 | ESMP |

⁶ Parks will be constructed on already allocated lands (for community parks) by Local Government

Section 3: Budget Allocation

To carryout Environmental Assessment as per ESMF-PCP and PEPA, there is need to allocate budget in PC-I.

The IEE/EIA/ESMPs of each sub-project will be included in the bidding documents and the contracts. In this manner, the social and environmental management instruments will be included in the overall scope of works/services and BOQs, and the contractor will implement the mitigation measures included in the contracts alongside other works/services.

| Activity | Budget Allocation (PKR) |
|--|-------------------------|
| Environmental Impact Assessment (EIA) | |
| Hiring of Environmental Consultant | 100,0000-15,0000 |
| Implementation of EIA | 100,0000 |
| EIA Submission fee | 30,000 |
| Initial Environmental Examination (IEE) | |
| Hiring of Environmental Consultant | 500,000-800,000 |
| Implementation of IEE | 500,000- 700,000 |
| IEE Submission fee | 15, 000 |

Section 4: Monitoring & Supervision

Environment Focal Person (EFP) and Social Focal Point (SFP) and MCs of their respective region to monitor the contractor to ensure complete and proper implementation of the works/services in accordance with the contract. During this phase, environmental and social monitoring will be carried out to ensure that the mitigation measures given in the IEE/EIA/ESMPs are effectively implemented. The environmental and social monitoring will include the following:

- Environmental and social monitoring to ensure effective implementation of ESMPs and EMPs particularly the mitigation measures included in these documents.
- The monitoring will be conducted with the help of checklists prepared on the basis of the mitigation plans included in environmental and social management instruments.
- Laboratory analysis will be conducted if specified in the ESMPs.
- Photographic records will be maintained where applicable/useful.
- Preparation of monitoring reports.

Annexure E. Project Appraisal

Project ID: 03-13-05-01-01

Project Description : Improvement and Rehabilitation of Parks in Burewala City

| Sr. No. | Description | Unit | Value | Remarks |
|---------|--|-------|-------|---------|
| 1 | Net Present Value (NPV) | Rs. | (349) | |
| 2 | Financial Internal Rate of Return (FIRR) | % | 0% | |
| 3 | Benefit Cost Ratio (BCR) | Ratio | 1.01 | |
| 4 | Payback Period | Years | 5 | |

| Year No. | Year | Costs | | | Benefits | | | | Net (Cost)/ Benefits | PV @ % 22.32 | |
|----------|-----------|--------------|----------|------------|------------------------|----------------|-------------------------|----------------|----------------------|-----------------|--------------------------|
| | | Capital Cost | O&M Cost | Total Cost | Cost saving to society | Direct Revenue | Cost Savings/ Reduction | Total Benefits | | Discount Factor | PV |
| | | A | B | C=A+B | D | E | F | G=D+E+F | | H=G-C | I=(1.22.32) ⁿ |
| 0 | 2023-2024 | 370.00 | | 370 | | | | - | (370) | 1 | (370) |
| 1 | 2024-2025 | | 9.25 | 9 | | | 11.04 | 11 | 2 | 0.82 | 1 |
| 2 | 2025-2026 | | 10.74 | 11 | | | 12.82 | 13 | 2 | 0.67 | 1 |
| 3 | 2026-2027 | | 12.47 | 12 | | | 14.89 | 15 | 2 | 0.55 | 1 |
| 4 | 2027-2028 | | 14.48 | 14 | | | 17.28 | 17 | 3 | 0.45 | 1 |
| 5 | 2028-2029 | | 16.82 | 17 | | | 20.07 | 20 | 3 | 0.37 | 1 |
| 6 | 2029-2030 | | 19.53 | 20 | | | 23.31 | 23 | 4 | 0.30 | 1 |
| 7 | 2030-2031 | | 22.68 | 23 | | | 27.06 | 27 | 4 | 0.24 | 1 |
| 8 | 2031-2032 | | 26.33 | 26 | | | 31.43 | 31 | 5 | 0.20 | 1 |
| 9 | 2032-2033 | | 30.58 | 31 | | | 36.49 | 36 | 6 | 0.16 | 1 |
| 10 | 2033-2034 | | 35.51 | 36 | | | 42.37 | 42 | 7 | 0.13 | 1 |
| 11 | 2034-2035 | | 41.23 | 41 | | | 49.20 | 49 | 8 | 0.11 | 1 |
| 12 | 2035-2036 | | 47.88 | 48 | | | 57.14 | 57 | 9 | 0.09 | 1 |
| 13 | 2036-2037 | | 55.59 | 56 | | | 66.35 | 66 | 11 | 0.07 | 1 |
| 14 | 2037-2038 | | 64.56 | 65 | | | 77.04 | 77 | 12 | 0.06 | 1 |
| 15 | 2038-2039 | | 74.96 | 75 | | | 89.46 | 89 | 14 | 0.05 | 1 |
| 16 | 2039-2040 | | 87.05 | 87 | | | 103.88 | 104 | 17 | 0.04 | 1 |
| 17 | 2040-2041 | | 101.08 | 101 | | | 120.63 | 121 | 20 | 0.03 | 1 |
| 18 | 2041-2042 | | 117.37 | 117 | | | 140.07 | 140 | 23 | 0.03 | 1 |
| 19 | 2042-2043 | | 136.29 | 136 | | | 162.65 | 163 | 26 | 0.02 | 1 |
| 20 | 2043-2044 | | 158.26 | 158 | | | 188.87 | 189 | 31 | 0.02 | 1 |
| 21 | 2044-2045 | | 183.77 | 184 | | | 219.32 | 219 | 36 | 0.01 | 1 |
| 22 | 2045-2046 | | 213.40 | 213 | | | 254.67 | 255 | 41 | 0.01 | 0 |
| 23 | 2046-2047 | | 247.80 | 248 | | | 295.73 | 296 | 48 | 0.01 | 0 |
| 24 | 2047-2048 | | 287.74 | 288 | | | 343.40 | 343 | 56 | 0.01 | 0 |
| 25 | 2048-2049 | | | - | | | | - | - | 0.01 | - |
| Total | | 370 | 2,015 | 2,385 | - | - | 2,405 | 2,405 | 20 | | (349) |

Assumptions for Financial Appraisal

Costs:

- 1 Capital cost of the Project incorporates both the initial one-off costs such as engineering cost, project construction cost, development cost, procurement cost of equipment, machinery & other assets, utility set up cost, and any other costs to be incurred during the construction period.
- 2 Operating and maintenance (O&M) cost shall be incurred during operational phases of the project. Operation and maintenance cost includes electricity and other utility cost, administrative expenses, maintenance cost, payroll cost and other overheads etc.
- 3 Inflation rate is taken for O&M costs @ 16.12%, which is average inflation of last 5 years.

Benefits:

- 4 Benefits include the potential saving in the opportunity cost of vehicles. Project would provide effective protection to the vehicles against the solar radiation and ultraviolet rays, rain, hail, wind, and dust, thereby slowing down the deterioration of vehicles and reducing the cost of maintenance.
- 5 Inflation rate is applied at cost savings @ 16.12%, which is average inflation of last 5 years.
- 6 Residual Value had been taken as nil.

Estimated Project Life:

- 7 The life estimates of assets are compiled after review of design criteria for MC assets and international best practices. The Life Estimates taken in IDAMP are as follow:

| Asset | Useful Life |
|-------------------------------------|-------------|
| Buildings/ Civil Works | 25 |
| Tubewell Pumps | 15 |
| Disposal Pumps | 15 |
| OHR | 50 |
| Water Pipelines | 25 |
| Rising Mains/ Transmission Mains | 25 |
| Sewerage/ RCC Pipelines | 25 |
| Vehicles | 10 |
| Machinery & Equipment | 15 |

Macro-economic Indicators

- 8 The discount rate used for computation of present value of cash flows is taken @ 22.32 % per anum, which is KIBOR prescribed by State Bank of Pakistan as at April 11, 2023.
- 9 Exchange rate is taken as 284.65 PKR/ USD as per Exchange Rates for Mark to Market Revaluation provided at State Bank of Pakistan at April 07, 2023.

Project ID: 03-13-01-06-01

Project Description : Construction of Underground Water Storage Tank

| Sr. No. | Description | Unit | Value | Remarks |
|---------|--|-------|-------|--|
| 1 | Net Present Value (NPV) | Rs. | (229) | NPV=PV of benefits @ 22.32% - PV of costs @ 22.32% |
| 2 | Financial Internal Rate of Return (FIRR) | % | 14% | FIRR |
| 3 | Benefit Cost Ratio (BCR) | Ratio | 2.17 | BCR= Total Benefits ÷ Total Costs |
| 4 | Payback Period | Years | 7.25 | PBP= Capital costs ÷ Annual Net Benefits |

| Year No. | Year | Costs | | | Benefits | | | | Net (Cost)/ Benefits | PV @ % 22.32 | |
|----------|-----------|--------------|----------|------------|------------------------|----------------|-------------------------|----------------|----------------------|-----------------|--------------------------|
| | | Capital Cost | O&M Cost | Total Cost | Cost saving to society | Direct Revenue | Cost Savings/ Reduction | Total Benefits | | Discount Factor | PV |
| | | A | B | C=A+B | D | E | F | G=D+E+F | | H=G-C | I=(1.22.32) ⁿ |
| 0 | 2023-2024 | 137.50 | | 138 | | | | - | (138) | 1 | (138) |
| 1 | 2024-2025 | 275.00 | | 275 | 30.25 | | | 30 | (245) | 0.82 | (200) |
| 2 | 2025-2026 | 137.50 | 13.75 | 151 | 35.13 | | | 35 | (116) | 0.67 | (78) |
| 3 | 2026-2027 | | 15.97 | 16 | 40.79 | | | 41 | 25 | 0.55 | 14 |
| 4 | 2027-2028 | | 18.54 | 19 | 47.36 | | | 47 | 29 | 0.45 | 13 |
| 5 | 2028-2029 | | 21.53 | 22 | 55.00 | | | 55 | 33 | 0.37 | 12 |
| 6 | 2029-2030 | | 25.00 | 25 | 63.86 | | | 64 | 39 | 0.30 | 12 |
| 7 | 2030-2031 | | 29.03 | 29 | 74.16 | | | 74 | 45 | 0.24 | 11 |
| 8 | 2031-2032 | | 33.71 | 34 | 86.11 | | | 86 | 52 | 0.20 | 10 |
| 9 | 2032-2033 | | 39.14 | 39 | 100.00 | | | 100 | 61 | 0.16 | 10 |
| 10 | 2033-2034 | | 45.45 | 45 | 116.12 | | | 116 | 71 | 0.13 | 9 |
| 11 | 2034-2035 | | 52.78 | 53 | 134.83 | | | 135 | 82 | 0.11 | 9 |
| 12 | 2035-2036 | | 61.29 | 61 | 156.57 | | | 157 | 95 | 0.09 | 8 |
| 13 | 2036-2037 | | 71.17 | 71 | 181.81 | | | 182 | 111 | 0.07 | 8 |
| 14 | 2037-2038 | | 82.64 | 83 | 211.11 | | | 211 | 128 | 0.06 | 8 |
| 15 | 2038-2039 | | 95.96 | 96 | 245.15 | | | 245 | 149 | 0.05 | 7 |
| 16 | 2039-2040 | | 111.43 | 111 | 284.66 | | | 285 | 173 | 0.04 | 7 |
| 17 | 2040-2041 | | 129.39 | 129 | 330.55 | | | 331 | 201 | 0.03 | 7 |
| 18 | 2041-2042 | | 150.25 | 150 | 383.84 | | | 384 | 234 | 0.03 | 6 |
| 19 | 2042-2043 | | 174.47 | 174 | 445.71 | | | 446 | 271 | 0.02 | 6 |
| 20 | 2043-2044 | | 202.60 | 203 | 517.56 | | | 518 | 315 | 0.02 | 6 |
| 21 | 2044-2045 | | 235.25 | 235 | 600.99 | | | 601 | 366 | 0.01 | 5 |
| 22 | 2045-2046 | | 273.18 | 273 | 697.87 | | | 698 | 425 | 0.01 | 5 |
| 23 | 2046-2047 | | 317.21 | 317 | 810.36 | | | 810 | 493 | 0.01 | 5 |
| 24 | 2047-2048 | | 368.35 | 368 | 940.99 | | | 941 | 573 | 0.01 | 5 |
| 25 | 2048-2049 | | 427.72 | 428 | 1,092.68 | | | 1,093 | 665 | 0.01 | 4 |
| Total | | 550 | 2,996 | 3,546 | 7,683 | - | - | 7,683 | 4,138 | | (229) |

Assumptions for Financial Appraisal

Costs:

- 1 Capital cost of the Project incorporates both the initial one-off costs such as engineering cost, project construction cost, development cost, procurement cost of equipment, machinery & other assets, utility set up cost, and any other costs to be incurred during the construction period.
- 2 Operating and maintenance (O&M) cost shall be incurred during operational phases of the project. Operation and maintenance cost includes electricity and other utility cost, administrative expenses, maintenance cost, payroll cost and other overheads etc.
- 3 Inflation rate is taken for O&M costs @ 16.12%, which is average inflation of last 5 years.

Benefits:

- 4 Benefits include the potential saving in the opportunity cost of vehicles. Project would provide effective protection to the vehicles against the solar radiation and ultraviolet rays, rain, hail, wind, and dust, thereby slowing down the deterioration of vehicles and reducing the cost of maintenance.
- 5 Inflation rate is applied at cost savings @ 16.12%, which is average inflation of last 5 years.
- 6 Residual Value had been taken as nil.

Estimated Project Life:

- 7 The life estimates of assets are compiled after review of design criteria for MC assets and international best practices. The Life Estimates taken in IDAMP are as follow:

| Asset | Useful Life |
|-------------------------------------|-------------|
| Buildings/ Civil Works | 25 |
| Tubewell Pumps | 15 |
| Disposal Pumps | 15 |
| OHR | 50 |
| Water Pipelines | 25 |
| Rising Mains/ Transmission Mains | 25 |
| Sewerage/ RCC Pipelines | 25 |
| Vehicles | 10 |
| Machinery & Equipment | 15 |

Macro-economic Indicators

- 8 The discount rate used for computation of present value of cash flows is taken @ 22.32 % per anum, which is KIBOR prescribed by State Bank of Pakistan as at April 11, 2023.
- 9 Exchange rate is taken as 284.65 PKR/ USD as per Exchange Rates for Mark to Market Revaluation provided at State Bank of Pakistan at April 07, 2023.

Project ID: 03-13-06-01-01

Project Description : Solarization of the municipal buildings

| Sr. No. | Description | | Unit | Value | Remarks |
|---------|--|--|-------|-------|---------|
| 1 | Net Present Value (NPV) | NPV=PV of benefits @ 22.32% - PV of costs @ 22.32% | Rs. | 498 | |
| 2 | Financial Internal Rate of Return (FIRR) | FIRR | % | 37% | |
| 3 | Benefit Cost Ratio (BCR) | BCR= Total Benefits ÷ Total Costs | Ratio | 22.53 | |
| 4 | Payback Period | PBP= Capital costs ÷ Annual Net Benefits | Years | 7.25 | |

| Year No. | Year | Costs | | | Benefits | | | | Net (Cost)/ Benefits | PV @ % 22.32 | |
|----------|-----------|--------------|----------|------------|------------------------|----------------|-------------------------|----------------|----------------------|-----------------|--------------------------|
| | | Capital Cost | O&M Cost | Total Cost | Cost saving to society | Direct Revenue | Cost Savings/ Reduction | Total Benefits | | Discount Factor | PV |
| | | A | B | C=A+B | D | E | F | G=D+E+F | | H=G-C | I=(1.22.32) ⁿ |
| 0 | 2023-2024 | 330.00 | 1.65 | 332 | | | | - | (332) | 1 | (332) |
| 1 | 2024-2025 | | 1.92 | 2 | 72.60 | | | 73 | 71 | 0.82 | 58 |
| 2 | 2025-2026 | | 2.22 | 2 | 84.30 | | | 84 | 82 | 0.67 | 55 |
| 3 | 2026-2027 | | 2.58 | 3 | 97.89 | | | 98 | 95 | 0.55 | 52 |
| 4 | 2027-2028 | | 3.00 | 3 | 113.67 | | | 114 | 111 | 0.45 | 49 |
| 5 | 2028-2029 | | 3.48 | 3 | 132.00 | | | 132 | 129 | 0.37 | 47 |
| 6 | 2029-2030 | | 4.05 | 4 | 153.28 | | | 153 | 149 | 0.30 | 45 |
| 7 | 2030-2031 | | 4.70 | 5 | 177.98 | | | 178 | 173 | 0.24 | 42 |
| 8 | 2031-2032 | | 5.45 | 5 | 206.67 | | | 207 | 201 | 0.20 | 40 |
| 9 | 2032-2033 | | 6.33 | 6 | 239.99 | | | 240 | 234 | 0.16 | 38 |
| 10 | 2033-2034 | | 7.35 | 7 | 278.68 | | | 279 | 271 | 0.13 | 36 |
| 11 | 2034-2035 | | 8.54 | 9 | 323.60 | | | 324 | 315 | 0.11 | 34 |
| 12 | 2035-2036 | | 9.92 | 10 | 375.76 | | | 376 | 366 | 0.09 | 33 |
| 13 | 2036-2037 | | 11.52 | 12 | 436.34 | | | 436 | 425 | 0.07 | 31 |
| 14 | 2037-2038 | | 13.37 | 13 | 506.67 | | | 507 | 493 | 0.06 | 29 |
| 15 | 2038-2039 | | 15.53 | 16 | 588.35 | | | 588 | 573 | 0.05 | 28 |
| 16 | 2039-2040 | | 18.03 | 18 | 683.19 | | | 683 | 665 | 0.04 | 26 |
| 17 | 2040-2041 | | 20.94 | 21 | 793.32 | | | 793 | 772 | 0.03 | 25 |
| 18 | 2041-2042 | | 24.31 | 24 | 921.20 | | | 921 | 897 | 0.03 | 24 |
| 19 | 2042-2043 | | 28.23 | 28 | 1,069.70 | | | 1,070 | 1,041 | 0.02 | 23 |
| 20 | 2043-2044 | | 32.78 | 33 | 1,242.14 | | | 1,242 | 1,209 | 0.02 | 22 |
| 21 | 2044-2045 | | 38.07 | 38 | 1,442.37 | | | 1,442 | 1,404 | 0.01 | 20 |
| 22 | 2045-2046 | | 44.20 | 44 | 1,674.88 | | | 1,675 | 1,631 | 0.01 | 19 |
| 23 | 2046-2047 | | 51.33 | 51 | 1,944.87 | | | 1,945 | 1,894 | 0.01 | 18 |
| 24 | 2047-2048 | | 59.60 | 60 | 2,258.39 | | | 2,258 | 2,199 | 0.01 | 17 |
| 25 | 2048-2049 | | 69.21 | 69 | 2,622.44 | | | 2,622 | 2,553 | 0.01 | 17 |
| Total | | 330 | 488 | 818 | 18,440 | - | - | 18,440 | 17,622 | | 498 |

Assumptions for Financial Appraisal

Costs:

- 1 Capital cost of the Project incorporates both the initial one-off costs such as engineering cost, project construction cost, development cost, procurement cost of equipment, machinery & other assets, utility set up cost, and any other costs to be incurred during the construction period.
- 2 Operating and maintenance (O&M) cost shall be incurred during operational phases of the project. Operation and maintenance cost includes electricity and other utility cost, administrative expenses, maintenance cost, payroll cost and other overheads etc.
- 3 Inflation rate is taken for O&M costs @ 16.12%, which is average inflation of last 5 years.

Benefits:

- 4 Benefits include the potential saving in the opportunity cost of vehicles. Project would provide effective protection to the vehicles against the solar radiation and ultraviolet rays, rain, hail, wind, and dust, thereby slowing down the deterioration of vehicles and reducing the cost of maintenance.
- 5 Inflation rate is applied at cost savings @ 16.12%, which is average inflation of last 5 years.
- 6 Residual Value had been taken as nil.

Estimated Project Life:

- 7 The life estimates of assets are compiled after review of design criteria for MC assets and international best practices. The Life Estimates taken in IDAMP are as follow:

| Asset | Useful Life |
|-------------------------------------|-------------|
| Buildings/ Civil Works | 25 |
| Tubewell Pumps | 15 |
| Disposal Pumps | 15 |
| OHR | 50 |
| Water Pipelines | 25 |
| Rising Mains/ Transmission Mains | 25 |
| Sewerage/ RCC Pipelines | 25 |
| Vehicles | 10 |
| Machinery & Equipment | 15 |

Macro-economic Indicators

- 8 The discount rate used for computation of present value of cash flows is taken @ 22.32 % per annum, which is KIBOR prescribed by State Bank of Pakistan as at April 11, 2023.
- 9 Exchange rate is taken as 284.65 PKR/ USD as per Exchange Rates for Mark to Market Revaluation provided at State Bank of Pakistan at April 07, 2023.

Project ID: 03-13-01-01-01

Project Description : Solarization of Tube wells and Water Supply System

| Sr. No. | Description | Unit | Value | Remarks |
|---------|--|-------|-------|--|
| 1 | Net Present Value (NPV) | Rs. | 272 | NPV=PV of benefits @ 22.32% - PV of costs @ 22.32% |
| 2 | Financial Internal Rate of Return (FIRR) | % | 37% | FIRR |
| 3 | Benefit Cost Ratio (BCR) | Ratio | 22.53 | BCR= Total Benefits ÷ Total Costs |
| 4 | Payback Period | Years | 7.25 | PBP= Capital costs ÷ Annual Net Benefits |

| Year No. | Year | Costs | | | Benefits | | | | Net (Cost)/ Benefits H=G-C | PV @ % 22.32 | |
|----------|-----------|--------------|----------|------------|------------------------|----------------|-------------------------|----------------|-------------------------------|--------------------------|-------|
| | | Capital Cost | O&M Cost | Total Cost | Cost saving to society | Direct Revenue | Cost Savings/ Reduction | Total Benefits | | Discount Factor | PV |
| | | A | B | C=A+B | D | E | F | G=D+E+F | | I=(1.22.32) ⁿ | J=HxI |
| 0 | 2023-2024 | 180.00 | 0.90 | 181 | | | | - | (181) | 1 | (181) |
| 1 | 2024-2025 | | 1.05 | 1 | 39.60 | | | 40 | 39 | 0.82 | 32 |
| 2 | 2025-2026 | | 1.21 | 1 | 45.98 | | | 46 | 45 | 0.67 | 30 |
| 3 | 2026-2027 | | 1.41 | 1 | 53.40 | | | 53 | 52 | 0.55 | 28 |
| 4 | 2027-2028 | | 1.64 | 2 | 62.00 | | | 62 | 60 | 0.45 | 27 |
| 5 | 2028-2029 | | 1.90 | 2 | 72.00 | | | 72 | 70 | 0.37 | 26 |
| 6 | 2029-2030 | | 2.21 | 2 | 83.60 | | | 84 | 81 | 0.30 | 24 |
| 7 | 2030-2031 | | 2.56 | 3 | 97.08 | | | 97 | 95 | 0.24 | 23 |
| 8 | 2031-2032 | | 2.98 | 3 | 112.73 | | | 113 | 110 | 0.20 | 22 |
| 9 | 2032-2033 | | 3.45 | 3 | 130.90 | | | 131 | 127 | 0.16 | 21 |
| 10 | 2033-2034 | | 4.01 | 4 | 152.01 | | | 152 | 148 | 0.13 | 20 |
| 11 | 2034-2035 | | 4.66 | 5 | 176.51 | | | 177 | 172 | 0.11 | 19 |
| 12 | 2035-2036 | | 5.41 | 5 | 204.96 | | | 205 | 200 | 0.09 | 18 |
| 13 | 2036-2037 | | 6.28 | 6 | 238.00 | | | 238 | 232 | 0.07 | 17 |
| 14 | 2037-2038 | | 7.29 | 7 | 276.37 | | | 276 | 269 | 0.06 | 16 |
| 15 | 2038-2039 | | 8.47 | 8 | 320.92 | | | 321 | 312 | 0.05 | 15 |
| 16 | 2039-2040 | | 9.83 | 10 | 372.65 | | | 373 | 363 | 0.04 | 14 |
| 17 | 2040-2041 | | 11.42 | 11 | 432.72 | | | 433 | 421 | 0.03 | 14 |
| 18 | 2041-2042 | | 13.26 | 13 | 502.48 | | | 502 | 489 | 0.03 | 13 |
| 19 | 2042-2043 | | 15.40 | 15 | 583.47 | | | 583 | 568 | 0.02 | 12 |
| 20 | 2043-2044 | | 17.88 | 18 | 677.53 | | | 678 | 660 | 0.02 | 12 |
| 21 | 2044-2045 | | 20.76 | 21 | 786.75 | | | 787 | 766 | 0.01 | 11 |
| 22 | 2045-2046 | | 24.11 | 24 | 913.57 | | | 914 | 889 | 0.01 | 11 |
| 23 | 2046-2047 | | 28.00 | 28 | 1,060.84 | | | 1,061 | 1,033 | 0.01 | 10 |
| 24 | 2047-2048 | | 32.51 | 33 | 1,231.85 | | | 1,232 | 1,199 | 0.01 | 10 |
| 25 | 2048-2049 | | 37.75 | 38 | 1,430.42 | | | 1,430 | 1,393 | 0.01 | 9 |
| Total | | 180 | 266 | 446 | 10,058 | - | - | 10,058 | 9,612 | | 272 |

Assumptions for Financial Appraisal

Costs:

- 1 Capital cost of the Project incorporates both the initial one-off costs such as engineering cost, project construction cost, development cost, procurement cost of equipment, machinery & other assets, utility set up cost, and any other costs to be incurred during the construction period.
- 2 Operating and maintenance (O&M) cost shall be incurred during operational phases of the project. Operation and maintenance cost includes electricity and other utility cost, administrative expenses, maintenance cost, payroll cost and other overheads etc.
- 3 Inflation rate is taken for O&M costs @ 16.12%, which is average inflation of last 5 years.

Benefits:

- 4 Benefits include the potential saving in the opportunity cost of vehicles. Project would provide effective protection to the vehicles against the solar radiation and ultraviolet rays, rain, hail, wind, and dust, thereby slowing down the deterioration of vehicles and reducing the cost of maintenance.
- 5 Inflation rate is applied at cost savings @ 16.12%, which is average inflation of last 5 years.
- 6 Residual Value had been taken as nil.

Estimated Project Life:

- 7 The life estimates of assets are compiled after review of design criteria for MC assets and international best practices. The Life Estimates taken in IDAMP are as follow:

| Asset | Useful Life |
|-------------------------------------|-------------|
| Buildings/ Civil Works | 25 |
| Tubewell Pumps | 15 |
| Disposal Pumps | 15 |
| OHR | 50 |
| Water Pipelines | 25 |
| Rising Mains/ Transmission Mains | 25 |
| Sewerage/ RCC Pipelines | 25 |
| Vehicles | 10 |
| Machinery & Equipment | 15 |

Macro-economic Indicators

- 8 The discount rate used for computation of present value of cash flows is taken @ 22.32 % per anum, which is KIBOR prescribed by State Bank of Pakistan as at April 11, 2023.
- 9 Exchange rate is taken as 284.65 PKR/ USD as per Exchange Rates for Mark to Market Revaluation provided at State Bank of Pakistan at April 07, 2023.

Project ID: 03-13-02-01-02

Project Description : Solarization of disposal stations

| Sr. No. | Description | | Unit | Value | Remarks |
|---------|--|--|-------|-------|---------|
| 1 | Net Present Value (NPV) | NPV=PV of benefits @ 22.32% - PV of costs @ 22.32% | Rs. | 126 | |
| 2 | Financial Internal Rate of Return (FIRR) | FIRR | % | 31% | |
| 3 | Benefit Cost Ratio (BCR) | BCR= Total Benefits ÷ Total Costs | Ratio | 3.54 | |
| 4 | Payback Period | PBP= Capital costs ÷ Annual Net Benefits | Years | 7.25 | |

| Year No. | Year | Costs | | | Benefits | | | | Net (Cost)/ Benefits | PV @ % 22.32 | |
|----------|-----------|--------------|----------|------------|------------------------|----------------|-------------------------|----------------|----------------------|-----------------|--------------------------|
| | | Capital Cost | O&M Cost | Total Cost | Cost saving to society | Direct Revenue | Cost Savings/ Reduction | Total Benefits | | Discount Factor | PV |
| | | A | B | C=A+B | D | E | F | G=D+E+F | | H=G-C | I=(1.22.32) ⁿ |
| 0 | 2023-2024 | 148.01 | 7.40 | 155 | | | | - | (155) | 1 | (155) |
| 1 | 2024-2025 | | 8.59 | 9 | 32.56 | | | 33 | 24 | 0.82 | 20 |
| 2 | 2025-2026 | | 9.98 | 10 | 37.81 | | | 38 | 28 | 0.67 | 19 |
| 3 | 2026-2027 | | 11.59 | 12 | 43.91 | | | 44 | 32 | 0.55 | 18 |
| 4 | 2027-2028 | | 13.46 | 13 | 50.98 | | | 51 | 38 | 0.45 | 17 |
| 5 | 2028-2029 | | 15.62 | 16 | 59.20 | | | 59 | 44 | 0.37 | 16 |
| 6 | 2029-2030 | | 18.14 | 18 | 68.75 | | | 69 | 51 | 0.30 | 15 |
| 7 | 2030-2031 | | 21.07 | 21 | 79.83 | | | 80 | 59 | 0.24 | 14 |
| 8 | 2031-2032 | | 24.46 | 24 | 92.70 | | | 93 | 68 | 0.20 | 14 |
| 9 | 2032-2033 | | 28.41 | 28 | 107.64 | | | 108 | 79 | 0.16 | 13 |
| 10 | 2033-2034 | | 32.99 | 33 | 124.99 | | | 125 | 92 | 0.13 | 12 |
| 11 | 2034-2035 | | 38.30 | 38 | 145.14 | | | 145 | 107 | 0.11 | 12 |
| 12 | 2035-2036 | | 44.48 | 44 | 168.54 | | | 169 | 124 | 0.09 | 11 |
| 13 | 2036-2037 | | 51.65 | 52 | 195.70 | | | 196 | 144 | 0.07 | 10 |
| 14 | 2037-2038 | | 59.97 | 60 | 227.25 | | | 227 | 167 | 0.06 | 10 |
| 15 | 2038-2039 | | 69.64 | 70 | 263.88 | | | 264 | 194 | 0.05 | 9 |
| 16 | 2039-2040 | | 80.87 | 81 | 306.42 | | | 306 | 226 | 0.04 | 9 |
| 17 | 2040-2041 | | 93.90 | 94 | 355.82 | | | 356 | 262 | 0.03 | 9 |
| 18 | 2041-2042 | | 109.04 | 109 | 413.17 | | | 413 | 304 | 0.03 | 8 |
| 19 | 2042-2043 | | 126.62 | 127 | 479.78 | | | 480 | 353 | 0.02 | 8 |
| 20 | 2043-2044 | | 147.03 | 147 | 557.12 | | | 557 | 410 | 0.02 | 7 |
| 21 | 2044-2045 | | 170.73 | 171 | 646.93 | | | 647 | 476 | 0.01 | 7 |
| 22 | 2045-2046 | | 198.25 | 198 | 751.21 | | | 751 | 553 | 0.01 | 7 |
| 23 | 2046-2047 | | 230.21 | 230 | 872.30 | | | 872 | 642 | 0.01 | 6 |
| 24 | 2047-2048 | | 267.32 | 267 | 1,012.92 | | | 1,013 | 746 | 0.01 | 6 |
| 25 | 2048-2049 | | 310.41 | 310 | 1,176.20 | | | 1,176 | 866 | 0.01 | 6 |
| Total | | 148 | 2,190 | 2,338 | 8,271 | - | - | 8,271 | 5,933 | | 126 |

Assumptions for Financial Appraisal

Costs:

- 1 Capital cost of the Project incorporates both the initial one-off costs such as engineering cost, project construction cost, development cost, procurement cost of equipment, machinery & other assets, utility set up cost, and any other costs to be incurred during the construction period.
- 2 Operating and maintenance (O&M) cost shall be incurred during operational phases of the project. Operation and maintenance cost includes electricity and other utility cost, administrative expenses, maintenance cost, payroll cost and other overheads etc.
- 3 Inflation rate is taken for O&M costs @ 16.12%, which is average inflation of last 5 years.

Benefits:

- 4 Benefits include the potential saving in the opportunity cost of vehicles. Project would provide effective protection to the vehicles against the solar radiation and ultraviolet rays, rain, hail, wind, and dust, thereby slowing down the deterioration of vehicles and reducing the cost of maintenance.
- 5 Inflation rate is applied at cost savings @ 16.12%, which is average inflation of last 5 years.
- 6 Residual Value had been taken as nil.

Estimated Project Life:

- 7 The life estimates of assets are compiled after review of design criteria for MC assets and international best practices. The Life Estimates taken in IDAMP are as follow:

| Asset | Useful Life |
|-------------------------------------|-------------|
| Buildings/ Civil Works | 25 |
| Tubewell Pumps | 15 |
| Disposal Pumps | 15 |
| OHR | 50 |
| Water Pipelines | 25 |
| Rising Mains/ Transmission Mains | 25 |
| Sewerage/ RCC Pipelines | 25 |
| Vehicles | 10 |
| Machinery & Equipment | 15 |

Macro-economic Indicators

- 8 The discount rate used for computation of present value of cash flows is taken @ 22.32 % per anum, which is KIBOR prescribed by State Bank of Pakistan as at April 11, 2023.
- 9 Exchange rate is taken as 284.65 PKR/ USD as per Exchange Rates for Mark to Market Revaluation provided at State Bank of Pakistan at April 07, 2023.

Annexure F. Stakeholder's Consultative Session



Consultative Session - Burewala.pdf

| City | Date | Consultant Team | MC Team | |
|----------|------------------------------------|-------------------|--------------|-------------|
| | | | Designation | Name |
| Burewala | From 5-May-23 To 6-May-23 | Mr. Muhammad Fiaz | MOI | Mr. Waseem |
| | | Mr. Abdullah | Sub Engineer | Mr. AD Khan |
| | | | PMDFC DPO IT | Mr. Junaid |
| | | | PMDFC DPO ID | Mr. Amjid |
| | | | DPO GIS | Mr. Usama |

Punjab Municipal Development Fund Company (PMDFC)



Punjab Cities Program



Integrated Development and Asset Management Plan (IDAMP)

Consultative Session

Conducted on May 11, 2023

Municipal Committee Burewala

Prepared by: Regional Program Coordinator (South)

Agenda

| Consultative Session on IDAMP with Stakeholders at MC Burewala | |
|---|--|
| Under Punjab Cities Program (PCP) | |
| Organizing Date: May 11, 2023 | |
| Time | Activity Description |
| 10:30 AM | Registration of the Participants |
| 11:00 AM | Recitation from the Holy Quran |
| 11:10 AM | Importance of Community participation |
| 11:45 AM | Introduction and Description of the IDAMP activity being performed at MC, its purpose, objective |
| 12:30 PM | Description of main points of IDAMP Framework/guidelines |
| 1:45 PM | Description of main features of IDAMP of respective MC (The developed IDAMP for MC may be discussed as an example) |
| 2:15 PM | Discussion on Projects Identified in IDAMP |
| 2:45 PM | Open Discussion |
| 3:00 PM | Discussion to ensure women participation in the overall process |
| 3:30 PM | Closing of Session |

PROCEEDINGS OF SESSION

After registration of participants a brief session was conducted on IDAMP details are given below:

1. Introduction:

The IDAMP Framework sets out the principles/guidelines and policies for efficient and transparent asset management and reporting system. Thus, this Framework is designed to ensure the effective planning, careful management, accurate recording and reliable reporting of all the assets over the asset life cycle for optimized service delivery to the public.

2. Purpose of IDAMP Framework

The key purpose of IDAMP Framework is the effective management of asset portfolio of the MCs in order to achieve service delivery objectives.

- Encourage a consistent approach and a common methodology for development and management of assets.
- Provide guidelines to ensure informed decision making by MCs for investment in and management of those assets which help achieve the service delivery objectives.
- Establish principles for the development of detailed Standard Operating Procedures for implementation and sustainability of IDAMP.

3. Scope of IDAMP Framework:

IDAMP Framework is, in initial phase, applicable to the 16 Municipal Committees (MCs) of Punjab supported by the World Bank-funded Punjab Cities Program (PCP) to strengthen the performance of MCs in urban management and municipal service delivery. These MCs are listed below:

| Sr. No. | Northern Punjab | Central Punjab | Southern Punjab |
|---------|-----------------|----------------|-----------------|
| 1. | Daska | Gojra | Bahawalnagar |
| 2. | Hafizabad | Jaranwala | Burewala |
| 3. | Jhelum | Jhang | Khanewal |

| | | | |
|----|-----------|---------|----------|
| 4. | Kamoke | Kamalia | Kot Addu |
| 5. | Muridke | Okara | Vehari |
| 6. | Wazirabad | | |

Further, this IDAMP Framework provides principles and guidance about the following arenas of asset management:

- Planning of Assets Development of project proposals for rehabilitation/replacement or new assets creation.
- Appraisal of proposed projects.
- Selection of suitable projects for implementation.
- Operation and maintenance (O&M) planning of assets.
- Monitoring and Evaluation of implementation of IDAMP.

4. Legal Authority of IDAMP Framework

It is the responsibility of local governments to manage and develop assets within their jurisdiction, including infrastructure, buildings, land, and public resources.


5. Overview of IDAMP/Challenges faced by MCs

- Repetitive Transition in LG System.
- Institutional Fragmentation and Unclear Accountability.
- Weak Systems and Capacities at MCs.
- Weak MC Finances.
- Low Coverage & Quality of the Municipal Services.
- Poor Operation & Maintenance (O&M).
- Lack of multi-year planning for development and asset management.


6. Key Concepts

The processes have been derived from the well-established standards like ISO 55000 and International Infrastructure Asset Management Manual (IIMM). The process is contextualized for Punjab Province based on the intensive discussion with the respective officials overseeing the asset management.

Every asset is bound to have certain time period for performing its operations or providing services attributed to it from acquisition to disposal. This is referred to as *Asset Life Cycle*.



Asset Management is related to entire Life Cycle of an asset called Life Cycle Asset Management. After acquisition, the maintenance for operation is done continuously on the basis of assessment of performance or condition as well as for achievement of desired level of service and finally the decision of upgrading, renewal, replacement or disposal is taken.



The coordinated system for carrying out life cycle asset management in an effective and efficient manner is the one known as 'Asset Management System' (AMS).

A standard AMS has various components which include asset registration, asset categories, finance, asset maintenance and asset related reports.



7. Key Challenges

- Lack of multi-year planning for development and asset management.
- Weak Systems and Capacities.
- Non-availability of an effective asset management system.
- Lack of well-defined system for the prioritization of projects.
- Poor Operation & Maintenance (O&M).

8. Objectives of IDAMP

- The importance of physical assets to delivering service delivery objectives and outcomes.
- The quality of existing physical assets in terms of condition and asset performance.
- The assets needed to meet or sustain current levels of service, and to address current and future shortfalls.
- The feasible asset solutions to address identified shortfalls.
- The level of commitment and planned improvements.

9. Key Benefits of IDAMP

- Improved service delivery.
- Improved financial performance.
- Informed asset investment decisions.
- Managed risk.
- Demonstrated social responsibility.
- Improved efficiency and effectiveness.
- Enhanced public trust and confidence.
- Improved organizational sustainability.

10. Asset Portfolio Analysis

- Asset Condition Assessment:
 - i. Its age.
 - ii. Its operating environment (what weather etc. it is exposed to).
 - iii. Its apparent wear and tear.
 - iv. Asset's performance.
 - v. Asset's contribution to service delivery.

11. Asset Portfolio Analysis

- Asset Risk Management

1. Physical Condition

| Physical Condition | New/Excellent Condition | Minor Defects Only | Moderate Deterioration | Significant Deterioration | Unserviceable |
|--------------------|-------------------------|--------------------|------------------------|---------------------------|---------------|
| Score | 1 | 2 | 3 | 4 | 5 |

2. Asset Performance (KPIs)

| Performance (KPIs) | Meets Performance Targets | Minor Performance Deficiencies | Considerable Performance Deficiencies | Major Performance Deficiencies | Doesn't Meet Performance Targets |
|--------------------|---------------------------|--------------------------------|---------------------------------------|--------------------------------|----------------------------------|
| Score | 1 | 2 | 3 | 4 | 5 |

3. Asset reliability

| Reliability | As Specified by Manufacturer | Random Breakdown | Occasional Breakdown | Periodic Breakdown | Continuous Breakdown |
|-------------|------------------------------|------------------|----------------------|--------------------|----------------------|
| Score | 1 | 2 | 3 | 4 | 5 |

Asset Condition Rating

An average score shall then be calculated by the department technical team and final score shall be awarded on the basis of average score of all the factors.

| Average Score | 1 | 2 | 3 | 4 | 5 |
|-----------------|-----------|------|------|------|---------|
| Asset Condition | Excellent | Good | Fair | Poor | Failing |
| Category | A | B | C | D | E |

12. Methodology for the IDAMP

Step 1: Development of GIS based Assets Inventory

Step 2: Notification of Level of Service (LOS)

Step 3: Development of Project Proposals

Step 4: Operations and Maintenance (O&M) Costs Planning

Step 5: Financial Capacity Analysis

Step 6: Projects Screening and Phasing

Step 7: Finalization of Integrated Development and Asset Management Plan

13. Monitoring and Evaluation of IDAMP


















- Establishment of M&E Unit
 - i. A Monitoring and Evaluation (M&E) Unit shall be established for continuous monitoring of implementation and compliance of the IDAMP.
 - ii. Chief Officer of the concerned Local Government (MC) shall nominate a Municipal Officer (MO) who shall not be part of Technical Team of IDAMP or may create an independent unit with name of Monitoring and Evaluation Unit.
- Monitoring and Evaluation of IDAMP
 - a) Ensure that Asset Management System (AMS) is updated in all aspects.
 - b) Carry out monitoring of:
 - i. Levels of services.
 - ii. Performance of an asset, including financial and non-financial performance.
 - iii. The effectiveness of the asset management system.
 - c) M&E Unit shall receive and evaluate the following reports from the entity and Asset Managers:
 - i. Report on Key Performance Indicators (Target vs Achieved).
 - ii. Report on projects implementation status.
 - iii. Report on any hindrance observed while implementing the project.
 - d) Evaluation of projects implemented during the year and its status with respect to IDAM Plan developed
 - e) Conduct Internal Audit at planned intervals to identify and address potential gaps in system and identify opportunities for performance improvement.
 - f) Review the entity's asset management policies, procedures and systems, at planned intervals, to ensure its continuous improvement, adequacy, suitability and effectiveness.
 - g) Provide recommendation and guidelines to IDAMP Team.


Attend Sheet of Session

Municipal Committee Burewala
Consultative Session for IDAMP
Attendance Sheet

Dated: 11-05-2023

Venue: Municipal Committee Burewala

| Sr # | Name | Contact Number | Resident Address | Gender | Occupation | Sign |
|------|------------------------|----------------|-------------------------|--------|------------|---|
| | امینہ الدہلوی | | CO MC Burewala | | | |
| | حافظ محمد وسیم | | MO (C) MC Burewala | | |  |
| | عمار الطاق | | MO (P) MC Burewala | | |  |
| | الہودتہ | | S. Engineer MC Burewala | | |  |
| | ایم سی | | SDO PHED Burewala | | |  |
| | مناد الدہلوی | | کوئٹہ | | |  |
| | میاں طارق شہزاد | | سی ایچ او ڈی ڈی | | |  |
| | حائفہ محمد ابراہیم خان | | ممبر ای این ایف ایف ڈی | | |  |
| | ایم ایف ایف ڈی | | ممبر ای این ایف ایف ڈی | | |  |
| | محمد سعید خان | | ممبر ای این ایف ایف ڈی | | |  |
| | صائمہ بیگم | | صدر ڈی این ایف ایف ڈی | | |  |
| | منگھو شہزاد | | PML N | | |  |
| | Aleem Khan | | PML N | | |  |
| | Adeel Maqsood | | ممبر ای این ایف ایف ڈی | | |  |
| | احمد شام داد | | صدر ای این ایف ایف ڈی | | |  |
| | جویریہ محمد مشہد | | سیکیورٹی ایڈمنسٹریٹر | | |  |
| | راول نور محمد | | ممبر ای این ایف ایف ڈی | | |  |
| | عمران امین | | ممبر ای این ایف ایف ڈی | | |  |




Verified by MC: CO/MO(I&S)

Municipal Committee Burewala
Consultative Session for IDAMP
Attendance Sheet

Dated:.....

Venue:.....

| Sr # | Name | Contact Number | Resident Address | Gender | Occupation | Sign |
|------|----------------|----------------|---------------------------|--------|------------|---------------|
| | Asif Ali | | صدر المحسن از ملک کٹرہندی | | | Asif Ali |
| | محمد علی | | کوئٹہ | | | M. Ali |
| | سید حامد | | سیدی | | | Hamid |
| | محمد عیاض | | عین سکریٹری ہر ملک | | | M. Ijaz |
| | ارشد ڈوگر | | ارشد ملک ہر ملک | | | A. Dogra |
| | محمد یونس | | سیدی | | | M. Younis |
| | محمد عامر | | سیدی | | | (Amir) |
| | محمد عثمان خان | | حزب سنی ہر ملک ہر ملک | | | (Uthman Khan) |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |


Verified by MC: CO/MO(I&S)

Banner and Participants Pictures







| Minutes of Meetings with Stakeholders for their Concerns | | | | | |
|---|--|--------------|---------------------------|---|---|
| Sr. No. | Agency / Department / Stakeholder | Date | Time | Representative | Issues / Needs / Preferences |
| 1. | MC-Burewala | May 11, 2023 | 11:10 AM – 11:45 AM | Mr. Imtiaz Ahmed Joiya (Chief Officer) | <p>Gave a clear understanding and introduction regarding the main features of project.</p> <p>Urgency and severity of present problems and issues in each sector of Burewala City.</p> <p>Sectoral planning and design of sectors, prioritized till 2030.</p> <p>Sectoral planning of sectors, prioritized till 2050.</p> <p>Insurance of Unit focusing on urban management and improvement of municipal services infrastructure for satisfactory service delivery.</p> <p>The allied facilities and a good infrastructure will be provided to the locals by prioritization of sectors.</p> |
| 2. | MC-Burewala | May 11, 2023 | 11:45 AM – 2:45 PM | Mr. Hafiz Muhammad Waseem (MfsO I&S) | <p>World Bank has started a great initiative to address the needs of general public.</p> <p>Unit officials will put all effort for the successful outcome of the project.</p> <p>All projects will be taken as per the suggestions and recommendation of the participants.</p> <p>Issues must be resolved with inclusive approach and collective wisdom.</p> <p>Community knows best about the issues occurring in the community that's why community engagement has been done at this level</p> <p>Committees will be established in each community for cleanliness of area</p> |

| | | | | | |
|-----------|--|--------------|-------------------------|--|--|
| | | | | | <p>State of the art machinery will be procured in next 2-3 months for solid waste management.</p> <p>Geo tagging of containers will be done for monitoring of the solid waste collection operations.</p> <p>All facilities including installation of dust bins, ducts for cabling etc. to be ensured during the design of roads.</p> |
| 3. | Councilor | May 11, 2023 | 2:45 PM – 3:30 PM | Mr. Sana Ullah (Councilor) | <p>Services provided by MC are not up to the mark. Hopefully implementation of this project public will be beneficial for the public.</p> |
| 4. | President Development Organization | May 11, 2023 | 2:45 PM – 3:30 PM | Ms. Saima Kanwal (President) | <p>General public will be get benefited through this project. There is a dire need carpeted road. There must be parks in Burewala City for public entertainment.</p> |
| 5. | Secretary Bar Council | May 11, 2023 | 2:45 PM – 3:30 PM | Ch. Muhammad Mushahid (Secretary) | <p>Some areas of Burewala are not properly maintained. City must have a hygienic environment.</p> |
| 6. | Vice President (Business Community) | May 11, 2023 | 2:45 PM – 3:30 PM | Rao Noor Muhammad (Businessman) | <p>The projects of The World Bank and PMDFC are admirable. This practice will help MC to provide better services to the public.</p> |

Closing of Session:

Overall the session was interactive and a great success in which healthy sharing of views took place. Session was closed with note of thanks.